

22/03/2001

ASS. REC. BY:

REF

CS3/SM019002256/Jcd3en

Special Instruction:

Surveyor  
menmen

Hue Jie

ASSIGNMENT (Office)

From (Person):

Huang shiang Yi

of

SMO

Date/Time:

8/2/19 @ 8.57am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 38758

Insured:

YP 87269

at Workshop m/s

Megastore Holdings

Tel:

9237 6951

of

25E Sungai Kerdut Street 1

Policy No:

DI8MTPEVE 001573

Claim No:

CMTD1900679

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/01/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9.25am @ 8/2/19

Person Contacted:

Mr. chong

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	YP 38758 - X
	YP 87269 - CS3/SM019002255/Jcd3
	DUA: 30/01/2019



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4015N
<b>Vehicle Details</b>	
Vehicle No.:	YP3875S
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	HINO
Vehicle Model:	HINO XZU710R-HKFMS3
Primary Colour:	Yellow
Manufacturing Year:	2016
Engine No.:	N04CUS28627
Chassis No.:	JHHUCS3H40K017987
Maximum Power Output:	-
Open Market Value:	\$31,742.00
Original Registration Date:	24 Aug 2016
First Registration Date:	24 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$1,588.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Aug 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$17,349.00
COE Rebate Amount:	\$13,067.00
<b>Total Rebate Amount:</b>	<b>\$13,067.00</b>

The information contained herein is correct as at 11 Feb 2019

OK

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2019		08 Feb 2019 08:57 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM SIANG HUAT PTE LTD, Co. Reg. No.: 199803003N		
Main Claimant:	MEGASTONE HOLDINGS PTE LTD, Co. Reg. No.: 199504015N		
Vehicle Reg. No.:	YP3875S	Date of Loss:	30/01/2019 16:00 - :59
Claim Type:	TP / CMTD1900679	Policy/Cover Note No.:	D18MTPCVE001573 (Comprehensive)
Vehicle Reg. No. (Insured):	YP8726G	Policy No. (Claimant):	
		Excess:	
Repairer:	MEGASTONE HOLDINGS PTE LTD (HQ) 25E Sungei Kadut Street 1, 729333 Sungei Kadut - Tel: 63652066		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2019]		
Driver/Custodian (Insured):	ZHANG KAI (), NRIC: G2243806P, Tel: +6584512066		
Adj Asg. Remarks:	PIC: MR CHONG CHEE KONG / 92376951 DID 63652639		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/02/2019 12:08
Date Of Accident	30/01/2019 16:10
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	YP3875S
Insured/Policyholder	
Name Of Registered Owner	MEGASTONE HOLDINGS PTE LTD
Co Reg No	199504015N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96146409
Vehicle Particulars	
Manufacturer	HINO
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28813308 MKC
Cover Note Number	
Driver	
Name of Driver	RAMASAMY KUMAR
Passport No/FIN	G7587792M
Date Of Birth	20/04/1984
Occupation	INDOOR
Date Of Driving Pass	21/11/2015
Driving Experience	3 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96146409
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address ---  
Postcode  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 3  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 5  
Passenger 1 NAME: : ---  
GENDER: : MALE  
Passenger 2 NAME: : ---  
GENDER: : MALE  
Passenger 3 NAME: : ---  
GENDER: : MALE  
Passenger 4 NAME: : ---  
GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. VEHICLE NOT AT IDAC, MSIG ASKED TO GO AHEAD WITH THE REPORT.

#### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP8726G  
Vehicle Make/Model/Colour  
Details Of Properties

Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number XB9541B  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**IDAC BUKIT BATOK (VAC)**  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbb@singnet.com.sg

  
Policyholder's Signature  
Date & Time: 1/2/2019




  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



YP3875S

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30 January 2019 at about 16:10 hours, I was driving YP3875S and being escorted by TMA XB9541B. While we were driving within our lane, suddenly, Vehicle B (YP8726G) hit onto the right side of XB9541B (TMA). Thereafter, Vehicle B (YP8726G) collided onto the right side of my vehicle.

I wish to state that Vehicle B hit onto XB9541B and there after collided onto my vehicle (YP3875S).

There was no injury involved. We exchange our driver's particulars and continue our journey.

Vehicle A : YP3875S


Vehicle B : YP8726G (caused the accident)

~~XXXXXXXXXX~~

Vehicle C : XB9541B

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 1/2/2019





Driver's Signature  
(If driver is not the policyholder)

Date & Time:

IDAC BUKIT BATOK (VAC)

511 Bukit Batok Street 23

Singapore 659545

Tel: 6560 3312 Fax: 6569 0722

Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)





































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2019		08 Feb 2019 08:57 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>




  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>LIM SIANG HUAT PTE LTD</b> , Co. Reg. No.: 199803003N								
Main Claimant:	<b>MEGASTONE HOLDINGS PTE LTD</b> , Co. Reg. No.: 199504015N								
Vehicle Reg. No.:	<b>YP3875S</b>	Date of Loss:	30/01/2019 16:00 - :59 [29 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / CMTD1900679</b>	Policy/Cover Note No.:	D18MTPCVE001573 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>YP8726G</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>MEGASTONE HOLDINGS PTE LTD (HQ)</b> 25E Sungei Kadut Street 1, 729333 Sungei Kadut - Tel: 63652066								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Hwang Shiang Yi</b> - 6329 5205]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... <b>[Final Rpt due 19/02/2019]</b>								
Driver/Custodian (Insured):	ZHANG KAI (), NRIC: G2243806P, Tel: +6584512066								
Adj Asg. Remarks:	PIC: MR CHONG CHEE KONG / 92376951 DID 63652639								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*YP3875S (CMTD1900679)**  
**[YP8726G]**  
**TP**  
**MEGASTONE HOLDINGS PTE LTD**  
**Jan 30 2019 4:00PM**  
**[LIM SIANG HUAT PTE LTD]**  
**MEGASTONE HOLDINGS PTE LTD**

Upload Documents		Upload Photos		Compose New Letter		View		View In Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
2	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
3	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
4	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
5	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
6	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
7	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
8	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
9	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
10	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
11	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
12	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
13	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
14	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
15	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
16	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
17	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
18	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
19	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
20	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
21	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
22	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
23	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
24	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
25	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
26	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
27	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
28	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
29	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
30	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
31	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
32	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
33	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
34	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
35	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	
36	11/02/19 09:50	General View						<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/19 15:51	PRI FR MEGASTONE HOLDINGS - YP3875S	 Load PDF	
2	07/02/19 16:15	Third Party E-filed GIA report(M)	 Load PDF	
3	08/02/19 08:55	TP - ASSIGN LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19002256/JCD3E2

Date: 20/02/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001573
Claimant Vehicle No :	YP3875S	Insured Vehicle No :	YP8726G
Date of Loss:	30/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900679

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	YP3875S	Engine No:	N04CUS28627
Make & Model:	HINO XZU710R-HKFMS3, 4.0 D (M)	Chassis No:	JHHUCS3H40K017987
Reg. Date:	24/08/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16
Front Left Side:	OHTSU 7 mm	Rear Left Side:	OHTSU 7 mm
Front Right Side:	OHTSU 7 mm	Rear Right Side:	OHTSU 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	08/02/2019	
Date Inspected:	08/02/2019 Inspected At:	MEGASTONE HOLDINGS PTE LTD (HQ) 25E Sungei Kadut Street 1 Singapore 729333
Estimated Period of Repair:	6.0 days	

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,500.00 -\$8,500.00

## REPAIR DETAILS

### Reference

**Part Source:****Parts:** N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for YP3875S)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >