

2400000

ASS. REC. BY:

REF: CDS/MSG/18.02.1093/TISDST Special Instruction:

SMV/CS/1

Indemnity

From (Person):

Juwyn Tay

of

MSH

Date/Time: 21.11.2018 3:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGS 7135R

Insured:

XD 781Z

at Workshop n/w:

JCM Rental

Tel:

6764 3438

of

1 Bukit Batok Crescent 104-47

Policy No:

MSD/YCT/18-001016-00

Claim No:

MSC/V/18-001511

Sum Insured:

Excess:

Make of Veh.

D.O.A 17-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

21-11-2018

H.O.D. Endorsement:

Date/Time:

21.11.2018 4:26pm

Person Contacted:

Mady

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SGS 7135R - X

XD 781Z - X

Repair Net Value: 96643

RECEIVED 05 MAR 2019


 5/3/2019

Tanglin

REF:

msl6

ASSIGNMENT

CWE 2022 March

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

20

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

battery weak

Veh No:

89S7135R

Vr Reg:

2007 March

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mykhi's Lancer 1.6A. CC 1584

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp. Reading:

T/Radio:

Insured / Std / NI / NA

Eng No:

C No:

JMYSTC55A74009352

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRM / STD Air / Rim or

Tyre Size:

F:

145/105R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A

D.O.I

22/1/18

Survey held at

Jen Rental

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt d/s, Frt, d/s, 4/C

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

battery weak

1st & 2nd Contact #04-47

Estimated repair range \$15,000 - \$18,000.

- No economical to repair.

30/11/2018.

Date/Time: File Page 01

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return 01

2)

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Workshop \$

Report Format:

PRE.

Lump Sum / I.B. / I.S

Days Of Repair:

20

Resurvey No. of Trip:

-

Survey Fee:

Transportation

1.00 - 100.00

Photos

Labors

120

10

130

GURDEEP SINGH SEKHON
CHA FOK SENG
REY FOO JONG HAN
JOH LAM CHUAN
VINDER SINGH
P. PADMAN
KWEH SOON HAN
PRADEEP KUMAR GOBIND
RUE JIAPEI
MUNIRAH BINTE MYDIN
LIM YUN HENG
SHANEN SIO NANOO SIVA DAS

KSCGP

J U R I S L L P

*Celebrating 25 Years of
Professional and Personalised
Legal Service*

REG/CS/PAY/

28 JAN 2019

MAIN OFFICE:

10 Hoe Chiang Road, #13-03A

Keppel Towers,
Singapore 089315

Tel: 6538 3611

Fax: 6538 3708

Website: www.kscgp.com

(Fax/Email not for service of court documents)

Registered in Singapore with limited liability

as a Limited Liability Partnership

Registration Number T10LL1855L

DID: 3152 0985

Email: jiapei@kscgp.com

Your Ref : MSC/V/18-001511

Our Ref : GS/18/5478/JCM/jp/el

Date : 25 January 2019

MSIG Insurance (Singapore) Pte. Ltd.

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

BY HAND

Dear Sirs,

JCM RENTAL PTE LTD

C/o 10 Hoe Chiang Road #13-03A Keppel Towers Singapore 089315

ACCIDENT INVOLVING SGS 7135R AND XD 781Z ALONG PAN-ISLAND EXPRESSWAY
("PIE") TOWARDS TUAS BEFORE PIONEER ROAD NORTH ON 17.11.2018

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 17 November 2018 along Pan-Island Expressway ("PIE") towards Tuas before Pioneer Road North, involving our client's motor vehicle bearing registration number SGS 7135R and the motor vehicle bearing registration number XD 781Z, which was insured by you at the material time.

We are instructed that the accident was caused by the negligent driving and/or management of the authorised driver of XD 781Z. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

(1)	Total Loss	-	\$	8,497.00
(2)	Loss of use (\$80 per day x 30 days)	-	\$	2,400.00
(3)	Survey fees	-	\$	650.00
(4)	LTA	-	\$	10.00
(5)	GIA search	-	\$	29.00
(6)	Incidentals	-	\$	100.00
(7)	Costs	-	\$	900.00
(8)	GST on items (6) & (7)	-	\$	70.00
			\$	12,656.00

BRANCH: PRIVATE PROPERTY CONVEYANCING
490 Lorong 5 Toa Payoh Biz 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6258 1825

BRANCH: HDB CONVEYANCING
490 Lorong 5 Toa Payoh Biz 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6258 1409

BRANCH: SHIPPING, ADMIRALTY & COMMERCIAL
82 Arab Street #03-01 & #03-02
Singapore 169789
Tel: 6634 1348 Fax: 6634 1358

BRANCH: CORPORATE & LITIGATION
61 Robinson Road
#15-02 Robinson Centre
Singapore 068893
Tel: 6617 8795 Fax: 6224 1812

The information contained in this letter / facsimile message is CONFIDENTIAL and may also be LEGALLY PRIVILEGED, intended only for the individual or entity named above. If you are not the intended recipient, you are hereby notified that any use, revelation, dissemination, distribution or copying of this document is strictly prohibited. If you have received this document in error, please notify us immediately by telephone (call the number above) and destroy the original message.

A copy each of the supporting documents are enclosed.

S/NO.	AVAILABLE DOCS	PARTICULARS
<u>Client's Documents</u>		
1.	17.11.2018	GIA Statement / Traffic Police report
2.		Witness(es) Statement
3.		Accident site photographs
4.		Video footage / CCTV / CD recording
5.		Repair bill / invoice / Excess Tax invoice
6.		Rental bill / invoice and agreement / receipts
7.		Vehicle Entry Permit receipt / E-day license for off-peak vehicle
8.		Towing fees / receipt (Singapore / Malaysia)
9.		Client sold off vehicle and produce letter from LTA
10.		Spare Part Ordering Form
11.		Levy at Custom / receipts
12.	14.01.2019	Survey invoice and surveyor's report
13.	14.01.2019	36 Original / Copies of damage photographs
14.		Enquire PARF / COE Rebate for Registered Vehicle
15.		Enquire Transfer fee
16.		Certificate of Insurance / Motor Cover Note / New Policy Schedule / Registration Card / Grant / Road Tax
17.	20.11.2018, 21.11.2018	Pre-repair Inspection Notices
18.		Traffic Police investigation results
19.		Estimated agreement between surveyor and repairer
20.	20.11.2018	Tax invoices and search results from General Insurance Association of Singapore (GIA) and Traffic Police search fees
<u>Third Party's Documents</u>		
21.	17.11.2018	GIA Statement / Traffic Police report
22.		Admission Note
23.	20.11.2018	LTA search / receipt / tax invoice
24.		Malaysia Vehicles Searches / service
25.		RCB / ACRA search
26.		Enhanced Individual search / receipt
27.		Property tax search / receipt
<u>Others (Apply only in chain collisions and/or any other documents)</u>		
28.		

We have, on 20 November 2018 and 21 November 2018, notified you of the accident and a pre-repair inspection of our client's motor vehicle was carried out by the appointed surveyors.


Subject to our client's instructions, please confirm in writing within 7 days hereof if you or your insured wish to inspect our client's vehicle or conduct a second re-inspection.

Please note that you or your insured should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured. In this event, you will be liable for any and all legal costs incurred.

Please also note that if your insured has a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter, which we will then forward to our client and/or the insurers for consideration on a without prejudice basis.

For avoidance of doubt, kindly note that this claim is made without prejudice to our client's personal injury claim.

Yours faithfully,



(Main Office)

Enc.

Cc client

Cc owner – Watt Wah Petroleum Pte Ltd

Cc driver – Ng Tong Soon



PRO
PLUS
AUTOMOBILE
ENGINEER

221 Balestier Road #10-01 Rocco Balestier Singapore 329828
Tel: (65) 6256 5255 Fax: (65) 6352 8802 Email: ethan88@singnet.com.sg / ethan88@gmail.com
Mobile: +65 96730595 / +65 9788 9808 / +65 96999248
Company Registration No: 40166800M

Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.

TO:

M/s JCM Rental Pte Ltd
1 Bukit Batok Crescent
#04-47 WEGA Plaza
Singapore 658064

INVOICE NO. 29673

OUR REFERENCE : PP/ET/CT.7135.TL.1-19

YOUR REFERENCE:

DATE : 14 January 2019

VEHICLE REGISTRATION NO : SCS 7135 R
VEHICLE MAKE /MODEL : Mitsubishi Lancer 1.6 (A)

- ☒ TO INSPECTION / APPRAISAL FEES / TOTAL LOSS
☐ TO AFFIRM AFFIDAVIT ON
☐ TO COURT ATTENDANCE ON
☐ TO REINSPECTION FEES
☒ TO PHOTOGRAPHY
☒ TO TRANSPORTATION CHARGES

- ☐ OTHERS (SPECIFY)
☐ SINGAPORE DOLLARS: SIX HUNDRED & FIFTY ONLY
☐

S\$ 650.00

E & O. E.



for PRO PLUS AUTOMOBILE ENGINEERS



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethan88@singnet.com.sg Email: ethan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

Our Ref : PP/ET/CT.7135.TL.1-19

14 January 2019

M/s JCM Rental Pte Ltd
1 Bukit Batok Crescent
#04-47 WCEGA Plaza
Singapore 658064

WITHOUT PREJUDICE

Dear Sirs,

SUBJECT : CONSTRUCTIVE TOTAL LOSS
VEHICLE REGISTRATION NO : SGS 7135 R
MAKE/MODEL : Mitsubishi Lancer 1.6 GLX (Auto)

We refer to your instruction to appraise the above-mentioned vehicle on 17 November 2018.

A static inspection was carried out and our report is enclosed for your perusal. The repair costs verbally quoted by several repairers is estimated to be in the region of a contract lump sum of \$14,000.00 NETT. The attached synopsis, prepared by ourselves, covering the damaged components, but without quotations, has been re-checked thoroughly by us against the actual damages sustained on the vehicle.

We have also been advised by the repairers, that, there may be a further supplementary quotation when repair commences. Invariably, the damages will not be known unless the parts/components are being dismantled for examination.

In consideration of the above, we are of the opinion, that this vehicle is too severely damaged to warrant economical repairs. Moreover, many of the damaged parts/components are unavailable at the local ' MITSUBISHI ' agent and may have to be imported/ordered from the country of origin. Apparently, freight charges are not included in the repair costs and this has to be borne by the insured initially.

Perpetually, we are of the conviction that this vehicle is too wholly unfit for further use pursuant to the Road Traffic Act, Cap.276 Rule 27 (d) Edn 1994. The n/s front chassis member is badly twisted, and replacement have to be certified by a Professional Engineer [PE], and subsequently approved by the Land Transport Authority. Moreover, replacement of chassis members, in our opinion, would also affect the vehicle uni-structural frame/body. Thus, we are recommending that this vehicle be written off as a ' **CONSTRUCTIVE TOTAL LOSS** '.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	
Owner ID:	Company
Vehicle Details	1659M
Vehicle No.:	
Vehicle to be Exported:	SG57135R
Intended Deregistration Date:	No
Vehicle Make:	03 Dec 2018
Vehicle Model:	MITSUBISHI
Primary Colour:	LANCER 1.6 A
Manufacturing Year:	Silver
Engine No.:	2007
Chassis No.:	4G18HY2337
Maximum Power Output:	JMYSTC53A7U009352
Open Market Value:	79.0 kW (105 bhp)
Original Registration Date:	\$11,116.00
First Registration Date:	22 Mar 2007
Transfer Count:	22 Mar 2007
Actual ARF Paid:	3
Intended PARF Rebate Details	\$12,228.00
PARF Eligibility:	
PARF Eligibility Expiry Date:	Forfeited
PARF Rebate Amount:	-
Intended COE Rebate Details	\$0.00
COE Expiry Date:	
COE Category:	21 Mar 2022
COE Period(Years):	E - Open Category
PQP Paid:	5
COE Rebate Amount:	\$24,715.00
Total Rebate Amount:	\$16,357.00
Message	\$16,357.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Nov 2018

OK

Market Value: \$23,000

Rebate: \$16,357

Nett: \$6,643 #

...../2

FINANCIAL ANALYSIS

(A) MARKET VALUE

The market value for this vehicle as at 17 November 2018 is estimated at \$25,000.00 .

(B) PREFERENTIAL ADDITIONAL REGISTRATION FEE [PARF]

Not applicable

(C) PREVAILING QUOTA PREMIUM [PQP]

A sum of \$24,715.00 was paid on 21 March 2018. Balance as at 17 November 2018 is stipulated at \$16,503.00

(D) COMPUTATION

SENARIO A : TO TREAT VEHICLE FOR ' CONSTRUCTIVE TOTAL LOSS '

Treating this vehicle for ' CONSTRUCTIVE TOTAL LOSS ', the third party's insurance liability is estimated according to the following formula:-

$$\begin{aligned} & (\text{Market Value}) - (\text{PQP}) \\ & = \$25,000.00 - \$16,503.00 = \$8,497.00 \end{aligned}$$

(E) COMPUTATION

SENARIO B : TO REPAIR VEHICLE TO ITS PRE-ACCIDENT CONDITION

The estimated cost of repairs to restore this vehicle to its pre-accident condition is about \$14,000.00 NETT [contract lump sum repairs] excluding supplementary quotations

COMPARISON OF SCENARIOS A & B

Comparing the costs derived from paragraphs (D) & (E), it can be seen that the third party's insurance liability would be reduced by a hefty \$5,503.00 [estimated]. If this vehicle would to be written off as a ' CONSTRUCTIVE TOTAL LOSS '

...../3

4-4

...../3

Note :

- * *Figures quoted are approximate.*
- * *A copy of Enquiry for PARF/COE dated 19 November 2018 enclosed.*

CONCLUSION

The vehicle is recommended for ' **CONSTRUCTIVE TOTAL LOSS** ' at the market value of **\$25,000.00**. It would be uneconomical to repair this vehicle to its road-worthy/pre accident condition. The third party's liability is approximately at **\$8,497.00**.

We have not given any instruction to the repairer to dispose the vehicle .

We are reverting this matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Very truly yours,
PRO PLUS AUTOMOBILE ENGINEERS



Errol Tan
Licensed Appraiser & Automobile Engineer

Encls:

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please contact us immediately by telephone so that we can arrange for its return.



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329828
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

VEHICLE INSPECTION REPORT

To: M/s JCM Rental Pte Ltd
1 Bukit Batok Crescent
#04-47 WCEGA Plaza
Singapore 658064

Insured :
Policy Number :
Claim Number :
Our Reference : PP/ET/CT.7135.TL.1-19
Own Damage/Sum Insured :
Excess :
Third Party/Insce Company :
Date : 14 January 2019

Instructed By : Ms Merly Ng
Date of Assignment : 18 November 2018
Date of Accident : 17 November 2018
Date of Inspection : 19 November 2018
Name of Workshop : JCM Rental Pte Ltd
Place of Inspection : 1 Bukit Batok Crescent
#04-47 WCEGA Plaza
Singapore 658064

PARTICULARS OF DAMAGED VEHICLE

Registration Number	: SGS 7135 R	Odometer Reading	: - Km
Make/Model	: Mitsubishi Lancer 1.6 (A)	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2007	Air Conditioner	: Fitted
Engine Number	: 4G18HY2337	View Mirrors	: Fitted -O/s & n/s*
Chassis Frame Number	: JMYSTCS3A7U009352	Seat Belts	: Fitted -Front & rear
Class/Type	: Passenger (Saloon)	Other Accessories	: (Specify)
Colour	: Metallic Silver		

PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine	
Paintwork	: Good	Modification/s	: -
Footbrakes	: Serviceable	Market Value	: -
Steering	: Serviceable	Scrap Value (PARF/OMV)	: -
Undercarriage (Front)	: O/s & n/s affected by accident		
Undercarriage (Rear)	: N/s affected by accident		

TYRE CONDITIONS ON VEHICLE

		NEAR SIDE	OFF SIDE
		70%*	70%
Front (Size)	: 195/60R15		
MAKE	: Nexen		
Rear (Size)	: 195/60R15	70%*	70%
MAKE	: Nexen		
SPARE (Size)	: -	-	
MAKE	: -		
Type of Road Wheels	: Alloy		

NOTE: The above percentages represent the estimated remaining life of the tyre threads


* Denotes damaged component/s

PRO PLUS AUTOMOBILE ENGINEERS

IMPACT OF VEHICLE

Direction of Impact (→)

Our investigation enclosed that the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the entire n/s body length. The encroachment resulted in the vehicle to collide with a man-made structure at its n/s front, & subsequently, its n/s front to crash onto a road divider. Apparently, the n/s n/s front & rear & its n/s front wheels were struck-upon, thus, damaging their suspension members/drive trains & misaligning their wheels cambers/geometries.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

☐ Damage Areas

Damages sustained were the front windscreen -cracked, bonnet & its inner reinforcement- dented/bent/buckled/warped over an extensive area, bonnet hinge n/s & n/s- bent/twisted, bonnet inner lock/catch- bent/shifted/disrupted, front bumper assembly, n/s front fender & its inner panel- dented/buckled, front support panel- thrusts inwards/buckled resulting in the air conditioner condenser & radiator assemblies- bent/shifted/ruptured, front door pillar n/s- buckled, n/s front & rear door & their inner reinforcement- crumpled, front suspension members n/s & n/s- bent/buckled/elongorous, bootlid & its inner reinforcement- dented/bent/buckled/warped over an extensive area, bootlid inner lock/striker- bent inwards/shifted, rear end panel- thrusts inwards/buckled, rear bumper assembly, rear fender n/s- buckled/warped, rear door lock pillar/dog leg n/s- buckled/sandwiched with n/s rear door assembly, centre door pillar n/s- buckled, front & rear chassis members- bent/misaligned etc-----

ESTIMATE

The estimate submitted by M/s JCM Rental Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts			Estimated number of days for repairs: NA
Labour Charges			
Paint Work			
Towing Charges			Number of photographs taken at time of static inspection: 36
Others			
TOTAL			

Remarks: In view of the above damages and cost of repairs, we suggest that this vehicle be written off as a ' CONSTRUCTIVE TOTAL LOSS '. This would save unwarranted time and expenses.

NOTE: The revised estimate was made from a visual inspection. Any discrepancies or missing damages should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.

Your Ref : XD 781Z.

Our Ref : SGS 7135R/JCM/jp/ps

Date : 20 November 2018

Fax : 6538 3708

Tel : 3152 0989

Email : accident@kseggp.com

MSIG Insurance (Singapore) Pte Ltd

BY FAX 6643 1349 ONLY

DATE OF ACCIDENT: 17 NOVEMBER 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of SGS 7135R to notify you of a road traffic accident on 17 November 2018 at about 11.30 am along PIE towards TUAS before Pioneer Road North, involving our client's vehicle registration number SGS 7135R and vehicle registration number **XD 781Z** which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

PS

Enc.

Your Ref : XD 781Z

Our Ref : SGS 7135R/JCM/jp/ps

Date : 21 November 2018

Acknowledgement

This is to confirm that I _____ [Full Name of Surveyor] of
_____ [Surveyor's Company] have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post - Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-179779
Date of Request: 20/11/2018

Your Ref No: SGS 7135R/JCM/JP/PS

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 17/11/2018
Place of Accident: PIE TWDS TUAS - PIONEER RD NRT
Client Vehicle No: SGS7135R

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-179783

Date of Request: 20/11/2018

Your Ref No: SGS 7135R/JCM/JP/PS

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Date of Accident: 17/11/2018

Vehicle No: SGS7135R

Location of Accident: PIE TOWARDS TUAS BEFORE PIONEER RD NORTH

Involving Vehicle No: XD781Z

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
XD781Z	PIE TOWARDS TUAS BEFORE PIONEER RD NORTH	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

a:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2018 11:32
Date Of Accident	17/11/2018 11:30
Exact Location Of Accident	PIE TOWARDS TUAS BEFORE PIONEER RD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS7135R
Insured/Policyholder	
Name Of Registered Owner	JCM RENTAL PTE LTD
Co Reg No	0
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98358403
Alternative Phone No	OFFICE-98358403

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	A 28958730 TMC
Cover Note Number	

Driver

Name of Driver	HAVIN D/O JOIHN JAYARAJ
NRIC No	S8103218A
Date Of Birth	15/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	11/03/2011
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98358403
Fax Number	
Contact Number	OFFICE-98358403
Email Address	NOEMAIL

Address	11 JURONG LAKE LINK
Postcode	S648155
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 92 BOON LAY WAY , POSTCODE: 609962 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8999999 - FAX NO: 66655791
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD781Z
Vehicle Make/Model/Colour	TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	HAVLIN D/O JOHN JAYARAJ
Approximate Age	
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	SGS7135R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

20 NOV 2018

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC BUKIT BATOK (VAC)
 511 Bukit Batok Street 23
 Singapore 659545
 Tel: 6560 3312 Fax: 6569 0722
 Email: vacbb@singnet.com.sg
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

A: S457B52

B: XD781Z

- (i) first impact: impact on (A) left rear
- (ii) to (iii) dragged 150m from lane 1 to lane 4.
- (ii) (A) hit divider on right front.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg



**SINGAPORE
POLICE FORCE**



T/20181117/2130

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

1 of 3

Report No T/20181117/2130

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/11/2018 20:12		Vide Report No.: J/20181117/0151		Station Diary No.: 91
Informant's Particulars				
Name of Informant: HAYLIN D/O JOHN JAYARAJ		Address: 11 JURONG LAKE LINK #08-37 SINGAPORE 648155		
ID Type / ID No.: NRIC NO / S8103218A		Contact No.: Home/Office: Mobile: 98356403		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Female	Age: 37	Date of Birth: 15/05/1981	Type of Informant: Driver	
Race: Indian		Language: English		Institution / School Name:
Occupation: SELF EMPLOYED		Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury: Attended by Police	Drink Drive: No	Date/Time of Accident: 17/11/2018 11:30	Type of Location:
Location: Along Road 1 Traveling Toward Road 2 PAN ISLAND EXPRESSWAY Along PIE towards Tuas before Pioneer Road North Exit at Nanyang Flyover				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGS7135R	Car				Seriously Damaged	0
XD781Z	Lorry				Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Scanned by CamScanner



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999



T/20181117/2130

2 of 3

Report No. T/20181117/2130

CONTINUATION OF REPORT

Driver	Name	HAVLIN D/O JOHN JAYARAJ	ID No.	S8103218A
Related Vehicle	SGS7135R (Car)	Contact No.	98358403	
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL	
Date Treatment	17/11/2018	Date Discharge	17/11/2018	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	

Brief Details.

On 17/11/2018 at about 1130hrs, I was driving a rental car, a silver in colour Mitsubishi Lancer, bearing registration plate number SGS7135R, along PIE towards Tuas on the most right lane. While travelling along Nanyang Flyover before Pioneer Road North Exit, I noticed an Esso Oil Tanker, bearing registration plate number, XD781Z, swerving from the 2nd lane. I noticed that the driver's head was on the steering wheel. The lorry then collided into the car I was driving causing me to collide into the railing on the right and subsequently dragged my car to the most left lane.

After my vehicle stopped moving, I managed to get out of the vehicle and my nose and lips were bleeding. I then waved at oncoming vehicles to try to ask them to call for help. Fortunately, a driver stopped and assisted to call for help. Subsequently, Traffic Police and Ambulance came and conveyed me to Ng Teng Fong General Hospital. I suffered a cut on my upper lip and bleeding from my nose. I was given 3 days of MC from 17/11/2018 to 19/11/2018.



SINGAPORE POLICE FORCE

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999



T/20181117/2130

3 of 3

Report No. T/20181117/2130

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sgt 2 MUHAMMAD ZAINULARIFFIN BIN MOHD
ZAINUDIN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
SI YEO CHUN JIAN
Contact No.: 65476213

Authentication Stamp
NP158

Signature Of Informant:

Date/Time:
17/11/2018 20:12

Classification Of Case:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/11/2018 09:37
Date Of Accident	17/11/2018 12:00
Exact Location Of Accident	PIE TOWARDS TUAS (LP : 1821)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD781Z
Insured/Policyholder	
Name Of Registered Owner	WATT WAH PETROLEUM PTE LTD
Co Reg No	0
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96967676
Alternative Phone No	OFFICE-67622167

Vehicle Particulars

Manufacturer	SCANIA
Model	TRUCK
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VCT/18-001016-00
Cover Note Number	

Driver

Name of Driver	NG TONG SOON
NRIC No	S1218787D
Date Of Birth	25/06/1956
Occupation	OUTDOOR
Date Of Driving Pass	24/10/1978
Driving Experience	40 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96967676
Fax Number	
Contact Number	OFFICE-96967676
EEmail Address	NOEMAIL

Address	179 LOMPANG ROAD #18-20
Postcode	S670179
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NOT WORKING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS7135R
Vehicle Make/Model/Colour	MIT LANCER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name DRIVER

Approximate Age

Injuries Sustain

REFER TO POLICE REPORT

Injured person in which vehicle?

SGS7135R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

19 NOV 2018
[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT TIMAH (13/10/18)
511 Bukit Timah Road #20
Singapore 259565
Tel: 6593 2012 Fax: 6593 0722
Email: idac@idac.org.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A hand-drawn diagram on lined paper. A curved line starts from the bottom left and goes up towards the top right. The word "Price" is written in cursive below the curve, and the word "Profit" is written in cursive above the curve.

DECLARATION

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature
Date & Time:



Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



Ng Tong Soon



**SINGAPORE
POLICE FORCE**



T/20181117/2136

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 3

Report No. T/20181117/2136

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/11/2018 20:43		Vide Report No.: J/20181117/0151		Station Diary No.: 127	
Informant's Particulars					
Name of Informant: NG TONG SOON			Address: APT BLK 179 LOMPANG ROAD #18-20 SINGAPORE 670179		
ID Type / ID No.: NRIC NO / S1218787D			Contact No.: Home/Office: 67622167 Mobile:		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 25/06/1956	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 2B,2A,2,3,4,5 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/11/2018 12:00	Type of Location:
Location: Along Road 1 PAN ISLAND EXPRESSWAY On PIE towards Tuas, after lamppost 1821 Lamp Post Number: 1821				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SGS7135R	Car	MITSUBISHI	LANCER 1.6 A	Silver	Seriously Damaged	1
XD781Z	Lorry	SCANIA	P340LA4X2 MNA	White	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181117/2136

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 3

Report No. T/20181117/2136

CONTINUATION OF REPORT

Driver			
Name	NG TONG SOON	ID No.	S1218787D
Related Vehicle	XD781Z (Lorry)	Contact No.	67622167
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/11/2018 at about 1200HRS, I was driving my vehicle XD781Z along PIE towards Tuas, the ground was wet as it was raining previously. It was at the area of Jalan Bahar and Pioneer Road North at lamp post 1821. That was when a car, SGS7135R tried to drive into my lane in front of my vehicle and I could not brake in time. My vehicle collided into the side of the vehicle and the accident moved towards the road shoulder. Both our vehicles were severely damaged.

Traffic police and ambulance both attended to our scene and I was issued a case card J/20181117/0151. A woman from the vehicle was conveyed to hospital by the ambulance. I was not injured severely and I have not seen the doctor yet. I was unable to exchange particulars with the other party.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20181117/2136

3 of 3

Report No. T/20181117/2136

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 TEO MING EN, RYAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

17/11/2018 20:43

Officer In Charge Of Case:

TP / GIT /

SI YEO CHUN JIAN

Contact No.: 65476213

Classification Of Case:

Authentication Stamp

NP168



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2018		21 Nov 2018 15:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case






































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WATT WAH PETROLEUM PTE LTD , Co. Reg. No.: 198600942D, Tel: +6596967676								
Main Claimant:	JCM RENTAL PTE LTD , Co. Reg. No.: 201711659M								
Vehicle Reg. No.:	SGS7135R	Date of Loss:	17/11/2018 12:00 - :59 [139 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001511	Policy/Cover Note No.:	MSD/VCT/18-001016-00 (Comprehensive) Coverage: 11/09/2018 - 31/12/2019						
Vehicle Reg. No. (Insured):	XD781Z	Policy No. (Claimant):							
		Excess:	S\$4,200.00						
Repairer:	JCM Rental Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-47 Wcega Plaza, 658064 Bukit Batok - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/02/2019]								
Driver/Custodian (Insured):	NG TONG SOON (62 / Male) , NRIC: S1218787D, Tel: +6596967676 Email:								
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY UNCLEAR Please appoint LXX AUTO to conduct the survey . Kindly contact MS MERYL NG @ 9138 1928 or 6734 3438 to arrange for survey.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (31/01/2019): Report Send Back Alerts - SGS7135R (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




































Claim Documents

*SGS7135R (MSC/V/18-001511)
[XD781Z]
TP
JCM RENTAL PTE LTD
Nov 17 2018 12:00PM
[WATT WAH PETROLEUM PTE LTD]
JCM Rental Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/12/18 13:09	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
58	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
59	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
60	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
61	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
62	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
63	06/12/18 13:10	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/11/18 10:54	TPD SGS7135R GIA REPORT	 Load PDF	
2	21/11/18 10:54	OI XD781Z GIA REPORT	 Load PDF	
3	21/11/18 11:45	TPD SGS7135R - PRI	 Load PDF	
4	21/11/18 11:48	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	
5	30/01/19 10:17	LOD with supporting documents - SGS7135R	 Load PDF	
6	30/01/19 10:17	TPD SGS7135R - COLOUR PHOTO A	 Load PDF	
7	30/01/19 10:17	TPD SGS7135R - COLOUR PHOTO B	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/19 11:08	PRS Invoice	 Load PDF	
2	06/03/19 11:08	Colour Photo	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18021093/T1SD3E2-1

Date: 06/03/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCT/18-001016-00
Claimant Vehicle No :	SGS7135R	Insured Vehicle No :	XD781Z
Date of Loss:	17/11/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-001511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS7135R	Engine No:	4G18HY2337
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A7U009352
Reg. Date:	22/03/2007 (Man. Year: 2007)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/11/2018	
Date Inspected:	22/11/2018 Inspected At:	JCM Rental Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-47 Wcega Plaza Singapore 658064
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

TOTAL LOSS ASPECT

Market Value : \$23,000.00
OMV : \$11,116.00
PARF Rebate (1) : \$0.00
Quota Premium Paid : \$24,715.00
COE Rebate (2) : \$16,357.00
Total Rebate (1) + (2) = : \$16,357.00

The total amount incurred will be Market Value \$23,000.00 minus Total Rebate \$16,357.00 = \$6,643.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 13 Dec 2018)

Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGS7135R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >