

Surveyor:

KASUL

DOI:

ASSIGNMENT

16/02/19

Date / Time:

7/2/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLA 8607 A

Claim No.:

59m01026

Name of Insured:

CHINA HOCK LENG

Policy No.:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

7/2/19

Make / Model:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLC 8986 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah motor.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/2
2/19SLC 8986 U. X;
SLA 8607 A. C/L/ARA 1700 2137/1006/19 : 00A: 21/11/19

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 12/02/19 - JIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: DO NOT

12/02/19

FILE REOPENED. OI REPAIR-ENDED TP. SEND
LETTER & EMAIL TO OI TO NOTIFY TP
C/L/ARA & NCD ISSUES.01/03/19 @
10:00AMEMAIL LIABILITY CLERK
GROUP TO OI. CONTINUED ACCIDENT
DURING IN REPAIR-ENDED TP. INFORMATION
TP C/L/ARA, REQUESTED TO RETURN IN AVAILABLE
NCD ISSUES.

UPLOADED 14 IN 00.

FINISHED

TP LOD IN BY EMAIL

02/03/19

UPLOADED PHOTOS UPDATE 14.

02/03/19

AXA APPROVED MANDATE

22/03/19

SEND ACCEPTANCE EMAIL TO TP.

23/03/19

RECEIVED DV. ALL DOCS IN ORDER.

TO CLOSE.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: PIP

SS 7,995.46 (5 days) Reduction: 51 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: C/L/ARA

SS 8,555.14

(OI REPAIR-ENDED TP)

Loss of Rental (LOR):

SS - (days)

Loss of Use (LOU):

SS 500.00 (500 x 5 days)

Loss of Income (LOI):

SS - (3 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS 9,055.14

Global Sum SS: -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 9,055.14

Name 1:

KAH MOTOR CO. SDN. BHD.

Payee 2: (Strike if N.A.)


SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLC8986U
Chassis No : JHMRC1890GC203093
Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES
Owner's Name : GOH CHER CHAY
Ins Policy No. :
Date of Accident : 7/2/2019

Document No. : SQT19000678
Date : 12. Feb 2019
Customer No. : WZA006
Svc Advisor : JACK NG
Engine No : K24W72011402
Date | Time : 12. Feb 2019 1:32:14 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO.) OWNER:GOH CHER CHAY OWNER INSURER:AVIVA LTD ACC DATE:07/02/2019 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE TP VEH:SLA 8607 A						
04715-T6A-900ZZ	FACERR.BUMPER <i>DE</i>	1	568.30	25	426.22	29.84	456.06
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>X SUC</i>	1	45.40	25	34.05	2.38	36.43
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>X SUC</i>	1	45.40	25	34.05	2.38	36.43
71502-T6A-003ZE	FACER.RR.BUMPER GARNISH <i>X SUC</i>	1	76.80	25	57.60	4.03	61.63
71507-T6A-003ZA	FACEL.RR.BUMPER GARNISH <i>X SUC</i>	1	76.80	25	57.60	4.03	61.63
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>me</i>	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>me</i>	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER <i>me</i>	8	2.30	25	13.80	0.97	14.77
68100-T6A-Q10ZZ	TAILGATE COMP <i>BT</i>	1	1070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE <i>me</i>	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE <i>? X SUC</i>	1	185.40	25	139.05	9.73	148.78
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>? X SUC</i>	1	105.30	25	78.97	5.53	84.50
75701-T6A-000	EMBLEMH <i>me</i>	1	26.30	25	19.72	1.38	21.10
66100-T6A-Q00ZZ	PANEL COMP.REAR <i>repair</i>	1	460.80	25	345.60	24.19	369.79
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>me</i>	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER <i>me</i>	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER <i>me</i>	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD <i>me</i>	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM <i>me</i>	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5 <i>me</i>	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT <i>me</i>	1	4.80	25	3.60	0.25	3.85

BG02R	WINDSCREEN DAM KIT, 1757	1	150.00	150.00	10.50	160.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00	560.00	39.20	599.20

49084

Nivitha (LKK Auto)

From: Jack Ng <jackng@honda.com.sg>
Sent: Thursday, 7 February 2019 11:31 AM
To: SG AXA Insurance SM Claims Service Team; SG AXA Insurance SM AXA SGP - Motor Survey
Subject: ACCIDENT BETWEEN SLC 8986 U AND YOUR INSURED SLA 8607 A
Attachments: GIA REPORT.PDF
Categories: Pragati

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report.

Thank you and have a great days ahead

Cheers !!!

Best Regards,
Jack Ng
Hp: 8288 6309
Email : Jackng@honda.com.sg
BODY REPAIR AND PAINT CENTRE
255 Alexandra Road Singapore 159937
DID : +65 6514 5481 FAX : +65 6362 5015
Kah Motor Co. Sdn. Bhd.
(A MEMBER OF ORIENTAL HOLDING BERHAD)
Website: www.honda.com.sg



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

<< Pls proceed DS with quantum as proposed

Type

🔔 Question

Message

Reply

Kah Motor Co. Sdn. Bhd.
A Member of Oriental Holdings Berhad
Body Repair & Paint Centre
8A Mandal Estate
Singapore 729903
Tel : +65 6941 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd

Date : 4/15/2019

L K K

8 Shenton Way

#27-01

Singapore 068811

Attn: Motor Claims Department

Your ref : SLA 8607 A

Our ref : SLC 8986 U

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLC 8986 U AND SLA 8607 A ON 07/02/2019


We refer to the item(s) marked (✓) below:

- (✓) We refer to your email dated 13/03/2019.
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- () Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to : **desmondtoh@honda.com.sg**
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following :-

Repair Cost	S\$8,555.14 payable to Kah Motor Co. Sdn. Bhd.
Loss of Use	S\$100.00 x 5 Working days = \$500.00
	payable to Goh Cher Hay
- (✓) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (✓) Letter of Authority, Discharge voucher

Thank you.

Yours faithfully,


Jack ng



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

12 FEBRUARY 2019

CHUA HOCK SENG
BLOCK 637 CHOA CHU KANG NORTH 6
#10-243
SINGAPORE 680637

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/ASM19002347/ha3
YOUR REF : SLA 8607A
ACCIDENT INVOLVING SLA 8607A AND SLC 8986U ALONG CLEMENTI AVENUE 6
ON 07.02.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s KAH MOTOR CO. SDN. BHD acting on behalf of the owner of SLC 8986U against your motor insurance policy.

Based on the accident report and accident, it was reported that your vehicle had collided to the Third Party vehicle SLC 8986U. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD – if applicable) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

anthochua@yahoo.com.sg
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 12 February, 2019 3:02 PM
To: anthochua@yahoo.com.sg
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SLA 8607A_ACCIDENT INVOLVING SLA 8607A AND SLC 8986U ALONG CLEMENTI AVENUE 6 ON 07.02.2019



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

12 FEBRUARY 2019

CHUA HOCK SENG
BLOCK 637 CHOA CHU KANG NORTH 6
#10-243
SINGAPORE 680637

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/ASM19002347/ha3
YOUR REF : SLA 8607A
ACCIDENT INVOLVING SLA 8607A AND SLC 8986U ALONG CLEMENTI AVENUE 6 ON 07.02.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s KAH MOTOR CO. SDN. BHD acting on behalf of the owner of SLC 8986U against your motor insurance policy.

Based on the accident report and accident, it was reported that your vehicle had collided to the Third Party vehicle SLC 8986U. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD – if applicable) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Authorization Letter for the Driver to drive the vehicle
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.) SLC 89864 &
(THIRD PARTY'S VEHICLE NO.) SLA 86075 ON 07/02/19
ALONG Clementi Ave 6 Junction.

I hereby authorize Kah Motor Co. Sdn Bhd (Kah Motor) and its agents or any person authorized by Kah Motor to do all or any of the following:

- To submit, resolve and make any claim(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher/indemnity forms and all necessary documents in connection with and arising out of the above claim.
- Any payment should be made in favour of my name / Kah Motor Co. Sdn. Bhd.



Owner Signature
(Co stamp & authorized signature if is Co registered vehicle)

Name : ROHMAN GOR CHER CHAY

NRIC No : 572727165

Vehicle No : SLC 89864

Date : 19/2/19



WITHOUT PREJUDICE to:

Any Personal Injury Claims

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SLA8607A (insd veh)	Model: Honda Odyssey - 2356u
	SLC8986U (TP veh)	
Date of Accident/ Time:	07/02/2019 @ 0705HRS	

Repair Estimate	: \$	17,796.65	
Final Repair Cost	: \$	8,555.14	(w GST)
Loss of Use	: \$	500.00	5 days at \$ 100 per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$		
Others:	: \$		
Final Settlement Sum	: \$	9,055.14	

Payee Name : KAH MOTOR CO. SDN. BHD

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: 27
	BOLA Liability: 100 (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

KAH MOTOR CO. SDN. BHD.
BODY REPAIR & PAINT CENTRE
8 MANDALAY ESTATE
SINGAPORE 720005

KAH MOTOR CO. SDN. BHD.
BODY REPAIR & PAINT CENTRE
8 MANDALAY ESTATE
SINGAPORE 720005

Signature of workshop representative / Workshop stamp
Name of Representative: Desmond Toh
Date: 22/05/2019

Signature of Witness / Workshop stamp (if applicable)
Name of Witness: Desmond Toh
Date: 22/05/2019

Signature of AXA's surveyor/representative:
Name of AXA's surveyor / Representative:
Date: 23/05/2019

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

6A Mandal Estate, SINGAPORE 729903

Mandal Parts Centre

Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223

Company Ref. No. S60FC1380G

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA006

Payment Term : 30 Days

Invoice No.	:	SINV-BM19000388
Invoice Date	:	18/03/19
Order No.	:	SVO19009563
Reference	:	
Job Card No.	:	07807
Date/Time Received	:	12/02/19 / 1:32:14 PM
Licence No.	:	SLC8986U
Model	:	ODYSSEY2.4 EXV-S 16YM
Car Chassis No.	:	JHMRC1890GC203093
Car Engine No.	:	K24W72011402
Mileage	:	59986
Service Advisor	:	JACK NG 1838
Served By	:	JACKNG
Page	:	1

No.	Description	Qty.	UoM	U. Price	Disc %	7% GST Amount Incd		
						Amount	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:GOH CHER CHAY							
	OWNER INSURER:AVIVA LTD							
	ACC DATE:07/02/2019							
	SURVEYED BY:							
	DATE:							
	REF NO:							
	TP INSURER:AXA INSURANCE							
	TP VEH:SLA 8607 A							
04715-T6A-900ZZ	FACERR.BUMPER	1	Each	568.30	25	426.22	29.84	456.06
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	Each	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	Each	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	8	Each	2.30	25	13.80	0.97	14.77
68100-T6A-Q10ZZ	TAILGATE COMP	1	Each	1,070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE	1	Each	117.40	25	88.05	6.16	94.21
75701-T6A-000	EMBLEMH	1	Each	26.30	25	19.72	1.38	21.10
BOSUN	1610 SUNDRIES	1	Hours	30.00		30.00	2.10	32.10
BOJSE	1610 BODY JOINT SEALANT FOR TAILGATE	1	Hours	120.00		120.00	8.40	128.40
BML02I	1610 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	280.00		280.00	19.60	299.60
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	380.00		380.00	26.60	406.60
BOMISC1	0671 REMOVE & RE-INSTALL REAR VIEW CAMERA. (N)	1	Hours	450.00		450.00	31.50	481.50
BOMISC1	0671 RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	Hours	450.00		450.00	31.50	481.50
BODAMKIT	0671 WINDSCREEN DAM KIT.	1	Hours	150.00		150.00	10.50	160.50
BG02R	1757 REPLACE RR. WINDSCREEN.(N)	1	Hours	560.00		560.00	39.20	599.20
BKTG02R	0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. (N) ALIGN TAILGATE.(N)	1	Hours	560.00		560.00	39.20	599.20
BMI03D	1757 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	Hours	280.00		280.00	19.60	299.60
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS	1	Hours	1,680.00		1,680.00	117.60	1,797.60
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) SUPPLEMENTARY PART	1	Hours	1,350.00		1,350.00	94.50	1,444.50

Printed by JACKNG on 18 Mar 2019 at 6:53:15 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your feedback by scanning the QR Code using mobile device.



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223

Company Ref. No. S60FC1380G

AXA INSURANCE S'PORE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer No. : WZA006

Payment Term : 30 Days

Invoice No.	:	SINV-BM19000388
Invoice Date	:	18/03/19
Order No.	:	SVO19009563
Reference	:	
Job Card No.	:	07807
Date/Time Received	:	12/02/19 / 1:32:14 PM
Licence No.	:	SLC8986U
Model	:	ODYSSEY2.4 EXV-S 16YM
Car Chassis No.	:	JHMRC1890GC203093
Car Engine No.	:	K24W72011402
Mileage	:	59966
Service Advisor	:	JACK NG 1838
Served By	:	JACKNG
Page	:	2

No.	Description	Qty.	UoM	U. Price	Disc %	7% GST Amount Incid		
						Amount	Amount	GST
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	Each	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER	1	Each	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	Each	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	Each	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	Each	3.70	25	2.77	0.19	2.96
73228-SZW-000	DAMPERSTD 5X5	2	Each	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT	1	Each	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.40
74940-TR0-003	BUZZER ASSYSMART	1	Each	60.10	25	45.07	3.15	48.22
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	Each	103.60	25	77.70	5.44	83.14

Sum Labor	6,290.00	440.30	6,730.30
Sum Item	1,705.46	119.38	1,824.84
Total SGD	7,995.46	559.68	8,555.14
Total Payable (SGD)			8,555.14

Printed by JACKNG on 18 Mar 2019 at 6:53:15 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.

Please give us your
feedback by scanning
the QR Code using
mobile device.


THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLA 8607A (Insd veh)	Model:	HONDA ODYSSEY 2.4 A
	SLC 8986U (TP veh)		
Date of Accident:	07/02/2019		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	17,796.65
Final Repair Cost	: \$	8,555.14
Loss of Use	: \$	500.00
Rental (if any)	: \$	5days at \$100.00 per day
LTA / GIA Search Fee	: \$	days

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	9,055.14

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No- BOLA Scenario No: _____
BOLA Liability: _____100_____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown	
1) KAH MOTOR CO.SDN.BHD.	: \$ 9,055.14

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

13/06/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002347/R1ha3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:PETER

Date : 13-06-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 8607A	Veh. Inspected	SLC 8986U
Policy No.	VPA/P1744839	Coverage (\$)	0.00
Claim No.	S9M01D2G	Excess (\$)	0.00
Assign From		Assign Date	07/02/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY 2.4 A	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMRC1890GC203093	Colour	WHITE
Odometer	059986	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	GOODYEAR	6 mm
L/H Front Tyre	215/55 R17	GOODYEAR	6 mm
R/H Rear Tyre	215/55 R17	GOODYEAR	6 mm
L/H Rear Tyre	215/55 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/02/2019	Inspection Date	13/02/2019
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 8986U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACERR.BUMPER (SN) (CONSISTENT)	DEFORMED	426.22	426.22
1	REFLECTOR ASSYR.RR (SN) (CONSISTENT)	SERVICEABLE	34.05	-
1	REFLECTOR ASSYL.RR (SN) (CONSISTENT)	SERVICEABLE	34.05	-
1	FACER.RR.BUMPER GARNISH (SN) (CONSISTENT)	SERVICEABLE	57.60	-
1	FACEL.RR.BUMPER GARNISH (SN) (CONSISTENT)	SERVICEABLE	57.60	-
1	SPACERR.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	14.32	14.32
1	SPACERL.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	14.32	14.32
8	CLIP,BUMPER (SN) (CONSISTENT)	NECESSARY	13.80	13.80
1	TAILGATE COMP (SN) (CONSISTENT)	BENT	803.10	803.10
1	WEATHERSTRIP TAILGATE (SN) (CONSISTENT)	NECESSARY	88.05	88.05
1	LOCKTAILGATE (SN) (CONSISTENT)	SERVICEABLE	139.05	-
1	SWITCH ASSYTAILGATE OPENER (SN) (CONSISTENT)	NOT NECESSARY	78.97	-
1	EMBLEMH (SN) (CONSISTENT)	NECESSARY	19.72	19.72
1	PANEL COMP,REAR (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	345.60	-
2	MOLDINGRR.WINDSHIELD SIDE (SN) (CONSISTENT)	NECESSARY	27.00	27.00
1	MOLDINGR.RR.WINDSHIELD CORNER (SN) (CONSISTENT)	NECESSARY	12.67	12.67
1	MOLDINGL.RR.WINDSHIELD CORNER (SN) (CONSISTENT)	NECESSARY	12.67	12.67
4	SPACERRR.W/SHIELD (SN) (CONSISTENT)	NECESSARY	11.70	11.70
1	RUBBER AWINDSHIELD DAM (SN) (CONSISTENT)	NECESSARY	2.77	2.77
2	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	12.75	12.75
1	CAPPIVOT (SN) (CONSISTENT)	NECESSARY	3.60	3.60
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
1	BUZZER ASSYSMART (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	45.07	45.07
1	LINING ASSYRR.PANEL (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	77.70	77.70
			2,552.38	1,735.46
LABOUR				
	BODY JOINT SEALANT FOR TAILGATE.		150.00	120.00

Report Ref No. CC4/ASM19002347/R1ha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	BODY JOINT SEALANT FOR END PANEL.	NOT NECESSARY	150.00	-
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		380.00	280.00
	REMOVE & RENEW REVERSE SENSORS.		380.00	380.00
	REMOVE & RE-INSTALL REAR VIEW CAMERA .		450.00	450.00
	RESET & CALLIBRATE SMART ENTRY SYSTEM.		450.00	450.00
	WINDSCREEN DAM KIT.		200.00	150.00
	REPLACE RR.WINDSCREEN.		560.00	560.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE.		560.00	560.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		800.00	280.00
	CUT OFF & RENEW RR PANEL RENEW ALL DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF PANEL COMP,REAR .		6,000.00	1,680.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		4,000.00	1,350.00
			14,080.00	6,260.00
GRAND TOTAL			16,632.38	7,995.46
RECOMMENDED COST OF REPAIRS				7,995.46

Report Ref No. CC4/ASM19002347/R1ha3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

S/PA01D3G

Reference

CC4/ASM19002047/RTha3d2

Loss Date

7 February 2019

Report Date

7 Feb 2019 12:19:53 PM

Request Date

5 April 2019

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SLOH966U

Make

THIRD HONDA

Model

ODYSSEY 2.4 (A)

Service Address

Primary Contact/Insured

CHUA HOCK SENG

BLK 637 CHOA CHU KANG NORTH 6, #10-243,

6BD637, Singapore

96904967

anthochua@yahoo.com.sg

Claim Handler

WANG Peter

peter.wang@asa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

NON-REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Martin	

