

15/5/2010

INS. CASE OWNER:

Jas Tan

CC.4, Asm 1900 2354, Kea3

LKK:

IDAC:

97606

Surveyor:

kel

DOI:

ASSIGNMENT

11/2/19

Date / Time :

11/2/19

Registered in Merimen:

Pre-assign / CCU / FTE

X0 5639 U

"VIRTUAL"

Sqm 01086



Insured Vehicle No. :

Claim No. :

Name of Insured :

PUBER GLOBAL PL

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A:

8/2/19

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SDA 18/8 2



INSRS:

WSP:

Tel :

Liability :

RMKS:

Chay Hoo



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

SDA 18/8 2. X; X0 5639 U. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF: AAAKenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng / toe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 859k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SOA 1818ZYr Regn: 03, 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Teanc.c. 24 P6Colour: Ch. Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: 165105

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BBUT3280001254Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Day Tan

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 8/2/19D.O.I. 11/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9602F
Vehicle Details	
Vehicle No.:	SDA1818Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.5 CVT ABS D/AB HID 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	VQ25408055A
Chassis No.:	JN1BBUJ32Z0001254
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$33,481.00
Original Registration Date:	26 Mar 2009
First Registration Date:	26 Mar 2009
Transfer Count:	4
Actual ARF Paid:	\$33,481.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2019
PARF Rebate Amount:	\$16,740.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$31,242.00
Total Rebate Amount:	\$47,982.00

The information contained herein is correct as at 11 Feb 2019

OK

SDA1818Z (NISSAN TEANA)

1 m rear bumper Br-

centric top chrome protector nc-
 2 m side lower moulding nc-
 1 m 4 m side retainer disc-
 6 m clips nc-

1 m rear boot Br-

logo nc-
 emblem TEANA' nc-
 emblem 250 XV nc-
 emblem V6 nc-
 inner lock disc-
 inner rubber disc/wr 5015m
 centre moulding chr-
 top spoiler chr-
 2 m hinges Br-
 1 m BH damper Br-
 1 m inner cushion - return

~~1 m radiator fan blade~~

6 m rear boot inner cushion clips nc-

2 m tail lamps chr

2 m side garnish n/s Br- & chr

SVA 1818 Z

1 pc rear end panel BTL

inner top garnish. cm

2 pc tail lamp panels N/S BTL

2 pc rear fender inner garnish. Return

8 u ~~inner~~ clips m

1 pc rear spare compartment top tool box ?

1 pc smart key sensor ?

2 pc ^{lamp} ~~tail gate~~ chrome moulding - \$80 x 2 = 160 m

1 set reverse camera - \$380 - ?

1 set reverse sensor

\$200/pc ?

CHENG HOE MOTOR PTE LTD
Blk 1019, Yishun Ind. Park A
#01-374, Singapore 768761
Tel: 6755 6142 Fax: 6755 7719
Email: chmotor@singnet.com.sg

CHENG HOE
6755 7719

SOA 1818 Z

① RAR rear bumper assy, tail lamps,
rear boot and attachment, spoiler,
lower skirt, To cutty, welding and renew
rear panel, tail lamp panels,
To KAR rear both fenders, rear
spare tyre compartment and rearing
the same

9501
#1100/✓✓

② RAR rear garnish, seat, car-pet etc #80/✓✓

③ Fully a respray on rear spoiler, boot,
hinges, rear both fenders, rear panel,
rear spare tyre compartment, compartment,
rear bumper, lower skirt and rear
affected area

10001
#1100/✓✓

④ RAR ~~rear~~ reverse sensor and
reset system

#10/✓~~#40~~/✓✓

⑤ Rubprady

#60/✓✓

#9261.18