

INS. CASE OWNER:

CC

1900

LKK:  
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
11/2/19	SLW 3108R. X.	Non-Reporting ltr (1st):	
	SHC 88552 - N51MCL 60242401/Kg 6334, 90A	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
13-2-19	SEEK MANDATE FOR LIABILITY.	Call OI:	
	MANDATE APPROVE LIABILITY.	After call ltr to OI:	
06-3-19	FILE PASS TO TYPIST TO PREPARE REPORT.	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: Sent By:			
FINALIZATION Date/Time: Confirm with:		Confirm by: CHS	
Repair Cost:	DIP S\$ 1,460.00 ( 3 days) Reduction: 40 %	Email <input checked="" type="checkbox"/>	Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: 11-04-19 Confirm with: EMILYN		Email <input checked="" type="checkbox"/>	Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 23	If NO or B 28, Ass. Lia :	
Repair Cost:	W/LST S\$ 1,562.20	DND REVERSED NOT PARKED TP.	
Loss of Rental (LOR):	W/LST S\$ 321.00 ( 3 days) x \$100		
Loss of Use (LOU):	S\$ - (\$ x days)		
Loss of Income (LOI):	S\$ - (\$ x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one)		
GIA/LTA Search	S\$ -		
Medical:	S\$ -		
Disbursement:	S\$ - (e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle	
Legal Cost	S\$ -	2) Report Format: TP	
Total:	S\$ 1,883.20 Global Sum S\$:	3) Survey fee: 350	
FINAL PAYMENT Date/Time: 11-04-19 Confirm with: EMILYN		Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	S\$ 1,883.20 Name 1: KAH MOTOR CO SDN BHD		
Payee 2: (Strike if N.A.)	S\$ Name 2:		
Payee 3: (Strike if N.A.)	S\$ Name 3:		

1370 / 1400p

III

ASSIGNMENT

Date: 12/2/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLW 3108R

at Workshop no: Kah Motor

of: 15 ubi Road 4

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Name of owner: waiting

FAEZO

82886304

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA Seen: Consistent?: Yes or No

Est. Repair: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP: / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

Veh No: SLW 3108R

Regn: 218

Type: Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz

cc: 1498

Colour: Grey A/C: Insured / Std / NI / NA

Sp Reading: 10759 T/Radio: Insured / Std / NI / NA

Eng/Mo:

CNo: JHMGK5850JX203900

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N / S / B / STD A/Rim or

Tyre Size: F: 185/55 R16

R:

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 4/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 104

The U/C / Chassis frame / Body Structure affected due to collision.

P/p: + 1,460.00 (RED: + 1,040 42%)

Date/Time, File Pass to? ☐ : Preli. Report

by ☐ : Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

by

Phone

Other

by

TOTAL

Report Format:

Lump Sum / L.B.L. /

Add Fee: ☐ Site Insp. \$

☐ Interview \$

☐ Tech. Insp. \$

☐ Weekend \$

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3760I
<b>Vehicle Details</b>	
Vehicle No.:	SLW3108R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	L15B33111699
Chassis No.:	JHMGK5850JX203900
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$16,223.00
Original Registration Date:	06 Feb 2018
First Registration Date:	06 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$16,223.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Feb 2028
PARF Rebate Amount:	\$12,167.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	05 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,400.00
COE Rebate Amount:	\$37,185.00
<b>Total Rebate Amount:</b>	<b>\$49,352.00</b>

The information contained herein is correct as at 12 Feb 2019

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711

Registration No : SLW3108R  
Chassis No : JHMGK5850JX203900  
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)  
Owner's Name : KUA CHI KIONG  
Ins Policy No. :  
Date of Accident : 4/2/2019

Document No. : SQT19000601 Page 1  
Date : 8. Feb 2019  
Customer No. : WZI007  
Svc Advisor : ARY CHUA WAI NGEE  
Engine No : L15B33111699  
Date | Time : 8. Feb 2019 3:46:33 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: KUA CHI KIONG OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 4/2/19 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTL. INSURANCE TP VEH: SHC8855L						
BOSUN	SUNDRIES	11	30.00	X	30.00	2.10	32.10
BKDR11K	STRAIGHTEN ALIGN FR L & RR DOOR.	1	1120.00	560	1120.00	78.40	1198.40
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1350.00	900	1350.00	94.50	1444.50
Sum Labor					2500.00	175.00	2,675.00

Survey By Wong HuiDate & Time 12/2/19

Excess

Status not submitSignature take ph. After repair 3 day.

Total Amount 2,500.00 175.00 2,675.00

Total (Inclusive of GST) 2,675.00

LRP Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledgement: Reparer

Signature

Date

Printed on 9/2/2019 9:17:10 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Monday, 11 February 2019 9:43 AM  
**To:** Faeaz; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Ary Chua; Manivel Priyadarshini  
**Subject:** RE: Accident involving SLW3108R & SHC8855L On 4/2/19  
**Attachments:** 4076\_001.pdf

9:57am @ 11/2/19  
person @ Ary  
vehicle not in

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLW3108R and let us have your report urgently.

This claim will be handled by Ms Priya.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Faeaz [mailto:faeaz@honda.com.sg]  
**Sent:** 11 February, 2019 9:26 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>; Sundari Nagarajan - III <sundari@iii.com.sg>  
**Cc:** Ary Chua <arychua@honda.com.sg>  
**Subject:** RE: Accident involving SLW3108R & SHC8855L On 4/2/19

Dear Gabriel,

Please kindly arrange LKK for the survey.

**Best Regards**

**Mohd Faeaz Bin Yaacob**  
**Senior Executive**  
**Kah Motor Body Repair Centre**  
**15, Ubi Road 4**

Singapore 408610

Tel : 68465678

Hp : 82886304

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Monday, 11 February, 2019 9:24 AM  
**To:** Faeaz <faeaz@honda.com.sg>; Sundari Nagarajan - III <sundari@iii.com.sg>  
**Cc:** Ary Chua <arychua@honda.com.sg>  
**Subject:** RE: Accident involving SLW3108R & SHC8855L On 4/2/19

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

---

**From:** Faeaz [mailto:faeaz@honda.com.sg]  
**Sent:** 09 February, 2019 9:30 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>; Sundari Nagarajan - III <sundari@iii.com.sg>  
**Cc:** Ary Chua <arychua@honda.com.sg>  
**Subject:** Accident involving SLW3108R & SHC8855L On 4/2/19

Dear Sir / Mdm,

Kindly arrange your surveyor to inspect our client vehicle which involve in the above accident with your insured on the above date.

Attached claim documents for your necessary action.

**Best Regards**

**Mohd Faeaz Bin Yaacob**

**Senior Executive**

**Kah Motor Body Repair Centre**

**15, Ubi Road 4**

**Singapore 408610**

**Tel : 68465678**


**Hp : 82886304**

**From:** Printer Service <[printservice@honda.com.sg](mailto:printservice@honda.com.sg)>

**Sent:** Saturday, 9 February, 2019 9:25 AM

**To:** Faeaz <[faeaz@honda.com.sg](mailto:faeaz@honda.com.sg)>

**Subject:** Attached Image



**Confidential Note:** The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.


If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.





Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.  
Registration No. 198703792-K



## Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	11 Feb 2019 15:32	Clim Veh Model Changed	(204360) HONDA JAZZ 1.5 (A).	[A] HOW MEI KWAN	
2	11 Feb 2019 15:32	Clim Created	Reg No: SLW3108R, Acct Date: 2019/02/04, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: Tokio Marine Insurance Singapore Ltd (HQ), Workshop: Kah Motor Co Sdn Bhd (Ubi)	[A] HOW MEI KWAN	
3	11 Feb 2019 15:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN	
4	11 Feb 2019 15:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/20	[A] HOW MEI KWAN	
5	11 Feb 2019 15:32	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN	
6	11 Feb 2019 15:32	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.	[A] HOW MEI KWAN	
7	11 Feb 2019 15:32	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN	
8	13 Feb 2019 12:54	Adj Mandate Request	Cur.Req:0.00:PODS: LIABILITY: 100% REMARK: B:23 OID REVERSED HIT PARKED TP (REFER TO TP VIDEO VIA EMAIL)	[A] Asher Sng Rong Yi	
9	13 Feb 2019 15:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/20. Mandate Remarks: PLEASE FORWARD US THIRD PARTY VIDEO FOOTAGE	[I] Priya	
10	13 Feb 2019 15:37	Adj Mandate Set	Maintained:PLEASE FORWARD US THIRD PARTY VIDEO FOOTAGE	[I] Priya	
11	14 Feb 2019 09:49	Label Removed	(30651):Vehicle Not In.	[A] HOW MEI KWAN	
12	18 Feb 2019 11:20	Adj Mandate Request	Cur.Req:0.00:TP VIDEO HAVE SEND TO YOUR EMAIL ON 13.02.19	[A] Asher Sng Rong Yi	
13	18 Feb 2019 11:40	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/02/20. Mandate Remarks: LIABILITY-100%	[I] Priya	
14	18 Feb 2019 11:40	Adj Mandate Set	Approved:0.00:LIABILITY-100%	[I] Priya	
15	06 Mar 2019 12:41	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN	
16	06 Mar 2019 12:41	Clim Dtl Modified	Insured Name: -> -.	[A] JOANNE LEE KHANG MIN	
17	06 Mar 2019 12:41	Clim Dtl Modified	Claimant's Name: -> -. Claimant's ID: -> -.	[A] JOANNE LEE KHANG MIN	
18	06 Mar 2019 12:41	Clim Dtl Modified	JPJ Reg. Date: -> 2018/02/06.	[A] JOANNE LEE KHANG MIN	
19	06 Mar 2019 12:41	Clim Details Notified		[A] JOANNE LEE KHANG MIN	
20	25 Mar 2019 12:24	Adj Mandate Request	Cur.Req:1883.20:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST: \$1,562.20 + (b) LOR w/GST: \$321.00 (3days x \$100) Total: a+b = \$1,883.20 VEH MODEL: HONDA JAZZ 1498cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi	

Date From



Date To



Audit Type None

Go

## Print Received Message

This mail is associated with :

**\*SLW3108R (MCT19020256)**  
**[SHC8855L]**

TP

KUA CHI KIONG

Feb 4 2019 5:00PM

[-]

Kah Motor Co Sdn Bhd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 25/03/2019 14:47 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$1883.20) - SLW3108R - Claim Handler: Priya

Approved:1883.20.

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

### Direct Settlement

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019 Edit Reg		11 Feb 2019 00:00 Edit Adj Rpt	\$s1,460.00 Edit Estimates	\$s1,460.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by adjuster]																					
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R																							
Main Claimant:	KUA CHI KIONG, ID: S7933760I																							
Vehicle Reg. No.:	SLW3108R	Date of Loss:	04/02/2019 17:00 - :59 [11 Months and 29 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / MCT19020256	Policy/Cover Note No.:	MCOM0015																					
Vehicle Reg. No. (Insured):	SHC8855L	Policy No. (Claimant):	MT000712																					
		Excess:																						
Repairster:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671																							
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]																							
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/02/2019]																							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
<ul style="list-style-type: none"><li>• III_SG (25/03/2019): Alert - Adj Mandate Approved (\$\$1883.20) - SLW3108R - Claim Handler: Priya</li><li>• III_SG (18/02/2019): Alert - Adj Mandate Approved (\$\$0.00) - SLW3108R - Claim Handler: Priya</li><li>• III_SG (13/02/2019): Alert - Adj Mandate Maintained - SLW3108R - Claim Handler: Priya</li></ul>																								
<div><div><div></div><div>ALL ASSOCIATED TASKS</div></div><div><div>View All</div><div>Search Tasks</div><div>Create New Task</div><div>Complete</div></div></div> <table><thead><tr><th>Due Date</th><th>Priority</th><th>Type</th><th>Task Group</th><th>Subject</th><th>Handler</th><th>Assigned By</th><th>Completed On</th><th>Created On</th><th>Done?</th></tr></thead><tbody><tr><td colspan="10">No results.</td></tr></tbody></table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

## Claim Documents

\*SLW3108R (MCT19020256)  
[SHC8855L]  
TP  
KUA CHI KIONG  
Feb 4 2019 5:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos		Compose New Letter		View Use Viewer	
Video							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail	Print
1	18/02/19 11:39	Video - Accident					Load MP4	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
15	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 12:21	General View					Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 12:21	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 12:21	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 12:21	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 12:21	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 12:21	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 12:25	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 12:25	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 12:25	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 12:25	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 12:25	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	11/02/19 15:32	ACKNOWLEDGEMENT EMAIL TO III DD 11.02.19					Load PDF	
2	11/02/19 15:32	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT					Load PDF	
3	16/02/19 17:47	TP ESTIMATE - MARKED					Load PDF	
4	06/03/19 12:45	RENTAL RECEIPT					Load PDF	
5	06/03/19 12:45	LOD					Load PDF	
6	15/05/19 12:36	WORKSHOP INVOICE					Load PDF	
7	15/05/19 12:36	AUTHORISATION TO ACT FORM					Load PDF	
8	15/05/19 12:36	DISCHARGE VOUCHER					Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)					Thumbnail	Print
1	13/02/19 15:35	ID SAS REPORT					Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19002370/UEA3N2

Date: 15/05/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SLW3108R Insured Vehicle No: SHC8855L  
 Date of Loss: 04/02/2019 Nature of Claim: TP Claim No: MCT19020256

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLW3108R  
 Make & Model: HONDA JAZZ, 1.5 (A) Engine No: L15B33111699  
 Reg. Date: 06/02/2018 (Man. Year: 2017) Chassis No: JHMGK5850JX203900  
 Colour: Grey Odometer: 10759 km  
 Engine Capacity: 1498 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16  
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm  
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	30.00	0.00	30.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,460.00	1,010.00	40.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,500.00</b>	<b>1,460.00</b>	<b>1,040.00</b>	<b>41.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>175.00</b>	<b>102.20</b>	<b>72.80</b>	<b>41.60</b>
<b>Nett Amount (S\$)</b>	<b>2,675.00</b>	<b>1,562.20</b>	<b>1,112.80</b>	<b>41.60</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		<b>321.00</b>		
<b>Nett Liability (S\$)</b>		<b>1,883.20</b>		

## INSPECTION

Date of Assignment: 11/02/2019  
 Date Inspected: 12/02/2019 Inspected At: Kah Motor Co Sdn Bhd (Ubi)  
 15 Ubi Road 4  
 Singapore 408610  
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2019)
<b>Parts:</b>	144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW3108R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	30.00 FS	*- FS
						F=Franchise part. S=SpcNett.
<b>Total Parts (S\$)</b>					<b>30.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN ALIGN FR L & RR DOOR	New	1,120.00	560.00
2	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,350.00	900.00
Gross Labour Cost (S\$)			2,470.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >