

ASS. REC. BY:

REF

CS. / SMD19002372/UTD3

n2  
Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Menmen

Anoh Pau loong of

SMD

Date/Time: 11/2/19 @ 10:52am

Estimated Cost:

Bill to:

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 2661Y

Insured:

SBR 5515E

at Workshop m/s

Asia Motor sports

Tel:

6745 3811

of

15 kaki Bkt Rd 4 # 01-53

Policy No:

D18M7PV0/014625

Claim No:

CMTD1900760

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/2/2019

CA / REV / REP. / REV 24 HRS <sup>up</sup>

H.O.D. Endorsement:

Date/Time:

1:51pm @ 11/2/19

Person Contacted:

Mr. too

Vehicle  IN /  OUT

Date/Time

Action/Instruction ( X ) Estimate

SLQ 2661Y - NA/MSG19002238/r3

D.O.A: 5/2/2019

SBR 5515E - NA/MSG19002238/r3

D.O.A: 5/2/2019

Dismantle: 12/2/2019



## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Feb 2019		11 Feb 2019 10:52 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TAN POH ANN, ID: S6840888A, Tel: +6598501930, Email: glenntwy@gmail.com	
Main Claimant:	GOH KEE LING(WU QILIN), ID: S7609625B	
Vehicle Reg. No.:	SLQ2661Y	Date of Loss: 05/02/2019 15:00 - :59
Claim Type:	TP / CMTD1900760	Policy/Cover Note No.: D18MTPV01014625 (Comprehensive)
Vehicle Reg. No. (Insured):	SBR5515E	Policy No. (Claimant):
		Excess:
Repairer:	Asia Motorsports Solution Pte Ltd-kaki Bukit (HQ) 15 KAKI BUKIT ROAD 4, #01-05/53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 6745 3811	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/02/2019]	
Driver/Custodian (Insured):	TAN POH ANN (50 / Male), NRIC: S6840888A, Tel: +6598501930	

[View All](#)   [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS <input type="checkbox"/>										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9625B
<b>Vehicle Details</b>	
Vehicle No.:	SLQ2661Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	2NR8716373
Chassis No.:	NSP1707071940
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$21,499.00
Original Registration Date:	30 Jun 2017
First Registration Date:	30 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$12,099.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2027
PARF Rebate Amount:	\$9,074.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$35,869.00
<b>Total Rebate Amount:</b>	<b>\$44,943.00</b>

The information contained herein is correct as at 12 Feb 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

#### ACCIDENT STATEMENT

Date Of Report	07/02/2019 11:34
Date Of Accident	05/02/2019 15:00
Exact Location Of Accident	BLK 685 HOUGANG AVE 4
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ2661Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOH KEE LING(WU QILIN)
NRIC No	S7609625B
Email Address	GOHKEELING@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97974370
Alternative Phone No	OTHERS-97974370

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28982813 QMX
Cover Note Number	

#### Driver

Name of Driver	GOH KEE LING(WU QILIN)
NRIC No	S7609625B
Date Of Birth	01/04/1976
Occupation	OUTDOOR
Date Of Driving Pass	11/03/2002
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97974370
Fax Number	
Contact Number	OTHERS-97974370
Email Address	GOHKEELING@YAHOO.COM.SG

Address BLK 272C PUNGGOL WALK  
 #06-587  
 Postcode 823272  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

MY VEH WAS STATIONARY AT THE STOP LINE TO GIVEWAY FOR ONCOMING VEH AT BLK 685 HOUGANG AVE 4. SUDDENLY VEH B CAME FROM BEHIND AND HIT ONTO THE REAR PORTION OF MY VEH. VEH B DRIVER ADMIT THAT HIS VEH HIT ONTO MY VEH.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: HAVEN'T RETRIEVE  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY**

Vehicle Registration Number SBR5515E  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver TAN POH ANN  
 NRIC/Passport Number S6840888A  
 Contact Number 98501930  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	GOH KEE LING(WU QILIN)
Approximate Age	
Injuries Sustain	BACK & NECK
Injured person in which vehicle?	SLQ2661Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*pls refer to the statement.*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

HP-9797 H370,

5/2/2019

1500PM

SLQ2661Y



Not Authorized

N/S \$6000

Sdy.  
Theoph. Harcup

Vehicle No. SLQ 2661Y TOYOTA SIENTA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	Tail Gate	Subsp 17	1482.00	/
2	Tail Gate Dampers @ \$294.20	17	588.40	X
1	Tail Gate Toyota Centre Badge	new	73.00	/ 68.00
2	Tail Gate rubber stopper	17	24.00	X
1	Tailgate centre garnish	17	449.00	X
1	Tail Gate Inner Lock	20/30m	325.00	/
1	Tail Gate lock catch	17	40.00	X
1	Tail Gate Inner Trim Board Cover	17	233.00	X
1	Tail Gate inner handle garnish	17	48.00	X
1	Tail Gate Windscreen Moulding	new	177.00	/ 121.10
1	Tail Gate Windscreen wiper	REFIX 17	0.00	X
1	Tail Gate Wiper motor	17	482.00	X
2	Tail Gate reflectors @578.50	o/s car	1157.00	17c 485.10
2	RHS & LHS Taillamps @982.40	o/s car	1964.80	17c 650.10
1	Rear Bumper Top Centre Pad	20/30m	482.00	/
2	Rear Bumper Side Pad @ \$144.00	20/30m	288.00	/
1	Rear Bumper	20	1282.00	/ 801.10
2	Rear Bumper side reflectors @98.40	new	196.80	/
1	Rear End Panel Top Garnish	Trim	378.00	/ 245.10
1	Boot Edge Weatherstrip	7w1	257.00	/
1	Rear floor panel top cover	17	346.00	X
1	Rear floor panel tool tray	new	298.00	/
1	Rear End Panel ( Outer )	20	978.00	/ 645.10
			11549.00	6344.50
less 25%			2887.25	25%
			8661.75	4258.77
<b>SPECIAL NETT ITEMS</b>				
1 set	Tail Gate Inner Trim Board Clips	17	60.00	X
1 set	Rear Bumper Clips	new	50.00	/
1	Rear number plate w/holder	scr	75.00	40
1	Rear Windscreen Sealant	new	100.00	40
1	Rear windscreen video camera	REFIX /LABOUR 17	0.00	X
1	Rear Tailgate top spoiler	REFIX /LABOUR 17	0.00	X
1	Rear Tailgate top spoiler sealant	17	60.00	X
1	Rear End Panel Sealant	new	100.00	50
1 set	Reverse Parking Sensors	shunt	280.00	200
1	Reverse Camera	shunt	480.00	380
<b>TOTAL PARTS</b>			9866.75	

760

Vehicle No. SLQ 2661Y

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1400.00 —	750
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1000.00 —	900
3	To remove, refix wiring system at accident damaged areas and check for proper function	150.00 —	30
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	200.00 —	80
5	To remove and refix rear windscreen	140.00 —	120
6	To remove and refix rear windscreen video camera	100.00 } }	50
7	To remove and replace reverse sensors and camera and check for proper function	180.00 } }	
8	To perform anti-rust treatment on affected areas	180.00 —	60
	Labour Total :	3350.00	
<b>TOTAL (PARTS &amp; LABOUR):</b>		<b>13216.75</b>	<b>1990</b>

P-425837  
 S.N - 760.00  
 Lab - 1990.00  
 750837  
 202  
 6006.

Insurance Company shall not be notified of any of the following:

- Spray painting
- To remove damaged parts during resurvey
- To remove any part subject to confirmation
- To remove any part on a "Whitish Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002372/UTD3N2

Date: 27/02/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01014625
Claimant Vehicle No :	SLQ2661Y	Insured Vehicle No :	SBR5515E
Date of Loss:	05/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900760

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLQ2661Y	Engine No:	2NR8716373
Make & Model:	TOYOTA SIENNA, 1.5 (A)	Chassis No:	NSP1707071940
Reg. Date:	30/06/2017 (Man. Year: 2016)	Odometer:	26665 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,866.75	5,518.37	4,348.38	44.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,990.00	1,360.00	40.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,216.75</b>	<b>7,508.37</b>	<b>5,708.38</b>	<b>43.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,216.75</b>	<b>6,000.00</b>	<b>7,216.75</b>	<b>54.60</b>

## INSPECTION

Date of Assignment:	11/02/2019	
Date Inspected:	11/02/2019 Inspected At:	Asia Motorsports Solution Pte Ltd-kaki Bukit (HQ) 15 KAKI BUKIT ROAD 4, #01-05/53 BARTLEY BIZ CENTRE Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2019)
<b>Parts:</b> M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLQ2661Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Badly Dented	1,482.00 FL	*1,482.00 FL
2	2		*TAIL GATE DAMPERS	Not Necessary	588.40 FL	*- FL
3	1		*TAIL GATE TOYOTA CENTRE BADGE	Necessary	73.00 FL	*68.10 FL
4	2		*TAIL GATE RUBBER STOPPER	Not Necessary	24.00 FL	*- FL
5	1		*TAIL GATE CENTRE GARNISH	Not Necessary	449.00 FL	*- FL
6	1		*TAIL GATE INNER LOCK	Dented/Jammed	325.00 FL	*325.00 FL
7	1		*TAIL GATE LOCK CATCH	Not Necessary	40.00 FL	*- FL
8	1		*TAIL GATE INNER TRIM BOARD COVER	Not Necessary	233.00 FL	*- FL
9	1		*TAIL GATE INNER HANDLE GARNISH	Not Necessary	48.00 FL	*- FL
10	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	177.00 FL	*121.10 FL
11	1		*TAIL GATE WINDSCREEN WIPER (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*TAIL GATE WIPER MOTOR	Not Necessary	482.00 FL	*- FL
13	1		*TAIL GATE REFLECTORS	O/s Cracked	1,157.00 FL	*485.10 FL
14	1		*RHS & LHS TAILLAMPS	O/s Cracked	1,964.80 FL	*650.10 FL
15	1		*REAR BUMPER TOP CENTRE PAD	Deformed/Torn	482.00 FL	*482.00 FL
16	2		*REAR BUMPER SIDE PAD	Deformed/Torn	288.00 FL	*288.00 FL
17	1		*REAR BUMPER	Distorted	1,282.00 FL	*801.10 FL
18	2		*REAR BUMPER SIDE REFLECTORS	Cracked	196.80 FL	*196.80 FL
19	1		*REAR END PANEL TOP GARNISH	Torn	378.00 FL	*245.10 FL
20	1		*BOOT EDGE WEATHERSTRIP	Twisted	257.00 FL	*257.00 FL
21	1		*REAR FLOOR PANEL TOP COVER	Not Necessary	346.00 FL	*- FL
22	1		*REAR FLOOR PANEL TOOL TRAY	Cracked	298.00 FL	*298.00 FL
23	1		*REAR END PANEL (OUTER)	Dented	978.00 FL	*645.10 FL
24	1		*SET TAIL GATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
26	1		*REAR NUMBER PLATE W/HOLDER	Scratched	75.00 FS	*40.00 FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
28	1		*REAR WINDSCREEN VIDEO CAMERA (NPA)	Not Necessary	0.00 FS	*- FS
29	1		*REAR TAILGATE TOP SPOILER (NPA)	Not Necessary	0.00 FS	*- FS
30	1		*REAR TAILGATE TOP SPOILER SEALANT	Not Necessary	60.00 FS	*- FS
31	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
32	1		*REVERSE CAMERA	Shorted	480.00 FS	*380.00 FS
33	1		*SET REVERSE PARKING SENSORS	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,754.00</b>	<b>7,104.50</b>
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,887.25	1,586.13
<b>Total Parts (\$\$)</b>	<b>9,866.75</b>	<b>5,518.37</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	1,400.00	750.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,000.00	900.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO REMOVE/REFIX INNER TRIMS,FITTINGS,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	200.00	80.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	140.00	120.00
6	TO REMOVE AND REFIX REAR WINDSCREEN VIDEO CAMERA }	New	100.00	50.00
7	TO REMOVE AND REPLACE REVERSE SENSORS AND CAMERA AND CHECK FOR PROPER FUNCTION }	New	180.00	0.00
8	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,350.00</b>	<b>1,990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >