

22/03/2002

ASS. REC. BY:

REF:

CS MSG19002382/RISd3a

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

Merimen

From (Person): Chhica Nyuk Pui

of

MSG

Date/Time: 11/2/19 @ 11:47am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGZ 2525U

Insured:

SGZ 9085B

at Workshop m/s

Performance Motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

2760 2055 QMX

Claim No:

584297

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/2/2019

CA / REV / REP. / REV 24 HRS ^(up)

H.O.D. Endorsement:

Date/Time:

12:19pm @ 11/2/19

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SGZ 2525U-X

SGZ 9085B-X

12/2/19

Send preli revised via merimen

SYNOPSIS

Form

REF:

67225

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SG2 2525U**
at Workshop m/s **PERFORMANCE**
of **2013 ALFA ROMEO**
Insured: **MSH**

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *up*

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SG2 2525U** Yr Regn: **2013** *OUT*
Type: **C** M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **B.M.W 316I 1.6 A** C.C. **1598**

Colour: **WHITE** A/C: Insured / Std / NI / NA

Sp. Reading: **61135** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WBA3A16090NS35648**

Gen. Cond: **C** Good / Fair / Poor / Burnt

Steering: **C** Inorder / Jammed / Leaked / Burnt or

Brake: **C** Inorder / Jammed / Leaked / Burnt or

Modi: **C** Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/50R17**
R: **2 -**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Continental**

Front

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **02/02/19** D.O.I. **11/02/19**

Survey held at **PERFORMANCE**

Des. of Damages: Frt **C** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/03/19	Confirmed P/P \$ 1,974.00 / 3 days with Reserve! (\$ 1,715.95 Red 47%)

RECEIVED 18 MAR 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) **12/03/19** ☒ : Final Report
Typist

Date/Time, File Return to?

2) _____

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee: **150**

Transportation

) S + RS SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) **1,974.00 P/P**

150
10
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2019		11 Feb 2019 11:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SOH MEI LUAN, ID: S1147418G		
Main Claimant:	LEE MEI KUEN, ID: S7406722J		
Vehicle Reg. No.:	SGZ2525U	Date of Loss:	02/02/2019 13:00 - :59 [63 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584297	Policy/Cover Note No.:	27602055QMX (Comprehensive) Coverage: 23/11/2018 - 22/11/2019
Vehicle Reg. No. (Insured):	SGZ9085B	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/02/2019]		
Adj Asg. Remarks:	Car in, request survey by today. on WP. Please contact us ASAP if you cannot attend this assignment. OI not reported. Contact : Caroline at 6319 0174		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chhia Nyuk Pui	Date: 12 Feb 2019
<u>Preliminary Advice</u>	

Insured Vehicle No	: SGZ9085B	Accident Date	: 02/02/2019
TP Vehicle No	: SGZ2525U	Assignment Date	: 11/02/2019
Make	: BMW 316I	Est. Duration of Repair	: 3.00
Date of Inspection	: 11/02/2019	Inspection At : PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,689.95
Revised Amount	:S\$	1,974.00
Check Items (Estimated)	:S\$	101.65
Total	:S\$	2,075.65
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/02/2019 09:32
Date Of Accident	02/02/2019 13:40
Exact Location Of Accident	FARRER ROAD H05 TAXI STAND
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGZ2525U
Insured/Policyholder	
Name Of Registered Owner	LEE MEI KUEN
NRIC No	S7406722J
Email Address	VCCETAM18@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96289185
Alternative Phone No	OTHERS-98329935
Vehicle Particulars	
Manufacturer	BMW
Model	316AI
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	TAM YEW MENG VICTOR
NRIC No	S7131744G
Date Of Birth	07/09/1971
Occupation	INDOOR
Date Of Driving Pass	11/01/1990
Driving Experience	29 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98329935
Fax Number	
Contact Number	OTHERS-96289185
EMAIL Address	VCCETAM18@GMAIL.COM

Address	92 KING'S DRIVE
Postcode	266459
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	SBP9595H
	-
	-
Insurance Company of Driver's Own Vehicle	AXA INSURANCE PTE LTD
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAM KHAI YIH EDYSON
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGZ9085B
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KYI PETER @ CHOO PETER
NRIC/Passport Number	S0337382G
Contact Number	98716129
Address	BLK 5 FARRER ROAD #13-54
Postcode	260005
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

7 Feb 2019
8:51 am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

7 Feb 2019
8:51 am

Reporting Centre/Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TURNING INTO FARRER ROAD (TURNING LEFT) FROM
 ERAPRESS ROAD ON FEB 2, 2019 @ around 1:38 pm. WEATHER CLEAR
 AND SUNNY. AS I WAS SLOWLY TRAVELLING ALONG FARRER ROAD
 APPROACHING HOS TAXI STAND, I SAW A TAXI STOPPED ALONG THE
 ROAD (LEFT LANE) AND NOT AT TAXI STAND. I STOPPED
 BEHIND ANOTHER PASSENGER VEHICLE (TAXI WAS IN FRONT
 OF THIS PASSENGER VEHICLE) AND ~~PRIOR TO STOPPING, I~~
~~WAS ONLY TRAVELLING AT AROUND 20~~. THE VEHICLE
 SGZ 9085 B ~~CA~~ BEHIND MY VEHICLE COULD NOT
 STOP ON TIME AND HIT MY REAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 7 Feb 2019
 8:59 am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 7 Feb 2019
 8:59 am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

7/2/2019
 @ 8:59 am

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



*Car is
already being
worked on
with wiper
diver*

GST REG. NO : M2 - 0020081 - X

07 FEB 2019

E S T I M A T E

Estimate No. : b1 50000
Date Estimated : 07/02/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
LEE MEI KUEN (LI MEIJUAN)
92 KING'S DRIVE

Singapore 266459

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGZ2525U	NS35648	30/10/2013	316iA/4	0

DESCRIPTION

Replace rear bumper and remove attachment etc

Spray painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE

850 1,275.00

934 1,038.00

150 177.00

40.00

Total Labour 1: 2,530.00

DESCRIPTION

REAR DECORATIVE STRIP (SPORT LINE)

RR BUMPER TRIM PANEL PRIMED (LINES/

REAR PDC HOLDER SET

(S/L) LH PROTECTION FOIL

(S/L) RH PROTECTION FOIL

QTY PRIC

1 61.25

1 1,058.30

1 24.60

1 7.90

1 7.90

VALUE

61.25

1,058.30

24.60

7.90

7.90

Total Parts : 1,159.95

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date&Time 11/02/19 @ 1445 Excess S\$

Surveyor's Name RASUL Sign

Surveyor's Tel 64796601 Authored Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 3 days

Labour 1 : 2,530.00

Parts : 1,159.95

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 258.30

Grand Total : 3,948.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50000
Date Estimated : 07/02/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
LEE MEI KUEN (LI MEIJUAN)
92 KING'S DRIVE

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 266459

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SGZ2525U	NS35648	30/10/2013	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the rear bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
Sundries	40.00		40.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	0.00
Total Labour & Parts :	1,974.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	1,974.00
GST @7%:	138.18
Grand Total :	2,112.18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2019		11 Feb 2019 11:47 Edit Adj Rpt	S\$1,974.00 Edit Estimates	S\$1,974.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SOH MEI LUAN , ID: S1147418G								
Main Claimant:	LEE MEI KUEN , ID: S7406722J								
Vehicle Reg. No.:	SGZ2525U	Date of Loss:	02/02/2019 13:00 - :59 [63 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 584297	Policy/Cover Note No.:	27602055QMX (Comprehensive) Coverage: 23/11/2018 - 22/11/2019						
Vehicle Reg. No. (Insured):	SGZ9085B	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/03/2019]								
Adj Asg. Remarks:	Car in, request survey by today. on WP. Please contact us ASAP if you cannot attend this assignment. OI not reported. Contact : Caroline at 6319 0174								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGZ2525U (584297)**
[SGZ9085B]
TP
LEE MEI KUEN
Feb 2 2019 1:00PM
[SOH MEI LUAN]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Assessment Reports						1 per page <input type="button" value="1"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	08/02/19 15:53	Accident Statement From: SC - Reg. No: SGZ9085B, Claimant: SOH MEI LUAN			Load HTM	<input type="button" value="Print"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	12/02/19 14:11	Adjuster Immediate Advice			Load HTM	<input type="button" value="Print"/>	
Photos/Images						3 per page <input type="button" value="3"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	18/03/19 10:25	Odometer Reading			Load JPG <input type="button" value="Print"/>		
2	18/03/19 10:25	Chassis Number			Load JPG <input type="button" value="Print"/>		
3	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
4	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
5	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
6	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
7	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
8	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
9	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
10	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
11	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
12	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
13	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
14	18/03/19 10:25	General View			Load JPG <input type="button" value="Print"/>		
Documentation						1 per page <input type="button" value="1"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	07/02/19 14:07	SGZ2525U E-FILE REPORT			Load PDF	<input type="button" value="Print"/>	
2	07/02/19 14:07	Estimate			Load PDF	<input type="button" value="Print"/>	

Documents Checklist

DOCUMENTS CHECKLIST		<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19002382/R1SD3E2

Date: 19/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27602055QMX

Claimant Vehicle No : SGZ2525U

Insured Vehicle No : SGZ9085B

Date of Loss: 02/02/2019

Nature of Claim: TP

Claim No: 584297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGZ2525U

Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)

Engine No: A340J507N13B16A

Reg. Date: 30/10/2013 (Man. Year: 2013)

Chassis No: WBA3A16090NS35648

Colour: White

Odometer: 61135 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,199.95	40.00	1,159.95	96.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,689.95	1,974.00	1,715.95	46.50
+ GST 7.00/7.00% (S\$)	258.30	138.18	120.12	46.50
Nett Amount (S\$)	3,948.25	2,112.18	1,836.07	46.50

INSPECTION

Date of Assignment: 11/02/2019

Date Inspected: 11/02/2019 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2019)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ2525U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
2	1		*RR BUMPER TRIM PANEL PRIMED (LINES/	Repair	1,058.30 FS	*- FS
3	1		*SET REAR PDC HOLDER	Not Necessary	24.60 FS	*- FS
4	1		*(S/L) LH PROTECTION FOIL	Not Necessary	7.90 FS	*- FS
5	1		*(S/L) RH PROTECTION FOIL	Not Necessary	7.90 FS	*- FS
6	1		*REAR DECORATIVE STRIP (SPORT LINE)	Not Necessary	61.25 FS	*- FS
					Total Parts (\$\$)	1,199.95 40.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC	New	1,275.00	850.00
2	SPRAY PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >