

22/03/2002

ASS. REC. BY:

REF:

08/MSG19002385/RHd32

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Kwok woon chao

of

MSG

Date/Time:

11/2/19 @ 9:39am

Estimated Cost:

Bill to:

OD

TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

WC 4290P

Insured:

at Workshop m/s

Tan chong Industrial

Tel:

66622287

of

23 Jalan Buroh

Policy No:

B29088496MKF

Claim No:

583341

Sum Insured:

Excess:

TBA

Make of Veh:

(Client's Record)

D.O.A.

24/01/2019

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:47am @ 11/2/19

Person Contacted:

Alfred

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

Investigation

Apply SCDF

WC4290P-X

19/02/19

Alfred agreed to km at 40k.

19/2/19 @ 2:57pm and revert to Woon Chao via Meimen. Repairer agreed COR ≤ \$40k

02/2@14:52pm authorise repair by Kenneth

Paul


REF:

24724

ASSIGNMENT

COR XOMBY 2021/2022

From _____ Date _____
Estimated Cost _____
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
To Inspect Vehicle No: **WC 4290P**
at Workshop n/s **THE CHONG**
of **23, Jalan Buroh**
Insured **MSIA**
Policy No. _____
Claims No. _____
Sum Insured _____ Excess: **TBA**
(Client's Record)
Make of Veh. _____
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: **SSK**
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / ☒ (REV) / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT



Veh No: **WC 4290P** Yr Regn: **2011 JCM**
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
☒ Truck / Trailer or _____
Make: **NISSAN CASH** C.C. **1301P**
Colour: **WHITE** A/C Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **C684CLS 00197**
Gen. Cond: Good / Fair / Poor / ☒ Burnt
Steering: Inorder / Jammed / Leaked / ☒ Burnt or
Brake: ☒ Inorder / Jammed / Leaked / Burnt or
Mod: ☒ Nil / S/Rim / STD A/Rim or
Tyre Size: F: **295/80R22.5**
R: **D/O**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **FIREMAX**
Front Rear
R/Bal. **8** mm R/Bal. **8/8** mm
L/Bal. **8** mm L/Bal. **8/8** mm
D.O.A. **24/01/19** D.O.I. **11/02/19**
Survey held at **THE CHONG**
Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

27/2 @ 3:30pm email to Alfred authorize repair excess \$50, All in lump sum
40,000/- inclusive supplementary & check items

lump sum \$40,000/- (Red: 27,350.30:40%)

RECEIVED 17 MAY 2019

[Signature]
17/5/2019

Date/Time: File Pass to? ☐ : Preli. Report
17/5 Typist ☒ : Final Report
Date/Time: File Return to? _____

Days Of Repair: **14**
Resurvey No. of Trip: **1**

Survey Fee:	300
Transportation	
Photos	
Other	
Fire Report	170.00
TOTAL	10

Report Format: **OD**
Lump Sum / I.B.E. IS **40,000/-**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

[Signature]

[Signature]
27/2/19

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019		11 Feb 2019 09:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YATSEN TECHNOLOGIES PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	WC4290P	Date of Loss:	24/01/2019 12:00 - :59 [91 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 583341	Policy/Cover Note No.:	B29088496MKF(COMP) (Comprehensive) Coverage: 01/07/2018 - 30/06/2019
		Excess:	S\$0.00
Repairer:	Tan Chong Industrial Machinery Pte Ltd (Jalan Buroh) 23 Jalan Buroh, 619479 Boon Lay - Tel: 66622287		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/02/2019]		
OD Investigation	Yes		
Driver/Custodian:	SIVANEASAN SELVAM (58 / Male), NRIC: S2647699B, Tel: +6587009661		
Adj Asg. Remarks:	TO REVERT		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Alfred Lee <alfred_lee@tanchong.com>
Sent: Thursday, 16 May 2019 5:06 PM
To: Denise Tay (LKKAuto)
Subject: Re: WC 4290P / OD / MSIG

Dear Ms Denise Tay,

The repair is completed and invoiced at the Lump sum of \$40,000.00 before gst.

Regards,

Alfred Lee
Tan Chong Industrial Machinery Pte Ltd
DID : 6703 8755
FAX : 6266 5862

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 16 May 2019 4:58 PM
To: Alfred Lee
Subject: RE: WC 4290P / OD / MSIG

Dear Alfred,

Any finalization since repair has been done and collected by insured?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alfred Lee <alfred_lee@tanchong.com>
Sent: Wednesday, 17 April 2019 2:26 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: Re: WC 4290P / OD / MSIG

Dear Denise,

Vehicle already completed and collected by owner.

Regards,

Alfred Lee
Tan Chong Industrial Machinery Pte Ltd
DID : 6703 8755
FAX : 6266 5862

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 19 Feb 2019

Preliminary Advice

Vehicle No	: WC4290P	Accident Date	: 24/01/2019
Make	: NISSAN CGB45CLSMNB	Policy No.	: B29088496MKF(COMP)
Assignment Date	: 11/02/2019	Excess	: S\$0.00
Date of Inspection	: 11/02/2019	Est. Duration of Repair	: 14.00
Inspection At	: TAN CHONG INDUSTRIAL MACHINERY PTE LTD (JALAN BUROH) 23 JALAN BUROH SINGAPORE 619479		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	67,350.30
Revised Amount	:S\$	58,425.00
Check Items (Estimated)	:S\$	3,440.56
Total	:S\$	61,865.56
Lump Sum Repair	:S\$	40,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	6,600.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,400.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. REPAIRER AGREED REPAIR COST NOT MORE THAN \$40,000.00 ON LUMP SUM BASIS.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 12 Feb 2019

Preliminary Advice

Vehicle No	: WC4290P	Accident Date	: 24/01/2019
Make	: NISSAN CGB45CLSMNB	Policy No.	: B29088496MKF(COMP)
Assignment Date	: 11/02/2019	Excess	: S\$0.00
Date of Inspection	: 11/02/2019	Est. Duration of Repair	: 14.00
Inspection At	: TAN CHONG INDUSTRIAL MACHINERY PTE LTD (JALAN BUROH) 23 JALAN BUROH SINGAPORE 619479		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	67,350.30
Revised Amount	:S\$	58,425.00
Check Items (Estimated)	:S\$	3,440.56
Total	:S\$	61,865.56

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	6,600.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,400.00

Remarks

- (x) The vehicle is economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.
- (x) Pending Investigation, SCDF Report and repairer's repair cost, repairer is asking for lump sum repair. Please take note the margin of repair is \$48,400/-

Denise Tay (LKKAuto)

From: SCDF Payment Acknowledgement <donotreply@scdf.gov.sg>
Sent: Tuesday, 12 February 2019 2:07 PM
To: SUR
Subject: Order Confirmation

CyberSource*
the power of payment

Receipt

Date: 02-12-2019
Order Number:
FR2019021202672

Billing Information

LKK Auto Consultants Pte Ltd
Denise Tay
BLK 51 UBI AVE 1 #01-25
singapore
SG
532932

sur@lkkauto.com
62563561

Payment Details

Visa
xxxxxxxxxxxx9189

Order Total

Total amount SGD 170.00

Please keep a copy of this receipt for your records



SINGAPORE CIVIL DEFENCE FORCE
91 UBI AVENUE 4
SINGAPORE 408827
TELEPHONE: 6280 0000
GST REG NO: MG-8400000-5

TAX INVOICE/RECEIPT

Name : Denise Tay
Address : BLK 51 UBI AVE 1 #01-25
#01-25
Singapore 532932

Receipt No : 5499516231176250203027
Date/Time : 12/02/2019 14:04
eService ID : FR2019021202672

S/No	Payment Mode	Description	Reference No	Net Amount	GST (7% GST)	Gross Amount
1	Credit Card	Fire Report	FR2019021202672	170.00	0.00	170.00
					Total Amount (SGD)	170.00

REMARKS:

Date and Time [24/01/2019 12:20] - Location of Fire [FORT ROAD ALLIANCE PLANT]

Note: This is a computer generated receipt. No signature is required. Receipt is void if payment is dishonoured.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2472G
Vehicle Details	
Vehicle No.:	WC4290P
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	NISSAN
Vehicle Model:	CGB45CLSMNB
Primary Colour:	White
Secondary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	GE13336853B
Chassis No.:	CGB4CLS00197
Maximum Power Output:	-
Open Market Value:	\$156,059.00
Original Registration Date:	14 Jun 2011
First Registration Date:	14 Jun 2011
Transfer Count:	3
Actual ARF Paid:	\$7,803.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$28,189.00
COE Rebate Amount:	\$6,600.00
Total Rebate Amount:	\$6,600.00

The information contained herein is correct as at 12 Feb 2019

OK

55,000
6,600

48,400

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	WC4290P
Vehicle Type:	B69 - Goods (Open) Concrete Mixer/Cement Mixer
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	NISSAN
Vehicle Model:	CGB45CLSMNB
Chassis No.:	CGB4CLS00197
Propellant:	Diesel
Engine No.:	GE13336853B
Engine Capacity:	13074 cc
Maximum Power Output:	-
Maximum Laden Weight:	34000 kg
Unladen Weight:	13000 kg
Year Of Manufacture:	2008
Original Registration Date:	14 Jun 2011
Lifespan Expiry Date:	-
COE Category:	C - Goods Vehicle & Bus
Quota Premium:	\$28,189.00
COE Expiry Date:	13 Jun 2021
Road Tax Expiry Date:	29 Jan 2019
Inspection Due Date:	29 Jul 2019
Intended Transfer Date:	12 Feb 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 30 Jan 2019 to 29 Jul 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	298.00	-	298.00
Total Amount Payable:			323.00

You may print this page for reference.

OK

Print

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 22 February 2019 3:18 PM
To: ALFRED_LEE@TANCHONG.COM
Cc: SUR
Subject: WC 4290P / OD / MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **WC 4290P (Excess \$0,00/-)**. All in lump sum **\$40,000/- inclusive supplementary and check items**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***WC4290P (583341)**

OD

Jan 24 2019 12:00PM

[YATSEN TECHNOLOGIES PTE LTD]
Tan Chong Industrial Machinery Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 22/02/2019 14:52 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$40000.00) - WC4290P - Claim Handler: Kwok Woon Choo

Approved:40000.00;lumpsum repair up to \$40K including supp parts and check items. Excess \$0.

DOCUMENTS SUMMARY

There are no documents.

MVA219011698 | VAC - Sin Ming
 ENTRY DATE & TIME: 24/01/2019 15:45
 SUBMITTED BY: CHRISTINA ONG Mui Lan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2019 15:45
Date Of Accident	24/01/2019 12:20
Exact Location Of Accident	FORT ROAD ALLIANCE PLANT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC4290P
Insured/Policyholder	
Name Of Registered Owner	YATSEN TECHNOLOGIES PTE LTD
Co Reg No	-
Email Address	YATSENTEC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87009661
Alternative Phone No	OFFICE-87009661

Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29088496MKF (COMP)
Cover Note Number	

Driver

Name of Driver	SIVANEASAN SELVAM
NRIC No	S2647699B
Date Of Birth	05/01/1961
Occupation	INDOOR
Date Of Driving Pass	19/12/1989
Driving Experience	29 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87009661
Fax Number	
Contact Number	OTHERS-87009661
Email Address	YATSENTEC@GMAIL.COM

Page 1 of 1

Address	BLK 75 WHAMPOA DRIVE #15-364
Postcode	320075
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. NOTE: *INFORMED DRIVER TO MAKE POLICE REPORT AND SUBMIT TO INSURER* (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Printed on: 25-Jan-19, 7:31

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



24 JAN 2013

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

R. S. S. S. S.

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Kindy we bring to Accident Report:

For Road Alliance plant The the Vehicle
start ready 1/2 hours this Error Running after
1/2 hour's Fire ready after Engine Automatically caught
fire

DECLARATION

/We declare the foregoing particulars are true in every respect.

2: 14N 10J

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No:



WJ0000000000

Sketch Plan #3 Pg. 1

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7886, Fax +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.2.301

COMMERCIAL VEHICLE - FLEET
Comprehensive

Goods Carrying Vehicle - Sch II

Certificate No. B 29088496 MKP

Excess: SGD1,500

1. Index Mark and Registration Number of Vehicle
 WC4290P

2. Name of Policyholder
 Yatsen Technologies Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 30/07/2018

4. Date of Expiry of Insurance
 30/06/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use in connection with the Policyholder's business.
 Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 Use for social domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
- (3) Use for the carriage of passengers for hire or reward.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).


I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers

for Chief Executive Officer

ELYM201808151514

MSIG-MSIG





**SINGAPORE
POLICE FORCE**



E/20190124/2064

1 of 2

POLICE REPORT (NP299)

Report No. E/20190124/2064

Police Station Of Origin
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Date/Time Report Made 24/01/2019 17:34	Vide Report No.	Station Diary No. 127
Name Of Informant SIVANEASAN SELVAM	Address APT BLK 75 WHAMPOA DRIVE #15-364 SINGAPORE 320075	
ID Type / ID No. NRIC NO / S2647699B	Contact No. Home/Office Mobile 87009661	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Other heavy truck and lorry drivers	Sex Male	Age 58
Institution/School Name	Date of Birth 05/01/1961	Race Indiar
Date/Time Of Incident 24/01/2019 12:20	Location Of Incident Allience Plant along Fort road	

Brief details.

On 24/1/19 at about 1220hrs, I was at the Alliance Plant located which is a construction site set up along Fort road. I parked the company truck (cement mixer) registration plate number WC4290P inside the site and left the engine "on". About half hour later, I noticed black smoke coming out from the internal of the truck as such quickly proceed to check. I saw fire inside the truck as such quickly turn "off" the truck engine, pull out the key and call for assistance. Shortly, we managed to put out the fire. I reported the matter to my boss who informed for me to lodge a report for the company to take up the mater with the insurance company for claiming purpose. No one was injure during the accident.

Signature Of Officer Recording The Report: E / Staff Sgt LIM BENG LEE	Signature Of Informant: S. Selvam.
Signature Of Interpreter: Not applicable	Date/Time: 24/01/2019 17:34
Officer In-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / Staff Sgt AMIRUDIN BIN NORDIN Contact No.: 63910000	Classification Of Case:

Authentication Stamp



SN 061



**SINGAPORE
POLICE FORCE**



E/20190124/2064

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20190124/2064

- white smoke from left side. waiting @ right side.
- open right door. saw fire coming from left under the box.
- fire light already. take water from lorry and fire extinguisher to put out fire. 15 min fire put out.
- call fire & told of incident. called insurance officer Elyn. Tow truck came in 3 to 4 hours. 8-9 pm. He not there when tow truck came. mixer gear box.
- No modifications. Only gear box, repaired 1 week ago.
- mechanic checked no problem in gear box.
- Lorry never run 2 weeks. Repaired 1 week ago.

Signature Of Officer Recording The Report:

E / Staff Sgt LIM BENG LEE

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
E / Tanglin Police Divisional Investigation Branch /
Staff Sgt AMIRUDIN BIN NORDIN
Contact No.: 63910000

Authentication Stamp

Signature Of Informant:

S. Selvam.

Date/Time:
24/01/2019 17:34

Classification Of Case:

TAN CHONG INDUSTRIAL MACHINERY PTE LTD

23 JALAN BUROH

SINGAPORE 619479

TEL:67038755 FAX:62665862

From **ALFRED LEE** Date **09-Feb-19**
 To **MSIG INSURANCE (SINGAPORE) PTE LTD** Our ref **AL/4290-010/0219**
 Attn **MOTOR CLAIM DEPT** Tel **68277880**
 Fax **68277809**

VEH NO : WC4290P

Model : CGB4CLSMNB

Chassis : CGB4CLS-00197

Eng No : GE13-336853B

1. The above vehicle was inspected by TCIM and append here under is the estimated repair cost :

Claim type: Own Damage CLAIM

Description	Qty	Unit Price		Amount
GKB4 CABIN ASSY <i>Burnt</i>	1	\$ 65,000.00	25%	\$ 48,750.00
LOWER STEP GRANISH RH <i>Xan</i>	1	\$ 472.42	25%	\$ 354.32
LOWER STEP GRANISH LH <i>Xan</i>	1	\$ 472.45	25%	\$ 354.34
FRONT LID GRILLE <i>Xan</i>	1	\$ 627.48	NETT	\$ 627.48
FRT LID ASSY <i>Xan</i>	1	\$ 920.51	NETT	\$ 920.51
LOWER GRILLE <i>Xan</i>	1	\$ 399.60	NETT	\$ 399.60
UD EMBLEM <i>Xan</i>	1	\$ 128.50	NETT	\$ 128.50
CABIN TILT BRACKET -RH <i>? Xan</i>	1	\$ 761.24	NETT	\$ 761.24
CABIN TILT BRACKET - LH <i>? Xan</i>	1	\$ 761.24	NETT	\$ 761.24
CABIN ABSORBER <i>? Xan</i>	4	\$ 99.90	NETT	\$ 399.60
CABIN AIR BELLOW- FRT <i>? Xan</i>	4	\$ 379.62	NETT	\$ 1,518.48
STEERING WHEEL ASSY <i>Burnt</i>	1	\$ 1,650.00	25%	\$ 1,237.50
ENGINE WIRING HARNESS <i>Burnt</i>	1	\$ 2,850.00	25%	\$ 2,137.50

Estimated parts cost

\$ 58,350.30

Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.

\$ 1,800.00 *1500*

TO REMOVE AND REPLACE CABIN ASSY.
 TO REPLACE TILT BRACKET, LH AND RH CABIN BRACKET ASSY
 TO REPLACE CAB LINK, BUMPER LH, BUMPER STEP AND GRILLES

\$ 7,200.00 *4800*
(15 DAYS)

Estimated labour cost

\$ 9,000.00

EST. LABOUR & PARTS COST

\$ 67,350.30

1. All prices quoted are subjected to 7% GST. The above quotation is based on initial visual inspection only.

Thank you and regards

ALFRED LEE
 Marketing Executive
 Service Department

DID : 67038755
 HP: 97879034

Passul
Hp 900/0068

14 days

43

EXCESS: TBA

REVERT

11/02/19 @ 1611

Resurvey
after
repair

NOTE: TO get letter of
undertaking for inspection
repair

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019		11 Feb 2019 09:39 Edit Adj Rpt	S\$40,000.00 Edit Estimates	S\$40,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YATSEN TECHNOLOGIES PTE LTD, Co. Reg. No.: -								
Vehicle Reg. No.:	WC4290P	Date of Loss:	24/01/2019 12:00 - :59 [91 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 583341	Policy/Cover Note No.:	B29088496MKF(COMP) (Comprehensive) Coverage: 01/07/2018 - 30/06/2019						
		Excess:	S\$0.00						
Repairer:	Tan Chong Industrial Machinery Pte Ltd (Jalan Buroh) 23 Jalan Buroh, 619479 Boon Lay - Tel: 66622287								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/03/2019]								
OD Investigation	Yes								
Driver/Custodian:	SIVANEASAN SELVAM (58 / Male) , NRIC: S2647699B, Tel: +6587009661 Email: yatsentec@gmail.com								
Adj Asg. Remarks:	TO REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (22/02/2019): Alert - Adj Mandate Approved (S\$40000.00) - WC4290P - Claim Handler: Kwok Woon C... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WC4290P (583341)
OD
Jan 24 2019 12:00PM
[YATSEN TECHNOLOGIES PTE LTD]
Tan Chong Industrial Machinery Pte Ltd










Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page					
No	Finalized On	VAC (Sin Ming)								Thumbnail	Print			
1	24/01/19 16:23	Accident Statement							1	Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	12/02/19 16:04	Adjuster Immediate Advice							1	Load HTM				
2	19/02/19 14:56	Adjuster Immediate Advice							1	Load HTM				
Photos/Images									3 per page					
No	Finalized On	VAC (Sin Ming)								Thumbnail	Print			
1	24/01/19 16:08	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
2	24/01/19 16:08	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
3	24/01/19 16:08	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
4	24/01/19 16:08	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
5	24/01/19 16:08	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
6	24/01/19 16:08	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
7	24/01/19 16:08	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
8	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
9	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
10	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
11	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
12	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
13	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
14	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
15	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
16	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
17	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
18	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
19	24/01/19 16:21	Accident Photo [Linked Accident Report Documents]							1	Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	12/02/19 14:39	General View							1	Load JPG	<input checked="" type="checkbox"/>			
2	12/02/19 14:39	General View							1	Load JPG	<input checked="" type="checkbox"/>			
3	12/02/19 14:39	General View							1	Load JPG	<input checked="" type="checkbox"/>			
4	12/02/19 14:39	General View							1	Load JPG	<input checked="" type="checkbox"/>			
5	12/02/19 14:39	General View							1	Load JPG	<input checked="" type="checkbox"/>			
6	12/02/19 14:39	General View							1	Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
7	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/02/19 14:39	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/05/19 09:56	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
57	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
65	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
66	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
67	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
68	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
69	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
70	17/05/19 09:56	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/01/19 15:42	Status of Driving Licence	Load PDF	
2	28/01/19 13:07	E MAIL FR EILEEN NG ATTACH POLICE REPORT	Load PDF	
3	28/01/19 13:10	Police Report	Load PDF	
4	11/02/19 09:38	OD ESTIMATE + GIA REPORT.	Load PDF	
5	11/02/19 09:38	E MAIL FR WORKSHOP	Load PDF	
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	24/01/19 16:01	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	24/01/19 16:01	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	24/01/19 16:01	Sketch Plan #3 [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 18:10	WC 4290P FIRE INVESTIGATION REPORT	Load PDF	
2	28/05/19 08:47	Investigation Report	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	24/01/19 16:23	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	24/01/19 16:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	24/01/19 16:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	24/01/19 16:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	24/01/19 16:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	24/01/19 16:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	24/01/19 16:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	24/01/19 16:08	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	24/01/19 16:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	24/01/19 16:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	24/01/19 16:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	24/01/19 16:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	24/01/19 16:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	24/01/19 16:21	Accident Photo	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
14	24/01/19 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	24/01/19 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	24/01/19 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	24/01/19 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	24/01/19 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	24/01/19 16:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	24/01/19 16:01	Sketch Plan	 Load TIF	
2	24/01/19 16:01	Sketch Plan #2	 Load TIF	
3	24/01/19 16:01	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19002385/R1TD3E2

Date: 28/05/2019

REFERENCE

Insured/Claimant: YATSEN TECHNOLOGIES PTE LTD

Policy No: B29088496MKF(COMP)

Date of Loss: 24/01/2019

Nature of Claim: OD

Claim No: 583341

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WC4290P**

Make & Model: NISSAN CGB45CLSMNB, 13.1 D (M)

Engine No: GE13336853B

Reg. Date: 14/06/2011 (Man. Year: 2008)

Chassis No: CGB4CLS00197

Colour: White

Odometer: 0 km

Engine Capacity: 13074 cc

Market Value/New Car Price: S\$55,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Firemax 8 mm

Rear Left Side: Firemax 8/8 mm

Front Right Side: Firemax 8 mm

Rear Right Side: Firemax 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	58,350.30	52,125.00	6,225.30	10.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,000.00	6,300.00	2,700.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	67,350.30	58,425.00	8,925.30	13.25
Approved Total (Overridden) (S\$)		40,000.00		
(S\$)	67,350.30	40,000.00	27,350.30	40.61
+ GST 7.00/7.00% (S\$)	4,714.52	2,800.00	1,914.52	40.61
Nett Amount (S\$)	72,064.82	42,800.00	29,264.82	40.61

INSPECTION

Date of Assignment: 11/02/2019

Date Inspected: 11/02/2019 Inspected At:

Tan Chong Industrial Machinery Pte Ltd
(Jalan Buroh)
23 Jalan Buroh
Singapore 619479

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 May 2019)	
Parts:	N/A	NISSAN CGB45CLSMNB 13.1 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WC4290P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GKB4 CABIN ASSY	Burnt	65,000.00 FL	*65,000.00 FL
2	1		*LOWER STEP GRANISH RH (NOT NECESSARY)	Not Consistent With The Impact	472.42 FL	*- FL
3	1		*LOWER STEP GRANISH LH (NOT NECESSARY)	Not Consistent With The Impact	472.45 FL	*- FL
4	1		*FRONT LID GRILLE (NOT NECESSARY)	Not Consistent With The Impact	627.48 FS	*- FS
5	1		*FRT LID ASSY (NOT NECESSARY)	Not Consistent With The Impact	920.51 FS	*- FS
6	1		*LOWER GRILLE (NOT NECESSARY)	Not Consistent With The Impact	399.60 FS	*- FS
7	1		*UD EMBLEM (NOT NECESSARY)	Not Consistent With The Impact	128.50 FS	*- FS
8	1		*CABIN TILT BRACKET - RH	Serviceable	761.24 FS	*- FS
9	1		*CABIN TILT BRACKET - LH	Serviceable	761.24 FS	*- FS
10	4		*CABIN ABSORBER	Serviceable	399.60 FS	*- FS
11	4		*CABIN AIR BELLOW - FRT	Serviceable	1,518.48 FS	*- FS
12	1		*STEERING WHEEL ASSY	Burnt	1,650.00 FL	*1,650.00 FL
13	1		*ENGINE WIRING HARNESS	Burnt	2,850.00 FL	*2,850.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	75,961.52	69,500.00
- List Item Discount on L Items 25.00/25.00% (S\$)	17,611.22	17,375.00
Total Parts (S\$)	58,350.30	52,125.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT	New	1,800.00	1,500.00
2	TO REMOVE AND REPLACE CABIN ASSY. TO REPLACE TILT BRACKET, LH AND RH CABIN BRACKET ASSY. TO REPLACE CAB LINK, BUMPER LH, BUMPER STEP AND GRILLES	New	7,200.00	4,800.00
Gross Labour Cost (\$\$)			9,000.00	6,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >