

2/03/2002

ASS. REC. BY:

REF:

CS3/MSG/19002393/Rcd301

Special Instruction:

Surveyor:

Rauw

ASSIGNMENT (Office)

From (Person):

Meinen

Katherine Wong

of

MSG

Date/Time: 11/2/19 @ 9:25am

Estimated Cost:

Bill to:

OD ☒ TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 3891 A

Insured:

YP 51032

at Workshop m/s

Seng Hwe Motor

Tel:

67555205

of

Blk 1018, Yishun Ind. Park A # 01-350

Policy No:

29058616MCC

Claim No:

584401

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/2/2019

CA / REV / REP. / REV 24 HRS (up)

12/2/19 @ Afternoon

H.O.D. Endorsement:

Date/Time:

10-13umg 11/2/19

Person Contacted:

Mr. Kueh

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJY 3891A - CS/ASM18008072 / Atbs2 DOA: 2/5/2018
	YP 51032 - X
	Before paint: 14/2/2019.
	After paint: 22/2/2019.

John

REF:

63000

COE XPIRY: 2020/ANH

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / ☒ P / WS / TP RES / OD RES / EVA / INV / MV **PRS**
To inspect Vehicle No: **SY4 3891A**
at Workshop m/s: **Senh Huelk m/s**
of: **1018, Yishun Ind Pk A #01-350**
Insured: **MSIA**
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **33k**
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: **6** days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: **SY4 3891A** Yr Regn: **2010 ANH**
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **TOYOTA WISH 2.0 A** c.c. **1987**
Colour: **Grey** A/C: Insured / Std / NI / NA
Sp. Reading: **292077** T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: **ITD6J20W X05001333**

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ order / Jammed / Leaked / Burnt or

Brake: ☒ order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ Rim / STD A/Rim or

Tyre Size: F: **225/45R17**
R: **225/45R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 05/02/19	D.O.I. 12/02/19

Survey held at: **Senh Huelk m/s**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$5,000 - \$6,000

John
27/2/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: **6**

Resurvey No. of Trip: **2**

Survey Fee:

Transportation

☐ S+RS ☐ SI

☐ Photos

☐ Others

☐ :

TOTAL

2)

Add Fee:

☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format: **PRE**

Lump Sum / L.B.I. (\$)

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2019		11 Feb 2019 09:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Ng Tian Seh Contractor Pte Ltd, Co. Reg. No.: 200815026W		
Main Claimant:	Tan Mei Lan Joanne, ID: S75163008		
Vehicle Reg. No.:	SJY3891A	Date of Loss:	05/02/2019 16:00 - :59 [101 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584401	Policy/Cover Note No.:	29055616MKC (Comprehensive) Coverage: 12/12/2018 - 11/12/2019
Vehicle Reg. No. (Insured):	YP5103Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/02/2019]		
Adj Asg. Remarks:	on WP, Liability unclear, Non Reporting. Contact Person: Mr Kueh / 6755 5205.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ISLAND LAW LLC**Advocates & Solicitors**

(UEN No. 200918269D)

(GST Reg No. 200918269D)

KIRPAL SINGH SHARMA
NG KWONG LOONG

SUNITA CARMEL NETTO

Our Ref : FS. 03891A. 19. PD (SHM). ap

Your Ref : JP 5103Z

101 Upper Cross Street
#04-04 People's Park Centre
Singapore 058357
Tel: (65) 6221 3211
Fax: (65) 6225 3210
(65) 6225 3054

Date: 7 FEBRUARY 2019

MSIG INSURANCE (SINGAPORE) PTE LTDAttn: Motor Claims DepartmentBy e-mail:
(claims@sig.msig-asia.com)

Dear Sirs,

ACCIDENT INVOLVING SJY 3891A AND JP5103Z ALONG SELETAR NORTH LINK
TOWARDS YISHUN DAM ON 05/02/2019 AT 1600 HRS(NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)We act for TAN MEI LAN JOANNE who has appointed the undermentioned
workshop to repair his/her motor vehicle no. SJY 3891A.

Please be informed that the said vehicle can be inspected at:

Name	:	<u>SENG HWEE MOTOR</u>
Address	:	<u>BLK 1018 YISHUN INDUSTRIAL PARK A</u> <u># 01-350</u> <u>SINGAPORE 768760</u>
Person to contact	:	<u>MR KUEH</u>
Tel	:	<u>6755 5205</u>

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any
intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter
without further reference to you.

Yours faithfully

LKK AUTO
68411972

ISLAND LAW LLC

cc: Client (SJY 3891A) (By Fax: 6753 4407)

For Surveyor
Please initial here after completion
of pre-repair inspection. Thank you.Appointed surveyor :
(Name & Signature)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 6300B

Vehicle Details

Vehicle No.: SJY3891A
Vehicle to be Exported: No
Intended Deregistration Date: 14 Feb 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 2.0 AUTO
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: 3ZRA406573
Chassis No.: JTDGJ20WX05001333
Maximum Power Output: 106.0 kW (142 bhp)
Open Market Value: \$22,003.00
Original Registration Date: 26 Aug 2010
First Registration Date: 26 Aug 2010
Transfer Count: 1
Actual ARF Paid: \$22,003.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Aug 2020
PARF Rebate Amount: \$12,101.00

Intended COE Rebate Details

COE Expiry Date: 25 Aug 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$42,810.00
COE Rebate Amount: \$6,548.00
Total Rebate Amount: \$18,649.00

The information contained herein is correct as at 14 Feb 2019

OK

33,000
18,649

14,351

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2019 16:26
Date Of Accident	05/02/2019 16:00
Exact Location Of Accident	ALONG SELETAR NORTH LINK TWDS YISHUN DAM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY3891A
Insured/Policyholder	
Name Of Registered Owner	TAN MEI LAN JOANNE
NRIC No	S7516300B
Email Address	MLTAN_75@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96751300
Alternative Phone No	OFFICE-96158440

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 2.0 AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA19082/1
Cover Note Number	26/02/2018-25/02/2019

Driver

Name of Driver	CHUNG HON WAI JASON
NRIC No	S7401897A
Date Of Birth	24/01/1974
Occupation	INDOOR
Date Of Driving Pass	26/07/1996
Driving Experience	22 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96158440
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	665A PUNGGOL DRIVE 06-506
Postcode	821665
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN MEI LAN JOANNE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP5103Z
Vehicle Make/Model/Colour	ISUZU
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RANGANATHAN KARTHIK
NRIC/Passport Number	G2335391T
Contact Number	83025070

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN MEI LAN JOANNE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJY3891A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 6 Feb 2019


Driver's Signature
(If driver is not the policyholder)
Date & Time: 06 Feb 19 / 1637 hr


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only

Claim OD

Claim TP

☒ Claim OD/TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]
6 Feb 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
06 FEB 19 / 1637hr

Reporting Centre Personnel's Signature
Name:
NRIC/HN No.:

[Signature]

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190206/2049

1 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20190206/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/02/2019 15:57	Vide Report No.:	Station Diary No.: 39
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHUNG HON WAI, JASON			Address: APT BLK 665A PUNGGOL DRIVE #06-506 SINGAPORE 821665	
ID Type / ID No.: NRIC NO / S7401897A			Contact No.:	Mobile: 96158440
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 45	Date of Birth: 24/01/1974	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: SUPERVISOR			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

General Information of the Accident:				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 05/02/2019 16:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SELETAR NORTH LINK YISHUN AVENUE 1 Along Seletar North Link towards Yishun Dam				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJY3891A	Car	TOYOTA	WISH 2.0 AUTO	Silver	Slightly Damaged	1
YP5103Z	Lorry	ISUZU	NPR85UH5A	White	Slightly Damaged	2

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		

POLICE REPORT Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190206/2049

2 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20190206/2049

CONTINUATION OF REPORT

Driver			
Name	CHUNG HON WAI, JASON	ID No.	S7401897A
Related Vehicle	SJY3891A (Car)	Contact No.	96158440
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Tan Mei Lan Joanne	ID No.	S7516300B
Related Vehicle	SJY3891A (Car)	Contact No.	96751300
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	05/02/2019	Date Discharge	05/02/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 05/02/2019 at about 1600hrs, I was driving my vehicle SJY3891A along Seletar North Link towards Yishun Dam with my wife. My vehicle was in stationary stopped as the vehicle in front of mine has stopped as there is a jam.

Suddenly, I felt an impact from the rear of my vehicle. As such I made a check with my wife if she is alright. She informs me that she felt headache at that point of time. As such I stepped out of my vehicle and made a check with the rear driver. When I was outside my vehicle I realised I had an accident with vehicle YP5103Z.

I ask the driver of YP5103Z if he was sleeping however he never reply. As such I requested for his particulars which he gave and we exchange our particulars and took photos of the scene. I also made a check on my vehicle and discovered that there were damages found at the rear of my vehicle. The driver of YP5103Z informs me that he wanted a private settlement as such I told him that after I check how much is the repair cost and will let him know and he acknowledged. We then drove off our vehicle.

On 05/02/2019 night, my wife informed me that she felt pain at her back and neck area as such I send her to Sengkang General Hospital to make a check and she was entitled with a total of 3 days of medical leave from 05/02/2019 to 07/02/2019.

I wish to state the I have the CCTV footage of the accident in my memory card.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999



T/20190206/2049

3 of 4

Report No. T/20190206/2049

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190206/2049

4 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20190206/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 IVIN ONG HONG CHUAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:

06/02/2019 15:57

Classification Of Case:

SN 005



Singapore Police Force






































...CLAIM SUBFOLDER...(Pending for Survey Report)














CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Feb 2019		11 Feb 2019 09:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Ng Tian Seh Contractor Pte Ltd , Co. Reg. No.: 200815026W									
Main Claimant: Tan Mei Lan Joanne , ID: S7516300B									
Vehicle Reg. No.: SJY3891A		Date of Loss: 05/02/2019 16:00 - :59 [101 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 584401		Policy/Cover Note No.: 29055616MKC (Comprehensive) Coverage: 12/12/2018 - 11/12/2019							
Vehicle Reg. No. (Insured): YP5103Z		Policy No. (Claimant):							
		Excess:							
Repairer: Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 12/02/2019]									
Adj Asg. Remarks: on WP. Liability unclear. Non Reporting. Contact Person: Mr Kueh / 6755 5205.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY3891A (584401)
[YP5103Z]
TP
Tan Mei Lan Joanne
Feb 5 2019 4:00PM
[Ng Tian Seh Contractor Pte Ltd]
Seng Hwee Motor

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
2	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
3	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
4	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
5	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
6	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
7	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
8	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
9	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
10	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
11	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
12	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
13	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
14	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
15	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
16	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
17	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
18	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
19	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
20	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
21	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
22	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
23	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
24	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
25	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
26	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
27	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
28	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
29	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
30	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
31	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
32	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
33	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
34	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
35	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
36	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	
37	23/02/19 12:58	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/02/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/02/19 13:00	Before paint photographs	 Load JPG	<input checked="" type="checkbox"/>
40	23/02/19 13:00	Before paint photographs	 Load JPG	<input checked="" type="checkbox"/>
41	23/02/19 13:00	Before paint photographs	 Load JPG	<input checked="" type="checkbox"/>
42	28/02/19 12:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	28/02/19 12:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	28/02/19 12:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	28/02/19 12:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	28/02/19 12:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	28/02/19 12:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	28/02/19 12:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/02/19 11:07	PRI from Island Law LLC, SJY3891A E-file & Police report	 Load PDF	
2	08/02/19 15:51	TP disagree with our SJE list, proceed to appoint LKK Auto Consultants	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19002393/R1CD3E2

Date: 01/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29055616MKC

Claimant Vehicle No: SJY3891A

Insured Vehicle No: YP5103Z

Date of Loss: 05/02/2019

Nature of Claim: TP

Claim No: 584401

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY3891A

Make & Model: TOYOTA WISH, 2.0 (A)

Reg. Date: 26/08/2010 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 1987 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 3ZRA406573

Chassis No: JTDGJ20WX05001333

Odometer: 292077 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/02/2019

Date Inspected: 12/02/2019 Inspected At:

Seng Hwee Motor (HQ)

Blk 1018 Yishun Industrial Park A #01-350

Singapore 768760

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 01 Mar 2019)

Parts: M1-MPV TOYOTA WISH 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJY3891A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >