

ASS. REC. BY:

REI 03 / CTI 19002395 / Ucd31

Special Instruction:

Surveyor: Manus

ASSIGNMENT (Office)

From (Person): Chong Buan Senof CTIDate/Time: 11/2/19 @ 9:02am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 9849R

Insured:

GBF 3581P

at Workshop m/s:

Power Autocare

Tel:

81812212

of

1 Kaki Bukit Ave 6 # 02-11

Policy No:

DMCVSN19047119000

Claim No:

8NM19D200589C02

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A. 31/1/19CA / REV / REP. / REV 24 HRS ^{up}12/2/19

H.O.D. Endorsement:

Date/Time:

11:25am @ 11/2/19

Person Contacted:

GeryVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLE 9849R - X</u>
	<u>GBF 3581P - CS / SM / 18023106 / Atd3</u>
	<u>Dismantle: 13/2/2019</u>
	<u>After repair: 18/2/2019.</u>
	<u>Create Manual.</u>

D.O.A: 14/12/2018

CTI

INSPECTION

Date: 12/2/2019

Estimated Cost:

OD: WS / PR RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLE 9849R

Address: power Autocare

1kaki Blk Ave 6 #02-11

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: Gary @ 818/2212

Vehicle No: SLE 9849R

Type: Car / M/Cycle / Bus / Van / Utility / Taxi / Prime Mover / Truck / Trailer or

Make: Honda vezel

Color: silver

Sp. Boarding: 43948

Eng No:

C/Nr: RU 1111 3207

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Free / Jammed / Leaked / Burnt or

Brake: Free / Jammed / Leaked / Burnt or

Mod: Nil / SRRim / STD A/Rim or

Tyre Size F: 215/60 R16

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Est. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

GA / REV / REP: 24 HRS ^{up} 5331A

Date: Person Contacted: LEA 46744

Vehicle IN / OUT

BS: DM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 3-1/1/19

Rear: R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 12/2/19

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: Action / Instruction

No. returned. PLS

- 3-4/2

Date/Time: File Pass No:

: Prelim. Report

: Final Report

Date/Time: File Return No:

Report Format: PRS

Lump Sum / I.B.T.:

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee: 150

Transportation:

Add Fee:

- Site Insp: 15
- Interview: 15
- Tech. Fee: 15
- Weekend: 15

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 17:41 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	TANG PEE ENG, ID: S1545331A		
Vehicle Reg. No.:	SLE9849R	Date of Loss:	31/01/2019 16:00 - :59
Claim Type:	TP / SNM19D200589C02	Policy/Cover Note No.:	DMCVSN19047119000
Vehicle Reg. No. (Insured):	GBF3581P	Policy No. (Claimant):	5084297151-02
		Excess:	S\$0.00
Repairer:	Power Autocare (HQ) 1 Kaki Bukit Ave 6, #02-11 Kal Bukit @ Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/05/2019]		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 11 February 2019 9:02 AM
To: assignments
Subject: FW: OUR REF: SNM19D200589C02 / PRE REPAIR SURVEY ACCIDENT INVOLVING SLE9849R & GBF3581P ON 31.1.19

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Natalie Ng <natalie_ng@rssolomon.com>
Sent: Monday, 11 February 2019 9:00 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: pearlyn_goh@rssolomon.com; Admin A <admin-a@lkkauto.com>
Subject: Re: OUR REF: SNM19D200589C02 / PRE REPAIR SURVEY ACCIDENT INVOLVING SLE9849R & GBF3581P ON 31.1.19

Dear Mr Chong,

Well noted and thank you for your reply.

Best Regards,

Natalie Ng | Office Manager 人事与行政经理



R. S. SOLOMON LLC
WWW.RSSOLOMON.COM

R. S. Solomon LLC | 正氣律師事務所

Head Office: 300 Beach Road The Concourse #12-03/04 Singapore 199555 | Branch: Blk 184 Toa Payoh Central #02-354 Singapore 310184

t +65 6817 7498 | f +65 6292 2665 | e natalie_ng@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

On Mon, 11 Feb 2019 at 08:56, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Save as to costs

Dear Natalie,

We will appoint LKK.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Natalie Ng [mailto:natalie_ng@rssolomon.com]

Sent: Monday, 11 February, 2019 8:41 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: pearlyn_goh@rssolomon.com

Subject: Re: OUR REF: SNM19D200589C02 / PRE REPAIR SURVEY ACCIDENT INVOLVING SLE9849R & GBF3581P ON 31.1.19

Dear Mr Chong,

We thank you for your email of 8th February 2019.

Please be informed that our client will be engaging his independent surveyors.

In this respect, please arrange your Surveyors to contact Mr Gary of Power Autocare at mobile no. 81812212 for a pre-repair survey of our client's vehicle located at 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883.

Thank you and Best Regards,

Natalie Ng | Office Manager 人事与行政经理



R. S. SOLOMON LLC
ATTORNEYS & SOLICITORS

R. S. Solomon LLC | 正氣律師事務所

Head Office: 300 Beach Road The Concourse #12-03/04 Singapore 199555 | **Branch:** Blk 184 Toa Payoh Central #02-354 Singapore 310184

t +65 6817 7498 | f +65 6292 2665 | e natalie_ng@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

On Fri, 8 Feb 2019 at 17:36, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5331A
Vehicle Details	
Vehicle No.:	SLE9849R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B4033213
Chassis No.:	RU11113207
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,054.00
Original Registration Date:	22 Sep 2016
First Registration Date:	22 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$10,076.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2026
PARF Rebate Amount:	\$7,557.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$39,187.00
Total Rebate Amount:	\$46,744.00

The information contained herein is correct as at 12 Feb 2019

OK

MVA319015241 / VAC - Kaki Bukit
 ENTRY DATE & TIME: 01/02/2019 11:21
 SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/02/2019 11:21
Date Of Accident	31/01/2019 16:50
Exact Location Of Accident	ALONG JALAN DEMAK & JLN PERGAM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE9849R
Insured/Policyholder	
Name Of Registered Owner	TANG PEE ENG
NRIC No	S1545331A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98524582
Alternative Phone No	Others-98524582
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084297151-02
Cover Note Number	
Driver	
Name of Driver	TANG PEE ENG
NRIC No	S1545331A
Date Of Birth	02/06/1962
Occupation	INDOOR
Date Of Driving Pass	24/02/1981
Driving Experience	37 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98524582

Fax Number	
Contact Number	OTHERS-98524582
EMail Address	NOEMAIL
Address	BLK 107 #09-359 TAMPINES ST 11
Postcode	521107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : TANG BEE LENG Gender: : Female
Passenger 2	Name: : TAY HONG MUI Gender: : Female
Passenger 3	Name: : TAN TIN MOY Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION, WHILE I WAS THE MIDST OF TRAVELLING STRAIGHT ON MY LANE. SUDDENLY VEHICLE B DRIVE OUT FROM THE SMALL ROAD AND THUS COLLIDED ONTO MY VEHILCE FRONT RIGHT HAND SIDE.WHICH RESULTED TO SUSTAIN DAMAGE. AFTER THE INCIDENT, THE SAID DRIVER SIGN A LETTER AND ADMIT HIS MISTAKE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3581P
-----------------------------	----------

5/28/2019

E-FILE

Vehicle Make/Model/Colour	TOYOTA HIACE MANUAL
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LOW KAH WAI
NRIC/Passport Number	S9518866D
Contact Number	96560096/91470053
Address	246 KIM KEAT LINK #06-23
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 2019 FEB 01 10:20 AM

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


01 FEB 2019

IDAC KAKI BUKIT (VAC)

Reporting **23 Kaki Bukit Ave 4**
 Name: **Singapore 415933**
 TEL: **67416697** Fax: **67492305**
 Email: **vgckb@singnet.com.sg**

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Reter
e-file

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature of Policyholder
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time:

01 FEB 2010

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4

Reporting Centre
Singapore 415933
Name:
Tel: 67416697 Fax: 67492305
NRIC/ID No:
Email: vackb@singnet.com.sg

Accident Sketch Plan

31 January 2019

~~#03~~ 1650

Low Kah Wai

S95188660

96560096

Kim Kert Link BIK246

#06-23

Crown Buddy

91470053

Frankie

I was driving my van along jln denak & jln persam, ~~was~~ unable to brake in time, I crashed into a silver vezel (SLE9849R).

Settle by 1720



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 17:41 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	+, Co. Reg. No.: -								
Main Claimant:	TANG PEE ENG , ID: S1545331A								
Vehicle Reg. No.:	SLE9849R	Date of Loss:	31/01/2019 16:00 - :59 [28 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200589C02	Policy/Cover Note No.:	DMCVSN19047119000						
Vehicle Reg. No. (Insured):	GBF3581P	Policy No. (Claimant):	5084297151-02						
		Excess:	S\$0.00						
Repairer:	Power Autocare (HQ) 1 Kaki Bukit Ave 6, #02-11 Kai Bukit @ Autobay, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/05/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE9849R (SNM19D200589C02)
[GBF3581P]
TP
TANG PEE ENG
Jan 31 2019 4:00PM
[-]
Power Autocare

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print					
1	01/02/19 11:42	Accident Statement	1	Load HTML						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print					
1	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
2	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
3	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
4	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
5	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
6	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
7	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
8	01/02/19 11:34	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
2	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
3	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
4	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
5	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
6	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
7	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
8	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
9	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
10	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
11	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
12	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
13	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
14	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
15	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
16	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
17	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
18	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
19	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
20	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
21	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					
22	28/05/19 11:06	General View	1	Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
23	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/05/19 11:06	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/05/19 11:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
73	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	28/05/19 11:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/05/19 17:42	pri contact	 Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	01/02/19 11:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	01/02/19 11:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	01/02/19 11:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	01/02/19 11:42	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	01/02/19 11:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	01/02/19 11:42	Accident Sketch Plan	 Load TIF	
2	01/02/19 11:42	Accident Sketch Plan	 Load TIF	
3	01/02/19 11:42	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19002395/UCD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN19047119000	
Claimant Vehicle No: SLE9849R	Insured Vehicle No: GBF3581P	
Date of Loss: 31/01/2019	Nature of Claim: TP	Claim No: SNM19D200589C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE9849R		Engine No: L15B4033213
Make & Model: HONDA VEZEL, 1.5 (A)		Chassis No: RU11113207
Reg. Date: 22/09/2016 (Man. Year: 2015)		Odometer: 43948 km
Colour: Silver		
Engine Capacity: 1496 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	22/05/2019	
Date Inspected:	12/02/2019 Inspected At:	Power Autocare (HQ) 1 Kaki Bukit Ave 6, #02-11 Kai Bukit @ Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE9849R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages. running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >