

ASS. REC. BY:

REF:

083/AIG/19002400/Ecd302

Special Instruction:

Survivor
Mentor

Steve

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

11/2/19 @ 10.56am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 9094P

Insured:

SKW 658EE

at Workshop m/s

Prestige Auto

Tel:

90210057

of

191 Tanjong Katong Road

Policy No:

0999994378

Claim No:

0884270387SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/01/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 1:48pm @ 11/2/2019

Person Contacted:

Mr. Chong

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SME 9094P - X
	SKW 658EE - X
	After repair: 27/3/2019

1081/1124

Surveyor: SteveREF: AIG

PRS

ASSIGNMENT

From:

Date:

2013/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 9094P

at Workshop m/s

Prestige Auto

of

3023A Ubi Rd 1 #01-64

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SME 9094P

Yr Regn:

Nov / 09Type: M:Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

C.C

1591

Colour

Beige

A/C:

Insured / Std / NI / NA

Sp.Reading

88922

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH0U4IBMAU 910926

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/1/19

D.O.I.

20/3/19

Survey held at

Prestige Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/3/19surveyor went on 19/3/19 - But there's no one there.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

180

Transportation:

S + RS, \$

Photos

Others

10

TOTAL

190

Report Format :

PRG

Lump Sum / I.B.I.: (\$

Your password will expire in 1 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 11/2/2019 10:56:55 AM
Attachments:  190177.pdf  SKW6588E.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS

翠 NOTARY PUBLIC-公证官

玲 COMMISSIONER FOR OATHS-宣誓官

律

師 CATHERINE C. LIM

館 DIRECTOR

LL.B (HONS) SINGAPORE-法律系-律師

M.B.A. (BUSINESS LAW)-商業系-碩士

20 Havelock Road #03-01

Central Square Singapore 059765

UEN No. 201310922K

Tel: (65) 6438 5500

Fax: (65) 6438 0111

www.catherinelimllc.com

Email: info@catherinelimllc.com

CATHERINE LIM LLC is a law corporation

with limited liability

Your Ref: SKW 6588E

Our Ref: CI/190177/T/PA.sg

29 January 2019

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way

#07-16

Singapore 079120

Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Aph Trading Pte Ltd

210 Turf Club Road

#LO-A25 The Grandstand

Singapore 287995

CERTIFICATE OF POSTING

(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)****ACCIDENT INVOLVING SME 9094P / SKW 6588E ON 28.01.2019 ALONG QUEEN STREET**We are instructed by **PLANNING FACTS** to notify you of a road traffic accident involving our client's vehicle No. SME 9094P and vehicle No. SKW 6588E driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue:

Prestige Auto

191 Tanjong Katong Road

Singapore 436993

Chong Hoi:

9021 0057

Fax: 6842 3217

Yours faithfully



Catherine Lim

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9734D
Vehicle Details	
Vehicle No.:	SME9094P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	G4FC9U754901
Chassis No.:	KMH DU41BMAU910926
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,406.00
Original Registration Date:	25 Nov 2009
First Registration Date:	25 Nov 2009
Transfer Count:	2
Actual ARF Paid:	\$11,406.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2019
PARF Rebate Amount:	\$5,703.00
Intended COE Rebate Details	
COE Expiry Date:	24 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$2,651.00
COE Rebate Amount:	\$1,160.00
Total Rebate Amount:	\$6,863.00

The information contained herein is correct as at 21 Mar 2019

OK

MVA319013625 / VAC - Field Unit
 ENTRY DATE & TIME: 29/01/2019 09:22
 SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 29/01/2019 09:22
 Date Of Accident 28/01/2019 21:55
 Exact Location Of Accident QUEEN STREET
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME9094P
 Name Of Registered Owner PLANNING FACTS
 Co Reg No 53369734D
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-92288478

Manufacturer HYUNDAI
 Model AVANTE 1.6 AT ABS D/AB 2WD 4DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy NO
 Policy Number 5105489562
 Cover Note Number

Name of Driver HOO TECK YONG (HE DERONG)
 NRIC No S7110210F
 Date Of Birth 30/03/1971
 Occupation OUTDOOR
 Date Of Driving Pass 02/05/1997
 Driving Experience 21 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-83582424
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 176 BISHAN STREET 13 #
 Postcode 570176
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION, WHILE IN THE MIDST OF TRAVELLING ON MY LANE, VEHICLE B (SKW6588E) WHICH IS DRIVING OUT FROM THE SMALL ROAD, DROVE OUT AND THUS COLLIDED ONTO MY VEHICLE FRONT RIGHT HAND SIDE, WHICH RESULTED TO SUSTAIN DAMAGED.

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH DRIVER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKW6588E
 Vehicle Make/Model/Colour PEUGEOT 3008 1.6 E-HDI ETG ACTIVE SUV
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that exist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



29 JAN 2018


Policyholder's Signature
Date & Time: 29 JAN 2018
2:00 PM
2:00 PM
2:00 PM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting: 29 JAN 2018
Name: Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yock@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer e-fb

DECLARATION

I/We declare the foregoing particulars are true in every respect.

I am a valid holder of
 a valid driving licence

Policyholder's Signature: [Signature]

Date & Time: [Signature]



Driver's Signature: [Signature]
 (if driver is not the policyholder)
 Date & Time: [Signature]

29 JAN 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415993

Tel: 67416697 Fax: 67492305

Email: yacka@singnet.com.sg

MOTOR CAR (Pri)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990039	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991711	Front Exhaust Pipe			
1067	990719	Battery			
1068	990754	Battery Cover			

From RM Dm

R

Vehicle No.

SME 9094P

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991384	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992093	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992382	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994433	Steering Wheel Airbag			
1128	994455	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991299	Frt Passenger Seat			
1135	995432	Frt LH Seat Belt Assy			
1136	990247	Sucker			

DD

NLC

2/3/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2019 Edit Reg		11 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	APOH TRADING PTE LTD , Co. Reg. No.: 201427205M								
Main Claimant:	PLANNING FACTS , Co. Reg. No.: 53369734D								
Vehicle Reg. No.:	SME9094P	Date of Loss:	28/01/2019 22:00 - :59 [110 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0884270387SG	Policy/Cover Note No.:	0999994378 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKW6588E	Policy No. (Claimant):							
		Excess:							
Repairer:	Prestige Auto () 191 Tanjong Katong Road, 436993 Katong - Tel: 90210057/62574781								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 20/02/2019]								
Claimant's Solicitor:	CATHERINE LIM LLC - Tel: 6438 5500								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
- AIG_SG (13/02/2019): Request to upload TP GIA Report - AIG_SG (12/02/2019): No OI GIA Report									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME9094P (0884270387SG)
[SKW6588E]
TP
PLANNING FACTS
Jan 28 2019 10:00PM
[APOH TRADING PTE LTD]
Prestige Auto

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images										3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	28/03/19 14:33	General View								 Load JPG	☒		
2	28/03/19 14:33	General View								 Load JPG	☒		
3	28/03/19 14:33	General View								 Load JPG	☒		
4	28/03/19 14:33	General View								 Load JPG	☒		
5	28/03/19 14:33	General View								 Load JPG	☒		
6	28/03/19 14:33	General View								 Load JPG	☒		
7	28/03/19 14:33	General View								 Load JPG	☒		
8	28/03/19 14:33	General View								 Load JPG	☒		
9	28/03/19 14:33	General View								 Load JPG	☒		
10	28/03/19 14:33	General View								 Load JPG	☒		
11	28/03/19 14:33	General View								 Load JPG	☒		
12	28/03/19 14:33	General View								 Load JPG	☒		
13	28/03/19 14:33	General View								 Load JPG	☒		
14	28/03/19 14:33	General View								 Load JPG	☒		
15	28/03/19 14:33	General View								 Load JPG	☒		
16	28/03/19 14:33	General View								 Load JPG	☒		
17	28/03/19 14:33	General View								 Load JPG	☒		
18	28/03/19 14:33	General View								 Load JPG	☒		
19	28/03/19 14:33	General View								 Load JPG	☒		
20	28/03/19 14:33	General View								 Load JPG	☒		
21	28/03/19 14:33	General View								 Load JPG	☒		
22	28/03/19 14:33	General View								 Load JPG	☒		
23	28/03/19 14:33	General View								 Load JPG	☒		
24	28/03/19 14:33	General View								 Load JPG	☒		
25	28/03/19 14:33	General View								 Load JPG	☒		
26	28/03/19 14:33	General View								 Load JPG	☒		
27	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
28	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
29	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
30	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
31	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
32	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
33	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
34	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
35	28/03/19 14:36	Photo After Spray								 Load JPG	☒		
Documentation										1 per page		☒	

Photos/Images			3 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	13/02/19 13:43	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
^ v
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19002400/ECD3E2

Date: 29/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994378
Claimant Vehicle No : SME9094P **Insured Vehicle No :** SKW6588E
 Date of Loss: 28/01/2019 Nature of Claim: TP Claim No: 0884270387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME9094P**
 Make & Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A) Engine No: G4FC9U754901
 Reg. Date: 25/11/2009 (Man. Year: 2009) Chassis No: KMHDU41BMAU910926
 Colour: Beige Odometer: 88922 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/02/2019
 Date Inspected: 20/03/2019 Inspected At: Prestige Auto
 191 Tanjong Katong Road
 Singapore 436993
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH FENDER	Dented	0.00 F	*- F
2	1		*FRT RH FENDER BADGE	Necessary	0.00 F	*- F
3	1		*FRONT RH DOOR	Repair	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >