

N8/INC19002410 / Nvd302

REF:

Inc

JM

Surveyor: NAZ

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLL 8181C

Policy No. 5085597481-02 (8/11/18 - 7/11/19)

Claims No. MT/1030932-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S		
X	X	Y	

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Estl. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 1958U Yr Regn: 3 OCT 2017

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA PRIUS HYBRID c.c. 1798

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 110,997 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU703565066

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/RIm / STD / R/Im or _____

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OITSU / PIR / SUMI /

TOYO / YOKO or DANANTI (F), WESTLAK (R)

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 4/2/19 U.O.I. 8/2/19

Survey held at CDGE LOYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

INC 979

Date / Time Action / Instruction

SHC1958U-cc3/AIG18011720/Klwa392

DVA: 28/6/2018

SLL 8181C - X

20/2/19 FINALIZED PART BY PART REPAIR \$2244.29 / 3 DAYS

(Red 6300.54, 747)

RECEIVED 22 FEB 2019

Date/Time, File Pass to?

: Prelim Report
 : Final Report

1)

Date/Time, File Return to?

2) 21/2 - typist

Report Format: TP

Lump Sum / I.B.I. (\$) 2244.29

Days Of Repair: 3

Resurvey No. of Trip: 1

*Survey Fee: 160

Transportation: _____

Add Fee: : Site Insp (\$ _____) S + RS _____ SI

: Interview (\$ _____) Photos _____

: Tech. Invo (\$ _____) Others _____

: Weekend (\$ _____) TOTAL 160

TP Claims against NTUC Income: Follow-Through Survey

21/2/2019

S/NC	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Estimate	Tentative repair cost
1	MT/1030932-002	COMFORT TRANSPORTATION PTE LTD	SHC 1958U	SLL 8181C	4/2/2019	\$8,566.83	\$2,244.29
2	MT/1031940-002	COMFORT TRANSPORTATION PTE LTD	SHA 3694C	SJL 3650Y	5/2/2019	\$1,785.68	\$900.00
3	MT/1033052-001	COMFORT TRANSPORTATION PTE LTD	SHA 3749D	GBH 6126R	15/2/2019	\$850.00	\$350.00
4	MT/1033055-001	COMFORT TRANSPORTATION PTE LTD	SHD 3199A	SLF 3432T	14/2/2019	\$2,399.06	\$1,200.00
5	MT/1031629-002	COMFORT TRANSPORTATION PTE LTD	SH 8548S	SJJ 8434H	12/2/2019	\$6,822.16	\$2,750.00
6	MT/1031383-002	COMFORT TRANSPORTATION PTE LTD	SHD 3198C	SJU 9736Y	9/2/2019	\$1,829.12	\$550.00
7	MT/1032845-002	COMFORT TRANSPORTATION PTE LTD	SHD 4145Z	SMA 1458Y	18/2/2019	\$2,574.90	\$1,000.00
8	MT/1033061-001	COMFORT TRANSPORTATION PTE LTD	SH 9493J	SJS 8276A	15/2/2019	\$5,712.08	\$2,750.00

Claim received from LKK Auto

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5085597481-02		HOON QIYUAN (HONG QIYUAN)	S8141264B	GPC	drivo CLASSIC	SLL8181C	SLL8181C	08/11/2018	07/11/2019

Continue

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHC1958U
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZRS066344
Chassis No.:	JTDKB3FU703565066
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	03 Oct 2017
First Registration Date:	03 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Oct 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$28,257.00
Total Rebate Amount:	\$32,007.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2019 13:40
Date Of Accident	04/02/2019 14:20
Exact Location Of Accident	RIVERVALE DRIVE TWDS SENGKANG E WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1958U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	WONG CHEE WAI
NRIC No	S7626622J
Date Of Birth	01/09/1976
Occupation	OUTDOOR
Date Of Driving Pass	22/09/2006
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88680741
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 183D RIVERVALE CRESCENT #13-225
Postcode	544183
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL8181C
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HOON QIYUAN
NRIC/Passport Number	S8141264B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 07.02.2019@1145HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04.02.2019 I was travelling along Rivervale Drive twds Sengkang East Way
with no passenger onboard.
As I was wanting to proceed straight suddenly Veh (B) SLL 8181C hit onto my
vehicle rear portion.
left.
As the accident took place too fast I could not take evasive action to prevent the accident.
I have company video and photos at scene to support my claims .
No injury in this accident .
Veh(B) SLL 8181C MR Hoon Qiyuan S 8141264B

DECLARATION



I/We declare the foregoing particulars are true in every respect.
 PORT TRANSPORTATION PTE LTD
 REG. NO. 199303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 07.02.2019@1145HRS

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Willa J. 7/2



Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305266377


DMER
 S COMFORT TRANSPORTATION PTE LTD
 DMER NO. 7010045
 ESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 (R) 65508755 (C)
 (P)
 IDENT CARD NO.

REGN NO.: SHC1958U	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4)	DATE/TIME IN 04.02.2019 14:20
YR OF MANU. 03.10.2017	TARGET DATE
CHASSIS CODE JTKDK3FU703565066	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 04.02.2019
 NATURE: 3P 04.02.19 -

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



REMOVED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

No.: **SHC1958U**

JU NTUC LKK

Vehicle No.:

SHC1958U

Signature/Date


Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard



REPAIR ESTIMATE

VEHICLE NO : SHC 1958U

8/2/2019 11:20

MAKE :

MODEL : TOYOTA PRIUS

Handwritten notes:
 NUL 7U
 P.P.

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER			\$ 1,126.60
REAR TRUNK LID LOCK			\$ 457.90
REAR TRUNK LID GLASS (BLACK COLOR)			\$ 733.50
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$ 889.70
REAR TRUNK LID LOGO(PRIUS)			\$ 52.90
REAR TRUNK LID LOGO(HYBRID)			\$ 52.90
REAR TRUNK LID LOGO(TOYOTA STAR)			\$ 47.00
REAR BUMPER			\$ 458.60
REAR BUMPER RE-INFORCEMENT			\$ 318.80
REAR BUMPER UNDER COVER			\$ 552.60
REAR BUMPER SIDE RETAINER			\$ 112.70
REAR BUMPER UNDER SIDE COVER (LH)			\$ 232.00
REAR BUMPER TOWING COVER			\$ 82.70
REAR BUMPER CLIPS			\$ 22.00
RETAINER, REAR BUMPER, SIDE, LH			\$ 94.80
SEAL, REAR BUMPER SIDE, LH			\$ 148.40
TAIL LAMP ASSY (LOWER) (LH)			\$ 548.40
REAR END PANEL			\$ 602.10
REAR END PANEL GARNISH			\$ 121.60
REAR WINDSCREEN GLASS WITH MOULDING			\$ 1,778.30
SUB TOTAL			\$ 8,433.50
LESS 25% DISCOUNTED TOTAL			\$ 6,325.13
REAR NO. PLATE WITH TRIM COVER			\$ 100.00
REAR TRUNK LID APPS STICKER			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STCIKER			\$ 60.00
REAR BUMPER REVERSE SENSOR			\$ 135.70
REAR WINDSCREEN SEALANT			\$ 46.00
LABOUR CHARGE			\$ 381.70
Panel Beating			\$ 800.00
Spray Painting Charge			\$ 900.00
Wiring Charge			\$ 30.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor			\$ 80.00
TOTAL LABOUR			\$ 1,860.00
ESTIMATE TOTAL			\$ 8,566.83

LKK APPROVAL
 the Repairer must provide the following information to the motor surveyor:
 • To complete the repair estimate
 • To conduct a motor survey
 • Parts prices are subject to motor survey
 • The estimate is issued on a "Without Prejudice" basis
 • All work must be approved
 • Subject to motor survey must be resurveyed and is subject to final approval from Insurance Company
 Approved by Repairer
 Signature:
 Date:

Handwritten signature and date:
 [Signature]
 12/2/19

Handwritten notes:
 BEFORE PAINT PHOTOS
 CHECK ITEMS PHOTOS

Handwritten notes:
 NA 2 LKIC
 8/2/19 1550
 P/P
 350ms-

Handwritten notes in right margin:
 XSVL
 XSVL
 XSVL
 XR
 /NE
 /NE
 /NE
 ?/CK
 /BT
 /DE
 XSVL
 ?XSV
 ?XSV
 /NE
 XSVL
 ?XSV
 ?XSV
 ?XSV
 XNN

Handwritten notes in right margin:
 XNN
 /NE
 /NE
 /not work
 XNN
 400
 400
 XNN
 /
 30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No 305266377
Date : 12/02/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : NAZ
: SHC1958U Date of Accident : 04/02/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- SLL8181C
###
- The finalized amount shall be:

(a) Spare Parts after List discount		<u>\$1,364.29</u>
(b) Labour Charges	###	<u>\$880.00</u>
Total for Part-By-Part Repair Cost		<u>\$2,244.29</u>
N		
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: <u>20%</u>		<u> </u>
Final Lumpsum Repair cost		<u> </u>
- Estimated normal period for repairs: 3 working days
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 2012/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 11.02.2019
Time: 18:21:18
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305266377
REGN NO : SHC1958U
MILEAGE : 000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 03.10.2017
DATE/TIME IN : 04.02.2019 14:20
ACCIDENT DATE : 04.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	47.00	25.00	35.25	/
0002	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67	/
0003	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67	/
0004	28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1 N	30.00	2.50-	30.00	/
0005	28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1 N	40.00	0.25	40.00	/
0006	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1 N	30.00	0.03-	30.00	/
0007	04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50	/
0008	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95	/
0009	09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1 N	135.70	2.50-	135.70	/
0010	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45	/
0011	04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10	/

SUB-TOTAL : 1,364.29

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.02.2019

REPAIR ESTIMATE

Time: 18:21:18

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305266377
REGN NO : SHC1958U
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 03.10.2017
DATE/TIME IN : 04.02.2019 14:20
ACCIDENT DATE : 04.02.2019

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 L PANEL BEATING- REAR	400.00				400.00
0001 23-502 SPRAYPAINT ON AFFECTED AREA	400.00				400.00
0002 20-00 TUFF COAT ON AFFECTED PARTS.	50.00				50.00
0003 L REMOVE/REFIX REVERSE SENSOR	30.00				30.00
					SUB-TOTAL : 880.00
					TOTAL : 2,244.29

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO

Veron Chen (LKKAuto)

From: Naz (LKKAuto)
Sent: Wednesday, 20 February 2019 10:46 AM
To: Jumani Bin Masudin
Cc: Veron Chen (LKKAuto); SUR
Subject: SHC 1958U FINALIZATION
Attachments: FINALIZED.pdf

Dear Mr Jumarni,

Finalized Part by Part Repair \$\$2244.29 / 3 Days.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19002410/Nvd3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 22-02-2019	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLL 8181C	Veh. Inspected	SHC 1958U
Policy No.	5085597481-02	Coverage (\$)	0.00
Claim No.	MT/1030932-002	Excess (\$)	0.00
Assign From		Assign Date	08/02/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703565066	Colour	BLUE
Odometer	110997	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/02/2019	Inspection Date	08/02/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1958U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TRUNK LID COVER	SERVICEABLE	1,126.60	-
1	REAR TRUNK LID LOCK	SERVICEABLE	457.90	-
1	REAR TRUNK LID GLASS (BLACK COLOR)	SERVICEABLE	733.50	-
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	TO REPAIR SEE LABOUR	889.70	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	47.00	47.00
1	REAR BUMPER	CRACKED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER UNDER SIDE COVER (LH)	SERVICEABLE	232.00	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	82.70	-
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	RETAINER, REAR BUMPER, SIDE , LH	SERVICEABLE	94.80	-
1	SEAL, REAR BUMPER SIDE, LH	SERVICEABLE	148.40	-
1	TAIL LAMP ASSY (LOWER) (LH)	SERVICEABLE	548.40	-
1	REAR END PANEL	SERVICEABLE	602.10	-
1	REAR END PANEL GARNISH	SERVICEABLE	121.60	-
1	REAR WINDSCREEN GLASS WITH MOULDING	NOT NECESSARY	1,778.30	-
	LESS 25% DISCOUNT		-2,108.37	-376.21
			6,325.13	1,128.59
SPECIAL NETT ITEMS				
1	REAR NO. PLATE WITH TRIM COVER (SN)	NOT NECESSARY	100.00	-
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			381.70	235.70

Report Ref No. NS/INC19002410/Nvd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF GARNISH SUB-ASSY, BACK DOOR, OUTSIDE.		800.00	400.00
	SPRAY PAINTING CHARGE.		900.00	400.00
	WIRING CHARGE.	NOT NECESSARY	30.00	-
	TUFF KOTE.		50.00	50.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			1,860.00	880.00
	GRAND TOTAL		8,566.83	2,244.29
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,244.29

Report Ref No. NS/INC19002410/Nvd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.