

Claim received from LKK Auto

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)**Policy Query**

| | | | |
|---------------------------------------|--------------------------------------|--------------------|---|
| Policy No. | <input type="text"/> | Date of Accident | <input type="text" value="08/02/2019 17:19"/> |
| Vehicle No.(For Motor) | <input type="text" value="PA7310P"/> | Certificate Number | <input type="text"/> |
| <input type="button" value="Search"/> | | | |

| Select | Policy No. | Certificate Number | Policyholder Name | Policyholder NRIC | Product | Cover Type | Vehicle No. | Insured Object | Commence Date | Expiry Date |
|-----------------------|---------------|--------------------|--|-------------------|---------|------------------------------|-------------|----------------|---------------|-------------|
| <input type="radio"/> | 5066996197-04 | | EML TRANSPORT SERVICE PTE. LTD. | 201003462H | GFT | Third Party, Fire & Theft | PA7310P | PA7310P | 13/08/2018 | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------------|
| Date Of Report | 08/02/2019 13:42 |
| Date Of Accident | 08/02/2019 07:00 |
| Exact Location Of Accident | ALONG KHATIB MRT TAXI STAND |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------------------|
| Vehicle Registration Number | SHD3739S |
| Insured/Policyholder | |
| Name Of Registered Owner | COMFORT TRANSPORTATION PTE LTD |
| Co Reg No | 199303821R |
| Email Address | FLEETSAFETY@CDGTAXI.COM.SG |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-65508768 |

Vehicle Particulars

| | |
|--------------|--------------|
| Manufacturer | HYUNDAI |
| Model | IONIQ HYBRID |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

| | |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | YES |
| Policy Number | D-18088936MFSH |
| Cover Note Number | |

Driver

| | |
|----------------------|---------------------------|
| Name of Driver | LEONG CHIANG NANG |
| NRIC No | S1059319J |
| Date Of Birth | 23/12/1949 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 03/08/1970 |
| Driving Experience | 48 YEARS AND 6 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98716063 |
| Fax Number | |
| Contact Number | |
| Email Address | MIKEANNA2309@YAHOO.COM.SG |

| | |
|---|--|
| Address | BLK 158 LORONG 1 TOA PAYOH #09-1504 |
| Postcode | 310158 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - TAXI DRIVER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| Insurance Company of Driver's Own Vehicle | - |

General Information of the Accident

| | |
|--------------------|------------|
| Type Of Accident | SIDE SWIPE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-------------------------------|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 2 |
| Passenger 1 | NAME: : - GENDER: : FEMALE |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident


REFER ATTACHED

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | - |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-------------|
| Vehicle Registration Number | PA7310P |
| Vehicle Make/Model/Colour | PRIVATE BUS |
| Details Of Properties | |
| Vehicle Category | BUS |
| Name of Driver | GAO QIANG |
| NRIC/Passport Number | G8358586U |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |



Nature Of Damage

RH FRONT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 109303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Wendy
NRIC/FIN No.: 08 FEB 2019

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

| |
|--|
| On 08.02.2019 I was travelling along Khatib MRT Taxi Stand with one female passenger onboard. |
| As I was travelling straight and suddenly Veh(B) PA 7310P cut into my lane and hit my left rear portion of my vehicle. |
| As the accident took place too fast I could not take evasive action to prevent the accident. |
| I have company video and photos at scene to support my claims . |
| No injury in this accident. |
| Veh(B) PA 7310P MR Gao Qiang G 8358586U |
| |
| |
| |
| |
| |
| |
| |
| |
| |

DECLARATION

I/We declare the foregoing particulars are true in every respect

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 08.01.2019@0900HRS

Reporting Centre Personnel's Signature

Name: 08 FEB 2019

NRIC/FIN No.: June Tan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

| | |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID: | 3821R |

Vehicle Details

| | |
|-------------------------------|----------------------|
| Vehicle No.: | SHD37395 |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 12 Feb 2019 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | AE IONIQ HEV 1.6 DCT |
| Primary Colour: | Blue |
| Manufacturing Year: | 2018 |
| Engine No.: | G4LEJU081794 |
| Chassis No.: | KMHC851CVKU107568 |
| Maximum Power Output: | 103.6 kW (138 bhp) |
| Open Market Value: | \$24,883.00 |
| Original Registration Date: | 13 Sep 2018 |
| First Registration Date: | 13 Sep 2018 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$11,837.00 |

Intended PARF Rebate Details

| | |
|-------------------------------|-------------|
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 12 Sep 2026 |
| PARF Rebate Amount: | \$8,877.00 |

Intended COE Rebate Details





| | |
|-----------------------------|--------------------------------------|
| COE Expiry Date: | 12 Sep 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$25,872.00 |
| COE Rebate Amount: | \$24,524.00 |
| Total Rebate Amount: | \$33,401.00 |

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Feb 2019

OK



Date/Time: 08.02.2019 14:29

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305266552

OWNER

IS COMFORT TRANSPORTATION PTE LTD

OWNER NO. 7010045

RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(P)

QUINT CARD NO.

REGN NO.:

SHD3739S

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN

08.02.2019 07:50

YR OF MANU

13.09.2018

TARGET DATE

CHASSIS CODE

KMHC851CVKU107568

COMPLETION DATE/TIME


JOB DESCRIPTION

Accident Date: 08.02.2019

NATURE: 3P 08.02.2019/C

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

No.: SHD3739S

LKE

Exit Pass

Vehicle No.:

SHD3739S

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3739S

DATE 8/2/2019 14:58

MAKE :

MODEL : HYUNDAI IONIQ

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|---|------|------------|--------------------|
| | Rear Bumper | | | \$ 459.40 |
| | Rear Bumper Side Bracket (LH) | | | \$ 33.10 |
| | Rear Bumper Cover Clips | | | \$ 22.00 |
| | Rear Fender (LH) | | | \$ 1,768.30 |
| | Rear Fender Inner Lining (LH) | | | \$ 73.60 |
| | Rear Windscreen Moulding | | | \$ 28.20 |
| | Fuel Lid Cover | | | \$ 83.30 |
| | Rear Door (LH) | | | \$ 1,789.90 |
| | Rear Wheel Hub-Cap (LH) | | | \$ 134.10 |
| | SUB TOTAL | | | \$ 4,391.90 |
| | LESS 20% | | | \$ 878.38 |
| | DISCOUNTED TOTAL | | | \$ 3,513.52 |
| | Rear Bumper Advertisement Logo | | | \$ 50.00 |
| | Rear Bumper Rubber Mat | | | \$ 50.00 |
| | Rear Windscreen Sealant | | | \$ 46.00 |
| | Rear Door Comfortdelgro & Apps Sticker (LH) | | | \$ 80.00 |
| | | | | \$ 226.00 |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 800.00 |
| | Spray Painting Charge | | | \$ 900.00 |
| | Wiring Charge | | | \$ 30.00 |
| | Tuff Kote | | | \$ 50.00 |
| | Remove/Refix Reverse Sensor | | | \$ 120.00 |
| | Transfer of Door | | | \$ 120.00 |
| | Rear Wheel Alignment | | | \$ 120.00 |
| | TOTAL LABOUR | | | \$ 2,140.00 |
| | ESTIMATE TOTAL | | | \$ 5,879.52 |
| | | | | 5889.52 |

LKK Auto Consultants, hence notify the Repaired of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No cash refund is allowed
- Supplementary charges must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NA2 LKK
8/2/19 1535
P/P
4 DAYS
BEFORE PAINT PHOTOS

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305266552
Date : 25.02.2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHD3739S

Date of Accident : 08.02.2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- PA 7310P
2. The finalized amount shall be:

| | | |
|---|-----|-------------------|
| (a) Spare Parts after List discount | | \$3,506.48 |
| (b) Labour Charges | | \$1,410.00 |
| Total for Part-By-Part Repair Cost | | \$4,916.48 |
| | | |
| (c.) Lumpsum Repair (if applicable) | | |
| Total for Lumpsum repair cost after Less: | 20% | \$0.00 |
| Final Lumpsum Repair cost | | \$0.00 |

3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148355

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 28/2/19

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|---|--------|--------------------------------|---------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | N | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | 7.49 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

REPAIR ESTIMATE*

DATE 8/2/2019 14:58

MAKE :

MODEL : HYUNDAI IONIQ

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|---|------|------------|-------------|
| | Rear Bumper | | / | \$ 459.40 |
| | Rear Bumper Side Bracket (LH) | | / | \$ 33.10 |
| | Rear Bumper Cover Clips | | NN X | \$ 22.00 |
| | Rear Fender (LH) | | / | \$ 1,768.30 |
| | Rear Fender Inner Lining (LH) | | SVC X | \$ 73.60 |
| | Rear Windscreen Moulding | | 28.30 / | \$ 28.20 |
| | Fuel Lid Cover | | SVC X | \$ 83.30 |
| | Rear Door (LH) | | / | \$ 1,789.90 |
| | Rear Wheel Hup-Cap (LH) | | / | \$ 134.10 |
| | SUB TOTAL | | 4213.1 | \$ 4,391.90 |
| | LESS 20% | | | \$ 878.38 |
| | DISCOUNTED TOTAL | | 3370.48 | \$ 3,513.52 |
| | | | | |
| | Rear Bumper Advertisement Logo | | NN X | \$ 50.00 |
| | Rear Bumper Rubber Mat | | / | \$ 50.00 |
| | Rear Windscreen Sealant | | / | \$ 46.00 |
| | Rear Door Comfortdelgro & Apps Sticker (LH) | | / | \$ 80.00 |
| | S Fuel Tank Lid (Petrol Only) sticker | nee | / | \$ 10.00 |
| | | | | \$ 226.00 |
| | | | | |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 800.00 |
| | Spray Painting Charge | | | \$ 900.00 |
| | Wiring Charge | | | \$ 30.00 |
| | Tuff Kote | | | \$ 50.00 |
| | Remove/Refix Reverse Sensor | | | \$ 120.00 |
| | Transfer of Door | | | \$ 120.00 |
| | Rear Wheel Alignment | | | \$ 120.00 |
| | | | | |
| | NA2 LKK | | | |
| | 8/2/19 1535 | | | |
| | P/P | | | |
| | 4 DAYS + 1 PM | | | |
| | Before Paint Removal | | | |
| | TOTAL LABOUR | | | \$ 2,140.00 |
| | ESTIMATE TOTAL | | | \$ 5,879.52 |
| | | | | 5889.60 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

VEHICLE NO. : SHD3739S
MODEL IONIQ(G2)
JOB NO 305266552

TYPE OF CASE : TP-PA7310P
SURVEY BY : LKK/Nq3
DATE : 14/02/19

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.02.2019

Time: 12:36:10

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305266552
 REGN NO : SHD3739S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 08.02.2019 07:50
 ACCIDENT DATE : 08.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

| | | | | | | | |
|------|-------------------|---------------------------|-----|----------|-------|----------|---|
| 0001 | 04-01-0104-0576-G | IONIQVC PANEL ASSY-QUARTE | 1 L | 1,768.30 | 20.00 | 1,414.64 | / |
| 0002 | 03-01-0104-2061-G | IONIQV1/3 CAP ASSY-WHEEL | 1 L | 134.10 | 20.00 | 107.28 | / |
| 0003 | 04-01-0104-0596-G | IONIQ PANEL ASSY-REAR DOO | 1 L | 1,789.90 | 20.00 | 1,431.92 | / |
| 0004 | 28-01-0103-2013-A | I40V3 APP LOGO REAR DOOR | 1 N | 80.00 | 2.00- | 80.00 | / |
| 0005 | 04-01-0104-2282-G | IONIQVC COVER-RR BUMPER# | 1 L | 459.40 | 20.00 | 367.52 | / |
| 0006 | 04-01-0104-2531-G | IONIQVC BRACKET ASSY-RR B | 1 L | 33.10 | 20.00 | 26.48 | / |
| 0007 | 28-01-0302-2017-A | PRIVC FUEL TANK LID (PETR | 1 N | 10.00 | 2.00- | 10.00 | / |
| 0008 | 04-01-0104-2259-G | IONIQ WINDSCREEN MOULDING | 1 L | 28.30 | 20.00 | 22.64 | / |
| 0009 | 05-01-0199-0032-A | (ALL)WINDSCREEN AHESIVE-3 | 2 N | 46.00 | 2.00- | 46.00 | / |

SUB-TOTAL : 3,506.48

JOB NATURE

| | | | |
|--------|-----------------|--------|---|
| 0000 L | REAR BUMPER MAT | 50.00 | / |
| 0001 L | PANEL BEATING | 600.00 | |

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.02.2019

Time: 12:36:10

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305266552
REGN NO : SHD3739S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 13.09.2018
DATE/TIME IN : 08.02.2019 07:50
ACCIDENT DATE : 08.02.2019

| JOB / PARTS DESCRIPTION | | QTY | IND | UNIT-PRICE | DISC% | AMOUNT |
|-------------------------|---------------------------------------|--------|-----|------------|-------|----------|
| 0002 23-502 | SPRAYPAINT ON AFFECTED AREA | 600.00 | | | | |
| 0003 17-01 | CHECK ALL LIGHTING | 30.00 | | | | |
| 0004 20-00 | TUFF COAT ON AFFECTED PARTS. | 50.00 | | | | |
| 0005 20-22 | REMOVE/REFIX REVERSE SENSOR | 30.00 | | | | |
| 0006 20-02 | REMOVE/REFIX DOOR PARTS TO ASSIST REP | 50.00 | | | | |
| SUB-TOTAL : | | | | | | 1,410.00 |
| TOTAL : | | | | | | 4,916.48 |

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Veron Chen (LKKAuto)

From: Naz (LKKAuto)
Sent: Thursday, 28 February 2019 6:01 PM
To: Lim Kwok Eng
Cc: Fauzy Bin Mokhtar; Roger How Keen Meng; Tan Pei Wei; SUR; Veron Chen (LKKAuto)
Subject: Re: SHD 3739S FINALIZATION
Attachments: FINALIZED.pdf

Dear Mr Lim,

Finalized Part by Part Repair \$4916.48 / 5 Days subject to insurance approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Kwok Eng <limke@cde.com.sg>
Sent: Tuesday, 26 February 2019 7:43 PM
To: Naz (LKKAuto)
Cc: Fauzy Bin Mokhtar; Roger How Keen Meng; Tan Pei Wei
Subject: SHD3739S finalize

Dear Naz,

Pls refer attached, Photo before paint taken by Naz.

Best Regards

Lim Kwok Eng

Taxi Crash Repairs / ComfortDelgro Engineering Pte Ltd

Tel. 6214-8355 / 6214-8156

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



| | | | | |
|--|--|-----------------|--------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19002413/Nvd3s2 | | | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: 04-03-2019 |  |
| Code: INC4 | | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | PA 7310P | Veh. Inspected | SHD 3739S | |
| Policy No. | 5066996197-04 | Coverage (\$) | 0.00 | |
| Claim No. | MT/1031301-002 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 08/02/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI IONIQ | c.c | 1580 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | KMHC851CVKU107568 | Colour | BLUE | |
| Odometer | 56726 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65R15 | MICHELIN | 5 mm | |
| L/H Front Tyre | 195/65R15 | MICHELIN | 5 mm | |
| R/H Rear Tyre | 195/65R15 | MICHELIN | 5 mm | |
| L/H Rear Tyre | 195/65R15 | MICHELIN | 5 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 08/02/2019 | Inspection Date | 08/02/2019 | |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | | |

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3739S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER | CRACKED | 459.40 | 459.40 |
| 1 | REAR BUMPER SIDE BRACKET (LH) | CRACKED | 33.10 | 33.10 |
| 10 | REAR BUMPER COVER CLIPS | NOT NECESSARY | 22.00 | - |
| 1 | REAR FENDER (LH) | DEFORMED | 1,768.30 | 1,768.30 |
| 1 | REAR FENDER INNER LINING (LH) | SERVICEABLE | 73.60 | - |
| 1 | REAR WINDSCREEN MOULDING | NECESSARY | 28.30 | 28.30 |
| 1 | FUEL LID COVER | SERVICEABLE | 83.30 | - |
| 1 | REAR DOOR (LH) | DEFORMED | 1,789.90 | 1,789.90 |
| 1 | REAR WHEEL HUP-CAP (LH) | SCRATCHED | 134.10 | 134.10 |
| | LESS 20% DISCOUNT | | -878.40 | -842.62 |
| | | | 3,513.60 | 3,370.48 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | REAR BUMPER ADVERTISEMENT LOGO (SN) | NOT NECESSARY | 50.00 | - |
| 1 | REAR BUMPER RUBBER MAT (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR WINDSCREEN SEALANT (SN) | NECESSARY | 46.00 | 46.00 |
| 1 | REAR DOOR COMFORTDELGRO & APPS STICKER (LH) | NECESSARY | 80.00 | 80.00 |
| 1 | FUEL TANK LID (PETROL ONLY) STICKER (SN) | NECESSARY | 10.00 | 10.00 |
| | | | 236.00 | 186.00 |
| <u>LABOUR</u> | | | | |
| | PANEL BEATING. | | 800.00 | 600.00 |
| | SPRAY PAINTING CHARGE. | | 900.00 | 600.00 |
| | WIRING CHARGE. | | 30.00 | 30.00 |
| | TUFF KOTE. | | 50.00 | 50.00 |
| | REMOVE / REFIX REVERSE SENSOR. | | 120.00 | 30.00 |
| | TRANSFER OF DOOR. | | 120.00 | 50.00 |
| | REAR WHEEL ALIGNMENT. | NOT NECESSARY | 120.00 | - |
| | | | 2,140.00 | 1,360.00 |
| GRAND TOTAL | | | 5,889.60 | 4,916.48 |

Report Ref No. NS/INC19002413/Nvd3s2

| | | | |
|--|--|--|----------|
| RECOMMENDED COST OF REPAIRS (CONFIRMED) | | | 4,916.48 |
|--|--|--|----------|

Report Ref No. NS/INC19002413/Nvd3s2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.