

INS. CASE OWNER: CCU AXA1900 ^{Asm} WAA, KLB39 LKK: 18/2/19
 IDAC:

Surveyor: KOBASURY DOI: 18/02/19 Date / Time: 18/2/19
 Registered in Merimen: _____

Pre-assign / CCU / FTE
 Insured Vehicle No.: SHB 99810 Claim No.: 09moic8v/92938
 Name of Insured: TRANS UPB SERVICES VLL Policy No.: VPA / P16805W
 Insured Tel No.: _____ HP: _____ Make / Model: KE MULET
 Excess Sec II :\$S _____ D.O.A: 26/1/19 Place of Accident: VSO BISHAW ST 24 4
 Is driver the owner? (YES / NO) Nature of Accident: _____
 If NO, Driver Name / Age: Yong Yook pin OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: % Final ? Yes / No

SKA 3127M → → → → →
 INSRs: WSP: Tel: Liability: RMKS: Lim Tan
 INSRs: WSP: Tel: Liability: RMKS: _____
 INSRs: WSP: Tel: Liability: RMKS: _____
 INSRs: WSP: Tel: Liability: RMKS: _____

Date/Time	STAGE	DATE / PIC
18/02/19	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	
	After call Itr to OI	<u>18/02/19-JC</u>
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorization To Act	<input checked="" type="checkbox"/>
	Release Voucher	<input type="checkbox"/>
	Final Repair Bill	<input checked="" type="checkbox"/>
	Car Rental Invoice	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill	<input type="checkbox"/>
	PIR	<input type="checkbox"/>
	Mandate/Reject Instruction	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form	<input type="checkbox"/>
	Post-Repair Photos	<input checked="" type="checkbox"/>
	Others: <u>DO FORM</u>	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 Repair Cost: 1,500.00 (5 days) Reduction: 34 % Email Call

FINAL SETTLEMENT Date/Time: 03/05/19 Confirm with: RICHARD Email Call
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 21
 Repair Cost: (w/gov) 53,1658.50 IF NO or B 28, Ass. Lia: COW PROVIDED TO PAPK)

Loss of Rental (LOR): \$5 - (1 days)
 Loss of Use (LOU): \$5 300.00 x 3 days
 Loss of Income (LOI): \$5 - (5 x days)
 LOR only LOU only LOR + LOU LOR + LO [Tick only one]
 GIATA Search: \$5 -
 Medical: \$5 -
 Disbursement: \$5 - (e.g. Tow/ Independent)
 Legal Cost: \$5 -
 Total: \$5 1,958.50 Global Sum \$S: -
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee: 9550.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call
 Payee 1: \$5 1,958.50 Name 1: LIM TAN MOTOR FOR LOD
 Payee 2: (Strike if N.A.) \$5 - Name 2: _____
 Payee 3: (Strike if N.A.) \$5 - Name 3: _____

COPY SENT
 6/9/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19002499/hb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 12-02-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 9981D	Veh. Inspected	SKA 3127M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/02/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/01/2019	Inspection Date	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

ESTIMATE TO REPAIR

VEHICLE NO. : SKA 3127 M
 MAKE : B.M.W
 MODEL : X6 3.0 A
 YEAR : 2011
 CHASSIS NO : WBAFG22070LL80464

SURVEYOR NAME :
 DATE OF SURVEY : 19.02.2019
 TIME OF SURVEY :

DATE : 12-Feb-19
 DATE OF ACCIDENT : 28-Jan-19
 THIRD PARTY REF : SHB 9981 D / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper <i>See</i>				\$ 1,273.80 ⁷
1 pc	O/S Front Fender Arch Garnish <i>W</i>				\$ 205.75 ⁷
16 pcs	O/S Front Fender Arch Garnish Clips		\$ 5.00		\$ <i>See</i> 80.00 ⁷
	To putty and spray painting				\$ 450.00 ⁴⁰⁰
	Labour Charges				\$ 350.00 ²²⁰
<i>Not with work Renewy 84 point 3 days</i>					
<div style="border: 1px solid black; padding: 5px;"> <p>LTK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> To remedy defective spray painting To replace damaged partial colour resurvey Parts prices are subject to confirmation This price estimate is on "Without Prejudice" basis No deposit/advance payment is required Supplementary works must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer: Signature: Date:</p> </div>					
TG/RA-	Total				\$ 2,359.55

Lim Tan Motor Pte Ltd

Bldg 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9071D
Vehicle Details	
Vehicle No.:	SKA3127M
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X6 3.0 A
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	06717497N55B30A
Chassis No.:	WBAFG22070LLB0464
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$66,304.00
Original Registration Date:	16 Feb 2011
First Registration Date:	16 Feb 2011
Transfer Count:	0
Actual ARF Paid:	\$66,304.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Feb 2021
PARF Rebate Amount:	\$39,782.00
Intended COE Rebate Details	
COE Expiry Date:	15 Feb 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$58,890.00
COE Rebate Amount:	\$10,711.00
Total Rebate Amount:	\$50,493.00

The information contained herein is correct as at 13 Feb 2019

OK

Service Request Details

Claim
S9M01C8V

Reference
None

Loss Date
January 28, 2019

Request Date
February 12, 2019

Due Date
February 19, 2019

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
SKA3127M

Make
TPVD

Model
BMW

Service Address

*Ym Tan.
- Richard call in.
VnI, will arrange with
Surveyor.*

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

+ Upload Documents

NAME	 Accident Statement
TYPE	Reports & Statement
SUB-TYPE	
AUTHOR	Merimen
DATE UPLOADED	
NAME	 PRI FROM WORKSHOP WITH TP GIA SKA3127M & ESTIMATE.msg
TYPE	Forms / Claim Documents
SUB-TYPE	Claim Form
AUTHOR	KUMAR Shallendra
DATE UPLOADED	February 12, 2019
NAME	 REPLY FROM WORKSHOP.msg
TYPE	Forms / Claim Documents
SUB-TYPE	Claim Form

AI THOR

KUMAR Shallendra



Re:<MANDATE IA> S9M01C8V

Type

🔍 Question

Message

PLS PROCEED AS PROPOSED

Reply



01 MAR 2019

Date: _____

Your Ref: CC4/ASM19002499/hb3

Our ref: LTP012019/011 (SKA 3127 M)

(WITHOUT PREJUDICE)

Attention To : MR VIC ALPEH (From LKK Auto Consultants Pte Ltd)

Insurance Company : AXA INSURANCE PTE LTD

Dear Sir/Mdm,

IN THE MATTER OF ACCIDENT INVOLVING SKA3127M & SHB9981D ON 28.01.2019

We refer to the above matter.

We are instructed and authorised by our client to quantify, to act and negotiate settlement in related to the above road traffic accident that was caused by your insured.

All supporting documents are enclosed herewith:-

<input checked="" type="checkbox"/> Authorization To Act	<input checked="" type="checkbox"/> Original Tax Invoice no. INV38955
<input type="checkbox"/> Original Rental Receipt and Agreement	<input type="checkbox"/> LTA search receipt
<input type="checkbox"/> Letter Of Discharge	<input type="checkbox"/> _____

Survey was done by Insurance instruction and was surveyed by Mr Kenneth on 18-Feb-19

As a result of the accident, our client's vehicle was damaged and has been put to loss and Expenses, particulars of which are as follows:-

1] Cost of repair (Inclusive of 7% GST)	\$ 1,658.50
2] Loss of Use (\$140.00 x 3 Days)	\$ 420.00
Total	<u>\$ 2,078.50</u>

Please acknowledge receipt of this letter within 14 days. If you agreeable to the above, please forward your payment. Payment to be issued directly to LIM TAN MOTOR PTE LTD within 4 weeks. Should there be any injury related to this matter, any settlement agreed is WITHOUT PREJUDICE to the related injury claim.

Your faithfully

Mandy Lim

Email: mandy@ltm.sg

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 18 April, 2019 3:40 PM
To: claims
Cc: Admin A; Vic (LKKAUTO); disk Yao@ava-ins.com; alicelim@ava-ins.com; IreneNg@ava-ins.com
Subject: YOUR REF : P1680520 (SHB 9981D)_ACCIDENT INVOLVING SHB 9981D AND SKA 3127M AT/ALONG 280 BISHAN STREET 24 CAR PARK ON 28/01/2019

18 APRIL 2019

TRANS-CAB SERVICES PTE LTD
SINGAPORE

Dear Sir/Madam,

OUR REF : CC4/ASM19002499/Khb3
YOUR REF : P1680520 (SHB 9981D)
ACCIDENT INVOLVING SHB 9981D AND SKA 3127M AT/ALONG 280 BISHAN STREET 24 CAR PARK ON 28/01/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s LIM TAN MOTOR PTE LTD acting on behalf of the owner of SKA 3127M against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

Please be informed that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal.

We also wish to advise that there is an excess of S\$5,000/- is attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- 1) Any settlement equal to or above the excess, you shall be liable to make the payment of \$5000/-; or
- 2) Any settlement below the excess, you shall be liable for the amount settled.

We shall keep you informed of the third party claim settlement and thereafter kindly let us have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by us for the above subject matter, we expressly reserve all our rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

As insurers, we shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / vicalpeh@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto
Consultants
Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

To Whom It May Concern

AUTHORIZATION TO ACT

I/We, LIM KIM SOON ('the third party Claimant') of BLK 212 BISHAN STREET 23 #02-263 SINGAPORE 570212 (Address) owner of SKA3127M (vehicle number) hereby authorize LIM TAN MOTOR PTE LTD ('the workshop') to act for me with respect to my/our claim for repair costs and/or rental and/or Loss of use ('claim') for my/our vehicle number SKA3127M that was damaged pursuant to the accident which occurred on 28-Jan-19 (date) along BISHAN STREET 24 BLK 280 OPEN SPACE CARPARK (locate on) involving vehicle number SHB9981D (the accident').


I/We further authorize the workshop to settle my above mentioned claim in a Manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

Dated this 29th (day) of January (month) 2019 (year)


A hand-drawn signature consisting of a large, stylized 'A' shape with a vertical line through it, and a horizontal line at the base.

Signed By ' the third party claimant '




A hand-drawn signature in cursive script, appearing to read 'Lim Tan'.

Signed By ' the workshop '



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SHB 9981D (Insd veh)	Model: BMW X6
	SKA 3127M (TP veh)	
Date of Accident/ Time:	28/01/2019 @ 1745HRS	

Repair Estimate	S	2,524.72	
Final Repair Cost	S	1,658.50	
Loss of Use	S	300.00	3 days at S 100 per day
Rental (if any)	S	-	days at S per day
LTA / GIA Search Fee	S	-	
Others:	S	-	
	S		
Final Settlement Sum	S	1,958.50	

Payee Name : LIM TAN MOTOR PTE LTD

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability <u>100</u> (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.



[Handwritten Signature]



Signature of workshop representative / Workshop stamp
 Name of Representative: **Mandy Lim**
 Date: **3rd May 2019**

Signature of Witness / Workshop stamp (if applicable)
 Name of Witness: **Richard Ang**
 Date: **3rd May 2019**



[Handwritten Signature]

Signature of AXA's surveyor/representative:
 Name of AXA's surveyor /Representative:
 Date:



LIM TAN MOTOR PTE LTD
林陳摩哆私人有限公司

Company's Registration No.: 199307277D
 GST Registration No.: M2-0119086-0

Branch
 (Warranty and Performance) Blk 9 Sector C #01-38/40/42
 Sin Ming Industrial Estate, Singapore 575644
 Tel: +65 6452 2135 Fax: +65 6452 2159

Main Office / Workshop
 Blk 176 Sin Ming Drive #03-09/10/06
 Sin Ming Autocare Singapore 575721

Tel: +65 6452 0893 (24Hrs)
 Fax: +65 6458 9127
 Email: sales@LTM.sg

Blk 17 Sector A #01-65
 Sin Ming Industrial Estate, Singapore 575675

WWW.LTM.SG

LIM KIM SOON
 BLK 212 BISHAN STREET 23
 #02-263
 SINGAPORE 570212

TAX INVOICE

ATTN : MOTOR CLAIMS DEPT
 TEL :
 FAX :
 A/C NO. : 30L0/616

MILEAGE :
 W.O NO. : SO39710
 CAR NO. : SKA3127M
 MAKE : BMW
 MODEL : X 6

NO : INV38955
 DATE : 28-02-2019
 TERMS : COD
 PAGE : 1

DESCRIPTION	QTY	U.PRICE	DIS	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR	1 UNIT			1,550.00

SINGAPORE DOLLARS : ONE THOUSAND SIX HUNDRED FIFTY EIGHT AND FIFTY CENTS ONLY

REMARKS: D.O.A : 28.01.2019
 LKK REF : CC4/ASM19002499/hb3

TOTAL QTY: 1.00

SUBTOTAL	1,550.00
DISCOUNT	0.00
TOTAL	1,550.00
GST 7 %	108.50
NET	1,658.50
Deposit	0.00
Balance	1,658.50



[Handwritten Signature]

AUTHORISED SIGNATURE(S)

CUSTOMER NAME / SIGNATURE / DATE

Customer Acknowledgement

I/We confirm that I/We incurred the repair costs herein and will observe my/our Agreement with the repairer. I/We declare the repair for the above vehicle have been completed to my/our satisfaction



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19002499/Khb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date : 09-05-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 9981D	Veh. Inspected	SKA 3127M
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01C8V	Excess (\$)	0.00
Assign From		Assign Date	12/02/2019
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. X6 (A)	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAFG22070LL80464	Colour	METALLIC BEIGE
Odometer	155417	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/50 R19	MICHELIN	8 mm
L/H Front Tyre	255/50 R19	MICHELIN	8 mm
R/H Rear Tyre	255/50 R19	MICHELIN	8 mm
L/H Rear Tyre	255/50 R19	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/01/2019	Inspection Date	18/02/2019
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 3127M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	BUCKLED	1,273.80	1,273.80
1	O/S FRONT FENDER ARCH GARNISH (CONSISTENT)	NOT NECESSARY	205.75	-
16	O/S FRONT FENDER ARCH GARNISH CLIPS @\$5.00 (CONSISTENT)	NECESSARY	80.00	80.00
			1,559.55	1,353.80
LABOUR				
	TO PUTTY AND SPRAY PAINTING.		450.00	400.00
	LABOUR CHARGES.		350.00	220.00
			800.00	620.00
GRAND TOTAL			2,359.55	1,973.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,550.00

Report Ref No. CC4/ASM19002499/Khb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
EMAIL.png	Letters and Correspondence	Others	KADRI Mateen	10 April 2019
FBI FROM WORKSHOP WITH TP GIA SKA3127M & ESTIMATE.png	Forms / Claim Documents	Claim Form	KUMAR Shalmita	12 February 2019
REPLY FROM WORKSHOP.png	Forms / Claim Documents	Claim Form	KUMAR Shalmita	12 February 2019