

ASS. REC. BY:

REF:

CS3/MSG19002502/Tcd3k

Special Instruction:

Surveyor:

menmen

ASSIGNMENT (Office)

From (Person):

Monica chung

of

MSG

Date/Time:

12/2/19 @ 3:10pm

Estimated Cost:

Bill to:

~~OD / TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SGN 3432K

Insured:

C7BD 69187

at Workshop m/s

Eng Soon painting

Tel:

6760 6271

of

Blk 4, Yew Tee Ind. Est 343J

Policy No.:

B28684805MKC

Claim No.:

58 4574

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.:

08/02/2019

CA / REV / REP. / REV 24 HRS

lup

13/2/19 @ 2:30pm (ow)

H.O.D. Endorsement:

Date/Time:

2:19pm @ 12/2/19

Person Contacted:

Mr. Teo

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SGN 3432K - N/A / INC 10004759 / RIKI
	C7BD 69187 - X
	Diamondite: 18/2/2019
	After repair: 25/2/2019

DUA: 10/3/2010

PRIS

Tan Jiah

REF: MSIG

ASSIGNMENT

From: Date: 13/2/19.

Veh No: SGN3432K Regn: Nov 06

Estimated Cost

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

OD: P / WS / TP RES / OD RES / EVA / INV / MV

Make: Toyota A/His C.C. 1598

To inspect Vehicle No: SGN3432K

Colour: Silver A/C: Insured / Std / NI / NA

at Workshop m/s: Eng Soon Painting

Sp. Reading: 216855 T/Radio: Insured / Std / NI / NA

of: Blk 4, Yew Tee Ind. Est 3435

Eng/No: m R0537EC 10.7136437

Insured

Gen. Cond: Good / Fair / Poor / Burnt

Policy No

Steering: In order / Jammed / Leaked / Burnt or

Claim No

Brake: In order / Jammed / Leaked / Burnt or

Sum Insured

Excess:

(Client's Record)

Make of Veh:

2:30 pm @ owner waiting

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 185 / 70R14 R: 185 / 70R14

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front R/Bal: 6 mm Rear R/Bal: 6 mm

IDAC Accident Rport: Consistent? : Yes or No

L/Bal: 6 mm D.O.A.

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

D.O.I. 13/2/19 @ 245pm

Survey held at: Eng Soon Painting

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

Frt N/S The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction No 917.

Estimated repair range \$4,000 - \$5,000.

Signature: 27/2/2019

Date/Time: File Pass to?

- : Preli. Report
- : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Date/Time: File Return to?

- Add Fee: Site Insp (\$)
- Interview (\$)
- Tech Insp (\$)
- Weekend (\$)

Transportation

S + P + G

Photos

Other

Total

120
10
130

Report Format: PRE.

Lump Sum / LB (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2019		12 Feb 2019 15:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM TRADERS PTE LTD, Co. Reg. No.: 200305123D		
Main Claimant:	ELBC, Co. Reg. No.: 53367249W		
Vehicle Reg. No.:	SGN3432K	Date of Loss:	08/02/2019 17:00 - :59 [146 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584574	Policy/Cover Note No.:	B28684805MKC (Comprehensive) Coverage: 23/03/2016 - 22/03/2019
Vehicle Reg. No. (Insured):	GBD6918T	Policy No. (Claimant):	
		Excess:	
Repairer:	Eng Soon Painting Svc (HQ) BLK 4 YEW TEE IND EST 393J WOODLANDS ROAD, 677969 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/02/2019]		
Driver/Custodian (Insured):	TIAN HU (32 / Male), NRIC: G2627628X, Tel: +6584976817		
Adj Asg. Remarks:	LIAB 0% SJE DISAGREE APPOINT LKK PLS CONTACT AND CONTACT 6760 6271		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7249W
Vehicle Details	
Vehicle No.:	SGN3432K
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4617849
Chassis No.:	MR053ZEC107136437
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	15 Nov 2006
First Registration Date:	15 Nov 2006
Transfer Count:	2
Actual ARF Paid:	\$16,891.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Nov 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$51,641.00
COE Rebate Amount:	\$39,944.00
Total Rebate Amount:	\$39,944.00

The information contained herein is correct as at 20 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/02/2019 16:20
Date Of Accident	08/02/2019 17:30
Exact Location Of Accident	ALONG EU TONG SEN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN3432K
Insured/Policyholder	
Name Of Registered Owner	ELBC
Co Reg No	53367249W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96629439

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092932123-01
Cover Note Number	

Driver

Name of Driver	LEE KIN YIN
NRIC No	S0028453Z
Date Of Birth	03/05/1951
Occupation	OUTDOOR
Date Of Driving Pass	09/11/1970
Driving Experience	48 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96629439
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address APT BLK 332 TAN CHING ROAD #04-179
 Postcode 610332
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD6918T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

ELBC

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2019		12 Feb 2019 15:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LIM TRADERS PTE LTD , Co. Reg. No.: 200305123D								
Main Claimant:	ELBC , Co. Reg. No.: 53367249W								
Vehicle Reg. No.:	SGN3432K	Date of Loss:	08/02/2019 17:00 - :59 [146 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 584574	Policy/Cover Note No.:	B28684805MKC (Comprehensive) Coverage: 23/03/2016 - 22/03/2019						
Vehicle Reg. No. (Insured):	GBD6918T	Policy No. (Claimant):							
		Excess:							
Repairer:	Eng Soon Painting Svc (HQ) BLK 4 YEW TEE IND EST 393J WOODLANDS ROAD, 677969 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 13/02/2019]								
Driver/Custodian (Insured):	TIAN HU (32 / Male) , NRIC: G2627628X, Tel: +6584976817 Email:								
Adj Asg. Remarks:	LIAB 0% SJE DISAGREE APPOINT LKK PLS CONTACT AND CONTACT 6760 6271								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGN3432K (584574)
[GBD6918T]
TP
ELBC
Feb 8 2019 5:00PM
[LIM TRADERS PTE LTD]
Eng Soon Painting Svc

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/02/19 09:55	Accident Statement From: SC - Reg. No: GBD6918T, Claimant: LIM TRADERS PTE LTD	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/02/19 13:58	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/02/19 14:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	23/02/19 14:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	23/02/19 14:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 14:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 14:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
35	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
36	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
37	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
38	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	23/02/19 14:05	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
52	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
53	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
54	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
55	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
56	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
57	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
58	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
59	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
60	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
61	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
62	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
63	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
64	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
65	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
66	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
67	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
68	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
69	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
70	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
71	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
72	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
73	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
74	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
75	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
76	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
77	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
78	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
79	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
80	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
81	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>
82	28/02/19 12:52	Photo After Spray		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/02/19 09:55	TP SGN3432K E-REPORT From:SC - Reg. No: GBD6918T, Claimant: LIM TRADERS PTE LTD	Load PDF	
2	12/02/19 09:55	PRI From:SC - Reg. No: GBD6918T, Claimant: LIM TRADERS PTE LTD	Load PDF	
3	12/02/19 10:27	SJE DISAGREE APPOINT LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19002502/T1CD3E2
Date: 01/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28684805MKC
Claimant Vehicle No : SGN3432K	Insured Vehicle No :	GBD6918T
Date of Loss: 08/02/2019	Nature of Claim:	TP
		Claim No: 584574

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN3432K	Engine No:	3ZZ4617849
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107136437
Reg. Date:	15/11/2006 (Man. Year: 2006)	Odometer:	216853 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/02/2019	
Date Inspected:	13/02/2019	Inspected At:
		Eng Soon Painting Svc (HQ) BLK 4 YEW TEE IND EST 393J WOODLANDS ROAD Singapore 677969
Estimated Period of Repair:	5.0 days	

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN3432K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >