

12/03/2002

ASS. REC. BY:

REF:

CS3/CTI 19002527/Gcd30

Special Instruction:

Surveyor

MEMPH

## ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

12/2/19 @ 11:11 am

Estimated Cost:

Bill to:

OD / ~~HP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 8604E

Insured:

SJM 247K

at Workshop m/s

Ah Luck Motor

Tel:

9108 5653

of

3015 Subi Road 1

Policy No:

DMPCSN 30807118000

Claim No:

SNM19112000597

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/01/2019

14/2/19 @ 2pm (COW)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

2:30pm @ 12/2/19

Person Contacted:

Ah Luck

Vehicle IN (OUT)

Date/Time

Action/Instruction

(X)

Estimate

# 01-382

(Insp)

SJF 8604E - X

SJM 247K - X

PRS  
XHL

REF: CFI

8431C


(~2028)

SIF 8604E

12 Jun 2008

Date: 14/2/19  
Estimated Cost:  
OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SIF 8604E  
at Workshop no: Ah Luck  
of: 3015 Ubi Road | #01-232  
Insured:  
Policy No:  
Claims No:  
Sum Insured:  
Excess:  
(Client's Record)  
Make of Veh:  
(Policy Condition)

~~SPM~~  
owner waiting



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:  
IDAC Accident Report: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SIF 8604E  
Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Toyota wish  
Colour: Black  
Sp. Reading: 169111  
A/C: Insured / Std / NI / NA  
T/Radio: Insured / Std / NI / NA

Eng/No: ZNE 100 404426  
C/No:  
Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15  
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R/Bal: 6 mm, L/Bal: 6 mm, D.O.I.:  
Rear: R/Bal: 6 mm, L/Bal: 6 mm, D.O.I.: 14-02-19 2330 pm  
Survey held at: w/s  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction: \$5000 - \$6000

Date/Time: File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee:

Transportation:

5 x R: 3

Helos:

Other:

Total:

Total:

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Insp (\$)  
☐ Weekend (\$)

Report Format: PRS

Lump Sum / L.B.: 15

150
150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2019		12 Feb 2019 11:11 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	LEE MENG HOCK		
Vehicle Reg. No.:	SJF8604E	Date of Loss:	31/01/2019 14:00 - :59
Claim Type:	TP / SNM19D2000597	Policy/Cover Note No.:	DMPCSN30807118000
Vehicle Reg. No. (Insured):	SJM247K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ah Luck Motor & Trading (HQ) 3015 Ubi Road 1, #01-232, 408704 Ubi - Tel: 91085653		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Tuesday, 12 February 2019 11:04 AM  
**To:** Daniel Poon & Co.; Daniel Poon & Co.  
**Cc:** assignments; Admin A  
**Subject:** CTP REF NO. SNM19D200597C02 DP REF NO. DP.SL.ISK.10857.19.ALM - ACCIDENT INVOLVING SJM2147K AND SJF8604E ON 31 JANUARY 2019  
**Attachments:** PRS FROM DANIEL POON.pdf

### WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with Ah Luck Motor.

Thank you.

**Irene Tay**

Executive

Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



#### Disclaimer :

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8431C
Vehicle Details	
Vehicle No.:	SJF8604E
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1ZZ3078811
Chassis No.:	ZNE100404426
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,044.00
Original Registration Date:	12 Jun 2008
First Registration Date:	12 Jun 2008
Transfer Count:	2
Actual ARF Paid:	\$11,910.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$37,906.00
COE Rebate Amount:	\$35,341.00
<b>Total Rebate Amount:</b>	<b>\$35,341.00</b>

The information contained herein is correct as at 15 Feb 2019

OK

Owner IC & LIC Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE

Vehicle Number: S1498431C

Name: LEE MENG HOCK

Birth Date: 22 Apr 1961

Issue Date: 05 May 2014

982301276K

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1498431C

Name: LEE MENG HOCK

Race: CHINESE

Date of birth: 22-04-1961

Sex: M

Country/Place of birth: SINGAPORE

5306310

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg

EFFECTIVE DATE: 20 Jul 1985

NP 428A

Licence No. S1498431C

5306310

Barcode

NRIC No. S1498431C

Date of issue: 28-04-2014

Address: APT BLK 298A COMPASSVALE STREET #15-190 SINGAPORE 541298

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/02/2019 17:13
Date Of Accident	31/01/2019 14:45
Exact Location Of Accident	PIE TOWARD TUAS LP 951
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF8604E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE MENG HOCK
NRIC No	S1498431C
Email Address	MHLEE298@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96269529
Alternative Phone No	OTHERS-96269529

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00008810
Cover Note Number	

### Driver

Name of Driver	LEE MENG HOCK
NRIC No	S1498431C
Date Of Birth	22/04/1961
Occupation	INDOOR
Date Of Driving Pass	20/07/1985
Driving Experience	33 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96269529
Fax Number	
Contact Number	OTHERS-96269529
Email Address	MHLEE298@YAHOO.COM

Nature Of Damage  
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number                      SJM2147K  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category                                      PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

Address	BLK 298A COMPASSVALE ST #15-190
Postcode	541298
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JPV5613 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	<b>ROAD:</b> 10 UBI AVENUE 3 , <b>POSTCODE:</b> 408865 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 65470000 - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	JPV5613
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

### SKETCH PLAN

1

**SKETCH PLAN**

Vehicle  
A - SJF8604E  
B - JPV5613  
C - SJM2147K



Legend  
Vehicle: [rectangle with triangle on top]  
Motorcycle: [circle]

I/We declare the foregoing particulars are true in every respect.  
Please be advised that your insurer may have a fourteen (14) days (fourteen) whereby the claim against your policy must be made within the stipulated timeframe from the day of purchase. Kindly check your policy for more details.

Date &amp; Time

Driver's Signature \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2019		12 Feb 2019 11:11 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>LEE MENG HOCK</b>								
Vehicle Reg. No.:	<b>SJF8604E</b>	Date of Loss:	31/01/2019 14:00 - :59 [127 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D2000597</b>	Policy/Cover Note No.:	DMPCSN30807118000						
Vehicle Reg. No. (Insured):	<b>SJM2147K</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Ah Luck Motor &amp; Trading (HQ)</b> 3015 Ubi Road 1, #01-232, 408704 Ubi - Tel: 91085653								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 21/02/2019]</b>								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SJF8604E (SNM19D2000597)**  
**[SJM2147K]**

TP





LEE MENG HOCK

Jan 31 2019 2:00PM

[-]

**Ah Luck Motor & Trading**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
10	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
11	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
12	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
13	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
14	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
15	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
16	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
17	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
18	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
19	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
20	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
21	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
22	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
23	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
24	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
25	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
26	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
27	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
28	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
29	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
30	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
31	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
34	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
35	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
36	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>
37	23/02/19 14:45	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/02/19 14:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/02/19 14:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/02/19 14:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/02/19 14:45	General View	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19002527/GCD3E2

Date: 04/04/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30807118000

Claimant Vehicle No: SJF8604E Insured Vehicle No: SJM2147K

Date of Loss: 31/01/2019 Nature of Claim: TP Claim No: SNM19D2000597

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJF8604E**

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3078811

Reg. Date: 12/06/2008 (Man. Year: 2008) Chassis No: ZNE100404426

Colour: Black Odometer: 169111 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 12/02/2019

Date Inspected: 14/02/2019 Inspected At: Ah Luck Motor & Trading (HQ)  
3015 Ubi Road 1, #01-232  
Singapore 408704

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJF8604E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >