

ASS. REC. BY:

REP

CS/FCI19002541/Klsdbn2

Special Instruction:

Surveyor

Kalvin

ASSIGNMENT (Office)

From (Person):

Jouane Young

of

FCI

Date/Time:

9:32am @ 12/2/19

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB800SD

Insured:

SHC 8717C

at Workshop m/s

Premier Automotive

Tel:

8544 6689

of

23 Chengi South Ave 2 #01-02

Policy No:

Claim No:

D19000896MFst

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up

H.O.D. Endorsement:

Date/Time:

11:56am @ 12/2/19

Person Contacted:

Vineet

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 800SD-X
	SHC 8717C-CS/FCI16010867/71gbd1
	D.O.A. 9/6/16
12/2/19	Email preti revised to FCI

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 80050 Yr Regn: 3' Aug 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Z30 cc: 1582Colour: Silver A/C: Insured / Std / Nil / NASp. Reading: 222051 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: TM A P 28 14 VH J 121493

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inord / Jammed / Leaked / Burnt or

Brake: Inord / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 5/2/19 D.O.I. 12/2/19Survey held at Premier

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
7/3/19	Went p/p \$1323.99 / 2 Hrs.
	C \$ 390/- Red - 23%)

RECEIVED 07 MAR 2019

7/3/2019

Date/Time, File Pass to?

07/03/19

1) Typ: 4

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ 1,323.99 p/p)Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

110

50

50

27

237



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000896MFSH

Our ref: CS/FCI19002541/K1sd3

DATE: 13/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 8005D


We thank you for your instruction on 12/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/2/2019 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$1,713.99
Revised Estimate Amount	: S\$1,323.99
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kalvin Ang

Technical Investigator

Technical Investigation & Reconstructionist (SAE-A)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 February 2019 12:19 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000896MFSH/1, SHC 8005D
Attachments: SHC 8005D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 8005D
Date of survey: 12/2/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 12 February 2019 12:03 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000896MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 12 February 2019 9:32 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000896MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	31 Aug 2016 / 08:32:18	Receipt No.:	AAKMO002-AX253-160831-000017
Asset Type:	Vehicle	Transaction Amount:	\$53,777.00
Asset ID:	SHB8005D	Channel:	AA Counterless - KOMOCO MOTORS PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20160831083218928044		

Vehicle No.:	SHB8005D
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	31 Aug 2016
Original Registration Date:	31 Aug 2016
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 GDH 1.6 TCI 5DR DCT
Chassis No.:	TMAD281UVHJ121493
Engine No.:	D4FBGZ105448
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1582
Power Rating:	-
Unladen Weight:	1496
Maximum Laden Weight:	1940
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2016
Open Market Value:	\$19,922.00
Minimum PARF Benefit:	\$7,453.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	31 Aug 2016 08:32:18
COE No.:	2016083101004698M
COE Expiry Date:	30 Aug 2024
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$41,215.00
Lifespan Expiry Date:	30 Aug 2024

Sketch Plan Pg. 4

PREMIER	SHB8005D
VEHICLE NO	
CONTACT NO	9628 5851
NEW MAILING ADDRESS (if any)	

	Licence Number: S1206697Z
	Name: NGOH SOCK HUAT
	Birth Date: 08 May 1956 Issue Date: 29 Aug 2018
	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO **S1206697Z**



Name
NGOH SOCK HUAT

吴金桦

Race
CHINESE

Date of birth
08-05-1956

Country/Place of birth
SINGAPORE

Sex
M

Land Transport Authority

VOCATIONAL LICENCE

Licence No : **S1206697Z**
Name : **NGOH SOCK HUAT**



Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS/CLASSES:

Class	Description	EFFECTIVE DATE	
		From	To
Class 3	Motor cars with unladen weight ≤ 3000kg with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight ≤ 2500kg	30 Dec 1981	

5993983



S1206697Z



18-07-2018

APT BLK 474 ANG MO KIO AVENUE 10
#09-850
SINGAPORE 560474



Licence No: S1206697Z

NP 428A

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
12	TAXI VL	22/01/1996



PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

12-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHB 8005 D

1 pc	o/s mirror assy <i>Broken</i>	\$ 742.49
	<i>o/s front door X repair</i>	
	<i>o/s front windscreen pillar X repair</i>	
	Less 20%	\$ 148.50
		\$ 593.99
S/NETT		
1 set	o/s door stickers <i>new</i>	\$ 100.00
	Sundry <i>new</i>	\$ 50.00 <i>20</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, etc.	\$ 650.00 <i>200</i>
	To putty and spray painting on front o/s door	\$ 100 <i>40</i>
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00 <i>X 2</i>
		\$ 1,713.99
		<i>2013.99</i>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.



Kalidat

12/2/19 1640L

2 hrs

P/P

Before Part photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002541/K1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8717C	Veh. Inspected	SHB 8005D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000896MFSH/1	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	12/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	TMAD281UVHJ121493	Colour	SILVER	
Odometer	222051	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/02/2019	Inspection Date	12/02/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8005D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	O/S MIRROR ASSY	BROKEN	742.49	742.49
1	O/S FRONT DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
1	O/S FRONT WINDSCREEN PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-148.50	-148.50
			593.99	593.99
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRY (SN)	NECESSARY	50.00	20.00
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
			150.00	120.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT O/S DOOR, ETC. INCLUSIVE OF THE REPAIR OF O/S FRONT WINDSCREEN PILLAR.		650.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT O/S DOOR.		500.00	410.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,270.00	610.00
	GRAND TOTAL		2,013.99	1,323.99
	RECOMMENDED COST OF REPAIRS			1,323.99

Report Ref No. CS/FCI19002541/K1sd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.