

ASS. REC. BY:

REF:

CS/III19002557/Ucd312 Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

From (Person):

Gubriel Wee

of

III

Date/Time:

12/2/19 @ 9.24am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 374

Insured:

SHA 7875X

at Workshop m/s

Tick Hui Motor

Tel:

6842 9049

of

1 Caki Bkt Ave 6 # 01-54

Policy No:

MCOM0015

Claim No:

MCT19010929

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/01/2019

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

11.11am @ 12/2/19

Person Contacted:

Connie

Vehicle:

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLK 374-X

SHA 7875X-CC3/AIG13012780/Hlg2-2w2 DUA: 12/7/13

Dismantle: 15/2/2019 10.55am

19/2/2019 11.58am

After repair: 14/3/2019 11.55am

ASS. REC. BY: *Marcus*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLK 374*at Workshop m/s *Techni*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *16812*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLK 374*Yr Regn: *6, 17*Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *BMW*Colour: *Black*Sp. Reading: *25242*

Eng/No: _____

C/No: *WBA 4U 32030 E A25530*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *225/45 R18*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *3.1.19*D.O.I. *12/2/19 1124pm*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PAS no holding. Rep 16
LTA 93691 byrs. & m.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: *3*

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: *PRE*

Lump Sum / I.B.I. (\$) _____)

TOTAL

120

10

120

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 12 February 2019 9:24 AM
To: Aridas @ Associates; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLK37U (Accident involving SLK37U and SHA7875X on 31.01.2019)
Attachments: sha7875x_20190211155848.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLK37U and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Aridas @ Associates [mailto:aridasv@singnet.com.sg]
Sent: 11 February, 2019 4:49 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLK37U (Accident involving SLK37U and SHA7875X on 31.01.2019)

Hi Sir,

Our client has chosen LKK Auto Consultants Pte Ltd.

Please liaise directly to:

Please contact Ms Connie at office number: 6842 9049.

**M/s Tick Hai Motor & Welding Services, Block 1 Kaki Bukit Avenue 6,
#01-54 Auto @ Kaki Bukit, Singapore 417883.**

Regards,
Marina

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Monday, 11 February 2019 4:09 PM

To: 'aridasv@singnet.com.sg' <aridasv@singnet.com.sg>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLK37U (Accident involving SLK37U and SHA7875X on 31.01.2019)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2679F

Vehicle Details

Vehicle No.: SLK37U

Vehicle to be Exported: No

Intended Deregistration Date: 12 Feb 2019

Vehicle Make: B.M.W.

Vehicle Model: 430I CONVERTIBLE LED NAV HUD MSPT

Primary Colour: Black

Manufacturing Year: 2017

Engine No.: F6131700B48B20B

Chassis No.: WBA4V32030EA25530

Maximum Power Output: 185.0 kW (248 bhp)

Open Market Value: \$51,205.00

Original Registration Date: 28 Jun 2017

First Registration Date: 28 Jun 2017

Transfer Count: 1

Actual ARF Paid: \$64,169.00 *32084*

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Jun 2027

PARF Rebate Amount: \$48,126.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2027

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$54,616.00

COE Rebate Amount: \$45,565.00

Total Rebate Amount: \$93,691.00

The information contained herein is correct as at 12 Feb 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CHEAPEST CAR

INSURANCE RENEWAL

Choice of \$0 excess

Option of any workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A

\$2300 Driveaway (inc: 1 Yr Insurance & Adv) 2.88%P.A

Monthly \$568 By Gv Finance

GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE.LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

bmw 430

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 430		Any	Any	2017	Any	Any	Any	Available
<div></div>	BMW	4 Series 430i Coupe M-Sport	\$179,800	\$16,800 /yr	07-Dec-2017	1,998 cc	9,000 km	Sports	Available
Attractive Financing Rate And Free Titan X! Comes With 3 Years/200,000Km Warranty By Agent PML! Stunning Black Sapphire Metallic Paintwork And Cognac Brown Dakota Leather Interior! Flexible In House F...									
Supreme Cars Pte Ltd									
Posted: 11-Feb-2019 Tags: 2017 BMW 430i, 2017 bmw 430i, BMW 430i, bmw 430i, BMW, 430i, Used BMW									
<div></div>	BMW	4 Series 430i Convertible M-Sport	\$196,800	\$18,640 /yr	02-Nov-2017	1,998 cc	9,600 km	Sports	Available
In House Finance And 7 Years Loan Available! Only 1 Ownership, Comes With 5 Years/200000 Km PML Warranty! Super Low Mileage Only Done At 9600 Km! Less Than 1-Year-Old Signature M-Series Blue 430 Conve...									
Speedo Motoring									
Posted: 28-Jan-2019 Tags: 2017 BMW 430i, 2017 bmw 430i, BMW 430i, bmw 430i, BMW, 430i, Used BMW									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 430, bmw 430 Singapore, used bmw 430 Singapore, used bmw 430, used vehicles Singapore or even buy used bmw 430 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

MSME19015565 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 01/02/2019 16:24
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

159 Tick Hai Motor

ACCIDENT STATEMENT

Date Of Report	01/02/2019 16:24
Date Of Accident	31/01/2019 15:30
Exact Location Of Accident	PIE TWDS TUAS NEAR UPP THOMSON RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK37U
Insured/Policyholder	
Name Of Registered Owner	YEW SWEE FONG
NRIC No	S1812679F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96972909
Alternative Phone No	OFFICE-96972909

Vehicle Particulars

Manufacturer	BMW
Model	430i

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	C0081216
Cover Note Number	

Driver

Name of Driver	LEE WEI XUAN
NRIC No	S9628393H
Date Of Birth	11/08/1996
Occupation	INDOOR
Date Of Driving Pass	23/10/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84482885
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 37 SUNBIRD AVENUE
 Postcode 487347
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : POH QIWEN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA7875X
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category TAXI
 Name of Driver KOH CHEE SIN
 NRIC/Passport Number S1149649J
 Contact Number 98716366
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLG4762D

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LEE WEI XUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLK37U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

POH QI WEN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLK37U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: 112/2019

1410 hrs

TOR HAT

Sketch Plan #2 Pg. 1

ETCH PLAN

Vehicle A: SLK37U

Pie toward Tuas

Vehicle B: SHA7875X

Vehicle C: SLG4762D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on lane 1 on PIE towards Tuas
 The traffic slow down I decelerate until I stop behind the Vehicle C
 (SLG4762D) Few Seconds later Vehicle B (SHA7875X)
 Violently hit the rear of my Vehicle and push it into collision
 with the vehicle C in front of me. I want to highlight that
 I never hit the Vehicle C until the Vehicle B collide into me
 Both front and back of my car are damaged I and my
 girlfriend suffer from injury and were given each
 Two days of MC

Police report attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)

Date & Time: 1 February 2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #3 Pg. 1

ANNEX E

NOTICE OF REPORTING

This is to confirm that Lee Wei Xuan (Hp: 84482885, residing at 37 Sunbird Avenue S (487347)), NRIC: S9628393H, has reported to the Police a non-injury traffic accident which occurred at PIE towards Tuas near the Upper Thomson Road exit on 31/01/2019 at about 3.30pm involving the following vehicles: SHA7875X (Comfort taxi, blue in colour), SLK37U (BMW430i, black in colour car, SLG4762D (Nissan, red in colour)

2. If accident was reported to the Police within 24 hrs of its occurrence, then he has complied with Sec 84(2) of the Road Traffic Act, Cap 276.


Rank / Name of Issuing officer: W/SSgt T091095 Farhana

Date: 01/02/2019

Time: 1155hrs

S/D Ref: 22

Police Post/ Unit: BEDOK NORTH NPC



Bedok North NPC
No. 30 Bedok North Road
Singapore 469676
Tel: 1800-2449999

Original – To be issued to informant
Duplicate- to be submitted to Traffic Police

...CLAIM SUBFOLDER...(Pending for Survey Report)






































PRI



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 May 2019 Edit Reg		12 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	YEW SWEE FONG , ID: S1812679F								
Vehicle Reg. No.:	SLK37U	Date of Loss:	31/01/2019 15:00 - :59 [19 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19010929	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA7875X	Policy No. (Claimant):							
		Excess:							
Repairer:	Tick Hai Motor (HQ) AUTOBAY#01-54, 435435 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents



















































*SLK37U (MCT19010929)
[SHA7875X]
TP
YEW SWEE FONG
Jan 31 2019 3:00PM
[-]
Tick Hai Motor
















































Upload Documents Upload Photos Compose New Letter			View View In Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/19 12:14	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
68	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
69	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
70	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
71	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
72	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
73	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
74	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
75	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
76	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
77	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
78	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
79	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
80	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
81	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
82	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
83	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
84	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
85	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
86	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
87	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
89	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
90	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
91	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
92	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
93	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
94	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
95	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
96	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
97	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
98	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
99	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
100	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
101	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
102	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
103	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
104	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
105	17/05/19 12:14	General View	 Load JPG	<input checked="" type="checkbox"/>
106	17/05/19 12:14	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
107	17/05/19 12:14	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
108	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
121	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
122	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
123	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
124	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
125	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
126	17/05/19 12:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
127	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
128	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
129	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
130	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
131	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
132	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
133	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
134	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
135	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
136	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
137	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
139	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
140	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
141	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
142	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
143	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
144	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
145	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
146	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
147	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
148	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
149	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
150	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
151	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
152	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
153	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
154	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
155	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
156	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
157	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
158	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
159	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
160	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
161	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
162	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
163	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
164	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
165	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
166	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
167	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
168	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
169	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
170	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
171	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
172	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
173	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
174	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
175	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
176	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
177	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
178	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
179	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
180	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
181	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
182	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
183	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
184	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
185	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
186	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
187	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
189	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
190	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
191	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
192	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
193	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
194	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
195	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
196	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
197	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
198	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
199	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
200	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
201	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
202	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
203	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
204	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
205	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
206	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
207	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
208	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
209	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
210	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
211	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
212	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
213	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
214	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
215	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
216	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
217	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
218	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
219	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
220	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
221	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
222	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
223	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
224	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
225	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
226	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
227	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
228	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
229	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
230	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
231	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
232	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
233	17/05/19 12:21	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
234	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
235	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
236	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
237	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
239	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
240	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
241	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
242	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
243	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
244	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
245	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
246	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
247	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
248	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
249	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
250	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
251	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
252	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
253	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
254	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
255	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
256	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
257	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
258	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
259	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
260	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
261	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
262	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
263	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
264	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
265	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
266	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
267	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
268	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
269	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
270	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
271	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
272	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
273	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
274	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
275	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
276	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
277	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
278	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
279	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
280	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
281	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
282	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
283	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
284	17/05/19 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19002557/UCD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SLK37U

Insured Vehicle No :

SHA7875X

Date of Loss: 31/01/2019

Nature of Claim:

TP

Claim No: MCT19010929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK37U**Make & Model: BMW 430i, 2.0 CONVERTIBLE MSPORT HID NAV
HUD (A)

Engine No:

F6131700B48B20B

Reg. Date: 28/06/2017 (Man. Year: 2017)

Chassis No:

WBA4V32030EA25530

Colour: Black

Odometer:

25242 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size:

225/45 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/02/2019

Date Inspected: 12/02/2019

Inspected At:

Tick Hai Motor (HQ)

AUTOBAY#01-54

Singapore 435435

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2019)
Parts:	192	BMW 430i 2.0 CONVERTIBLE MSPORT HID NAV HUD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK37U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >