

ASS. REC. BY:

REF: CS/INC19002566/R17d3^{SK}

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Daniel Koh

of

INC

Date/Time:

12/2/19 @ 10:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVT / CS

To Inspect Vehicle No.:

YN 1111 L

Insured:

SKJ 824G

at Workshop m/s

Lee Kuen Hwa Motor

Tel:

62699192

of

24 Sungai Kadut St-4

Policy No:

Claim No:

MT-1030591-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1/2/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11:43pm @ 12/2/19

Person Contacted:

Shewchen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

YN 1111 L - X

SKJ 824G-CC4-A1G13015713/M/pb3w2

DUA: 24/8/2013

lump sum \$3400/- (Red: 1997.37%/-)

Issue

REF: INC

4900E

ASSIGNMENT

Date: 12/2/19

Veh No: 4N 1111L Date Recd: 2012 Aug

Insured's Code

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OR / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Insured Vehicle No

YN 1111L

Make: ISUZU FVR 3450DC cc 2750

at Workshop no

Lee Kuan Hwa

Colour: MULTI A/C Insured / Std / NI / NA

at 24 sungai kadut st. 4

Sp. Reading: 269394 T/Radio: Insured / Std / NI / NA

Insured

Eng No

Policy No

C No: JAL FVR 347C7000 449

Claims No

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured

Excess

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or


Make of Veh

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 275 / 70R22-5

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMY

TOYO / YOKO or

Bal. or Market Value

Front

Rear

IDAC Accident Report

Consistent? : Yes or No

R/Bal: 8 mm

GIA / PR Seen

Consistent? : Yes or No

L/Bal: 8 mm

Est. Repairs

days Res: Yes or No

D.O.A. 01/02/19 D.O.I 12/02/19 2.26pm

Lump Sum

% 3 Val: Yes or No

Survey held at LEE KUAN HWA

CA / REV / REP. / 24 HRS *1up*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle IN / OUT

N/S FR

Date: Person Contacted

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 APR 2019

Date/Time: File Pass to?

☐ : Prel. Report

Days Of Repair: 5

n. 10/4 Typist

☒ Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

Survey Fee:

Transportation

Add Fee: ☐ Site Insp (\$)

☐ GPS (\$)

☐ Interview (\$)

☐ Photos

☐ Tech. Insp (\$)

☐ Other

☐ Weekend (\$)

☐

Report Format:

Lump Sum / L.B. (\$ 3400)

TOTAL

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Tuesday, 12 February 2019 10:11 AM
To: 'assignments@lkkauto.com'
Cc: Teng Ken Leong; Thio Tse Kiat
Subject: FW: TP CASES FARMED OUT TO LKK ON 12/2/2019

Dear Veron / Catherine,

Please assist to survey the vehicles as per Mr Toh's instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER	TIMING
1	SLH1636A	SJK3446B	VERMOGEN ACE / Pila 63583031	11-2-2019 / MT-1031440-001 / Muhammad Airwan	
2	EV6460R	XE783M	VOLKSWAGEN CENTRE / Edmund Goh 63057299	2-2-2019 / MT-1030828-001 / Helena Tan	10:00-12:00
3	SLU8379C	SIN6151R	CAR CRAFTERS / Jie Ren 94316186	25-1-2019 / MT-1029788-002 / Charlotte Chew	
4	SFS41K	SLF646M	C & C AUTOMOTIVE / Tay Jian Ye 81680997	25-1-2019 / MT-1029518-002 / Rajeswary	11:00-16:00
5	SMC5034A	SKW5684S	C & C FRANCE / Edwin Caina 91819978	7-12-2018 / MT-1023039-002 / Serene Lim	

6	SMA7409A	SLU7485K	HUA HONG PTE LTD / Jerleen 66619688	24-11-2018 / MT-1021408-002 / David Phua	10:00-12:00
7	YN1111L	SKJ824G	LEE KUAN HWA MOTOR / Siew Chen 62699192	1-2-2019 / MT-1030591-002 / Jeff Lin	
8	EA2318G	SHD2075E	TAN CHONG MOTOR / Lawrence Teo 64694091	23-1-2019 / MT-1029228-002 / Jared Liu	
9	SLM2790D	SHC6977G	WORLD AUTO / Ainee 63621776	4-2-2019 / MT-1031311-001 / David Phua	

Please contact workshops.

Please ack.

Thank You

Daniel Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/02/2019 17:19
Date Of Accident	01/02/2019 16:30
Exact Location Of Accident	ALONG SANJA ROAD NEAR BLK 603A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN1111L
Insured/Policyholder	
Name Of Registered Owner	SIN METAL INDUSTRIES
Co Reg No	42834900E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96865050
Vehicle Particulars	
Manufacturer	ISUZU
Model	FVR34SUQDC
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCV18S008393
Cover Note Number	
Driver	
Name of Driver	KHOO WEE PIN
NRIC No	S7790048I
Date Of Birth	25/06/1977
Occupation	OUTDOOR
Date Of Driving Pass	14/11/1995
Driving Experience	23 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96865050
Fax Number	
Contact Number	
Email Address	SBY5050S@YAHOO.COM.SG

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG SENJA RD TOWARDS 603A SENJA RD . WHEN I REVERSING INTO THE 603A SENJA RD , SUDDENLY VEHICLE B DRIVING FROM MY LEFT SIDE AND COLLIDED ONTO LEFT FRONT OF MY VEHICLE . NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ824G
Vehicle Make/Model/Colour	HYUNDAI/I30 (GD) 1.6 DOHC 6-SP AT ABS A/BAG SR/BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHU WEN SHEN
NRIC/Passport Number	S8614095J
Contact Number	91717120
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
 7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- A. Consent under the Personal Data Protection Act (PDPA)**
 I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
 REPORTING OFFICER
 JUN KEAT

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
 Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG SENJA RD TOWARDS 603A SENJA RD . WHEN I REVERSING INTO THE 603A SENJA RD , SUDDENLY VEHICLE B DRIVING FROM MY LEFT SIDE AND COLLIDED ONTO LEFT FRONT OF MY VEHICLE . NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

2 February 2019 at 2:17 PM

Date/Time:

2 February 2019 at 2:17 PM

Enquire Vehicle Registration Details

Owner Particulars	
NRIC/Passport/Company Cert No. :	42834900E
Owner ID Type :	Business
Owner Name :	SIN METAL INDUSTRIES
Registered Address :	280 WOODLANDS INDUSTRIAL PARK E5 #05-45 HARVEST @ WOODLANDS SINGAPORE 757322
Mailing Address :	-
Birth Date :	-
Vehicle Particulars	
Vehicle No. :	YN1111L
Previous Vehicle No. :	YN3236Y
Effective Date of Ownership :	10 Aug 2012
Original Regn Date :	10 Aug 2012
Registration Date :	10 Aug 2012
Year of Manufacture :	2012
Vehicle Type :	Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Scheme :	-
Vehicle Attachment 1 :	With Crane
Vehicle Attachment 2 :	-
Vehicle Attachment 3 :	-
Vehicle Make :	ISUZU
Vehicle Model :	FVR34SUQDC
Primary Colour :	White
Secondary Colour :	-
Passenger Capacity :	2
Chassis No. :	JALFVR347C7000449
Engine No. :	6HK1619531
Engine Capacity / Power Rating :	7790 cc / -
Maximum Power Output :	-
Propellant :	Diesel
Max Unladen Weight :	10740 kg
Maximum Laden Weight :	16000 kg
Open Market Value :	\$65,656.00
PARF Eligibility :	No
PARF Eligibility Expiry Date :	-
Minimum PARF Benefit :	-
No. of Transfers :	0
IU Label No. :	1510786437
COE No. :	2012080105000289C
COE Expiry Date :	09 Aug 2022
COE Category :	C - Goods Vehicle & Bus
COE Registration Category :	C - Goods Vehicle & Bus
Quota Premium (QP) / Prevailing Quota Premium :	\$55,805.00 / -
Actual QP Paid :	\$55,805.00
QP (Regn Cat) :	\$55,805.00
OPC Cash Rebate Eligibility :	No
QP during COE Bidding Exercise :	\$55,805.00
Additional Registration Fee Rate :	5.00 %
Actual ARF Paid :	\$3,283.00
Vehicle Lifespan Expiry Date :	09 Aug 2032
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message :	-

Print

OK

Save as PDF

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S77900481



Name
KHOO, WEE PIN
(QIU WEIBIN)
邱 维 斌

Race
CHINESE

Date of birth
25-06-1977

Sex
M

Country of birth
MALAYSIA




REPUBLIC OF SINGAPORE DRIVING LICENCE

Reference Number: S77900481

Name
KHOO, WEE PIN
(QIU WEIBIN)

Birth Date: 25 Jun 1977

Issue Date: 26 Feb 2018




002776707G

4093500



NRIC No. S77900481

9686 5050



Date of issue
03-09-2007

APT BLK 601A PUNGGOL CENTRAL #03-614
SINGAPORE 821601

NRIC No. S77900481 Date: 01/07/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 2B	Motorcycles $\leq$ 200 cc	15 Dec 1999
Class 2A	Motorcycles between 201 cc and 400 cc	15 Jan 2002
Class 2	Motorcycles $>$ 400 cc	25 Nov 2008
Class 3	Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg	14 Nov 1995
Class 4	Motor vehicles which are constructed to carry load or passengers and the unladen weight $>$ 2500kg	14 Dec 1999
Class 5	Motor vehicles which are not constructed to carry load or passengers and the unladen weight $\leq$ 7250kg	02 Feb 2000
	Motor vehicles not constructed to carry any load and the unladen weight $>$ 7250kg	

NP 428A



CERTIFICATE OF INSURANCE
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)


CERTIFICATE NO. DMCV18S008393	C18074888
Type of CI: Commercial Vehicle	
Cover: Comprehensive	A000588 JETTA INSURANCE AGENCY PTE LTD
1) Registration No. of Vehicle:	YN1111L
2) Name of Policyholder:	SIN METAL INDUSTRIES
3) Commencement Date of Insurance:	11/08/2018
4) Expiry Date of Insurance:	10/08/2019
5) Persons or Classes of Persons entitled to drive	
1) Any person who is driving on the Policyholder's order or permission	
Excess (Section 1) : S\$800.00	
Windscreen - Below 10 tons : S\$100.00	
Young & Inexp Drivers(Section 1) : S\$2,500.00	
6) Name of Finance Company/Hire Purchase Owner: NA	
7) Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
8) Limitations as to Use	
(1) Use in connection with the Policyholder's business	
(2) Use for carriage of passengers (other than for hire or reward) in connection with the Policyholder's business	
(3) Use for social domestic and pleasure purposes	
This Policy does not cover	
(1) Use for hire or reward, racing, pace-making, reliability trial or speed-testing	
(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle	
Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings (for Items 7 & 8).	

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Counter-signed by
 JETTA INSURANCE AGENCY PTE LTD

For and on behalf of
 ERGO Insurance Pte. Ltd.




 AUTHORIZED SIGNATURE

A000588/30/07/2018 17:32:03

NTUC 利來 4 車 12/2/19 16/2/19

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: NTUC Income Insurance Co-operative Ltd
75 Bras Basah Road NTUC Income Centre
Singapore 189557

Motor Claim Dept

Vehicle number : YN 1111 L
Make/Model : ISUZU FVR34SUQDC
Date of accident : 11.02.2019
Claim Type : TP Claim

Date: 11.02.2019
The Repaired the following:
• To resurvey before spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Accident involving YN 1111 L & SKJ 824 G along Sanja Rd Near BLK 603A
on 11.02.2019

Re: Estimate

1.	1 pc	Front step alloy panel LH <i>bro</i>	\$	159.00
2.	1 pc	Front step bracket <i>BT</i>	\$	382.00
3.	1 pc	Front step alloy inner garnish <i>MIS</i>	\$	174.00
4.	1 pc	Front step alloy small cover <i>MIS</i>	\$	12.00
5.	1 pc	Front door lower cover (outer) <i>SCA</i>	\$	283.00
6.	1 pc	Front door lamp <i>bro</i>	\$	52.00
7.	1 pc	Front door lamp inner cover <i>MIS</i>	\$	18.00
8.	1 pc	Front step panel <i>CRA</i>	\$	281.00
9.	1 pc	Front moon shape mudguard lower outer garnish <i>DE</i>	\$	218.00
10.	1 pc	Front bumper <i>BT</i>	\$	1,236.00
11.	1 pc	Front headlamp <i>CRA</i>	\$	284.00
12.	1 pc	Front headlamp bezel <i>SCA</i>	\$	51.00
13.	1 pc	Front small lamp <i>CRA</i>	\$	240.00
14.	1 pc	Front headlamp side seal <i>at</i>	\$	67.00

Rasul
HP 900100183
5 days
43
12/02/19 @ 1435
Remy after repair

To Towing Services
To Wiring Service
To Repair & Replace labour charge
To Putty & Spray Painting

15%
\$ 3,457.00 = *29387*
\$ 160.00 *X 1.1*
\$ 100.00 *50*
\$ 880.00 *700*
\$ 800.00 *600*

Total \$ 5,397.00 *42887*
-20%

李光華 摩哆燒焊
Your Faithfully,
LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

3,400
#34307

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: NTUC Income Insurance Co-operative Ltd
75 Bras Basah Road NTUC Income Centre
Singapore 189557

Motor Claim Dept

Vehicle number : YN 1111 L
Make/Model : ISUZU FVR34SUQDC
Date of accident : 11.02.2019
Claim Type : TP Claim

LEE Kuan Hwa Motor Service
the Repairer of the following:
Date: 11.02.2019
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Accident involving YN 1111 L & SKJ 824 G along Sanja Rd Near BLK 603A on 11.02.2019

Re: Estimate

1.	1 pc	Front step alloy panel LH <i>bro/</i>	\$	159.00
2.	1 pc	Front step bracket <i>bt/</i>	\$	382.00
3.	1 pc	Front step alloy inner garnish <i>mis/</i>	\$	174.00
4.	1 pc	Front step alloy small cover <i>mis/</i>	\$	12.00
5.	1 pc	Front door lower cover (outer) <i>sc/</i>	\$	283.00
6.	1 pc	Front door lamp <i>bro/</i>	\$	52.00
7.	1 pc	Front door lamp inner cover <i>mis/</i>	\$	18.00
8.	1 pc	Front step panel <i>cr/</i>	\$	281.00
9.	1 pc	Front moon shape mudguard lower outer garnish <i>de/</i>	\$	218.00
10.	1 pc	Front bumper <i>bt/</i>	\$	1,236.00
11.	1 pc	Front headlamp <i>cr/</i>	\$	284.00
12.	1 pc	Front headlamp bezel <i>sc/</i>	\$	51.00
13.	1 pc	Front small lamp <i>cr/</i>	\$	240.00
14.	1 pc	Front headlamp side seal <i>at/</i>	\$	67.00
			\$	3,457.00

To Towing Services	\$	160.00	X
To Wiring Service	\$	100.00	50
To Repair & Replace labour charge	\$	880.00	700
To Putty & Spray Painting	\$	800.00	600

Total \$ 5,397.00

李光華 摩 嘜 燒 焊
Your Faithfully,

LEE KUAN HWA MOTOR SERVICE

39, Westwood Avenue, Singapore 648719

TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19002566/R1td3s2

73 BRAS BASAH ROAD

Date: 11-04-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: JEFF LIN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 824G	Veh. Inspected	YN 1111L
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1030591-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	12/02/2019

2. Vehicle Particulars & Condition

Make & Model	ISUZU FVR34SUQDC	c.c	7790
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JALFVR347C7000449	Colour	MULTI
Odometer	269394 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	SUMITOMO	8 mm
L/H Front Tyre	275/70 R22.5	SUMITOMO	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	SUMITOMO	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	SUMITOMO	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/02/2019	Inspect Date / Time	12/02/2019 (02:26 PM)
Survey held at	LEE KUAN HWA MOTOR SERVICE 24 SUNGEI KADUT ST. 4 SINGAPORE 729050		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 1111L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT STEP ALLOY PANEL LH	BROKEN	159.00	159.00
1	FRONT STEP BRACKET	BENT	382.00	382.00
1	FRONT STEP ALLOY INNER GARNISH	MISSING	174.00	174.00
1	FRONT STEP ALLOY SMALL COVER	MISSING	12.00	12.00
1	FRONT DOOR LOWER COVER (OUTER)	SCRATCHED	283.00	283.00
1	FRONT DOOR LAMP	BROKEN	52.00	52.00
1	FRONT DOOR LAMP INNER COVER	MISSING	18.00	18.00
1	FRONT STEP PANEL	CRACKED	281.00	281.00
1	FRONT MOON SHAPE MUDGUARD LOWER OUTER GARNISH	DEFORMED	218.00	218.00
1	FRONT BUMPER	BENT	1,236.00	1,236.00
1	FRONT HEADLAMP	CRACKED	284.00	284.00
1	FRONT HEADLAMP BEZEL	SCRATCHED	51.00	51.00
1	FRONT SMALL LAMP	CRACKED	240.00	240.00
1	FRONT HEADLAMP SIDE SEAL	CUT	67.00	67.00
	LESS 15% DISCOUNT		-	-518.55
			3,457.00	2,938.45
LABOUR				
	TO TOWING SERVICES.	NOT NECESSARY	160.00	-
	TO WIRING SERVICE.		100.00	50.00
	TO REPAIR & REPLACE LABOUR CHARGE.		880.00	700.00
	TO PUTTY & SPRAY PAINTING.		800.00	600.00
			-	-
			-	-
			-	-
			1,940.00	1,350.00
GRAND TOTAL			5,397.00	4,288.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,400.00



Report Ref No. CS/INC19002566/R1td3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.