

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305265601

Date : 4. Feb. 2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHD4894U

Date of Accident: 31. Jan. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TRC940H
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less:                       
Final Lumpsum Repair cost \$3,100.00  
\$2,450.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : L. Ng  
Name : Larry Ng  
Tel : 6214 8316  
Fax : 6546 8156

Signature : NH  
Name : NAZ LKK  
Date : 21/2/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

REPAIR ESTIMATE\*

VEHICLE NO : SHD 4894U

DATE 1/2/2019 14:06

China

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 544.50
	Headlamp (LH)			\$ 1,388.00
	Front Fender (LH)			\$ 566.30
	Front Fender Shield (LH)			\$ 175.90
	Front Fender Retainer			\$ 24.60
	Frt Wheel Hub Cap,LH			\$ 107.10
	<b>SUB TOTAL</b>		2,605.90	\$ 2,806.40
	<b>LESS 20%</b>		2,084.72	\$ 561.28
	<b>DISCOUNTED TOTAL</b>			\$ 2,245.12
	Front Fender Advertisement Logo (LH)			\$ 100.00
			100	\$ 100.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring			\$ 30.00
	Tuff Kote			\$ 50.00
	Frt Wheel Alignment			\$ 80.00
	<b>TOTAL LABOUR</b>		870	\$ 1,160.00
	<b>ESTIMATE TOTAL</b>		3,054.72	\$ 3,505.12
			2,443.77	
			2,450	

? / CRK

/ SCR

/ DBF

?X SUC

?X SUC

/ SCR

Nett / NE

/

400

/ NE

40

X 22

Larry

NAZLUK

1/2/19 1715

LIS

3 DAYS

CHECK ITEMS &amp; NOTES

AFTER REPAIR PHOTOS.

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.