

Rafael

REF: MSG

1665w

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. **SLZ 81L**

at Workshop no/s **Performance Motor**

of **303 Alexandra Rd**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: **1000**

(Client's Record)

Make of Veh: _____

After 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **299K**

IDAC Accident Report: Consistent?: Yes or No


GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: **SLZ 81L** Yt Regn: **2018** **April**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **B.M.W 540I** c.c: **2998**

Colour: **BLACK** A/C: Insured / Std / NI / NA

Sp. Reading: **32660** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WBAJB320X0 6460089**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modt: Nil / R/Rim / STD A/Rim or

Tyre Size: F: **245/35R20**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal:	6 mm	R/Bal:	6 mm
L/Bal:	6 mm	L/Bal:	6 mm
D.O.A:	11/02/19	D.O.I:	18/02/19

Survey held at: **PERFORMANCE**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR & N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 2 APR 2019

Date/Time File Pass to? Preli. Report

114 Typast Final Report

Date/Time File Return to? _____

Days Of Repair: **6**

Resurvey No. of Trip: **1**

Add Fee: Site Insp (\$)

Interview (\$)

Tech Days (\$)

Weekend (\$)

Survey Fee: _____

Transportation: _____

Other: _____

TOTAL: _____

Report Format: **DD**

Lump Sum / U/C: (\$) **8685.19**

200
10
210