

ASS. REC. BY

REP

CS/CTI19002642/Rld302

Special Instruction

SMV Ver/01

RASH

ASSIGNMENT (Office)

From (Person)

Cheng Bun Sen

of

CTI

Date/Time

13/2/19 @ 1:40pm

Estimated Cost

Bill to

OD / (P) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 1282Y

Insured

SJK 3744R

at Workshop m/s

FALCON AIR

Tel:

6799 5665

of

8 penden loop (BKK)

Policy No:

PMPCSN 3071818000

Claim No:

SNM19D2 00717 002

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/12/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time

2:59pm 13/2/19

Person Contacted

Andy

Vehicle IN / (P)

Date/Time

Action/Instruction (✓) Estimate

SLF 1282Y-X

SJK 3744R-X

25/10/19

Submit PRS.

REF: CTI

## ASSIGNMENT

From:

Date:

25/2/19

Estimated Cost:

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLF 1282Y

At Workshop no:

at BLK 116, Bkt Batok west Ave 6

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3pm

Dominic @ 9657 4114

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLF 1282Y

At Page:

15/03/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA VEZEL

Colour:

BLACK

Sp Reading:

031227

Eng/No:

C/No:

RM1115043

Gen Cond: Good / Fair / Poor / Burnt

Steering: Locked / Jammed / Leaked / Burnt or

Brake: Locked / Jammed / Leaked / Burnt or

Modt: Nil / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

30/12/18

D.O.I.

25/02/19

Survey held at

116, BUKIT BATOK WEST AVE 6

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Range of Repair / days - 3k-4k / 5 days

RECEIVED 5 OCT 2019

Date/Time, File Pass to?



Preli. Report

1) 25/10 11:55 AM



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S / RS / ST

) Photo

) Other

) Total

Total

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Weekend (\$)

Report Format:

PPS -

Lump Sum / L.B.L. (%)

190
190

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Wednesday, 13 February 2019 1:40 PM  
**To:** assignments  
**Subject:** FW: OUR REF: SNM19D200717 / SLF1282Y CLAIMING TP AGAINST SJK 3744R DOA: 30.12.18

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Wednesday, 13 February 2019 1:07 PM  
**To:** ANDY <andy@falconair.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: OUR REF: SNM19D200717 / SLF1282Y CLAIMING TP AGAINST SJK 3744R DOA: 30.12.18

Without Prejudice

Dear Andy,

Will appoint accordingly.

Dear LKK,

Pls pri.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** ANDY [mailto:andy@falconair.com.sg]  
**Sent:** Wednesday, 13 February, 2019 12:17 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D200717 / SLF1282Y CLAIMING TP AGAINST SJK 3744R DOA: 30.12.18

Dear Chong Boon Sen

Kindly appoint Marcus Chua for this case

Best Regards  
Andy

---

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]  
**Sent:** Wednesday, February 13, 2019 11:55 AM  
**To:** ANDY <andy@falconair.com.sg>  
**Cc:** Falcon-Air Pandan <pandan@falconair.com.sg>  
**Subject:** OUR REF: SNM19D200717 / SLF1282Y CLAIMING TP AGAINST SJK 3744R DOA: 30.12.18

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Insured yet to report and we unable advise liability.**

Thank you.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

## Rasul (LKKAUTO)

---

**From:** ANDY <andy@falconair.com.sg>  
**Sent:** Friday, 18 October, 2019 3:06 PM  
**To:** Rasul (LKKAUTO)  
**Subject:** RE: SLF 1282Y DOA : 30/12/18

Bro

This case claimed OD

Thanks  
Andy

---

**From:** Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]  
**Sent:** Friday, October 18, 2019 3:02 PM  
**To:** ANDY <andy@falconair.com.sg>  
**Subject:** SLF 1282Y DOA : 30/12/18

Hi Andy,

Any update

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2693D
Vehicle Details	
Vehicle No.:	SLF1282Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4035043
Chassis No.:	RU11115043
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,054.00
Original Registration Date:	15 Aug 2016
First Registration Date:	15 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$10,076.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2026
PARF Rebate Amount:	\$7,557.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,503.00
COE Rebate Amount:	\$38,855.00
<b>Total Rebate Amount:</b>	<b>\$46,412.00</b>

The information contained herein is correct as at 20 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/12/2018 09:43
Date Of Accident	30/12/2018 20:20
Exact Location Of Accident	JLN BUKIT MERAH SLIP RD /ALEXANDAR RD JUNC TWD AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF1282Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DOMINIC JOSEPH
NRIC No	S2682693D
Email Address	DOMINIC.KOYAPPILLIL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96574114
Alternative Phone No	OFFICE-96574114

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00210102
Cover Note Number	

### Driver

Name of Driver	DOMINIC JOSEPH
NRIC No	S2682693D
Date Of Birth	24/05/1965
Occupation	INDOOR
Date Of Driving Pass	23/08/1996
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96574114
Fax Number	
Contact Number	OFFICE-96574114
Email Address	DOMINIC.KOYAPPILLIL@GMAIL.COM



Address	BLK 116 BUKIT BATOK WEST AVE 6 #02-234
Postcode	650116
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : SPOUSE GENDER: : FEMALE
Passenger 2	NAME: : SON GENDER: : MALE
Passenger 3	NAME: : SON GENDER: : MALE
Passenger 4	NAME: : DAUGHTER GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLANS

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK3744R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Sketch Plan Pg. 2**

### SKETCH PLAN

SKETCH PLAN

Alexandra Rd TOWN CITY

Queens way

Jln Bukit Merah

A: SLF 1282Y

B: SUK ~~1282~~  
3744R

stop-line

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ALEXANDRA RD FROM AYE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT ALEXANDRA RD FROM AYE

Accident happened at the slip-road from Jln Bukit Merah toward Alexandra Rd (toward AYE).

I was travelling along Alexandra Rd toward AYE when suddenly vehicle 5JK 3744 R emerged from the Jln Bukit merah slip road (on my left) and collided on to the left side of my vehicle.

Vehicle 5JK 3744 R failed to stop at the stop-line before proceeding on to Alexandra Rd.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





FALCON-AIR

DOMINIC JOSEPH  
BLK116 BUKIT BATOK WEST AVE6  
SINGAPORE 650116

Attention : Motor Claim Department  
Contact : 90705031

**FALCON-AIR AUTO SERVICES PTE LTD**

CO. REG. NO.: 1995-01140-D  
GST REG. NO.: 19-9501140-D

Estimate : ES003360

Date : 02/01/2019  
Vehicle Num. : SLF1282Y  
Make/Model : HONDA VEZEL-2016  
Chassis/Eng# : RU11115043  
Accident Date : 31/12/2018  
Claim No. :  
Reference : TP CLAIM - ECICS vs  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1 PC	LH CORNER PANEL		215.00
2.	1 PC	LH REAR WHEEL ARCH GARNISH		170.60
3.	1 PC	LH REAR DOOR		1,030.60
4.	1 SET	LH REAR DOOR BLACK TAPE		38.00
		List TotalS\$ :		1,454.20
		20.00% Discount S\$ :		290.84
				1,163.36
1.	1 PC	SPECIAL NETT ITEMS :		
		LH REAR RIM - 16"		765.00
		Special Nett Total S\$ :		765.00
		LABOUR :		
		TO TRANSFER DOOR PARTS/MECHANISMS		80.00
		TO TRANSFER TYRE TO NEW RIM AND BALANCING		50.00
		TO STRAIGHTEN REAR FENDER INNER PANEL, REAR BUMPER		500.00
		LH FRONT DOOR, INCLUDING REPLACEMENT OF PARTS		
		TO SPRAY PAINT LH FRONT DOOR, LH REAR DOOR, LH REAR		800.00
		CORNER PANEL, REAR BUMPER		
		Labour Total S\$ :		1,430.00

E. & O.E.

Total S\$ : 3,358.36



for FALCON AIR AUTO SERVICES PTE LTD

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Oct 2019		25 Oct 2019 15:08 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>DOMINIC JOSEPH</b> , ID: S2682693D									
Vehicle Reg. No.: <b>SLF1282Y</b>		Date of Loss: 30/12/2018 20:00 - :59 [28 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D200717C02</b>		Policy/Cover Note No.: DMPCSN30711818000							
Vehicle Reg. No. (Insured): <b>SJK3744R</b>		Policy No. (Claimant): MPC18A00210102							
		Excess: S\$0.00							
Repairer: <b>Falcon-Air Auto Services Pte Ltd (Pandan)</b> No 8 Pandan Loop, Clementi - Tel:									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 06/11/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLF1282Y (SNM19D200717C02)  
[SJK3744R]

TP

DOMINIC JOSEPH

Dec 30 2018 8:00PM

[-]

Falcon-Air Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	31/12/18 09:56	Accident Statement		Load HTM	
2	20/06/19 08:39	Addendum Sheet		Load TIF	
3	20/06/19 08:41	Accident Statement Addm. #1		Load HTM	

Photos/Images

3 per page

No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	31/12/18 09:52	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	31/12/18 09:52	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	31/12/18 09:52	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	31/12/18 09:52	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	31/12/18 09:52	Accident Photo [Linked Accident Report Documents]		Load JPG	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/10/19 15:13	Odometer Reading		Load JPG	
2	25/10/19 15:13	Chassis Number		Load JPG	
3	25/10/19 15:13	General View		Load JPG	
4	25/10/19 15:13	General View		Load JPG	
5	25/10/19 15:13	General View		Load JPG	
6	25/10/19 15:13	General View		Load JPG	
7	25/10/19 15:13	General View		Load JPG	
8	25/10/19 15:13	General View		Load JPG	
9	25/10/19 15:13	General View		Load JPG	
10	25/10/19 15:13	General View		Load JPG	
11	25/10/19 15:13	General View		Load JPG	
12	25/10/19 15:13	General View		Load JPG	
13	25/10/19 15:13	General View		Load JPG	
14	25/10/19 15:13	General View		Load JPG	
15	25/10/19 15:13	General View		Load JPG	
16	25/10/19 15:13	General View		Load JPG	
17	25/10/19 15:13	General View		Load JPG	
18	25/10/19 15:13	General View		Load JPG	
19	25/10/19 15:13	General View		Load JPG	
20	25/10/19 15:13	General View		Load JPG	
21	25/10/19 15:13	General View		Load JPG	
22	25/10/19 15:13	General View		Load JPG	
23	25/10/19 15:13	General View		Load JPG	
24	25/10/19 15:13	General View		Load JPG	
25	25/10/19 15:13	General View		Load JPG	
26	25/10/19 15:13	General View		Load JPG	
27	25/10/19 15:13	General View		Load JPG	
28	25/10/19 15:13	General View		Load JPG	
29	25/10/19 15:13	General View		Load JPG	
30	25/10/19 15:13	General View		Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
31	25/10/19 15:13	General View		Load JPG	<input checked="" type="checkbox"/>
32	25/10/19 15:13	General View		Load JPG	<input checked="" type="checkbox"/>
33	25/10/19 15:13	General View		Load JPG	<input checked="" type="checkbox"/>
34	25/10/19 15:13	General View		Load JPG	<input checked="" type="checkbox"/>
35	25/10/19 15:13	General View		Load JPG	<input checked="" type="checkbox"/>
36	25/10/19 15:13	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	31/12/18 09:52	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	31/12/18 09:52	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	

## Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	31/12/18 09:56	Accident Statement		Load HTM	
2	20/06/19 08:39	Addendum Sheet		Load TIF	
3	20/06/19 08:41	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	31/12/18 09:52	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	31/12/18 09:52	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	31/12/18 09:52	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	31/12/18 09:52	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	31/12/18 09:52	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)		Thumbnail	Print
1	31/12/18 09:52	Sketch Plan		Load TIF	
2	31/12/18 09:52	Sketch Plan #2		Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19002642/R1QD3E2

Date: 29/10/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30711818000

Claimant Vehicle No: SLF1282Y Insured Vehicle No: SJK3744R

Date of Loss: 30/12/2018 Nature of Claim: TP Claim No: SNM19D200717C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLF1282Y

Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A) Engine No: L15B4035043

Reg. Date: 15/08/2016 (Man. Year: 2016) Chassis No: RU11115043

Colour: Black Odometer: 31227 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 25/10/2019

Date Inspected: 25/02/2019 Inspected At: Falcon-Air Auto Services Pte Ltd (Pandan)  
No 8 Pandan Loop  
Singapore 128226

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLF1282Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >