

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/02/2019 15:12
Date Of Accident	05/02/2019 12:35
Exact Location Of Accident	532 BEDOK NORTH STREET 3, SINGAPORE 460532
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD4412T
-----------------------------	----------

### Insured/Policyholder

Name Of Registered Owner	SHEO BOON CHEW WINSON (XIAO WENZHO, WINSON)
NRIC No	S7734933B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96998304
Alternative Phone No	Office-93676368

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER 2.0I-L
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800099562
Cover Note Number	

### Driver

Name of Driver	SHEO BOON CHEW WINSON (XIAO WENZHO, WINSON) WINS
NRIC No	S7734933B
Date Of Birth	24/11/1977
Occupation	INDOOR
Date Of Driving Pass	13/08/2003
Driving Experience	15 YEARS AND 5 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-96998304
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	17A TELOK BLANGAH CRESCENT #06-274 SINGAPORE
Postcode	091017
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : Wai Hui Peng Gender: : Female
Passenger 2	Name: : Sheo Chiong Teng Gender: : Female
Passenger 3	Name: : Sheo Chiong Ru Gender: : Male

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

#carpark Moving in/ out of parking lot & Going straight SHB1002H SMD4412T WSVC19000274 Accident\_Description Was parking for CNY visiting at the public carpark behind Blk 532 Bedok North Street 3. Had just reversed into a parking lot beside a lorry GBE8843G on my right. Needed to adjust my vehicle in the lot so I switched to drive mode from reverse gear. As there is a lorry on my right I inched forward slowly relying on the drive mode without stepping on the accelerator while looking out for any vehicle from the right side. The next moment a taxi SHB1002H sped pass from my right side across my vehicle dislodging my front vehicle license plate in the process. As my vehicle was on drive mode and my feet on the brake as I was prepared to stop I stopped my vehicle in the nick of time. My front tyre is barely out of the parking lot. The taxi did not stop till much later. The taxi was moving easily more than 40kmh much faster than a normal carpark speed as it sped pass quickly from the right and the driver only stopped the vehicle 5 to 10 metres away. I think he did not exercise due caution as he approached the lorry given the

blind spot. This is probably why he did not stop or is even prepared to stop as he approached the lorry. He did not slow down. Had I not stopped my car in time given it is slow drive mode speed there would have been a full collision between both vehicles. No other damage on my car other than the dislodged vehicle license plate. The taxi driver did not even noticed my car beside the lorry. He realised it only much later explaining why he only stopped much later.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB1002H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

### Sketch Plan



Accident Photo



Accident Photo



Accident Photo





Accident Photo





Driving License

**REPUBLIC OF SINGAPORE** **DRIVING LICENCE**

Licence Number: **S 7734933 B**

Name: **SHEO BOON CHEW, WINSON**  
**(XIAO WENZHOU, WINSON)**


Birth Date: **24 Nov 1977**

Issue Date: **13 Aug 2003**




 **000743706A**

Driving License



Identification Card



Identification Card

