



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190300103
Date : 08.03.2019
Vehicle No. : SHB1002H
Your Ref No. : TAX/02/19/2023
Our Ref No. : 24100010
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
Parts					
COVER, FR BUMPER	1.00	\$ 495.50	(100.00)	\$ 495.50	\$ 0.00
SUPPORT, FR BUMPER LH	0.00	\$ 82.30	0.00	\$ 0.00	\$ 0.00
FENDER SUB-ASSY, FR , LH	1.00	\$ 933.10	(100.00)	\$ 933.10	\$ 0.00
EMBLEM, SIDE PANEL (HYBRID)	1.00	\$ 52.90	(25.00)	\$ 13.22	\$ 39.68
WHEEL, DISC	0.00	\$1555.10	0.00	\$ 0.00	\$ 0.00
TYRE	0.00	\$ 126.74	0.00	\$ 0.00	\$ 0.00
PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1249.60	(100.00)	\$1249.60	\$ 0.00
STICKER DECAL SMRT (DOOR)	1.00	\$ 60.00	0.00	\$ 0.00	\$ 60.00
PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1243.90	(100.00)	\$1243.90	\$ 0.00
PIXEL STICKER	2.00	\$ 60.00	0.00	\$ 0.00	\$ 120.00
PANEL SUB-ASSY, FENDER REAR LH	1.00	\$ 824.80	(100.00)	\$ 824.80	\$ 0.00
COVER, RR BUMPER ASSY	1.00	\$ 423.90	(100.00)	\$ 423.90	\$ 0.00
PAD, RR BUMPER, RH & LH , 1	0.00	\$ 3.80	0.00	\$ 0.00	\$ 0.00
PAD, RR BUMPER, RH & LH , 2	0.00	\$ 3.80	0.00	\$ 0.00	\$ 0.00
PAD, RR BUMPER, RH & LH , 3	0.00	\$ 3.80	0.00	\$ 0.00	\$ 0.00
SEAL, RR BUMPER ARM, RH & LH	0.00	\$ 11.00	0.00	\$ 0.00	\$ 0.00
MOULDING ASSY, BODY ROCKER PANEL , LH	0.00	\$ 576.00	0.00	\$ 0.00	\$ 0.00
WHEEL, DISC	0.00	\$1555.10	0.00	\$ 0.00	\$ 0.00
TYRE	0.00	\$ 126.74	0.00	\$ 0.00	\$ 0.00
Sub-Total					\$ 219.68
Labour					
TO REPAIR RH PORTION	1.00	\$1000.00	0.00	\$ 0.00	\$ 1000.00

Others

Authorised Signature
for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190300103
Date : 08.03.2019
Vehicle No. : SHB1002H
Your Ref No. : TAX/02/19/2023
Our Ref No. : 24100010
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
TO REPSRAY FRONT BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY FRONT FENDER LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY RIM	0.00	\$ 360.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FRONT DOOR LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO REPSRAY REAR DOOR LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY REAR FENDER LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY REAR BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY ROCKER PANEL MOULDING	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO CHECK WIRING AND SYSTEM FUNCTION	0.00	\$ 80.00	0.00	\$ 0.00	\$ 0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	0.00	\$ 240.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE AND REFIT TYRE	0.00	\$ 240.00	0.00	\$ 0.00	\$ 0.00
TO TRANSFER DOOR MECHANISM	0.00	\$ 240.00	0.00	\$ 0.00	\$ 0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$ 0.00	\$ 0.00
TO REPLACE SUNDRY PARTS	0.00	\$ 100.00	0.00	\$ 0.00	\$ 0.00
GRAND TOTAL					\$ 2,469.68

Remark :

Make/Model : PRIUS4
Accident Date : 05.02.2019

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorized Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/02/19/2023

From: SMRT Taxis Pte Ltd

Date: 15/02/2019


**ACCIDENT INVOLVING SHB 1002H & SMD 4412T ON 5/2/2019 AT THE CAR PARK
OF BLOCK 534 BEDOK NORTH STREET 3**

This is to confirm that the daily rental rate for SHB 598L is \$112.35 per day.

Please proceed to recover any rental loss from the third party as a result of the
above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 01/02/2019

Accident End Date : 06/03/2019

Date Generated : 06/03/2019

User Name : LeeGek

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/02/19/2023	SHB1002H	SMRT Taxis Pte Ltd	TOYOTA	PRIUS4	24100010	05/02/2019 3:32 PM	16/02/2019 9:21 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2019 13:08
Date Of Accident	05/02/2019 12:30
Exact Location Of Accident	CAR PARK OF BLK 534 BEDOK NORTH ST 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1002H
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	TAXI
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TAN WEE LIANG
NRIC No	S1818567I
Date Of Birth	20/01/1967
Occupation	OUTDOOR
Date Of Driving Pass	06/10/2004
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	77
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG THE CAR PARK OF BLK 534 BEDOK NORTH ST 3 AFTER DROPPING OFF A PASSENGER. SUDDENLY A CAR NO. SMD 4412T CAME OUT FROM THE PARKING LOT AND COLLIDED WITH MY TAXI.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD4412T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Bedok North St 3
car park of Bk 534

Ⓐ SHB 1002H
Ⓑ SMD 4412T

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.



in every re

k



SINGAPORE POLICE FORCE



T/20190207/7010

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190207/7010

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/02/2019 16:13		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN WEE LIANG			Address: APT BLK 732 WOODLANDS CIRCLE #10-77 SINGAPORE 730732		
ID Type / ID No.: NRIC NO / S1818567I			Contact No.: Home/Office: Mobile: 93881841		
Nationality: SINGAPORE CITIZEN			Email: desmondtan7773@gmail.com		
Sex: Male	Age: 52	Date of Birth: 20/01/1967	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/02/2019 12:30	Type of Location: Straight Road
Location: BEDOK NORTH STREET 3 (Open Space Carpark)				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 20 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB1002H	Car	TOYOTA	Prius	Maroon	Slightly Damaged	0
SMD4412T	Car	SUBARU		Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190207/7010

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190207/7010

CONTINUATION OF REPORT

Driver				
Name	TAN WEE LIANG		ID No.	S18185671
Related Vehicle	SHB1002H (Car)		Contact No.	93881841
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	07/02/2019		Date Discharge	07/02/2019
No. of Days granted Medical Leave	05		Degree of Injury	Slight
Driver				
Name	SLOW		ID No.	NIL
Related Vehicle	SMD4412T (Car)		Contact No.	96998304
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 05/02/2019 at about 12.30 p.m., I was driving my SMRT Maroon taxi, SHB1002H, at the open space carpark near Blk 534 Bedok North Street 3.

While I was driving, out of a sudden, there was a black Subaru car, SMD4412T, came out from its parking lot, and had collided to the left side of my taxi. The driver did not slow down or stop his car to check on oncoming vehicles, as there was a lorry parked beside the car, and that his view and blindspot blocked. I was unable to avoid the collision.

Due to the collision, there was a long dent and scratch from the left rear side bumper to left front side bumper. The damage was caused by the car's plate number. Both of us had exchanged our contact numbers and left the place. The driver told me to settle the issue via insurance claiming. Both of us had taken photographs of the damages.

On 07/02/2019, I had gone to Mount Alvernia Hospital and was given 5 days Medical Certificate (MC) due to pain on my neck, shoulder and backbone.



**SINGAPORE
POLICE FORCE**



T/20190207/7010

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190207/7010

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
MOHAMAD ZULFAZDLI BIN ABDULLAH
Contact No.: 65476204

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
07/02/2019 16:13

Classification Of Case:



Enquire Transaction History

Transaction History Details

Log Date/Time:	08 Feb 2019 / 14:01:54	Transaction Amount:	\$7.49
Asset Type:	Vehicle	Channel:	External Agency
Asset ID:	SMD4412T	Business Transaction Reference No.:	20190208140154224307
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)		
User ID:	ESASBAHO - BALQISH BINTE ABDUL HALIL		
Search Date / Time:	05 Feb 2019 12:30:00		
Insurance Company:	AIG ASIA PACIFIC INSURANCE PTE. LTD.		

Information displayed is correct as at the log date and time.

Enquire

[Enquire Related Logs](#)[Back to List](#)

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire

Enquire