

22/03/2002

ASS. REC. BY:

REF

es3/1pc19002648/Byd3^{s2}

Special Instruction:

Surveyor:

Mr Lim

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

13/2/19 @ 9.47am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 9936D

Insured:

SJB 56K

at Workshop m/s

H.L. Cycle

Tel:

9748 9940

of

1 Kaki Blk Ave 6 #02-58/60

Policy No:

Claim No:

19/19/19/VP05/021398

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/02/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10.41am @ 13/2/19

Person Contacted:

Mr Tan

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FBL 9936D-X
	SJB 56K-X
28/2/19	Submit PRS.

REF: **IPC****PRS**

ASSIGNMENT

From: Date: **13/2/19**

Estimated Cost:

OD **TP** / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: **FBL 9936D**at Workshop m/s: **H.L. Cycle**of **1 Kaki Bkt Ave 6 # 02-58/60**
Antobay

Insured:

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Vch:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: **3** days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **up**

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: **FBL 9936D** Yr Regn: **8/6/20A**Type: M/Car / **M/Cycle** / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **YAMAHA** YZF-R3 C.C. **321**Colour: **BLUE** A/C: Insured / Std / NI / NASp. Reading: **29044** T/Radio: Insured / Std / NI / NAEng/No: **H402E0047511**C/No: **MH3RHO71000006547**Gen. Cond: Good / **Fair** / Poor / BurntSteering: **Inorder** / Jammed / Leaked / Burnt orBrake: **Inorder** / Jammed / Leaked / Burnt orModi: Nil / **S/Rim** / STD A/Rim orTyre Size: F: **110/70R17**R: **150/60R17**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / **PIR** / SUMI /TOYO / YOKO or **Diablo** (Rear)

Front

Rear

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. mm L/Bal. mm

D.O.A. **1/2/2019**D.O.I. **13/2/19 2.01pm**Survey held at **HL Cycle**Des. of Damages: Frt / Rear / O/S / **W/S** / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 28 FEB 2019

MV 9,000/2
PV 5,051/2
NV 3,950/2

Date/Time, File Pass to?

☐
☐

Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) S + RS SI

) Photos

) Others

Report Format: **PRS**

Lump Sum / I.B.I. (\$)

TOTAL