

Surveyor

ASSIGNMENT (Office)

CWS

From (Person)

Eileen Lee

of

FCI

Date/Time

3:33pm 12/2/19.

Estimated Cost

Bill to:

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

3KT1259D

Insured

SHA 3838E

at Workshop m/s

Cycle & Carriage Kien
209 Pandeh Gardens

Tel:

65684501

of

Policy No.

Claim No.

D19000959MFSH

Sum Insured

Excess:

Make of Veh:

D.O.A

5/02/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

11:01am 13/2/19

Person Contacted:

Tay

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	3KT1259D - X
	SHA 3838E - X
08/2/19	Email preli revised to FCI
22/4/19	Final fig \$2756 confirmed by email (Ref 2070, 4370)

Tanaka

REF:

FCI

S/CT/259D

2015 May

From: _____ Date: _____

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To: (to post Vehicle No)

at Workshop no:

ed:

Insured:

Policy No:

Claims No:

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PP Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: _____

Veh No: _____ Page: _____

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: W9 Forte 1591

Colour: Car & S/ne A/C Insured / Std / NI / NA

Sp Reading: 42399 T/Radio: Insured / Std / NI / NA

Eng/No: KN1AF741MF54.04380

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/40R17 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstone

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 6 D.O.I. 26/2/19 0700 pm

Survey held at: C&C Pankaj

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 22 APR 2019

Date/Time: File Pass to: ☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to:

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transportation

Add Fee: ☐ Site Insp. - \$

☐ Interview - \$

☐ Transport - \$

☐ Workshop - \$

☐ 1st Trip

☐ 2nd Trip

☐ 3rd Trip

2014- typist

Report Format: cws

Lump Sum / LB for: p/p \$275612

135
50
50
25
260



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000959MFSH

Our ref: CS/FCI19002650/T1vd3

Date: 28/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SKT 1259D


We thank you for your instruction on 12/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/2/2019 at the premises of M/s CYCLE & CARRIAGE KIA PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,826.00
Revised Estimate Amount	: S\$2,316.00
"Check" Items Amount	: S\$530.00
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-02-2019	Our Ref No. D19000959MFSH
Accident Date	05-02-2019	Claim Type. Third Party
Insured Vehicle	SHA3838E	Third Party Vehicle. SKT1259D
Survey Location	209 PANDAN GARDENS	
Contact Person.	TAY JIAN YE	
Contact No.	65684567/ 0	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE KIA PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 22 April 2019 1:36 PM
To: Loi Ai Ting
Cc: Songcuan JR Lauro Araos; Andre Chow En De; Cheng Jo Jo; Tay Jian Ye; SUR
Subject: RE: SKT1259D, finalisation (Kia WIP: 44178) - photos

Dear Ai Ting,

WITHOUT PREJUDICE

Confirmed finalize amount \$2756 @ 3 working days.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>
Sent: Thursday, 18 April 2019 6:49 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>
Subject: SKT1259D, finalisation (Kia WIP: 44178) - photos

Hi, Veron,

Please confirm finalised amount at \$2,948.92.

Attached some photos for your reference.

Thanks.

Best Regards,

Loi Ai Ting
Customer Service Advisor

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4556 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Thursday, 18 April, 2019 5:44 PM

To: Don Bong Kiong Hua; Tay Jian Ye; Loi Ai Ting; Songcuan JR Lauro Araos; Coco Lu Ting; Andre Chow En De; Cheng Jo Jo

Subject: RE: PENDING FINALISE (3 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLP 8838X-DOA: 24/1/2019 (CHINA TAIPING TP)
- 2) SKT 1259D-DOA: 6/2/2019 (FCI TP)
- 3) SLS 3974C-DOA: 26/2/2019 (CHINA TAIPING TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 27 March 2019 1:34 PM

To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Tay Jian Ye (jianye.tay@cyclecarriage.com.sg) <jianye.tay@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; 'Songcuan JR Lauro Araos' <lauro.songcuan@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Cheng Jo Jo (jojo.cheng@cyclecarriage.com.sg) <jojo.cheng@cyclecarriage.com.sg>

Subject: PENDING FINALISE (4 VEHICLES)

Dear All,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

- 1) SLP 8838X-DOA: 24/1/2019 (CHINA TAIPING TP)
- 2) SMF 8728X-DOA: 2/1/2019 (CHINA TAIPING TP)
- 3) SKT 1259D-DOA: 6/2/2019 (FCI TP)
- 4) SLM 2369M-DOA: 19/1/2019 (CHINA TAPING TP)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Tay Jian Ye

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 12 February, 2019 3:33 PM
To: Tay Jian Ye
Cc: CWS Motor Claims; Eileen Lee
Subject: SURVEYOR APPOINTED; OUR REF : D19000959MFSH ; YOUR REF: SKT1259D

Dear Sir/Madam

PRI Request For **SKT1259D** Accident Involving **SHA3838E** On 05-02-2019 AT 18:40:00HRS.

Please find below details for your reference

- **Claim number :** D19000959MFSH
- **Insured vehicle number :** SHA3838E
- **Accident date :** 05-02-2019
- **Third-party vehicle number :** SKT1259D
- **Assignment type :** DIRECT SETTLEMENT
- **Surveyor :** LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge :** EILEEN LEE

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 28 February 2019 8:30 AM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000959MFSH/1, SKT 1259D
Attachments: SKT 1259D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKT 1259D
Date of survey: 26/2/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 13 February 2019 11:23 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000959MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 12 February 2019 3:33 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000959MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00005583 (Comprehensive - Classic Plan)

Car plate number: SKT1259D

Your name (As the policyholder): Teo Huei Huei Engel

Coverage start date: 25/05/2018

Coverage end date: 24/05/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: DBS Bank Ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 20/04/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8588
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8526269F



Name

TEO HUEI HUEI, ENGEL

張惠惠

Race

CHINESE

Date of birth

12-08-1985

Country/Place of birth

SINGAPORE

Sex

F



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S8526269F

Name

TEO HUEI HUEI, ENGEL

Birth Date 12 Aug 1985

Issue Date 16 Nov 2004



5524369



Sub No: S8526269F

Date of issue

04-09-2015

Address

APT BLK 138A LORONG 1A TOA PAYOH
#11-10
SINGAPORE 311138


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

16 Nov 2004

Class 3

Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers,
exclusive of the driver; and motor tractors
/vehicles $\leq$ 2500 kg



Licence No: S8526269F

NP 428A



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Teo Huei Huei, Engel Blk 138a Lorong 1a Toa Payoh #11-10 311138 Contact No	Cust No/Name	LCV04073/TEO HUEI HUEI, ENGEL
	Reg No/Reg Date	SKT1259D / 25/05/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MF5404380
	Engine No	G4FGFH768049
	Make/Model	KIA/15MY F K3 1.6 A SX 690 BLACK
	Colour/Trim	M9Y / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV04073	CRDVCH	08/02/2019/ 12:34		465 / Tay Jian Ye	44178

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER, REPAIR END PANEL				✓ 530 1650.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, END PANEL X				✓ 420 1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
E PNT88000 TO TRANSFER REAR PARKING SENSOR TO NEW PART				✓ 60.00
M SUNDRY TO APPLY ANTI CORROSION				17x 40.00
M SUNDRY SUNDRIES				✓ 20.00 ncc
M STAY-RR BUMPER LH	1.00	75.00	00.00	75.00 ✓
M STAY-RR BUMPER RH	1.00	75.00	00.00	75.00 XAN
M BEAM-RR BUMPER	1.00	365.00	00.00	BT 365.00 ✓
M BRACKET-RR BEAM LWR,CTR	1.00	5.00	00.00	5.00 XAN
M BRACKET-RR BEAM LWR MTG	2.00	5.00	00.00	10.00 XAN
M COVER-RR BUMPER	1.00	791.00	00.00	de 791.00 ✓
M COVER-RR BUMPER,UPR	1.00	245.00	00.00	de 245.00 ✓

SURVEYOR NAME: Tan JieSURVEYOR SIGNATURE: [Signature]DATE: 26/2/19REMARKS: WP' Resurvey before paint
surcl/handown
03days

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification (s) is allowed
- Supplier's price is subject to confirmation

	Nett	4,826.00
7% GST on	4826.00	337.82
Total Payable		5,163.82

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Surveyor : TAUFIKH LKK
 Company : TP MS FIRST CAP
 Emailed : 18/04/19, 6.50pm
 Date survey : 26.02.2019

VEHICLE NO : SKT 1259 D
 MODEL : KIA K3 1.6 A SX
 WIP : 44178

Material	:	\$	<u>1,476.00</u>
Labour	:	\$	<u>1,280.00</u>
Sub-Total	:	\$	<u>2,756.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>2,756.00</u>
GST 7%	:	\$	<u>192.92</u>
Grand Total	:	\$	<u>2,948.92</u>
Finalise By/Date	:	<u>LOI / 18/04/2019</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 3 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 5

☒ TP claim SHA3838E

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : NR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited Motor Claims Department 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name LCV04073/TEO HUEI HUEI, ENGEL Reg No/Reg Date SKT1259D / 25/05/2015 Date In/Mileage 27/02/2019/ 42399 Chassis/Package KNAFZ411MF540438C /KCX17 Engine No G4FGFH768049 Make/Model KIA/15MY F K3 1.6 A SX 690 BLACK Colour/Trim M9Y / WK
26/02/	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	18/04/2019/ 18:27	TLT	260 / AiTing	44178			
Description of Goods/ Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 550.00
E PNT98000 RESPRAY ON REAR BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 420.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 200.00
E PNT88000 TRANSFER REAR PARKING SENSOR TO NEW PANEL								✓ 60.00
M SUNDRY SUNDRIES								✓ 20.00
X	STAY-RR BUMPER LH				1.00	75.00	00.00	75.00
X	BEAM-RR BUMPER				1.00	365.00	00.00	365.00
X	COVER-RR BUMPER				1.00	791.00	00.00	791.00
X	COVER-RR BUMPER,UPR				1.00	245.00	00.00	245.00
Z TEXT TP CLAIM FIRST CAPITAL SHA3838E DOA : 05.02.19 SURVEYOR TAUFIKH LKK 26.02.19 REPAIR 03 DAYS								

Pro Forma

Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!

Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!

Parts	1,476.00	Nett	2,756.00
Labour	1,260.00	7% GST on	192.92
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	2,948.92
Diagnostics Job	0.00		
Sundry/Others	20.00		
Total(w/o GST)	2,756.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002650/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3838E	Veh. Inspected	SKT 1259D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000959MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	12/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAFZ411MF5404380	Colour	SILVER	
Odometer	42399	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/40 R17	ROADSTONE	6 mm	
L/H Front Tyre	215/40 R17	ROADSTONE	6 mm	
R/H Rear Tyre	215/40 R17	ROADSTONE	6 mm	
L/H Rear Tyre	215/40 R17	ROADSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/02/2019	Inspection Date	26/02/2019	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 1259D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	STAY-RR BUMPER LH (SN)	NECESSARY	75.00	75.00
1	STAY-RR BUMPER RH (SN)	NOT NECESSARY	75.00	-
1	BEAM-RR BUMPER (SN)	BENT	365.00	365.00
1	BRACKET-RR BEAM LWR,CTR (SN)	NOT NECESSARY	5.00	-
2	BRACKET-RR BEAM LWR,MTG (SN)	NOT NECESSARY	10.00	-
1	COVER-RR BUMPER (SN)	DEFORMED	791.00	791.00
1	COVER-RR BUMPER,UPR (SN)	DEFORMED	245.00	245.00
1	SUNDRIES (SN)	NECESSARY	20.00	20.00
			1,586.00	1,496.00
	<u>LABOUR</u>			
	TO RENEW REAR BUMPER,REPAIR END PANEL.		1,650.00	550.00
	PAINT WORK SPRAY REAR BUMPER,END PANEL.		1,260.00	420.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		30.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	TO TRANSFER REAR PARKING SENSOR TO NEW PART.		60.00	60.00
	TO APPLY ANTI COROSSION.	NOT NECESSARY	40.00	-
			3,240.00	1,260.00
	GRAND TOTAL		4,826.00	2,756.00
RECOMMENDED COST OF REPAIRS				2,756.00

Report Ref No. CS/FCI19002650/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.