



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19002667/Kbs3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG			Date : 08-07-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 352M	Veh. Inspected	SLC 3853C	
Policy No.	CN008780	Coverage (\$)	0.00	
Claim No.	S9M01DOE	Excess (\$)	0.00	
Assign From	LYNN KHONG	Assign Date	13/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11117911	Colour	METALLIC PEARL WHITE	
Odometer	060841	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	2 mm	
L/H Front Tyre	215/60 R16	DUNLOP	2 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/01/2019	Inspection Date	19/02/2019	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		