

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD
 64 CECIL STREET
 #04/#05 IOB BUILDING
 SINGAPORE 049711

TEL: 63476100 FAX: 62247743
 ATTN: Motor Claim Department

WS Ref: TP/III/AMK
 Claim Type: Third Party
 Accident Date: 09/02/2019
 TP Veh Reg No: SHA6193L

Estimate No: ES1991205/AMK
Date: 28 Feb 2019
Policy No: DMPCSN1809881800
Veh Reg No: SLX4146T
Make/Model: HYUNDAI ELANTRA
 AD 1.6 GLS
Chassis No: KMHD841CMJU647375
Engine No: G4FGJU151769
Reg. Date: 27/03/2018

Not Authored

*Refusing B4 painting
 2-3 days*

Estimate Repair Cost to Vehicle No :SLX4146T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER (UPPER)	459.40	1 PC	B ₁ 459.40	✓
2 REAR BUMPER LOWER COVER (BLACK)	250.10	1 PC	B ₁ 250.10	✓
3 REAR BUMPER REINFORCEMENT	294.80	1 PC	B ₁ 294.80	✓
4 REAR BUMPER REFLECTOR	31.90	1 PC	CM 31.90	✓
5 REAR BUMPER CLIP	2.00	5 PC	MC 10.00	✓
6 REAR BOOT INNER LOCK	117.00	1 PC	MC 117.00	X
			1,163.20	
	Less 20%		232.64	930.56
Special Net				
7 REVERSE SENSOR	200.00	1 SET	Shan 200.00	✓
			200.00	200.00
Labour				
8 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAIL LAMPS; KNOCKING & REPAIR REAR END PANEL & REALIGN REAR BOOT THE SAME	500.00	1 LA	500.00	300
9 PUTTY & RESPRAY & ATTACHMENTS, PARKING SENSORS, REAR END PANEL & ALL AFFECTED AREAS	600.00	1 LA	600.00	400
			1,100.00	1,100.00
Total				S\$ 2,230.56
Add GST @ 7%				156.14
Total Amount Payable				S\$ 2,386.70

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: