ASS, REC. BY:		M019002730	1000 Sept	Instruction:
WIND THE		GNMENT (Office)		-11
From (Person); Thelm	va Choo of	SMO	Dat	e/Time: 13 2 19 234
Estimated Cost:		Bill to:		
OD TE WS/TP RES/	OD RES/EVA/INV/	MV7CS		
To Inspect Vehicle No:	SIE 2	389x	Insured:	PC 7533C
at Workshop m/s	EM Solu	ltion	Tel:	PC 7533C
of	60 Sin Ming Drive	7-03-19		
Policy No: DIRMT			CMTDI	900844
Sum Insured:		Excess:		
Make of Veli: (Client's Recent)			D.0	DIOS   2019
CA / REV / REP. / RI	EV 24 HRS/up		H	O.D. Endorsement
Date/Time: 93Sumg	Person Conts	octed: Joseph	in Vehic	TUO (AI) oli
	truction ( × ) Esti	mate		
[2]	E2389(X->			
PCTS	33(->c			
Disma	ntle: 15/2/2019			
	4pir: 23 × 2019			

LERO SMI	0	6804B
. PRS	SoloMINI	(-2
Date 14 21	19 Voh 110 SIE2389	X ir Rogn 18 Apr 2
F-slimated Cost		/an / Lorry / Taxi / Prime Mover /
OD THE WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or	
	Make Nissan	n latio 1498
at Workshop m/s EM Solution	Colour Gold	A/C Insured / Std / NI / NA
160 Sin Ming Dive \$ 03-1		T/Radio: Insured / Std / NL/ NA
histored and	Eng/No:	11 -117 0-11
Policy No.	CANO INIB	AAC118 000 6964
Claims-No.	Gen. Cond. Good / Fair / Poor	
Sum Insured. Excess:	Steering: Inorder / Jammed / L	eaked / Burnt or •
(Client's Record)	Brake: Inder / Jammed / L	
Make of Veh:	Modi: Nil / S/Rim / STD/A/	
	Tyre Size: F: 18	35 / 65 R15
(Policy Condition)	R:	n
Remark. The veh had commenced its	N/S O/S BS / DUN / EXNOVA / GY / FS	/ LIZA / MICH OHTSU / PIR / SUMI /
repair at the time of inspection.	Тоуо/уоко ог	
Balt or Market Value: \$ 22K	Eront	Rear
IDAG Accident Rport. Consistent?: Yes or I	No R/Bal. b mm	R/Bal. 6 min
GIA / PR Seen: Consistent?: Yes or t	No L/Bal. '6 mm	L/Bal. 6 mm
Est Repairs: 6 days Res.: Yes or	No D.O.A.	1 D.O.I 14-02-19
Lum Sum: 20 % 3 Val.: Yes or		5:10
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Kear	of O/S / N/S / U/C / Rooftop or
Date: Person Contacted:		/ Body Structure affected due to collision.
Date / Time Action / Instruction \$5000	-\$6000	
RECEIVE	D 2 0 MAR 2019	
Date/Time_File Pass to? : Proff. Report	Days Of Repair:	C
: Final Report	Resurvey No. of Trip:	1 Survey Fee: 100
Oate/Time. File Return to?	,	Transportation ' 60
7)	Add Fee: Site Insp (\$	· )_s+Rs_si 60
	Interview (\$	) Photos
Report Format: PRC.	Tech, trys (\$	t diluit
Lump Sum / LB !: /3	- Westernal (\$	1.124

- 230

# ...CLAIM SUBFOLDER...(New Assignment)

	OLDER TRA	CONTRACTOR OF THE PROPERTY OF								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Authled	Status	S	
Main	13 Feb 2019		13 Feb 2019 14:34 Assign					processor and a	Assignment el Case	
M	tain	Re	ference		Claim Details		Docum	ents	Show	w All
CLAIM SUE	BFOLDER DE	TAILS				[Creat	ed by insurer]			-
insured:	AMARJIT	& SONS COACH	SERVICES (PRI	VATELIMI	TED) Co Rec	No : 30	1236600N			
Main Claimant:	TAY LAY S				Co. Keg.	140 20.	122009614			
Vehicle Reg. No.:	SJE2389	ЭX			Date of Loss:	12/02/2	2019 20:00 - :59			
Claim Type:	TP / CMT	D1900844			Policy/Cover Note No.:	D18MTS	CBU000692 (Co	mprehensiv	e)	
Vehicle Reg. No. (Insured):	PC7533C				Policy No. (Claimant):					
					Excess:					
tepairer:	Em Solution	on Pte Ltd (160 s	Sin Ming) (HQ)	160 Sin Min	g Drive, #03-19	Sin Mino	Autocity, 57572	2 Sin Mina	- Tel:	
Handling Insurer:		surance Singapo								
djuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561 .	[Final Rpt	due 22/	02/20191			
Adj Asg. Remarks:		INFORMED THAT						IITTED		
SSOCIATE	D MAIL REC	CEIVED						View All	Compose Case	o Mai
here are no	mail for this	case.						TICH AII	Compose Cas	e Mai
ALL ASSOC	TATED TASE	KS⊟				View A	II   Search Tasks	Create	New Task   Con	mplete
Due Date	Priority	Type Task 0	iroup Subje	ect Hand	ler Assign		Completed C			Done

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6804B
ehicle Details	
/ehicle No.:	SJE2389X
ehicle to be Exported:	No
ntended Deregistration Date:	15 Feb 2019
/ehicle Make:	NISSAN
/ehicle Model:	LATIO 1.5L A
rimary Colour:	Gold
Nanufacturing Year:	2007
ingine No.:	HR15212693A
Chassis No.:	JN1BAAC11Z0006964
Maximum Power Output:	80.0 kW (107 bhp)
)pen Market Value:	\$14,213.00
Original Registration Date:	18 Apr 2008
irst Registration Date:	18 Apr 2008
ransfer Count:	2
ctual ARF Paid:	\$14,213.00
ntended PARF Rebate Details	
ARF Eligibility:	Forfeited
ARF Eligibility Expiry Date:	-
ARF Rebate Amount:	\$0.00
itended COE Rebate Details	
OE Expiry Date:	17 Apr 2023
OE Category:	A - Car (1600cc & below)
OE Period(Years):	5
QP Paid:	\$19,328.00
OE Rebate Amount:	\$16,128.00
otal Rebate Amount:	\$16,128.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Feb 2019

SGCARMART.CON THE ONLY PLACE FOR SMART CAR BUYE

▶ Latio Used Vehicle List (12 vehicles)

Car Model Price Depreciation **Reg Date** Mileage **Eng Cap** Company Availabi Nissan Latio 1.5A (COE till \$11,800 \$7,830 /yr 16-Sep-2005 1,498 cc FredLink Auto Trading Availal 09/2020)

Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

Office No. - 67788997 / 67788995

Daniel Loh - 83938889 | Mohammad - 81121493 | Freddy Lee - 96923373

Nissan Latio 1.5A (COE till \$14,000 \$8,360 /yr 16-Nov-2005 1,498 cc - Apex Automotive Availal

100% Guaranteed Accident Free, Beautiful Leather Interior, Extremely Well Maintained, All Wear And Tear Parts Fully Replaced. Loans With Super Low Interest Rate! Is Very Good For Short Term Drive As I...

Office No. - 62513972

Dion Tan - 88625982 | Kelvin Sim - 97278548 | Tan - 93547280

Nissan Latio 1.5A (COE till \$16,777 \$5,860 /yr 24-Jan-2007 1,498 cc 138,000 km Availal

Major Wear And Tear Replace. Eg. Initial Coil, Engine Mounting. Shock Absorber, Radiator, Brake Pads And 2 More Paid Servicing To Go For Next Owner From TC. Thanks To The Previous Owners With Low Mile...

Office No. - -

Vincent - 97937987

Nissan Latio 1.5A (COE till \$16,999 \$5,590 /yr 29-Mar-2007 1,498 cc - Quan Feng Motors Availal (Singapore) Pte Ltd

One Of The Most Valuable Car In The Market. Well Maintained Condition, Flexible Bank/In House Loan Package Available, With Attractive Interest Rate, Low Deprecation, Trade Ins Available. Call Now To Ar...

Office No. - -

Andrew Ong - 90119549 | Louis Wong - 91129549

Nissan Latio 1.5A (COE till \$18,500 \$5,670 /yr 19-Jun-2007 1,498 cc - Hou Auto Availal

Well Kept. Low Depreciation. Loan Available. High Trade In. Call For Viewing.

Office No. - 94574576

Black - 94574576

Nissan Latio 1.5A (COE till \$18,800 \$5,490 /yr 16-Aug-2007 1,498 cc 170,000 km Car Search Availal

Consignment Unit, Call To Arrange A Test Drive Today!

Office No. - 62620728

Ken - 93388994 | Justin - 91827511 | Kelvin - 97593539 | Lester - 96192666

Nissan Latio 1.5A (COE till \$19,900 \$6,940 /yr 25-Jan-2007 1,498 cc - Prem Roy Motoring Availal

One Of The Most Valuable Car In The Market. Well Maintained Condition. Nice Sporty Black. Replaced Gear Box. Flexible Bank/In-House Loar Package Available, With Attractive Interest Rate. Consignment U...

Office No. - 66028046

Ashvini - 98896985

Nissan Latio 1.5A (COE till \$21,800 \$7,770 /yr 03-Jan-2007 1,498 cc 210,000 km Car Search Availal

One Of The Most Valuable Car In The Market. Well Maintained Condition. Nice Sporty Black. Replaced Gear Box. Flexible Bank/In House Loar Package Available, With Attractive Interest Rate. Consignment U...

Office No. - 62620728

Rachel - 91126538 | Justin - 91827511 | Kelvin - 97593539 | Lester - 96192666

Nissan Latio 1.5A Sports \$24,500 \$4,890 /yr 06-Jan-2009 1,498 cc - 5AT Motor Trading Availal (New 5-yr COE)

Careful Driver, No Major Repair Require, Bank And In House Loan Available, Low Interest Rate, High Trade In, Fast And Easy Approval, No Guarantor Needed, All Vehicles Inspected By Our Own Workshop, Lo...

Office No. - -

Wilson - 82555433 | Wee - 92479903

...

Nissan Latio 1.5A (New 5-yr \$24,800 \$4,950 /yr COE)

02-Jan-2009 1,498 cc

104,000 km Creative Auto

Availal

Owned This Unit With 90% Loan Amount Stated, Various Loan Options To Cater Your Comfortable Financial Plan, Hassle Free With Worksho Service, Extended Warranty Available, Low Mileage, One Of Our Comp...

Office No. - -

Tian Cheng - 88338380 | Alex Tan - 97556887 | Terence Leow - 90290899

Nissan Latio 1.5A (COE till 01/2024)

\$28,800 \$5,940 /yr

19-Jan-2009 1,498 cc

Yong Lee Seng Motor

Availal

Non Grab Or Go Jek Car. Evaluated By VICOM, Free 6 Months Maintenance And 1 Grooming.

\$5,580 /yr

Office No. - 68440123

Raymond Tang - 96250045 | Richmond Tang - 96200045

Nissan Latio 1.5A (COE till 01/2027)

\$44,000

01-Feb-2007 1,498 cc

117,000 km Prem Roy Motoring

Availal

Stunning Bright-Red Japanese Sedan! Not Only Is It Beautiful, Not Only Is It Fuel Efficient, It Is Also Going At An Affordable Price! Good Condition! Low Mileage! Comfortable Drive! Regular Maintenanc...

Office No. - 66028046

Kana - 96435365

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sal even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authoricar dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

#### SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

Mobile Number

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	W 32
Charles and State and Own	ACCIDENT STATEMENT
Date Of Report	13/02/2019 14:31
Date Of Accident	12/02/2019 20:30
Exact Location Of Accident	CTE TOWARDS YISHUN JUST BEFORE ANG MO KIO AVENUE 1
Country/State of Loss	SINGAPORE
C	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJE2389X
Insured/Policyholder	
Name Of Registered Owner	TAY LAY SUAN (ZHENG LIZUAN)
NRIC No.	S7506804B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97315000
Alternative Phone No	OFFICE-97315000
Vehicle Particulars	
Manufacturer	NISSAN
Model	LATIO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10825166
Cover Note Number	
Driver	
Name of Driver	ONG CHEE LIP
NRIC No	S0133306B
Date Of Birth	28/07/1953
Occupation	INDOOR
Date Of Driving Pass	19/09/1978
Driving Experience	40 YEARS AND 4 MONTHS
Gender	MALE

(LOCAL) +65-97315000

ONGCHEELIP@GMAIL.COM

Address NIL

Postcode

Was driver an employee of the Insured's Company NO

FRIEND If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

2

NO

YES

NO

1

NO

NO

NO

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

YES

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

### Circumstances of Accident

I was travelling along CTE towards Yishun just before Ang Mo Kio Avenue 1 exit. The traffic was clear. I was on the second lane from the left. When this vehicle PC7533C collided onto my rear bumper of my vehicle. Damages to my car were on the rear bumper portion. No injuries were involved but I will consult a doctor later as I felt pain on my back.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO

Was there any audio recorded?

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number PC7533C

Vehicle Make/Model/Colour TOYOTA / HIACE COMMUTER

**Details Of Properties** 

Vehicle Category COMMERCIAL VEHICLE

NIVENDIP SINGH SANDHU S/O KULDIP SINGH Name of Driver

NRIC/Passport Number S9102041F Contact Number 97566707

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1** 

Name

ONG CHEE LIP

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

YES

SJE2389X


Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

#### Sketch Plan



#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver. 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may
- 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- 5. Any false reporting may be referred to the Police for investigation. 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or l understand, acknowledge, agree and consent that: process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (colectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the insurer of the Insurers"), the insurers' lawyers'law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- in processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to The claims:
- (ii) investigating the accident and/or my claims.
- (a) carrying out ancior dealing with my instructions or responding to any enquiries by me.
  (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve declosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- packages), and/or (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (ionscrive) on: Purposes )

  (ii) all insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may lare permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

  (ii) my Personal Information may/can be disclosed by any of the Insurers and/or DIA to their third party service providers or agents (including their lawyers/law firms), which may be stied outside of Singapore, for one or more of the above Purposes.


**VERIFIED BY ALAX MARS** REPORTING OFFICER

Muhammad Firza Bin Ideris

Policyholder's Signature / Date & Time Driver's Signature (f

driver is not the policyholder) / Date & Time Witnessed by Reporting Centre

#### Sketch Plan



## Common Statement Pg. 1

## ACCIDENT STATEMENT (2000 characters)

traffic was clear. I was on the second lar collided onto my rear bumper of my vehi	un just before Ang Mo Kio Avenue 1 exit. The ne from the left. When this vehicle PC7533C icle. Damages to my car were on the rear ed but I will consult a doctor later as I felt pain
Taxi Voucher No.:	
DECLARATION  I/We declare that the above particulars & information provid  VERIFIED BY AJAX MARS REPORTING OFFICER -  MUHAMMAD FIRZA BIN IDERIS	ed above are true in every aspect
MARS Officer	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time:
13 February 2019 at 12:39 PM	13 February 2019 at 12:39 PM





1 of 3

Report No. T/20190213/2117

Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE

556129

Tel No: 1800-4880999

#### REPORT OF A TRAFFIC ACCIDENT

	ne Report N 019 15:01	Made:	Vide Report No.:	Station Diary No.: 53
Informa	nt's Partic	ulars		
Name of ONG Ch	f Informant: HEE LIP		Address: 66 PHOENIX ROAD #1	7-05 SINGAPORE 668201
	/ ID No.: O / S01333	06B	Contact No.: Home/Office:	Mobile: 97315000
National SINGAP	ity: ORE CITIZ	ΈN	Email:	
Sex: Male			Type of Informant: Driver	
Race: Chinese	Race: Chinese		Language:	Institution / School Name:
Occupat	tion: y director		Driving Licence Informa Class: 3	tion: Date of Expiry:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/02/2019 20:30	Type of Location: Straight Road	
	PRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
		Traffic Control: Not Controlled		Traffic Volume:	
Type of Collisi	ion: ing Vehicles - Head	d To Door		Anyone conveyed by ambulance:	

Details of V	ehicle Invo	lved				State of the state
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
PC7533C	Van					0
SJE2389X	Car	NISSAN	LATIO 1.5L	Gold	Slightly Damaged	0

Details of V	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJE2389X	AVIVA LTD	JN1BAAC11Z0006 964	13/04/2018	17/04/2019





2 of 3

Report No. T/20190213/2117

Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE 556129

Tel No: 1800-4880999

CONTINUATION OF REPORT

Details of Perso				256		
Any Pedestrian II			I I a af Da		0	NA
No. of Pedestrian	is injured: NIL		Use of Ped	aestriar	Cross	sing: NA
Driver						
Name	ONG CHEE LIP		ID No		S0133306B	
Related Vehicle	SJE2389X (Car)			Conta	ct No.	97315000
Hospital/Clinic	RAFFLESMEDICAL			Class Drivin Licend Expiry	g	Class: 3 Date of Expiry: NIL
Date Treatment	13/02/2019	13/02/2019 Date		harge	13/02	2/2019
No. of Days gran	ted Medical Leave	03	Degree of	Injury	Sligh	t

#### Brief Details.

On 12/02/2019 at about 2030hrs, I was travelling along CTE towards Yishun before Ang Mo Kio Ave 1 exit on the second lane from the left when suddenly I felt an impact from the rear side of my vehicle. I then stopped the vehicle and saw van PC7533C hit onto the rear side of my vehicle. We then exchanged particulars and took some photos. Subsequently both of us moved to the roadside and a LTA motorbike passed by and took some photos and informed us that we are good to go. We then went to the nearby carpark to talk things out and I then called for towtruck to tow my vehicle away. I then felt pain at the neck area and also on the right hand left two fingers, I then visited the clinic on 13/02/2019 and will followup on the pain as advised by the doctor. I wish to state that my vehicle only have front car camera. That is all.





3 of 3

Report No. T/20190213/2117

Police Station Of Origin: Serangoon N.P.C 50 Serangoon Avenue 2 #01-02 SINGAPORE 556129

Tel No: 1800-4880999

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

CONTINUATION OF REPORT

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 2 LIM HAO JIE	G Chr.
Signature Of Interpreter:	Date/Time:
Not applicable	13/02/2019 15:01
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:
Authentication Stamp	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	13 Feb 2019		13 Feb 2019 14:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Report  Cancel Case	4
	Main	R	eference	Claim De	tails	Documents		Show All
CLAIM SU	BFOLDER DE	TAILS			[Created	by insurer]		
Insured:	AMARJIT	& SONS COACH	SERVICES (PRIVA	TE LIMITED), Co	. Reg. No.: 20122	6698N		
Main Claimant:	TAY LAY	SUAN						
Vehicle Reg No.:	SJE238	9X		Date of		02/2019 20:00 - :59 9 Months and <b>25</b> Days From LTA Reg Date (Man Yr)]		
Claim Type	e: <b>TP</b> / CMTD1900844			Policy/0 Note No		rscBU000692 (Comprehensive)		
Vehicle Reg No. (Insured):	PC7533C			Policy N (Claima	Control of the contro			
				Excess				
Repairer:	Em Solut	ion Pte Ltd (160	Sin Ming) (HQ) 16	0 Sin Ming Drive, #	03-19 Sin Ming A	utocity, 575722 Sir	n Ming - Tel:	
Handling Insurer:			ore Pte. Ltd. (HQ)					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by XING GUO	QIANG] [Final	<b>Rpt</b> due 22/0	2/2019]
Adj Asg. Remarks:	-PLEASE B	E INFORMED THA	T OUR INSURED HA	S NOT REPORTED T	HE ACCIDENT -NO	TP SAS SUBMITTE	ED	
ASSOCIA	TED MAIL RE	CEIVED				Vie	w All Compos	e Case Mail
There are r	o mail for this	case.						
ALL ASSO	CIATED TAS	sks⊟			View All	Search Tasks C	reate New Task	Complete
Due Dat		Type Task	Group Subjec	t Handler	Assigned By	Completed On	Created O	Done?

### Claim Documents

\*SJE2389X (CMTD1900844)

[PC7533C]

TP

TAY LAY SUAN

Feb 12 2019 8:00PM

[AMARJIT & SONS COACH SERVICES (PRIVATE LIMITED)]

Em Solution Pte Ltd (160 Sin Ming)

Photos/Images			3 per page 🔻	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	-
1	23/02/19 14:41	General View	£ Load JPG	V
2	23/02/19 14:41	General View	Load JPG	<b>✓</b>
3	23/02/19 14:41	General View	£ Load JPG	V
4	23/02/19 14:41	General View	Load JPG	<b>V</b>
5	23/02/19 14:41	General View	Load JPG	V
6	23/02/19 14:41	General View	1 Load JPG	<b>V</b>
7	23/02/19 14:41	General View	Load JPG	<b>✓</b>
8	23/02/19 14:41	General View	Load JPG	V
9	23/02/19 14:41	General View	■ Load JPG	<b>✓</b>
10	23/02/19 14:41	General View	Load JPG	V
11	23/02/19 14:41	General View	■ Load JPG	~
12	23/02/19 14:41	General View	Load JPG	V
13	23/02/19 14:41	General View	Load JPG	V
14	23/02/19 14:41	General View	Load JPG	~
15	23/02/19 14:41	General View	■ Load JPG	V
16	23/02/19 14:41	General View	1 Load JPG	V
17	23/02/19 14:41	General View	Load JPG	V
18	23/02/19 14:41	General View	Load JPG	V
19	23/02/19 14:41	General View	■ Load JPG	~
20	23/02/19 14:41	General View	Load JPG	V
21	23/02/19 14:41	General View	Load JPG	<b>✓</b>
22	23/02/19 14:41	General View	Load JPG	V
23	23/02/19 14:41	General View	£ Load JPG	V
24	23/02/19 14:41	General View	1 Load JPG	~
25	23/02/19 14:41	General View	Load JPG	<b>✓</b>
26	23/02/19 14:41	General View	Load JPG	<b>✓</b>
27	23/02/19 14:41	General View	Load JPG	V
28	23/02/19 14:41	General View	1 Load JPG	<b>V</b>
29	23/02/19 14:41	General View	Load JPG	V
30	23/02/19 14:41	General View	Load JPG	<b>V</b>
31	23/02/19 14:41	General View	■ Load JPG	<b>✓</b>
32	23/02/19 14:41	General View	Load JPG	<b>Y</b>
33	23/02/19 14:41	General View	1 Load JPG	V
34	23/02/19 14:41	General View	■ Load JPG	V
35	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	V
36	23/02/19 14:43	Photographs of Damaged Parts	■ Load JPG	<b>V</b>
37	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	V

Pho	tos/Images		3 per page	<b>√ ∀</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	
38	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	1 4
39	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	G ✓
40	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	G ☑
41	23/02/19 14:43	Photographs of Damaged Parts	■ Load JPC	G ☑
42	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	G ☑
43	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	G ✓
44	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G ☑
45	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G ☑
46	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G 🔽
47	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G ✓
48	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	G ✓
49	23/02/19 14:43	Photographs of Damaged Parts	Load JPG	G 🔽
50	23/02/19 14:43	Photographs of Damaged Parts	Load JPG	
51	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	
52	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	_
1000	S24 530 55 65 65 65 65		1 Load JPC	
53	23/02/19 14:43	Photographs of Damaged Parts  Photographs of Damaged Parts	1 Load JPC	-
54				_
55	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	-
56	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	
57	23/02/19 14:43	Photographs of Damaged Parts	1 Load JP	1000
58	23/02/19 14:43	Photographs of Damaged Parts	1 Load JP	
59	23/02/19 14:43	Photographs of Damaged Parts	1 Load JP	
60	23/02/19 14:43	Photographs of Damaged Parts	1 Load JP	-
61	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	_
62	23/02/19 14:43	Photographs of Damaged Parts	1 Load JP	G ✓
63	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G ☑
64	23/02/19 14:43	Photographs of Damaged Parts	1 Load JP	G ✓
65	23/02/19 14:43	Photographs of Damaged Parts	■ Load JPe	G ✓
66	23/02/19 14:43	Photographs of Damaged Parts	■ Load JP	G ✓
67	23/02/19 14:43	Photographs of Damaged Parts	Load JP6	G ✓
68	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G ✓
69	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G <b></b> ✓
70	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G 🔽
71	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPG	G ✓
72	23/02/19 14:43	Photographs of Damaged Parts	Load JPG	
73	23/02/19 14:43	Photographs of Damaged Parts	Load JPC	-
74	23/02/19 14:43	Photographs of Damaged Parts	Load JPC	
75	23/02/19 14:43	Photographs of Damaged Parts	Load JPG	
76	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	
77	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	
78	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	
		Photographs of Damaged Parts  Photographs of Damaged Parts	1 Load JPC	
79	23/02/19 14:43		1 Load JPC	-
80	23/02/19 14:43	Photographs of Damaged Parts		
81	23/02/19 14:43	Photographs of Damaged Parts	1 Load JPC	
82	15/03/19 11:19	Photo After Spray	① Load JPC	
83	15/03/19 11:19	Photo After Spray	① Load JPC	
84	15/03/19 11:19	Photo After Spray	Load JP(	
85	15/03/19 11:19	Photo After Spray	1 Load JP	
86	15/03/19 11:19	Photo After Spray	1 Load JPC	
87	15/03/19 11:19	Photo After Spray	1 Load JPC	G 🔽

Merimen e-Claims Page 3 of 3

Pho	otos/Images		3 per	page 🔻	<b>✓</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	15/03/19 11:19	Photo After Spray	0	Load JPG	<b>▼</b>
89	15/03/19 11:19	Photo After Spray	0	Load JPG	V
Doc	cumentation		1 per	page 🔻	<b>V</b>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	19/03/19 10:09	PD LOD FR VISION LAW LLC - SJE2389X	0	Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/SMO19002730/GCD3E2

Date:

25/03/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Policy No:

D18MTSCBU000692

Claimant Vehicle

SJE2389X

Insured Vehicle No:

PC7533C

No: Date of Loss:

12/02/2019

Nature of Claim:

TP

Claim No:

CMTD1900844

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SJE2389X

Make & Model:

NISSAN LATIO, 1.5 L (A)

Engine No:

HR15212693A

Reg. Date: Colour:

18/04/2008 (Man. Year: 2007)

Chassis No: Odometer:

JN1BAAC11Z0006964 146513 km

**Engine Capacity:** 

1498 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Net	tt Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

13/02/2019

Date Inspected:

14/02/2019 Inspected At:

Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming

Autocity

Singapore 575722

Estimated Period of Repair:

6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

Adjuster Report Page 4 of 5

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2019)

Parts: 143 NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJE2389X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >