

INS. CASE OWNER: SEAN | CCF ASM | AXA1900 2726 U 9634 | LKK:
 IDAC:

Surveyor: MARUS | DOI: wey/m | Date / Time: 14/1/19
 Registered in Merimen:

Pre-assign / CCU / FTE:
 Insured Vehicle No.: SLN 6408C | Claim No.: SAMULATZ / 95788
 Name of Insured: NEW KIA UN. | Policy No.: UPA101250
 Insured Tel No.: | HP: | Make / Model: PENACOT
 Excess Sec II :SS: | D.O.A.: 18/1/19 | Place of Accident: WENTWORTH AVE 4
 Is driver the owner? (YES / NO) : | Nature of Accident:
 If NO, Driver Name / Age: 24w peng peng | OI GIA REPORT: YES / NO : ; TP GIA REPORT: YES / NO :
 Driver Tel No.: (VL: YES / NO) | Insured Liability: % Final ? Yes / No :

YN 5941G → → → → →

 INSRs: <u> </u> WSP: <u> </u> Tel: <u> </u> Liability: <u> </u> RMKS: <u> </u>	<u>LIU'S</u>	 INSRs: <u> </u> WSP: <u> </u> Tel: <u> </u> Liability: <u> </u> RMKS: <u> </u>	 INSRs: <u> </u> WSP: <u> </u> Tel: <u> </u> Liability: <u> </u> RMKS: <u> </u>	 INSRs: <u> </u> WSP: <u> </u> Tel: <u> </u> Liability: <u> </u> RMKS: <u> </u>	 INSRs: <u> </u> WSP: <u> </u> Tel: <u> </u> Liability: <u> </u> RMKS: <u> </u>
---	--------------	---	---	---	---

Date/Time	STAGE	DATE / PIC
<u>14/1/19</u>	Non-Reporting Itr (1st):	
<u>14/1/19</u>	Non-Reporting Itr (2nd):	
<u>14/1/19</u>	Non-Reporting Itr (Final):	
<u>14/1/19</u>	Notification Itr (if non-pickup):	
<u>14/1/19</u>	Call OI:	<u>20/1/19</u>
<u>14/1/19</u>	After call Itr to OI:	<u>20/1/19</u>
<u>16-4-19 @ 429</u>	Documentation Check List:	Handler Typist
<u>15/1/19</u>	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	After call Itr to OI:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Authorisation To Act:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Release Voucher:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Final Repair Bill:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Car Rental Invoice:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Towing Invoice:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	LTA / GIA:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Medical Bill:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	PIR:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	LOD:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Payment Breakdown Form:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Post-Repair Photos:	<input checked="" type="checkbox"/>
<u>16-4-19 @ 429</u>	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: MARUS
 Repair Cost: US \$2650.00 (4 days) Reduction: \$2064.00 Final Call

FINAL SETTLEMENT Date/Time: 14/1/19 Confirm with: Email Call
 Final Liability: % 50 (Agreed / Assessed) BOLA S/N No.: NIL
 Repair Cost: \$2650 SS 1325.00
 Loss of Rental (LOR): SS (80 days)
 Loss of Use (LOU): \$480 SS 240.00 (80 x 6 days)
 Loss of Income (LOI): SS (5 x days)
 LOR only LOU only LOR + LOU LOR + LO (Tick only one)
 GIA/LTA Search: SS
 Medical: SS
 Disbursement: SS (e.g. Tow/Independent)
 Legal Cost: SS
 Total: SS 1565.00 Global Sum SS:
 If NO or B 28, Ass. Lia: OT turning into CP from 2nd line. TP as straight.
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$30

FINAL PAYMENT Date/Time: Confirm with: Email Call
 Payee 1: SS 1565.00 Name 1: LIU'S BROTHER Engineering Workshop
 Payee 2: (Strike if N.A.) SS Name 2:
 Payee 3: (Strike if N.A.) SS Name 3:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 1196N

Vehicle Details

Vehicle No.: YN5941G
Vehicle to be Exported: No
Intended Deregistration Date: 13 Feb 2019
Vehicle Make: MITSUBISHI
Vehicle Model: CANTER FEB21ER35DEB (CBU)
Primary Colour: White
Manufacturing Year: 2014
Engine No.: 4P10B28833
Chassis No.: FEB21EA00680
Maximum Power Output: -
Open Market Value: \$31,715.00
Original Registration Date: 21 Aug 2014
First Registration Date: 21 Aug 2014
Transfer Count: 1
Actual ARF Paid: \$1,586.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Aug 2024
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$40,889.00
COE Rebate Amount: \$22,565.00
Total Rebate Amount: \$22,565.00

The information contained herein is correct as at 13 Feb 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 1196N

Vehicle Details

Vehicle No.: YN5941G
Vehicle to be Exported: No
Intended Deregistration Date: 13 Feb 2019
Vehicle Make: MITSUBISHI
Vehicle Model: CANTER FEB21ER3SDEB (CBU)
Primary Colour: White
Manufacturing Year: 2014
Engine No.: 4P10B28833
Chassis No.: FEB21EA00680
Maximum Power Output: -
Open Market Value: \$31,715.00
Original Registration Date: 21 Aug 2014
First Registration Date: 21 Aug 2014
Transfer Count: 1
Actual ARF Paid: \$1,586.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Aug 2024
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$40,889.00
COE Rebate Amount: \$22,565.00
Total Rebate Amount: \$22,565.00

The information contained herein is correct as at 13 Feb 2019

OK

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Thursday, 14 February 2019 10:28 AM
To: assignments
Cc: Admin A
Subject: FW: Request for 3rd party claims survey YN5941G Claims against SLN6408C
Attachments: YN5941G190118.pdf

****SMARTCLAIM NEW CASE****

Kindly arrange.TQ

11-ssame 14/2/19
vehicle In
SUREMOTUS

Best Regards,

Shu Pei Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Susan Low <liusbro@gmail.com>
Sent: Wednesday, 13 February 2019 5:15 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: Request for 3rd party claims survey YN5941G Claims against SLN6408C

Accident on 18/01/2019 Along Bedok North Avenue 4 Before Carpark Of Block 89
Involving YN5941G and SLN6408C

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____

◀ Re:RE: PROCEED DS

Type

🔍 Question

Message

Please proceed 50/50. kindly inform insured before proceeding

Reply



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/08/2019

Survey Details:

Date of loss	18-Jan-19
Date of appointment	14-Feb-19
Date of survey	14-Feb-19
Location of survey	J'S BROTHER AUTO ENGINEERING WORKSHOP

Vehicle Details:

Claim Type:	Third party
Vehicle number	YN 5941G
Make and Model	MITSUBISHI CANTER
Date of registration	21/8/2014
Excess	
Market Value	\$45,000
Parf Rebate	\$22,565
Nett Loss	\$22,435

Repair details:

Initial Estimate	\$	4,714.00
------------------	----	----------

Proposed/Revised repair cost:

Parts	\$	1,803.55
Check items (estimate)	\$	-
Labour	\$	870.00
Total	\$	2,673.55
Lump Sum(if applicable)	\$	2,650.00

Number of days for repair	4
---------------------------	---



Remarks:

04 RECOMMENDED REPAIR DAYS + 1PRS + 1SUNDAY= 6 DAYS

Mandate:

Liability(TP)		50%	
Proposed repair cost	\$	1,325.00	
Loss of use	\$	240.00	6days x \$40
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	-	
Others	\$	-	
Proposed Total	\$	1,565.00	



<MANDATE IA> - S9M01B53 {ACCIDENT INVOLVING SLN 6408C (OI) & YN 5941G (TP) ON 18/01/2019}

Type

 Question

Message

LIABILITY: 50% OI TURNING INTO CARPARK FROM 2ND LANE WHILE TP GOING STRAIGHT ON 1ST LANE: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1,565.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532017931 - Tel: 6741-1730 / 731 - Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YN5941G19018

Final Bill

Customer			
Name:	AXA Insurance Singapore Pte Ltd	Date:	19-02-19
Address:	Motor Claims Department 8 Shenton Way #27-01 AXA Tower Singapore 068811	Vehicle No:	YN5941G
		Model/Make:	Mitsubishi
		Canter:	FEB21ER3SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Corner Panel	\$ 474.60	\$ -
2	Signal Lamp	\$ 313.60	\$ -
3	Head Lamp	\$ 672.70	\$ -
4	Side Lamp	\$ 235.20	\$ -
5	Bumper Side	\$ 340.70	\$ -
6	Bumper Side	\$ 1,117.20	\$ -
7	Number Plate	\$ 300.00 SN	\$ -
8	"Corporate" Advertisement & Artwork	\$ 300.00 SN	\$ -
	To check all wiring & electrical component for proper function	\$ 60.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	\$ -
	To putty & spray painting & including touch up paint on accident affected area	\$ 600.00	\$ -

Total Parts & Labour of estimate for damaged vehicle	\$ 5,014.00
---	--------------------

Total amount in Lump Sum Basis for repaired vehicle	\$ 2,650.00
--	--------------------

SDLS: Two Thousand Six Hundred Fifty Only



M/s Liu's Brother Auto Engrg Wks

⏪ **Re:<MANDATE IA> - S9M01B53 {ACCIDENT INVOLVING
SLN 6408C (OI) & YN 5941G (TP) ON 18/01/2019}**

Type

🔗 Question

Message

pls proceed

Reply

Our Ref: YN5941G190118

Date: 19/02/2019

Your Ref:

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG BEDOK NORTH AVENUE 4 BEFORE CARPARK OF BLOCK 89
INVOLVING YN5941G AND SLN6408C ON 18/01/2019**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: 199001196N, the registered owners of m/vehicle – **YN5941G** at all material times of the above accident. Our/my vehicle was surveyed by "AXA" authorized appraiser and we/I based our/my claims on his recommendation for **S\$2,650-00** being the repair for **04** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **SLN6408C** when the same was involved in the aforesaid accident with our/my m/vehicle – **YN5941G**.

We/I whereby you are the insurers of m/vehicle **SLN6408C** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **YN5941G** has suffered loss and damage as follows:

(a) Cost of repairs	SS	2,650-00
(b) LOU for pre-repair notice 02 days @ SS80-00		160-00
(c) LOU Fee for 04 days @SS80-00		320-00
(d) GIA / LTA search fee		0-00

Total Amount **S\$ 3,130-00**

We/I enclose herewith copies of the supporting documents for vehicle no. **YN5941G** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle **YN5941G**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 16 April 2019 4:35 PM
To: inred27@gmail.com
Cc: Admin A
Subject: ACCIDENT INVOLVING SLN 6408C AND YN 5941G ALONG BEDOK NORTH AVE 4 ON 18.01.2019

LIEW CHIA LIN

Policy Holder

Dear Sir/Madam,

OUR REF : CC4/ASM19002736/Ujb3
YOUR REF : SLN 6408C

ACCIDENT INVOLVING SLN 6408C AND YN 5941G ALONG BEDOK NORTH AVE 4 ON 18.01.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s LIU'S BROTHER AUTO ENGINEERING WORKSHOP, acting on behalf of the owner of YN 5941G against your motor insurance policy.

Based on the accident report and accident scenario, both drivers has given conflicting versions.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to joyirene@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- **Video footage of accident (if any)**
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

Authorization To Act

Attn: Motor Claims Department

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

I / We, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of YN5941G (vehicle no.) hereby authorize **Liu's Brother Auto Engineering Workshop** ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. YN5941G that was damaged pursuant to the accident which occurred on 18/01/2019 (date) along Bedok North Avenue 4 Before Carpark Of Block 89 (location) involving SLN6408C ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 07th day of September (month) 20 19 (year)

3rd Party Claimant:

Workshop:

Signature: 



Name: Goldbell Leasing Pte Ltd

Address: No. 18 Tuas Avenue 10

Singapore 639142

Nric/ROC No: 199001196N

Signature: 

Name: Liu's Brother Auto Engrg Workshop

Address: 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

ROB No: 53291793J



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	BLN 6408C (Insd veh)	Model: MITSUBISHI CANTER
	YN 5941G (TP veh)	
Date of Accident/ Time:	18/01/2019 / 08:00	

Break Estimate	S	4,714.00	
Final Repair Cost	S	1,325.00	(WGST)
Loss of Use	S	240.00	8 days at S 40.00 per day
Rental (if any)	S		days at S per day
LTB / GIA Search fee	S		
Others	S		
Final Settlement Sum	S	1,965.00	

Payee Name: LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Is Third Party Workshop GIA Registered? YES NO (Indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability: 50 (%)
B) For GIA Registered Workshop:	BOLA Applicable: No / No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply

Remarks:


NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and/or our client have/had/hav against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

	
Signature of Workshop representative / Workshop stamp	Signature of Witness / Workshop stamp (if applicable)
Name of Representative: Liu's Brother Auto Engineering Workshop	Name of Witness: Low Siew Yian (S1543134B)
Date: 27 SEP 2019	Date: 27 SEP 2019
ROB No. 53291793J	
	
Signature of AXA's surveyor/representative	
Name of AXA's surveyor /Representative:	
Date:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19002736/Ugb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 11-10-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLN 6408C	Veh. Inspected	YN 5941G
Policy No.	VPA/P1932520	Coverage (\$)	0.00
Claim No.	S9M01B53	Excess (\$)	0.00
Assign From		Assign Date	14/02/2019
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI CANTER	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	FEB21EA00680	Colour	WHITE
Odometer	57328	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/01/2019	Inspection Date	14/02/2019
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 5941G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT RH CORNER PANEL (CONSISTENT)	CUT	474.60	474.60
1	FRONT RH SIGNAL LAMP (CONSISTENT)	CRACKED	313.60	313.60
1	FRONT RH HEAD LAMP (CONSISTENT)	CRACKED	672.70	672.70
1	FRONT RH SIDE LAMP (CONSISTENT)	BROKEN	235.20	235.20
1	FRT BUMPER SIDE O/S (CONSISTENT)	DISTORTED	340.70	340.70
1	FRT BUMPER (CONSISTENT)	BENT	1,117.20	1,010.30
	LESS 50% DISCOUNT		-	-1,523.55
			3,154.00	1,523.55
SPECIAL NETT ITEMS				
1	FRT 'CORPORATE' ADVERTISEMENT & ARTWORK (SN) (CONSISTENT)	NECESSARY	300.00	280.00
			300.00	280.00
LABOUR				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENTS FOR PROPER FUNCTION .		60.00	20.00
	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.		600.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		600.00	550.00
			1,260.00	870.00
GRAND TOTAL			4,714.00	2,673.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CC4/ASM19002736/Ugb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	59M01853	Vehicle Information	Incident Vehicle Registration #	YH5941G
Reference	CC4/ASMA19002736/Ujbs3a2	Make	Model	TPVD MITSUBISHI CANTER
Loss Date	18 January 2019	Service Address	...	
Report Date	31 Jan 2019 11:22:00 AM	Primary Contact/Insured	LIEW CHIA LIN (LIU CAULING) BLK 168C SIMEI LANE, #10-56, S2316B, Singapore 98814446 ireet27@gmail.com	
Request Date	24 September 2019	Claim Handler	NG Stacey 65688004351 stacey.ng@axa.com.sg	
Due Date				
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)			
Type of Loss	Third Party Vehicle Damage			
Services	Pending verification - Direct Settlement			

Actions

Next Step: Wait for Approve Invoice

[Add Invoice](#)

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type:

[Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019

 LKK Inspection (2).pdf	Forms / Claim Documents	LKK AUTO CONSULTANTS A9B-496 (TP)	17 October 2019 UPLOADED
 LKKAdjustmentLa (3).pdf	Forms / Claim Documents	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
 LETTER TO OI.pdf	Letters and Correspondence	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2019
 TP EST LIST MARKED.pdf	Reports & Statement	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2019
 PAIF COE REBATE.pdf	Reports & Statement	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2019
 MANDATE IA DD 21082019.pdf	Reports & Statement	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2019
 TP PRI EMAIL FROM WORKSHOP WITH YN5941G TP GIA REPORT.mpeg	Letters and Correspondence	DHIWAR Namrata	14 February 2019
 SLN6408C INSD GIA.PDF	Reports & Statement	DHIWAR Namrata	14 February 2019
 GIA YN5941G TP.PDF	Reports & Statement	VISHNU BATHAM Shekhar	31 January 2019