

2/03/2002

ASS. REC. BY:

REF:

CS3/CTI/19002739/Gcd302

Special Instruction:

Surveyor

Mennen

From (Person):

Irene Tay

of

CTI

Date/Time:

14/2/19 @ 5:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SGW 7918C

Insured:

S113527G

at Workshop m/s

Topmax

Tel:

90622722 / 67442653

of

Blk 3007 ubi Rd 1 # 01-410

Policy No:

DMPCSN 3047931800

Claim No:

SNM/9D200652

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

5/01/2019

CA / REV / REP. / REV 24 HRS <sup>1up</sup>

H.O.D. Endorsement:

Date/Time:

11:56am 14/2/19

Person Contacted:

Carmen

Vehicle IN/OUT

Date/Time

Action/Instruction (4) Estimate

SGW 7918C - NA/CTI/19002739/r3

DOA: 5/1/19

S113527G - NA/CTI/19002739/r3

DOA: 5/1/19

Dismanthle: 15/2/2019

After repair: 19/2/2019

## 151

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		14 Feb 2019 08:51 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	LIN YANGZHI		
Vehicle Reg. No.:	SGW7918C	Date of Loss:	05/01/2019 13:00 - :59
Claim Type:	TP / SNM19D200652	Policy/Cover Note No.:	DMPCSN3047931800
Vehicle Reg. No. (Insured):	SJJ3527G	Policy No. (Claimant):	
Repairer:	Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/02/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Wednesday, 13 February 2019 4:21 PM  
**To:** natalie\_ng@rssolomon.com  
**Cc:** Admin A; assignments  
**Subject:** FW: RE:PRE-REPAIR SURVEY ACCIDENT INVOLVING SGW7918C & SJJ3527G ON 5TH JANUARY 2019 AT ABOUT 1300HRS OUR REF [1902-7068 (TOP)(PD)]  
**Attachments:** 2019.02.11-PRI Letter.pdf; 2019.02.11- GIA report.pdf

### WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

As you have rejected our list of surveyors.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with RS SOLOMAN .

Thank you.

Regards,

**Irene Tay**

Executive

Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



#### Disclaimer :

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Irene Tay

**Sent:** Wednesday, 13 February, 2019 4:09 PM

**To:** 'natalie\_ng@rssolomon.com' <natalie\_ng@rssolomon.com>; 'topmax3007@yahoo.com.sg' <topmax3007@yahoo.com.sg>; 'pearlyn\_goh@rssolomon.com' <pearlyn\_goh@rssolomon.com>  
**Subject:** RE:PRE-REPAIR SURVEY ACCIDENT INVOLVING SGW7918C & SJJ3527G ON 5TH JANUARY 2019 AT ABOUT 1300HRS OUR REF [1902-7068 (TOP)(PD)]

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

**Irene Tay**

Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6192  
Fax (65) 62247478/62247175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Pearlyn Goh [mailto:[pearlyn\\_goh@rssolomon.com](mailto:pearlyn_goh@rssolomon.com)]

**Sent:** Tuesday, 12 February, 2019 5:26 PM

**To:** Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>

**Cc:** Natalie Ng <[natalie\\_ng@rssolomon.com](mailto:natalie_ng@rssolomon.com)>; [topmax3007@yahoo.com.sg](mailto:topmax3007@yahoo.com.sg)

**Subject:** RE:PRE-REPAIR SURVEY ACCIDENT INVOLVING SGW7918C & SJJ3527G ON 5TH JANUARY 2019 AT ABOUT 1300HRS OUR REF [1902-7068 (TOP)(PD)]

Dear Irene,

We act for the owner ('our client') of vehicle no. SGW7918C.

Our client's vehicle was involved in the aforesaid accident with your insured's vehicle no. SJJ3527G at the material time. As a result, our client's vehicle was damaged and before our client proceeds to repair his vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our client's vehicle within the stipulated timeline, our client will proceed to repair his vehicle without further reference to you.

Please see below, the following documents for your necessary action:-

1. Our letter of even date;
2. GIA report lodged by our client's driver.

Let us hear from you soonest.

Thank you and Best Regards

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0625G
Vehicle Details	
Vehicle No.:	SGW7918C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	R16B22000770
Chassis No.:	MRHFC5650HT000403
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,584.00
Original Registration Date:	30 Oct 2017
First Registration Date:	30 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$19,584.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2027
PARF Rebate Amount:	\$14,688.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$37,255.00
<b>Total Rebate Amount:</b>	<b>\$51,943.00</b>

The information contained herein is correct as at 15 Feb 2019

OK

MPA219018403 / Progressive Car Care Pte Ltd - HQ  
 ENTRY DATE & TIME: 11/02/2019 10:52  
 SUBMITTED BY: Soo Long Keat

**Your NCD will be affected due to late reporting**  
**Actual e-Filing Submission Date & Time: 11/02/2019 11:00**

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	11/02/2019 10:52
Date Of Accident	05/02/2019 13:00
Exact Location Of Accident	SLIP RD OF HOUGANG AVE 4 TO HOUGANG AVE 10
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW7918C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIN YANGZHI
NRIC No	S8910625G
Email Address	LINYANGZHI@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-97275694
Alternative Phone No	OFFICE-97275694

#### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 VTI CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	C0076688
Cover Note Number	

#### Driver

Name of Driver	LIN YANGZHI
NRIC No	S8910625G
Date Of Birth	26/03/1989
Occupation	INDOOR
Date Of Driving Pass	15/06/2010
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97275694
Fax Number	
Contact Number	OFFICE-97275694
EMail Address	LINYANGZHI@OUTLOOK.COM



Address	BLK 722 TAMPINES STREET 72 #08-23
Postcode	520722
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LIM BENG HUAT GENDER: : MALE
Passenger 2	NAME: : CHUA KIM HUA GENDER: : FEMALE
Passenger 3	NAME: : PASS GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE CAR CARE PTE LTD (6741 5336)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ3527G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CARISSA CHENG YING WEI
NRIC/Passport Number	S9050453C

Contact Number	82284498
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the authorised Third Party.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or assessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurance and non-insurance entities involved in this accident (all persons who have been involved in the accident, the accident shall be collectively referred to as the "Involved Parties") for any purpose. The necessary authority of Singapore and my relevant government agency/authority (such as the police, for the purpose(s) of:
  - (i) collecting, handling and/or dealing with my claims including the settlement of the claims (and any necessary investigations relating to the claims);
  - (ii) investigating the accident and/or any claims;
  - (iii) carrying out and/or dealing with any instructions or responding to any enquiries for any;
- (b) I am authorising my insurer including the handling of correspondence, statements, receipts, reports, photos etc., which could involve disclosure of my personal data/subject to being subject to delivery of the data to all "Involved Parties" or disclosure to third parties for any purpose.
- (c) My Personal Information may/are disclosed by any of the insurers and/or GIA or their third party service providers or agents including their lawyers/law firms, which may be third parties of Singapore, for use or reuse of the above Purpose(s).
- (d) My Personal Information will also be collected and used by some third party for the purpose of fraud detection, investigation and management by insurers and all future claims.
- (e) The information as collected under (d) above may be stored / disclosed:
  - (i) to all law enforcement or any other third parties that need to investigate, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purpose stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre/Person's Signature  
Name:  
NRIC/PRN No.:

## Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car A was stationary on the filter lane making a left turn for about 2 minutes. Car B collided with Car A despite no movement from Car A for a period of time.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
Please be advised that your insurer may have a limited (14) days choice whereby the claim against your policy may be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Payment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Feb 2019		14 Feb 2019 08:51		06 Mar 2019 13:58 <b>S\$0.00</b> (S\$0.00)		<b>Pending for Payment</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

- , Co. Reg. No.: -

Main Claimant:

**LIN YANGZHI**

Vehicle Reg. No.:

**SGW7918C**

Claim Type:

**TP / SNM19D200652**

Vehicle Reg. No. (Insured):

**SJJ3527G**

Repairster:

**Topmax Auto Body Shop (HQ)** Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722

Handling Insurer:

**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Irene Tay Hui Ping** - 638986192]

Adjuster:

**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... **[Final Rpt due 25/02/2019]**

Adj Asg. Remarks:

PLEASE SURVEY AND REVERT

Date of Loss:

05/01/2019 13:00 - :59  
**[14 Months and 6 Days From LTA Reg Date (Man Yr)]**

Policy/Cover Note No.:

DMPCSN3047931800

Policy No. (Claimant):

Excess:

S\$0.00

**[Created by insurer]**

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**


















































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGW7918C (SNM19D200652)  
[SJJ3527G]  
TP  
LIN YANGZHI  
Jan 5 2019 1:00PM  
[-]  
Topmax Auto Body Shop

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	06/03/19 13:58	Adjuster Report								Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	18/02/19 09:29	General View								Load JPG	<input checked="" type="checkbox"/>	
2	18/02/19 09:29	General View								Load JPG	<input checked="" type="checkbox"/>	
3	18/02/19 09:29	General View								Load JPG	<input checked="" type="checkbox"/>	
4	18/02/19 09:29	General View								Load JPG	<input checked="" type="checkbox"/>	
5	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
6	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
7	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
8	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
9	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
10	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
11	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
12	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
13	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
14	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
15	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
16	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
17	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
18	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
19	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
20	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
21	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
22	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
23	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
24	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
25	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
26	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
27	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
28	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
29	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
30	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
31	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
32	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
33	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	
34	18/02/19 09:30	General View								Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	18/02/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/02/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/02/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/02/19 09:30	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
39	18/02/19 09:30	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
40	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	18/02/19 09:30	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	23/02/19 14:26	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	23/02/19 14:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
85	23/02/19 14:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
86	23/02/19 14:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
87	23/02/19 14:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
88	23/02/19 14:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
89	23/02/19 14:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
90	23/02/19 14:26	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19002739/GCD3E2

Date: 06/03/2019

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3047931800		
Claimant Vehicle No :	SGW7918C	Insured Vehicle No :	SJJ3527G		
Date of Loss:	05/01/2019	Nature of Claim:	TP	Claim No:	SNM19D200652

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGW7918C</b>		Engine No:	R16B22000770
Make & Model:	HONDA CIVIC, 1.6 L VTI (A)		Chassis No:	MRHFC5650HT000403
Reg. Date:	30/10/2017 (Man. Year: 2017)		Odometer:	29749 km
Colour:	White			
Engine Capacity:	1597 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	14/02/2019	
Date Inspected:	14/02/2019	Inspected At: Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410 Singapore 408701
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 27 Feb 2019)

**Parts:** 143      HONDA CIVIC 1.6 L VTI (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** LKK Auto Consultants Pte Ltd/SGW7918C/06/03/2019 13:58

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/SGW7918C/06/03/2019 13:58. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SGW7918C/06/03/2019 13:58. Not valid without Reference section.
--

< END OF ESTIMATES >