Date: 15/2/2019

Immediate Advice

To : AXA Insurance Pte Ltd

Survey details

Date of loss	29/1/20129
Date of appointment	13/2/2019
Date of survey	14/2/2019
Location of survey	SC AUTO INDUSTRIES (S) PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	XD 5793G
Make and Model	SCANIA P380CB6X4MHZ
Date of registration	8/5/2012
Excess	\$1,500
Market Value	\$40,000.00
Parf Rebate	\$16,623.00
Nett Loss	\$23,377.00

Repair details

Initial Estimate	¢10 627 70
linitiai Estimate	\$19,637.78

Proposed/Revised repair cost:

Parts	\$9,267.22
"Check items (Estimated)	\$1,270.54
Labour	\$3,730.00
Total	\$14,267.76
Lump Sum (Estimated)	\$11,400.00

Number of days of repair 6 days (est)

Remarks:

The vehicle sustained damages at the front portion.

Damages Consistent Repair Cost Economical