

ASS. REC. BY:

REF: CS3 | FC19002805 | Jcd3

Special Instruction:

Surveyor:

**ASSIGNMENT (Office)**

From (Person): Merina Chia (CWS) of FCI Date/Time: 16/2/2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: JQR 6519 Insured: SHC 7163G

at Workshop m/s JC Motor Tel: 6584 6914

of F1 Woodlands Ave 10 #02-09

Policy No: \_\_\_\_\_ Claim No: D19000845MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 30/1/2019

(Client's Record) 18/2/2019 After lunch

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 16/2 Person Contacted: \_\_\_\_\_ Vehicle IN/OUT

Date/Time	Action/Instruction ( x ) Estimate
	<u>JQR 6519 - X</u>
	<u>SHC 7163G - X</u>
	<u>Dismantle: 19/2/2019</u>
	<u>After repair: 25/2/2019</u>
	<u>No MV</u>



**Catherine Chong (LKK Auto)**

---

**From:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>  
**Sent:** Thursday, 14 February, 2019 2:42 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWS Motor Claims; Merina Chia San San  
**Subject:** PRI: SURVEY ASSESSMENT - D19000845MFSH/1  
**Attachments:** Jobsheet\_D19000845MFSH\_TPD1.pdf

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	01-02-2019	<b>Our Ref No.</b> D19000845MFSH
<b>Accident Date</b>	30-01-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC7163G	<b>Third Party Vehicle.</b> JQR6519
<b>Survey Location</b>	71 WOODLANDS AVE 10#02-09 WOODLANDS INDUSTRIAL XCHANGE	
<b>Contact Person.</b>	XIAO XIANG	
<b>Contact No.</b>	0/ 91170086 ✓	<b>Fax No.</b> 65073849
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	JC MOTOR CONSULTANCY	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	CATHERINE LIM LLC	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MERINA CHIA SAN SAN	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

*12/2/19 After lunch anytime*




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FC119002805/Jcd3s2 Date: 02-04-2019	
Code: FCI2			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHC 7163G	Veh. Inspected	JQR 6519
Policy No.		Coverage (\$)	0.00
Claim No.	D19000845MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	14/02/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	PN15311YF005055655	Colour	SILVER
Odometer	83127 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60R15	TOYO	6 mm
L/H Front Tyre	185/60R15	TOYO	6 mm
R/H Rear Tyre	185/60R15	TOYO	6 mm
L/H Rear Tyre	185/60R15	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information			
Accident Date	30/01/2019	Inspect Date / Time	18/02/2019 ( 01:18 PM )
Survey held at	71 WOODLANDS AVE 10 #02-09		
Repairer	JC MOTORS PTE. LTD.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/FC119002805/Jcd3s2

Inspected By

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.