

27/03/2002

ASS. REC. BY:

REF:

C83/CT119002808/Ecd302

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Irene Tay of CT1 Date/Time: 14/2/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLQ 5606M Insured: SGN 6151Bat Workshop m/s T & S Motor Tel: 9756 7923.of BLK 5035 AMK #01-357Policy No: DMPCSN30847318011 Claim No: SNM190200774602

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/2/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 14/2 Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLQ 5606M - X</u>
	<u>SGN 6151B - X</u>
	<u>Dismantle: 14/2/2019</u>
	<u>After repair: 20/2/2019</u>

Steve

REF:

CTI

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SLQ 5606M

at Workshop no. T & S Motor

at BLK 5035 AMK #01-357

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

PRQ

repair large 2-3K

25/2/2019

Veh No. SLQ 5606M at Regn. 14/07/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer

C.C. 1590

Colour: Silver

A/C Insured / Std / NI / NA

Sp Reading: 20776

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMY SRCY 1A Gu 006925

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

12/2/2019

D.O.I.

14/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?



: Preli. Report

1)



: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

1) G-PS St

1) Photo

1) Film

1) ...

Total

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Report Format:

PRQ

Lump Sum / L.B. (\$)

190

190

RECEIVED 28 MAY 2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 17:50 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	PHUA KAH BENG, ID: S1507761A			
Vehicle Reg. No.:	SLQ5606M	Date of Loss:	12/02/2019 14:00 - :59	
Claim Type:	TP / SNM19D200774C02	Policy/Cover Note No.:	DMPCSN30847318011	
Vehicle Reg. No. (Insured):	SGN6151B	Policy No. (Claimant):	1700024156	
		Excess:	S\$0.00	
Repairer:	T & S MOTOR SERVICE (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #04-10, 568047 Ang Mo Kio - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 31/05/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 14 February, 2019 2:07 PM
To: Serene Tan
Cc: Serene Tan; Admin A; assignments
Subject: FW: PRE-REPAIR SURVEY
Attachments: 12022019163014.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with M Nedumaran.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road # 16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



View In
Steve

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Irene Tay
Sent: Wednesday, 13 February, 2019 5:39 PM
To: 'Serene Tan' <serene.tan@mneduco.com.sg>
Subject: FW: PRE-REPAIR SURVEY

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Please reply to our Branch Office for this matter

→ Branch Office: 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/T2/1912906/st
Your Reference : SGN 6151B

Date : 12th February 2019

BY EMAIL: claimsdept@sg.cntaiping.com

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 12/2/2019 INVOLVING VEHICLE NOS. SLQ 5606M AND SGN 6151B ALONG PAYA LEBAR FILTER ROAD HEADING TO PIE (TUAS).

We are instructed by PHUA KAH BENG (owner of motor vehicle no. SLQ 5606M) and/or T & S MOTOR SERVICE (the motor workshop for SLQ 5606M) to notify you of a road traffic accident on 12/2/2019 at about 1435 hours along PAY ALEBAR FILTER ROAD HEADING TO PIE (TUAS) involving our client's vehicle registration number [SLQ 5606M] and [SGN 6151B] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

M NEDUMARAN & CO

M NEDUMARAN & CO - (Branch Office)

Encl

c.c. 1) EE CHER LENG

(Vehicle : SGN 6151B)

- 2) NAME OF WORKSHOP :
T & S Motor Service
Blk 5035 Ang Mo Kio Industrial Park
#01-357
Singapore 569538
Telephone : 9756-7923

(Vehicle : SLQ 5606M)

(Attention : Mei Hua)

PCV Accident Report

(For Reporting only)

☐ Braddell ☐ Sln Ming ☐ Sg. Kadut ☐ Pandan ☐ Loyang

Section A - To Be Completed By Driver Who Is Involved in The Accident

Date & Time of Accident: Date: 12/2/19 Time: 14:35

Date & Time of Reporting: Date: _____ Time: _____

Place of Accident: Paya Lebar After Road leading to B1K131

Vehicle Reg. No.: SLQ 5606M Make / Model: Thit. Lancer

Purpose of Use at Time of Accident: Goods transportation / private usage / others: Private usage

Name: LOW CHOON HUA NRIC / FIN No.: S1563082E

Address: B1K131 Ang Mo Kio Ave 3 Street 12 #12-1597

Postcode: 560131 Date Of Birth: 4/9/1962

Home: _____ Handphone: 91893592

Email: tsmotor@service@hotmail.com Gender: (Male) Female

Occupation: Management / Sales / Retiree / Housewife / Technical / Education / Others: self employed

Type of Claims: Third Party Own Damage / Reporting Only Licence Pass Date: _____

Driver Status: Owner / Non-owner Years of Driving Experience: 36 22/4/1983

If you are not the owner, the owner's name & tel: Phua Kah Beng 93209119

Owner's Address: B1K131 Ang Mo Kio Ave 3 #12-1597 S(560131)

Relationship with Owner: husband Owner's NRIC / Company Reg. No.: S1507761A

Vehicle Towed In? Yes ☒ No ☐ My Insurance Company: _____

Police Reported? Yes ☒ No ☐ Police Report Reference No.: _____

Company's Vehicle? Yes ☒ No ☐ Insurance Policy No: _____

Do you have witness? Yes ☒ No ☐ Type of Policy: Comprehensive / Third Party Fire & Theft / Third Party Only

(If Yes, Witness Name & Contact No: _____)

Weather Condition: ☒ Clear / Cloudy / Light Rains / Heavy Rains

Road Condition: ☒ Dry ☐ Wet Was anyone injured in the accident? Yes ☒ No ☐

Other vehicle or property damage? ☒ Yes ☐ No Was Notice of Intended Prosecution given? Yes ☒ No ☐

Describe How Accident Happened: Please use SKETCH PLAN for accident description & sketch of accident scene

Third Party's Details (Use Annex 2 for Chain Collision as attachment)

Vehicle Make / Model: _____ Vehicle Reg. No.: SGN 6151B

Name of Driver: _____ NRIC No.: _____

Insurance Company: _____ Handphone: _____

Driver's Declaration: I declare that the information given in this report are true and correct and I undertake to assume full responsibilities for all consequences should any part given above be untrue.

Signature: _____

Date: _____

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	7761A

Vehicle Details

Vehicle No.:	SLQ5606M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	4A92CP5682
Chassis No.:	JMYSRCY1AGU006925
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$11,182.00
Original Registration Date:	14 Jul 2017
First Registration Date:	14 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$11,182.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2027
PARF Rebate Amount:	\$8,386.00

Intended COE Rebate Details

COE Expiry Date:	13 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QPR Paid:	\$45,201.00
COE Rebate Amount:	\$38,026.00
Total Rebate Amount:	\$46,412.00

The information contained herein is correct as at 14 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	13/02/2019 10:20
Date Of Accident	12/02/2019 14:35
Exact Location Of Accident	PAYA LEBAR FILTER ROAD HEADING TO PIE(TUAS)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLQ5606M
Insured/Policyholder	
Name Of Registered Owner	PHUA KAH BENG
NRIC No	S1507761A
Email Address	LOWCHOONHUA1962@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93209119
Alternative Phone No	OTHERS-91893597
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER EX 1.6 AT LED TAIL LAMP
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700024156
Cover Note Number	
Driver	
Name of Driver	LOW CHOON HUA
NRIC No	S1563082E
Date Of Birth	04/09/1962
Occupation	INDOOR
Date Of Driving Pass	22/04/1983
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91893597
Fax Number	
Contact Number	
EMail Address	LOWCHOONHUA1962@GMAIL.COM

Address	BLK 131 ANG MO KIO AVE 3 #12-1597
Postcode	560131
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : MDM ONG GENDER: : FEMALE
Passenger 2	NAME: : MDM PHUA GENDER: : FEMALE
Passenger 3	NAME: : MISS VITA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN6151B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/12/19 @ 14:35, I was driving along Paya Lebar turning to Filter Road heading to PTE (Tues). I stopped my car at Pedestrian crossing while pedestrian crossing. Suddenly I heard a loud bang from my rear. I alighted from my car and saw a car SMB151B bang onto my rear portion of my car.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

X Phua

Policyholder's Signature
Date & Time:

W.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 17:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	PHUA KAH BENG , ID: S1507761A								
Vehicle Reg. No.:	SLQ5606M	Date of Loss:	12/02/2019 14:00 - :59 [18 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200774C02	Policy/Cover Note No.:	DMPCSN30847318011						
Vehicle Reg. No. (Insured):	SGN6151B	Policy No. (Claimant):	1700024156						
		Excess:	S\$0.00						
Repairer:	T & S MOTOR SERVICE (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #04-10, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 31/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents









*SLQ5606M (SNM19D200774C02)
[SGN6151B]
TP
PHUA KAH BENG
Feb 12 2019 2:00PM
[-]
T & S MOTOR SERVICE

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)						Thumbnail	Print		
1	13/02/19 10:35	Accident Statement						Load HTM			
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)						Thumbnail	Print		
1	13/02/19 10:35	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	13/02/19 10:35	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	13/02/19 10:35	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	13/02/19 10:35	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
5	13/02/19 10:35	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
6	13/02/19 10:35	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
7	13/02/19 10:35	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
2	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
3	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
4	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
5	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
6	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
7	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
8	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
9	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
10	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
11	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
12	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
13	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
14	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
15	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
16	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
17	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
18	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
19	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
20	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
21	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
22	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		
23	28/05/19 11:28	General View						Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
24	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/05/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/05/19 11:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/05/19 11:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	28/05/19 11:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	28/05/19 11:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	13/02/19 10:30	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/05/19 17:51	pri contact	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	13/02/19 10:35	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	13/02/19 10:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/02/19 10:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/02/19 10:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/02/19 10:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/02/19 10:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/02/19 10:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/02/19 10:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	13/02/19 10:30	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19002808/ECD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30847318011

Claimant Vehicle
No: SLQ5606MInsured Vehicle
No: SGN6151B

Date of Loss: 12/02/2019

Nature of Claim: TP

Claim
No: SNM19D200774C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ5606M

Make & Model: MITSUBISHI LANCER, 1.6 (A)

Engine No: 4A92CP5682

Reg. Date: 14/07/2017 (Man. Year: 2017)

Chassis No: JMYSRCY1AGU006925

Colour: Silver

Odometer: 20776 km

Engine Capacity: 1590 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 14/02/2019 Inspected At:

T & S MOTOR SERVICE (HQ)
BLK 5035 ANG MO KIO INDUSTRIAL
PARK 2 #01-357
SINGAPORE 569538

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 10 Jun 2019)

Parts: 143 MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ5606M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >