

TP Claims against NTUC Income: Follow-Through Survey

21/2/2019

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Estimate	Tentative repair cost
1	MT/1030932-002	COMFORT TRANSPORTATION PTE LTD	SHC 1958U	SLL 8181C	4/2/2019	\$8,566.83	\$2,244.29
2	MT/1031940-002	COMFORT TRANSPORTATION PTE LTD	SHA 3694C	SJL 3650Y	5/2/2019	\$1,785.68	\$900.00
3	MT/1033052-001	COMFORT TRANSPORTATION PTE LTD	SHA 3749D	GBH 6126R	15/2/2019	\$850.00	\$350.00
4	MT/1033055-001	COMFORT TRANSPORTATION PTE LTD	SHD 3199A	SLF 3432T	14/2/2019	\$2,399.06	\$1,200.00
5	MT/1031629-002	COMFORT TRANSPORTATION PTE LTD	SH 8548S	SJJ 8434H	12/2/2019	\$6,822.16	\$2,750.00
6	MT/1031383-002	COMFORT TRANSPORTATION PTE LTD	SHD 3198C	SJU 9736Y	9/2/2019	\$1,829.12	\$550.00
7	MT/1032845-002	COMFORT TRANSPORTATION PTE LTD	SHD 4145Z	SMA 1458Y	18/2/2019	\$2,574.90	\$1,000.00
8	MT/1033061-001	COMFORT TRANSPORTATION PTE LTD	SH 9493J	SJS 8276A	15/2/2019	\$5,712.08	\$2,750.00

Claim received from LKK Auto

My Desktop

Notice of Loss

Policy Query

Policy No.

Date of Accident

12/02/2019 07:58

Vehicle No.(For Motor)

SJJ8434H

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5104587381		SATWANT SINGH S/O KUNDAN SINGH	S1684061J	GPC	drivo CLASSIC	SJJ8434H	SJJ8434H	11/10/2018	10/10/2019

Continue

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/02/2019 10:44
Date Of Accident	12/02/2019 00:05
Exact Location Of Accident	CHOA CHU KANG EAST FLYOVER T > CHOA CHU CRESCENT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SH8548S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	WEE BOOI HENG
NRIC No	S1434648A
Date Of Birth	27/08/1960
Occupation	OUTDOOR
Date Of Driving Pass	28/09/1978
Driving Experience	40 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96436341
Fax Number	
Contact Number	
EMail Address	WEEJOHN49@YAHOO.COM.SG

Address	BLK 106C PUNGGOL FIELD #04-514
Postcode	823106
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20190212/2009 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ8434H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

RH REAR

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police
Report.
T/20190312/1009

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

COMFORT Sketch Plan Form - P2



**SINGAPORE
POLICE FORCE**



T/20190212/2009

1 of 3

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20190212/2009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/02/2019 03:06		Vide Report No.: J/20190212/0001		Station Diary No.: 12	
Informant's Particulars					
Name of Informant: WEE BOOI HENG			Address: APT BLK 106C PUNGGOL FIELD #04-514 SINGAPORE 823106		
ID Type / ID No.: NRIC NO / S1434648A			Contact No.: Home/Office: Mobile: 96436341		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 58	Date of Birth: 27/08/1960	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 3 Date of Expiry:		

General information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 12/02/2019 00:05	Type of Location: Flyover
Location: Along Road 1 Traveling Toward Road 2 KRANJI EXPRESSWAY CHOA CHU KANG DRIVE ALONG KJE TOWARDS CHOA CHU KANG DR. CHOA CHU KANG EAST FLYOVER				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SH8548S	Car				Slightly Damaged	1
SJJ8434H	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190212/2009

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 3

Report No. T/20190212/2009

CONTINUATION OF REPORT

Driver			
Name	WEE BOOI HENG		ID No. S1434648A
Related Vehicle	SH8548S (Car)		Contact No. 96436341
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	MICHELLE		ID No. -
Related Vehicle	SH8548S (Car)		Contact No. 90256693
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12/02/2019 at about 0001hrs, I was driving my vehicle bearing vehicle no. SH8548S a blue comfort delgro taxi along KJE towards Choa Chu Kang flyover. On my vehicle, there was another passenger by the name of Michelle. I then stopped by the traffic light waiting for it to turn green. I was in the middle lane at the point of time. When the traffic light turned green in my favour, I proceeded on, turning right onto Choa Chu Kang flyover and was also changing to the third lane in the midst during the turning. Suddenly, a vehicle bearing SJJ8434H appeared out of no where on the third lane. I tried to stop but could not stop in time. Thus, the other vehicle collided onto my vehicle. As a result of the collision, my vehicle suffered damages on the front left portion.

After the collision, we alighted from the vehicle to make a cursory check of the vehicle. The other driver then insisted me to pay for the damages on his vehicle which I declined. I then called for the police as I think I was not at fault. The other driver then insisted that he is busy and then drove off without waiting for the arrival of the police.

He only left me his contact number 98534113.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999



T/20190212/2009

3 of 3

Report No. T/20190212/2009

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 LOUIS SEAH ZHENG LIANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 12/02/2019 03:06
Officer In Charge Of Case: TP / GIT / Insp TAN CHIN YONG Contact No.: 65476178	Classification Of Case: SN 035
Authentication Stamp NP168	Signature: Singapore Police Force

CASH SALES/INVOICE

No: 0002248



James Towing Services

Blk 288 Yishun Ave 6 #07-50 Singapore 760288
James Low HP: 9015 7488 • 9811 9966



日期 12/12/19
Date:

寶號
Messre:

COM FOR DELGR0

車號

Vehicle No:

SH 8548 S

型號

Model No:

Hyundai Taxi

由

From:

704 chuan kang st 53

到

To:

LOYALTY

時間 (日夜)

Time (day/night)

0200am

0300am

其他

Other:

BURDENT

現金

CASH\$

支票

CHEQUE:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
NOTES: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdeemeanor to your vehicle whilst being towed.

收貨人

Received by

96436341

經手人

Issued by

2

Date/Time: 12.02.2019 14:11

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305267946

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO.: SH 8548S

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL I-40

DATE/TIME IN
12.02.2019 00:05

YR OF MANU.
26.05.2016

TARGET DATE

CHASSIS CODE
KMHLB41UMGU089894

COMPLETION DATE/TIME:


UNT CARD NO.

JOB DESCRIPTION

Accident Date: 12.02.2019

NATURE: 3P 12.02.19/C

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SH 8548S

LIMITS

Vehicle No.:

SH 8548S

ervice Advisor

Signature/Date

Name of Service Advisor

Date

ned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

VEHICLE NO : SH 8548S

DATE 13/2/2019

MAKE :

MODEL : HYUNDAI i40

NTUC-4S

TS

LKK - Calvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet Hinge (LH/RH) <i>x su</i>		\$ 41.00	\$ 82.00
	Bonnet Absorber, LH <i>x su</i>			\$ 58.10
	Radiator Grille <i>x su</i>			\$ 1,110.10
	Front Bumper Cover <i>- Rhl</i>			\$ 1,052.20
	Front Bumper Sponge <i>7 su</i>			\$ 99.20
	Front Bumper Reinforcement <i>x su</i>			\$ 402.10
	Front Bumper Grille (LH) <i>x su</i>			\$ 93.60
	Front Bumper Grille Airduct (LH) <i>7 su</i>			\$ 26.20
	Front Bumper Bracket Top (LH) <i>x su</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>- m</i>			\$ 24.60
	Headlamp Support Panel Assy <i>7 su</i>			\$ 907.40
	Headlamp (LH) <i>- 7 su</i>			\$ 1,388.00
	Front Fender (LH) <i>- Rhl</i>			\$ 566.30
	Front Fender Shield (LH) <i>x su</i>			\$ 175.90
	Frt Wheel Hub Cab, LH <i>- 4 su</i>			\$ 107.10
	SUB TOTAL			\$ 6,115.20
	LESS 20%			\$ 1,223.04
	DISCOUNTED TOTAL			\$ 4,892.16
	Front Fender Advertisement Logo (LH) <i>- m</i>			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 500.00
	Wiring			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Frt Wheel Alignment			\$ 80.00
	<i>veh-Tow-in</i>			
	TOTAL LABOUR			\$ 1,830.00
	ESTIMATE TOTAL			\$ 6,822.16
				2750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin 10/10/19

13/2/19 1130h

3 Pys

4/5

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305267946

Date : 15/02/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SH 8548S

Date of Accident : 12-Feb-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SJJ8434H

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$2,750.00

\$2,750.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 22/2/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19002826/K1vd3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 22-02-2019	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJJ 8434H	Veh. Inspected	SH 8548S
Policy No.	5104587381	Coverage (\$)	0.00
Claim No.	MT/1031629-002	Excess (\$)	0.00
Assign From		Assign Date	13/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU089894	Colour	BLUE
Odometer	407581	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	7 mm
L/H Front Tyre	205/60 R16	CAMPEON	7 mm
R/H Rear Tyre	205/60 R16	CAMPEON	7 mm
L/H Rear Tyre	205/60 R16	CAMPEON	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/02/2019	Inspection Date	13/02/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8548S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	BONNET HINGE (LH/RH) @\$41.00	SERVICEABLE	82.00	-
1	BONNET ABSORBER, LH	SERVICEABLE	58.10	-
1	RADIATOR GRILLE	SERVICEABLE	1,110.10	-
1	FRONT BUMPER COVER	DEFORMED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	SERVICEABLE	99.20	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	402.10	-
1	FRONT BUMPER GRILLE (LH)	SERVICEABLE	93.60	-
1	FRONT BUMPER GRILLE AIRDUCT (LH)	SERVICEABLE	26.20	-
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (LH)	CRACKED	24.60	24.60
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	907.40	-
1	HEADLAMP (LH)	CRACKED	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	175.90	-
1	FRT WHEEL HUB CAB, LH	GRAZED	107.10	107.10
	LESS 20% DISCOUNT		-1,223.04	-627.64
			4,892.16	2,510.56
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING.		1,000.00	400.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE / REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	VEH TOW-IN. (NPA)		-	-
			1,830.00	840.00

Report Ref No. NS/INC19002826/K1vd3e2

GRAND TOTAL		6,822.16	3,450.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,750.00

Report Ref No. NS/INC19002826/K1vd3e2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.