

ASS. REC. BY:

REF:

CS/FA190003833/DH3 n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Serene (CASC) of FCI Date/Time: 14/2/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FV 4730M Insured: SHA 4349Tat Workshop m/s SG 98 Motor Tel: _____of BLK 4001 AMC #01-21Policy No: _____ Claim No: D19000998 MECH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9/2/2019
(Client's Record)**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement: _____

Date/Time: 14/2 Person Contacted: Rose Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>FV 4730M - X</u>
	<u>SHA 4349T - X</u>

REF:

Surveyor

ASSIGNMENT

CBE Aug 2022

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

FV 4730 M

Yr Regn:

Spt 2002

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kawasaki KRR-ZX150 148

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

N.A.

T/Radio: Insured / Std / NI / NA

Eng/No:

KR150FEA55001

C/No:

KR150KA55001

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90 R17

R:

- 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

09/02/2019

D.O.I.

15/02/2019

Survey held at

SG 98 Main AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front 4 O/S Rear 4 N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	First Capital SHA 4349T
	MV 6K LTA 925.00 NL 5K
	RECEIVED 06 AUG 2019
	MV: 6000 LTA 925 NL: 5075
06/08/19	pmaw 2/S 3901/- at 6 days 8 rev. (Red: 2348.50: 42%)

Date/Time, File Pass to?

☐

Preli. Report

1) 6/8 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 3900/-)

145

50

50

63

308

Catherine Chong (LKK Auto)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 14 February, 2019 2:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims; Serene Ler
Subject: PRI: SURVEY ASSESSMENT - D19000998MFSH/1
Attachments: Jobsheet_D19000998MFSH_TPD1.pdf

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

MOTOR SURVEY ASSIGNMENT

Date	12-02-2019	Our Ref No. D19000998MFSH
Accident Date	09-02-2019	Claim Type. Third Party
Insured Vehicle	SHA4349T	Third Party Vehicle. FV4730M
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21	
Contact Person.	LEENA	
Contact No.	64524898/ 0	Fax No. 64526898
Survey Type	WITHOUT PREJUDICE: NO EST.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6026C
Vehicle Details	
Vehicle No.:	FV4730M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	KAWASAKI
Vehicle Model:	KRR-ZX150
Primary Colour:	Silver
Manufacturing Year:	2002
Engine No.:	KR150EEA55001
Chassis No.:	KR150KA55001
Maximum Power Output:	-
Open Market Value:	\$3,650.00
Original Registration Date:	03 Sep 2002
First Registration Date:	03 Sep 2002
Transfer Count:	6
Actual ARF Paid:	\$548.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,859.00
COE Rebate Amount:	\$925.00
Total Rebate Amount:	\$925.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 20 Feb 2019

OK

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22 February 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : FV 4730M

Kawa KR 150

ACCIDENT DATE: 9 February 2019

Description	Qty	Quotation \$
1 Handle Bar <i>bst</i>	2	165.00 ✓
2 Head Cowling <i>broken</i>	1	235.00 ✓
3 Visor / B-BBQ <i>broken</i>	1	165.00 ✓
4 Head Lamp <i>broken</i>	1	285.00 ✓
5 Head Lamp Stay <i>bst</i>	1	195.00 ✓
6 Air Intake RH <i>broken / deformed</i>	1	240.00 ✓
7 Fork Tube <i>bst</i>	1 set	480.00 ✓
8 Fork Oil Seal <i>klc</i>	1	70.00 ✓
9 Front Mudguard <i>broken</i>	1	195.00 ✓
10 Front Rim <i>Dented</i>	1	320.00 ✓
11 Front Brake Disc <i>NH</i>	1	280.00 X
12 Fuel Tank <i>Dented</i>	1	390.00 ✓
13 Exhaust Pipe <i>cut</i>	1	450.00 ✓
14 Brake Lever <i>cut</i>	1	90.00 ✓
15 Clutch Lever <i>NH</i>	1	75.00 X
16 Front Signal Light RH <i>broken</i>	1	75.00 ✓
17 Brake Pump <i>NH</i>	1	80.00 X
18 Handle Bar Top Bracket <i>NH</i>	1	75.00 X
19 Front Seat <i>Damn</i>	1	95.00 ✓
20 Front Footrest <i>bst</i>	1	135.00 ✓
21 Radiator Assy <i>bst</i>	1	550.00 ✓
22 Pillion Grip <i>cut</i>	1	95.00 ✓
23 Balancer <i>cut</i>	1 set	190.00 ✓
24 Rear RH Fairing <i>cut</i>	1	95.00 ✓
25 Mirror <i>broken / dislodged</i>	1 set	140.00 ✓
Sub-Total		5,165.00
Less 10%		516.50
Sub-Total		4,648.50

4695.00
4189.50

VEHICLE NO : FV 4730M

Kawa KR 150

Nett Items

- 1 Ninja sticker *huc*
- 2 Front number plate *SVL*
- 3 Towing fee *huc*
- 4 Remove & replace parts, align & etc
- 5 Remove & replace fork assy, fork bracket, fork oil seal, top up fork oil
- 6 Replace rim, brake disc, brake pump
- 7 Align body frame
- 8 Putty & respray paint

290.00 80/-
15.00 X
50.00 30/-
350.00 200/-
200.00 80/-
700/-
80.00 30/-
280.00 100/-
450.00 180/-

Special Nett Items

- 1 Meter Assy *HH*

385.00 X

Sub-Total

2,100.00

Nett Total

6,748.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

4889.50

4/S 3900/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15/02/2019 C1730ms

NA Andrew

2/Sim

6 days.

yan

LKK Auto



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002833/Dtd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-08-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4349T	Veh. Inspected	FV 4730M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000998MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	KAWASAKI KRR-ZX150	c.c	148	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	KR150KA55001	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90 R17	MAXXIS	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	70/90 R17	MAXXIS	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S,N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/02/2019	Inspection Date	15/02/2019	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FV 4730M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	HANDLE BAR	BENT	165.00	165.00
1	HEAD COWLING	BROKEN	235.00	235.00
1	VISOR/B-BBQ	BROKEN	165.00	165.00
1	HEAD LAMP	BROKEN	285.00	285.00
1	HEAD LAMP STAY	BENT	195.00	195.00
1	AIR INTAKE RH	BROKEN / DEFORMED	240.00	240.00
1	SET FORK TUBE	BENT	480.00	480.00
1	FORK OIL SEAL	NECESSARY	70.00	70.00
1	FRONT MUDGUARD	BROKEN	195.00	195.00
1	FRONT RIM	DENTED	320.00	320.00
1	FRONT BRAKE DISC	NOT NECESSARY	280.00	-
1	FUEL TANK	DENTED	390.00	390.00
1	EXHAUST PIPE	CUT	450.00	450.00
1	BRAKE LEVER	CUT	90.00	90.00
1	CLUTCH LEVER	NOT NECESSARY	75.00	-
1	FRONT SIGNAL LIGHT RH	BROKEN	75.00	75.00
1	BRAKE PUMP	NOT NECESSARY	80.00	-
1	HANDLE BAR TOP BRACKET	NOT NECESSARY	75.00	-
1	FRONT SEAT	DAMAGED	95.00	95.00
1	FRONT FOOTREST	BENT	135.00	135.00
1	RADIATOR ASSY	BENT	550.00	550.00
1	PILLION GRIP	CUT	95.00	95.00
1	SET BALANCER	CUT	190.00	190.00
1	REAR RH FAIRING	CUT	95.00	95.00
1	SET MIRROR	BROKEN / DISLODGE	140.00	140.00
	LESS 10% DISCOUNT		-516.50	-465.50
			4,648.50	4,189.50
SPECIAL NETT ITEMS				
1	NINJA STICKER (SN)	NECESSARY	290.00	80.00

Report Ref No. CS/FCI19002833/Dtd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	15.00	-
1	METER ASSY (SN)	NOT NECESSARY	385.00	-
			690.00	80.00
	LABOUR			
	TOWING FEE.		50.00	30.00
	REMOVE & REPLACE PARTS,ALIGN & ETC.		350.00	200.00
	REMOVE & REPLACE FORK ASSY,FORK BRACKET,FORK OIL SEAL,TOP UP FORK OIL.		200.00	80.00
	REPLACE RIM,BRAKE DISC,BRAKE PUMP.		80.00	30.00
	ALIGN BODY FRAME.		280.00	100.00
	PUTTY & RESPRAY PAINT.		450.00	180.00
			1,410.00	620.00
	GRAND TOTAL		6,748.50	4,889.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,900.00

Report Ref No. CS/FCI19002833/Dtd3n2

MARKET VALUE: \$6,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$925.00=NETT VALUE: \$5,075.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.