

ASS. EDC TEL

REF CS3/III19002848/R1C0302

of Instruction

Surveyor
Name

Rasu
Gabriel Wee

ASSIGNMENT (Office)

III

Date/Time 28/2/19 @ 1:40pm

Estimated Cost

Bill to

OD/TP WS/TP RES/OD RES/EVA/INV/MVTC

To Inspect Vehicle No

8KA 6981J

Insured

SHD4092S

at Workshop no

Master Car Spray

Tel

9856 8137

of

36 Joh Guan Rd East #01-48

Policy No

GA392364/1

Claim No

MCT19020400

Sum Insured

Excess

Make of Veh:
(Client's Record)

D.O.A

13/02/2019

CA / REV / REP. / REV 24 HRS

1/3/19

H.O.D. Endorsement

Date/Time

3:05pm @ 28/2/19

Person Contacted

Pauline

Vehicle

OUT


Date/Time	Action/Instruction (X) Estimate
	call back julesen Hua Hong on 1/3/19.
	8KA 6981J -
	SHD 4092S -
	Disassemble : 5/3/2019 @ 12:17 pm
	After repair : 7/3/2019 @ 04:22 pm

REF:

4146E
COP No: 2023/56P

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SKQ 6981J**
 at Workshop m/s **MASTER CAR**
 of **36, Tott Nupin Rd Coast # 01-48**
 Insured: **111**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS **v /**
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No. **SKQ 6981J** Yr Regn: **2008 / 80P**
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **SUZUKI SWIFT 1.6 MT c.c. (586)**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp. Reading: **197217** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JSAE ZC 31500202649**
 Gen. Cond: Good Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: **195/50R15**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. **5** mm R/Bal. **5** mm
 L/Bal. **5** mm L/Bal. **5** mm
 D.O.A. **13/02/19** D.O.I. **01/03/19 @ 0428 pm**
 Survey held at **MASTER CAR**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
FRONT N/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 22 MAR 2019

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Days Of Repair: _____
 Resurvey No. of Trip: **2**
 Survey Fee: **120**
 Transportation _____
 Add Fee: Site Insp (\$) _____
 Interview (\$) _____
 Tech. Inv. (\$) _____
 Weekend (\$) _____
 Report Format: **PRE**
 Lump Sum / I.B.I. (\$) _____
 Survey Fee: **10**
 Total: **130**

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 28 February 2019 1:48 PM
To: Accident@kscgp.com; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Sherini Pillai; Zuhaidah Samsuri
Subject: RE: 1st Notice to conduct Pre-Repair Survey Yr Ref:SHD4092S
OurRef:SKQ6981J/MC/jp/mt
Attachments: prs1 ba skq6981j_20190227125351.pdf; 2nd PRS.PDF

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SKQ6981J
III INSURED VEHICLE NO. : SHD4092S
DATE OF LOSS : 13.02.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sherini**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: 28 February, 2019 10:00 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: 1st Notice to conduct Pre-Repair Survey Yr Ref:SHD4092SOurRef:SKQ6981J/MC/jp/mt

Dear Sirs,

We refer to the captioned matter and your letter of even date.

We enclose our 2nd Notice for Pre-Repair Survey for your attention and necessary action. Our client is not agreeable to your proposed surveyor.

The workshop's details are as follows:

Master Car Spray Services

36 Toh Guan Road East

#01-48 Enterprise Hub

Singapore 608580

Contact: Pauline / Tel: 9856 8137 / Fax: 6261 2883

Thank you.

Regards,

Wan Sim

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

To: Accident@kscgp.com

Cc: jiapei@kscgp.com

Sent: Thu, 28 Feb 2019 01:31:58 +0000

Subject:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: 27 February, 2019 4:58 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: jiapei@kscgp.com

Subject: RE: 1st Notice to conduct Pre-Repair Survey Yr Ref:SHD4092S OurRef:SKQ6981J/MC/jp/mt

Dear Sirs,

We refer to your email of even date. Please be informed that our client has instructed our firm to take over conduct of this matter.

Kindly confirm whether you are appointing any surveyors to survey our client's vehicle before he proceeds to repair his vehicle. Please let us have your proposed list of surveyors for our client's consideration.

Thank you.

Regards,

Wan Sim

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that

the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
To: Accident@kscgp.com
Cc: jiapei@kscgp.com
Sent: Wed, 27 Feb 2019 06:01:03 +0000
Subject:

Dear Sirs,

We refer to the matter above.

Hua Hong Pte Ltd have requested for a PRI to be conducted and LKK has been assigned. Kindly confirm that your client has decided to withdraw his claim from the workshop and instead he will be claiming with the help of solicitors.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]
Sent: 27 February, 2019 12:36 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: jiapei@kscgp.com
Subject: 1st Notice to conduct Pre-Repair Survey Yr Ref:SHD4092S Our Ref:SKQ6981J/MC/jp/mt

Dear Sirs,

Please find enclosed herewith the 1st Notice to Conduct Pre-Repair Survey for your kind attention and necessary action.

Thank you.

Regards,
May Teo
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or

entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located

both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4146E
Vehicle Details	
Vehicle No.:	SKQ6981J
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.6 MT
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	M16A1408775
Chassis No.:	JSAEZC31500202649
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$12,524.00
Original Registration Date:	22 Sep 2008
First Registration Date:	22 Sep 2008
Transfer Count:	4
Actual ARF Paid:	\$12,524.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$14,553.00
Total Rebate Amount:	\$14,553.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Mar 2019

OK

LKIC

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/02/2019 10:27
Date Of Accident	13/02/2019 18:05
Exact Location Of Accident	EDGEFIELD PLAINS & PUNGGOL FIELD JUNCTION
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKQ6981J
Insured/Policyholder	
Name Of Registered Owner	KONG WEI JIE
NRIC No	S8834146E
Email Address	WJ.ALEX69@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83661966
Alternative Phone No	OFFICE-83661966
Vehicle Particulars	
Manufacturer	SUZUKI
Model	SWIFT 1.6 MT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA392364/1
Cover Note Number	
Driver	
Name of Driver	KONG WEI JIE
NRIC No	S8834146E
Date Of Birth	08/09/1988
Occupation	OUTDOOR
Date Of Driving Pass	03/05/2010
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83661966
Fax Number	
Contact Number	OFFICE-83661966
E-Mail Address	WJ.ALEX69@GMAIL.COM

Address	APT BLK 207C PUNGGOL PLACE #05-968
Postcode	823207
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4092S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Feb 2019 Edit Reg		28 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	KONG WEI JIE , ID: S8834146E								
Vehicle Reg. No.:	SKQ6981J	Date of Loss:	13/02/2019 18:00 - :59 [124 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19020400	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD4092S	Policy No. (Claimant):	GA392364/1						
		Excess:							
Repairer:	Master Car Spray Service (HQ) 28 JALAN TUKANG JURONG, 619258 Jurong East - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/02/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ6981J (MCT19020400)
[SHD4092S]
TP
KONG WEI JIE
Feb 13 2019 6:00PM
[-]
Master Car Spray Service

Upload Documents Upload Photos Compose New Letter			View	View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
2	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
3	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
4	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
5	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
6	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
7	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
8	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
9	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
10	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
11	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
12	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
13	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
14	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
15	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
16	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
17	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
18	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
19	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
20	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
21	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
22	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
23	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
24	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
25	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
26	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
27	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
28	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
29	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
30	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
31	21/03/19 14:34	General View		Load JPG	<input checked="" type="checkbox"/>
32	21/03/19 17:34	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	21/03/19 17:34	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
34	21/03/19 17:34	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
35	21/03/19 17:34	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
36	21/03/19 17:34	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
37	21/03/19 17:34	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	21/03/19 17:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
65	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
66	21/03/19 17:50	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/19 13:51	EMAIL FROM III DD 15022019	Load PDF	
2	15/02/19 13:51	TP GIA REPORT	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	18/02/19 08:55	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19002848/R1CD3E2
Date: 22/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No : SKQ6981J	Insured Vehicle No :	SHD4092S	
Date of Loss: 13/02/2019	Nature of Claim:	TP	Claim No: MCT19020400

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ6981J	Engine No:	M16A1408775
Make & Model:	SUZUKI SWIFT, 1.6 MT (M)	Chassis No:	JSAEZC31S00202649
Reg. Date:	22/09/2008 (Man. Year: 2008)	Odometer:	197217 km
Colour:	White		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/02/2019	
Date Inspected:	01/03/2019	Inspected At: Master Car Spray Service (HQ) 36 TOH GUAN ROAD EAST #01-48 ENTERPRISE HUB SINGAPORE 608580
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2019)
Parts: 144	SUZUKI SWIFT 1.6 MT (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ6981J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >