



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/02/2019

User ID : GohKK2

Section A - Accident Details

Registration Number

SG5528A

Case Reference Number

BUS/02/19/1022

Registration Date

26/10/2017

Company Type

SMRT Buses Ltd

Make

VOLVO B9TL DD

Model

VOLVO

Name of Driver

Mohd Halif Bin Abd Hamid

Type of Accident

Side Swipe

Accident Date and Time

12/2/2019 5:00 PM

Accident Reported Date and Time

13/2/2019 2:48 PM

Is Surveyor Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date and Time

Replacement Vehicle issued?

No

Job Card Number

Special Instruction to ARC,if any

SG5528A - RIGHT REAR PORTION
SHD3123T (TP) - COMFORT TAXI. INSURED WITH III.

Prepared Date and Time

14/2/2019 10:38 AM

Chassis Number

YV3S4P920HA183451

Mileage

Work Shop

Repair Completion Date and Time

Section B - Summary of Repair Estimates

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Cost

\$1,325.00

\$0.00

Total Spray Cost

\$616.00

\$0.00

Total Spare Part Cost

\$3,267.04

\$0.00

Total Other Cost

\$0.00

\$0.00

TOTAL COST

\$5,208.04

\$0.00

Lump Sum Total

\$0.00

\$0.00

Number of Repair Days

4.0

Prepared / Adjusted By

Kok Khoon Goh

ARC / Surveyor Sign Off Date

14/02/2019 10:49 AM

Signature

Remarks

Section C - Quotation and Accident Invoice Details

Quotation Number

Invoice Number

Quotation Date

Invoice Date

Invoice Amount

Prepared Date



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/02/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,325.00						
Total Labour			\$1,325.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$616.00						
Total Spray Painting & Panel Beating			\$616.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012104	Body	A12-01983	SIDE SHEETMETAL PANEL	1.00	\$1,634.80	0.00	\$1,634.80	Replace	
6012103	Body	A12-01982	SIDE SHEETMETAL PANE	1.00	\$1,813.60	10.00	\$1,632.24	Replace	
Total					\$3,448.40		\$3,267.04		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									