

ASSIGNED BY:

REF:

CS/SMO 19002891/K1xd3⁷²

Special Instruction:

Surveyor

Kelvin

ASSIGNMENT (Office)

From Person

Gnoh paul ang

of

SMO

Date/Time:

14/12/19 @ 2.20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SHA 5389X

Insured:

FBC 38872

at Workshop m/s:

Comfort Daloro

Tel:

6214 8300

of

sq loyang Drive

Policy No:

018M1MCO1000619

Claim No:

CMTD1900867

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/02/2017

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

301pm @ 14/12/19

Person Contacted:

Juni

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 5389X - (S/F) 18003780/R/d3e2 DoA: 25/2/18
	FBC 38872 - X

Part 103

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 5389X Yr Regn: 6 Sep, 2018

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Zoniq CC: 1.5L

Colour: Blue A/C: Insured / Std / Nil / NA

Sp. Reading: 43742 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMHC85 / CVKH 107483

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoperative / Jammed / Leaked / Burnt or

Brake: Inoperative / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / VIC / DHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A. 11/2/19 D.O.A. 14/2/19

Survey held at CDGE (Loyang)

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

no front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/2/19	Check PIP \$ 730.23 / 2 Ag. (Red 244.41, 259) Suao PIP

RECEIVED 20 FEB 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 20/2 - typist

Report Format:

merimen

Lump Sum: PIP \$ 730.23

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Wash and (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

250

10

260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 19 Feb 2019

Preliminary Advice

Insured Vehicle No	: FBC3887Z	Accident Date	: 11/02/2019
TP Vehicle No	: SHA5389X	Assignment Date	: 14/02/2019
Make	: HYUNDAI AE IONIQ	Est. Duration of Repair	: 2.00
Date of Inspection	: 14/02/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	974.64
Revised Amount	:S\$	730.23
Check Items (Estimated)	:S\$	0.00
Total	:S\$	730.23

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments :The above survey was conducted on a 'Without Prejudice' basis

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

	Notif	Exp. Action	Assigned	Adj. Rpt	Adj. Rpt. Status	Ins. Action	Status
Main	14 Feb 2019		14 Feb 2019 14:20				New Assignment Cancel Case
			Assign				

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured	MUHAMMAD ARIFIN MUSTAFA, ID: S8102428F		
Main			
Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA5389X	Date of Loss:	11/02/2019 00:00 - :59
Claim Type:	TP / CMTD1900867	Policy/Cover Note No.:	D18MTMC01000619 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBC3887Z	Policy No. (Claimant):	
		Excess:	
Repairer	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Sumpo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/02/2019]		
Adj. Asg. Remarks:	+PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS & ESTIMATE SUBMITTED		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

No results.

ID	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.						

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHA5389X
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4LEJU081014
Chassis No.:	KMHC851CVKU107483
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,883.00
Original Registration Date:	06 Sep 2018
First Registration Date:	06 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$11,837.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Sep 2026
PARF Rebate Amount:	\$8,877.00
Intended COE Rebate Details	
COE Expiry Date:	05 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,872.00
COE Rebate Amount:	\$24,404.00
Total Rebate Amount:	\$33,281.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2019 07:47
Date Of Accident	11/02/2019 19:30
Exact Location Of Accident	GEYLANG RD TWDS LOR 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA5389X
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	ONG LAY HUAT
NRIC No	S6837737D
Date Of Birth	07/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	29/10/1988
Driving Experience	30 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96823344
Fax Number	
Contact Number	
Email Address	ONGLAYHUAT@SINGNET.COM.SG

Address	451A #07-371 SENGKANG WEST WAY
Postcode	791451
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	HOUgang NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBC3887Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	RHT FRT
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name RIDER

Approximate Age

Injuries Sustain LEFT ARM

Injured person in which vehicle? FBC3887Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police

Report

T/20190211/22100.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

Sketch Plan Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190211/2210

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20190211/2210

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/02/2019 23:20		Vide Report No.:		Station Diary No.: 161	
Informant's Particulars					
Name of Informant: ONG LAY HUAT		Address: APT BLK 451A SENGKANG WEST WAY #07-371 SINGAPORE 791451			
ID Type / ID No.: NRIC NO / S6837737D		Contact No.:		Mobile: 96823344	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 50	Date of Birth: 07/10/1968	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 2B,2A,3		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/02/2019 19:30	Type of Location:
Location: Junction of Road 1 and Road 2 GEYLANG ROAD LORONG 1 GEYLANG cross junction of geyleang road and lor 1 geyleang				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBC3887Z	Motorcycle	SUZUKI				0
SHA5389X	TAXI	HYUNDAI			Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190211/2210

2 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20190211/2210

CONTINUATION OF REPORT

Driver		ID No.		S6837737D	
Name	ONG LAY HUAT			Contact No.	96823344
Related Vehicle	SHA5389X (TAXI)			Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Hospital/Clinic	NIL			Date Discharge	NIL
Date Treatment	NIL			Degree of Injury	NIL
No. of Days granted Medical Leave	NIL				

Brief Details.

On 11/2/2019 at about 1930hrs, I am driving my taxi bearing SHA5389X along geylang road towards city on the second lane from the right. At the cross junction of geylang road and lor 1 geylang, I was driving straight suddenly a motorcycle bearing FBC3887Z that was riding on my left lane (3rd lane from the right) suddenly cut into my lane wanting to make a right turn. I could not react in time, the motorcycle right side collided on the left front of my vehicle. The rider then fell. I then alighted to make a check. Passerby assisted to call for police and ambulance. The police attended to me vide G/20190211/0141.

Due to the collision, the left front bonnet of my vehicle cracked. I was not injured due to the accident. I do not have the particulars of the rider as he was conveyed to Tan Tock Seng Hospital. I only have his phone number hp:84822463 and +60177899824.

There is CCTV installed in my vehicle and the TP took it from me.

I am lodging this report as the traffic police told me to do so.



SINGAPORE
POLICE FORCE



T/20190211/2210

3 of 3

Report No. T/20190211/2210




Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

CONTINUATION OF REPORT


Sketch Plan



Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 LEE JIA YI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 11/02/2019 23:20
Officer In Charge Of Case: TP / GIT / Insp TAN CHIN YONG Contact No.: 65476178	Classification Of Case: SN 085
Authentication Stamp NP168	Signature: 







Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305268880

CUSTOMER

R/MS: COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO: 7010045
ADDRESS: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL: (R) 65508755 (C)
(P)

REGN NO.: SHA5389X

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL: IONIQ(G2)

DATE/TIME IN: 14.02.2019 10:15

YR OF MANU: 06.09.2018

TARGET DATE

CHASSIS CODE: KMHC851CVKU107483

COMPLETION DATE/TIME:

SCOUNT CARD NO:

JOB DESCRIPTION


Accident Date: 11.02.2019

NATURE: 3P 11.02.2019

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Ref: No.:
Plate No.: SHA5389X CHIANG

Vehicle No.: SHA5389X

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

VEHICLE NO : SHA 5389X

DATE 14/2/2019 14:49

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price*	Amount
	Front Bumper Cover <i>✓</i>			\$ 418.30
	Front Bumper Bracket (LH) <i>✓</i>			\$ 28.00
	Front Bumper Clips 10 pcs <i>✓</i>			\$ 22.00
	SUB TOTAL			\$ 468.30
	LESS 20% <i>25%</i>			\$ 93.66
	DISCOUNTED TOTAL			\$ 374.64
	Labour Charge			200
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 250.00
				200
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 974.64
<p><i>Kaluh (UKK)</i></p> <p><i>14/2/19 1525hrs.</i></p> <p><i>2 Dgs</i></p> <p><i>P/P</i></p> <p><i>Before Paint photo</i></p> <div data-bbox="962 1610 1482 2022" data-label="Text"> <p>LKK Auto Consultants hence notify the repairer of the following:</p> <ul style="list-style-type: none"> • To survey & monitor spray painting • To inspect & sign parts during survey • Parts will be replaced on commission • Third party liability will be on "no-fault" basis • No liability for consequential damage • Supplemental claim must be made within 30 days • Is authorized to sign on behalf of LKK <p>Acknowledged by: _____</p> <p>Signature: _____</p> <p>Date: _____</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305268880
REGN NO : SHA5389X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 06.09.2018
DATE/TIME IN : 14.02.2019 10:15
ACCIDENT DATE : 11.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G IONIQV2 COVER-FR BUMPER# 1 418.30 25.00 313.72

0002 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 10 L 22.00 25.00 16.50

SUB-TOTAL : 330.22

JOB NATURE

0000 PB PANEL BEATING 200.00

0001 SP SPRAYPAINT CHARGE 200.00

SUB-TOTAL : 400.00

TOTAL : 730.22

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Our Job Ref No : 305268880
Date : 18/02/19

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive, Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHA5389X

Fax :

11/02/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


- Z The repair job shall bill to: SOMPO FBC3887Z
2. The finalized amount shall be:
- | | |
|---|-----------------|
| (a) Spare Parts after List discount | <u>\$330.22</u> |
| (b) Labour Charges | <u>\$400.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$730.22</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |


3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Kahr
Date : 19/2/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002891/K1VD3N2
Date: 28/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTMC01000619
Claimant Vehicle No :	SHA5389X	Insured Vehicle No :	FBC3887Z
Date of Loss:	11/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900867

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA5389X	Engine No:	G4LEJU081014
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU107483
Reg. Date:	06/09/2018 (Man. Year: 2018)	Odometer:	43742 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	374.64	330.22	44.42	11.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	400.00	200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	974.64	730.22	244.42	25.08
+ GST 7.00/7.00% (S\$)	68.22	51.12	17.10	25.07
Nett Amount (S\$)	1,042.86	781.34	261.52	25.08

INSPECTION

Date of Assignment:	14/02/2019	
Date Inspected:	14/02/2019	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$730.23

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Feb 2019)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA5389X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cracked	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER BRACKET (LH)	Serviceable	28.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					468.30	440.30
- List Item Discount on L Items 20.00/25.00% (\$\$)					93.66	110.08
Total Parts (\$\$)					374.64	330.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	200.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
Gross Labour Cost (S\$)			600.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >