



## Case Details

Case Reference Number : TAX/02/19/2058  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB1962L

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-5671-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd  
 Accident Date and Time : 09/02/2019 05:15 AM  
 Vehicle Age(In Months) : 48

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	DEF
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NEC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	

Total Spare Part Cost	1,464.22	Surveyor Total	815.63
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	819.18	Final Sur Total	652.50

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace ▾	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace ▾	
<b>Total Spare Part Cost</b>									1,464.22	<b>Surveyor Total</b>		815.63		
<b>Lump Sum Discount (%)</b>									20.00	<b>Lump Sum Dis (%)</b>		20		
<b>Final Spare Part Cost</b>									819.18	<b>Final Sur Total</b>		652.50		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	338.00	200	
<b>Total:</b>			<b>338.00</b>	<b>200.00</b>	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
<b>Total:</b>			<b>378.00</b>	<b>200.00</b>	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
<b>Total:</b>			<b>756.88</b>	<b>336.88</b>	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	819.18	652.50
Total Labour Cost	338.00	200.00
Total Spray Painting	378.00	200.00
Other	756.88	336.88
Overall Total	2,292.06	1,389.38
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	2,300.00	1,400.00
Surveyor Approved Amount		1,400.00
No of Repair Days*	3	2
Remarks		L/S REPAIR,PHOTO AFTER REPAIR
Surveyor Name		Hwee jie
Signature		
Survey Date	13/02/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: