

2/19/2019

ASS. REC. BY:

REF

CS/MSG19002901/41vd301

Special Instruction:

Surveyor

Taufich

ASSIGNMENT (Office)

From (Person):

Merimen

of

MS19

Date/Time:

15/12/19 @ 9:50am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD1184E

Insured:

SKW19004

at Workshop m/s

Premier Taxis

Tel:

6544 6682

of

23 Cheryi South Ave 2 #01-02

Policy No:

1000806143

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/2/2019

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10:41am @ 15/12/19

Person Contacted:

Vincent

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHD1184E - CS/FCI15067995/R1943k3

DOA: 9/15/2015

SKW19004 - X

20/2/19

Send preli revised via merimen

25/2/19

Final fig \$ 298.70 confirmed by email (Recd 48, 1475)

Tuffin

REF: MS16


ASSIGNMENT

Form: Date: 15/2/19
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: SHD 1184E
 at Workshop No: Premier Automotive
 at: 23 Changi South Ave 2 #01-02
 Insured:
 Policy No:
 Claim No:
 Sum Insured:
 Excess:
 (Client's Record)
 Make of Veh:

Veh No: SHD 1184E
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai 130
 Colour: Silver
 Sp. Reading: 124787
 Eng/No:
 C/No: TMAD2814VHJ12465
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: ~ ~

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt.

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res: Yes or No

Lump Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

1

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/2/19 @ 3:00pm

Survey held at

Premier Chngi Spt

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 25 FEB 2019

[Signature]

25/2/2019.

Date/Time: File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time: File Return to?

2) 25/2 - typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1. Site Insp

1. Interview

1. Tech. Insp

1. Weekend

TOTAL

Add Fee:

☐

Site Insp

☐

Interview

☐

Tech. Insp

☐

Weekend

Report Format:

merimen

Lump Sum / LB. # 13

298.70

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Feb 2019 16:41		15 Feb 2019 09:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TOKYO CENTURY LEASING (SINGAPORE) PTE. LTD., Co. Reg. No.: 197901535G			
Main Claimant:	PREMIER TAXIS PTE LTD			
Vehicle Reg. No.:	SHD1184E	Date of Loss:	12/02/2019 19:00 - :59 [39 Months and 22 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	1000806143 Coverage: 21/10/2018 - 20/10/2019	
Vehicle Reg. No. (Insured):	SKW1900U	Policy No. (Claimant):		
		Excess:		
Repairer:	Premier Taxis Pte Ltd - Changi South (HQ) 23 CHANGI SOUTH AVENUE 2, #01-02, 486443 Changi - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/02/2019]			
Adj Asg. Remarks:	on WP, liability unclear, TP agree SJE - assign LKK Auto Consultants Pte Ltd contact: 6544 6676 / 6544 6689			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Jowyn Tay Mei Ling	Date:	20 Feb 2019
<u>Preliminary Advice</u>			

Insured Vehicle No	: SKW1900U	Accident Date	: 12/02/2019
TP Vehicle No	: SHD1184E	Assignment Date	: 15/02/2019
Make	: NISSAN QASHQAI	Est. Duration of Repair	: 2.00
Date of Inspection	: 15/02/2019		
Inspection At	: PREMIER TAXIS PTE LTD - CHANGI SOUTH (HQ) 23 CHANGI SOUTH AVENUE 2, #01-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	346.70
Revised Amount	:S\$	298.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	298.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

<input type="checkbox"/>	The vehicle is economical/not economical for repair.
<input checked="" type="checkbox"/>	The above survey was conducted on a 'without prejudice' basis.

Text size + -

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1184E
Previous Vehicle No.: -
Effective Date of Ownership: 15 Feb 2017
Original Regn Date: 15 Feb 2017
Registration Date: 15 Feb 2017
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ124405
Engine No.: D4FBGZ114405
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$21,088.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Feb 2025
Minimum PARF Benefit: \$8,414.00
No. of Transfers: 0
IU Label No.: 1050703925
COE No.: 2017021501003646M
COE Expiry Date: 14 Feb 2025
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	13/02/2019 15:26
Date Of Accident	12/02/2019 19:25
Exact Location Of Accident	CANTONMENT ROAD // NEW BRIDGE ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD1184E
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	
Driver	
Name of Driver	MOHAMED SIDIQALI MARICAN S/O NOOR MOHAMED
NRIC No	S1420331A
Date Of Birth	20/01/1958
Occupation	OUTDOOR
Date Of Driving Pass	16/10/1984
Driving Experience	34 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83597518
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 51 #05-145 MARINE TERRACE
Postcode	440051
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PAX IN THE REAR SEAT - FOREIGNERS/KOREAN GENDER: : FEMALE
Passenger 2	NAME: : PAX IN THE REAR SEAT - FOREIGNERS/KOREAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 2 PAX VEH. B - NO PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW1900U
Vehicle Make/Model/Colour	NISSAN QASHQAI
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	LUCY
NRIC/Passport Number	
Contact Number	90047652
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF INJURED PERSON 1

Name MOHAMED SIDIQALI MARICAN S/O NOOR MOHAMED

Approximate Age

Injuries Sustain SEEK FOR MEDICAL TREATMENT @ CHANGI HSPTL & HAD 4 DAYS MC

Injured person in which vehicle? SHD1184E

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Signature]

13 FEB 2013

[Signature]


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

X 514207311A
N 51101184E

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: CHD 1184E

B: SKW 1900U.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

13 FEB 2013

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHD 1184E
51420351/17

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ENCLOSURE

Describe Circumstance of the Accident.

ON 12/02/2019 @ 1925HRS, I WAS DRIVING MY TAXI (SHD 1184 E), TRAVELLING ALONG THE TRAFFIC LIGHT JUNCTION OF CANTONMENT ROAD & NEW BRIDGE ROAD IN LANE 1 WITH 2 PASSENGERS ONBOARD.

I SLOWED DOWN MY TAXI TO A COMPLETE STOP – AS VEHICLES AHEAD OF ME STOPPED.

WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SKW 1900 U – NISSAN QASHQAI) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI


DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND VEHICLE B HAD DAMAGES ON THE FRONT PORTION.

AS A RESULT, I FELT SOME DISCOMFORT, WENT TO CHANGI GENERAL HOSPITAL FOR MEDICAL TREATMENT & HAD 4 DAYS OF MEDICAL LEAVE. NO AMBULANCE AT SCENE.


NO PASSENGERS ONBOARD VEHICLE B.

*VIDEO FOOTAGE CAPTURED.


DAMAGES FOUND ON VEHICLE A & VEHICLE B



PREMIER
TAXI



THIRD PARTY
VEHICLE


Driver's Signature & NRIC Number
Wednesday, February 13, 2019 @ 3:36:21 PM

(attended by )

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
Assessment number: SHD1184E
Version: 1810
Date calculated: 02/15/2019 11:09 AM

Full Report
Registration: SHD1184E
Printed: 15/02/2019 11:09 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-12
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	I30 (PD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 82 01
Registration:	SHD1184E
VIN number:	
Odometer:	
Model Specs	
5-DOOR	

[Signature]
20/2/19
Tan Jia 97445744
'WP'
15/2/19 @ 3:10 pm
Resurvey after repair
02 days
Sue Lkh auto.wm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
Assessment number: SHD1184E
Version: 1810
Date calculated: 02/15/2019 11:09 AM

Full Report
Registration: SHD1184E
Printed: 15/02/2019 11:09 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 2019-02-15

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
2583	REAR BUMPER REPAIR		20.0*	100.00
	Labour Cost		Hrs	WU
	Panel / Mechanical Labour		2.00	20.0
	Total of Labour			100.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER REPAIR PAINT PLASTIC		13.0	

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
Assessment number: SHD1184E
Version: 1810
Date calculated: 02/15/2019 11:09 AM

Full Report
Registration: SHD1184E
Printed: 15/02/2019 11:09 AM

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER REPAIR PAINT PLASTIC	30.60

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			13.0	
Preparation Comp. Work Plastic		1.70	17.0	85.00
Total	10 WU/h	3.00	30.0	150.00

Material Cost - Paint

	Price SGD
Repair Painting Plastic	30.60
Material-constant Plastic	18.10
Total	48.70

Extras

Code	Description	Price SGD
1000	Rear bumper clips	48.00*
	Total Extras	48.00

Final Calculation

	SGD	SGD
Labour Time Base 10 WU/h		
Total 20.0 WU X 50.00 SGD/h	100.00	
Total of Labour		100.00
Total Of Extras		48.00
Paint Work Time Base 10 WU/h		
Labour Cost 30.0 WU X 50.00 SGD/h	150.00	
Material Cost	48.70	
Total Paint Including Material		198.70
Repair Cost Excludes GST		346.70
GST (+7.0%)		24.27
Repair Cost Included GST		370.97

**Premier Automotive Services Pte
Ltd
#01-02, 23 Changi Sth Ave 2
486443**

Claim Reference:

Assessment number: SHD1184E

Version: 1810

Date calculated: 02/15/2019 11:09 AM

Full Report

Registration: SHD1184E

Printed: 15/02/2019 11:09 AM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHD1184E

Version: 1810

Date calculated: 02/23/2019 09:46 AM

Full Report

Registration: SHD1184E

Printed: 23/02/2019 9:47 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-12
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	I30 (PD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 82 01
Registration:	SHD1184E

VIN number:

Odometer:

Model Specs

5-DOOR

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
Assessment number: SHD1184E
Version: 1810
Date calculated: 02/23/2019 09:46 AM

Full Report
Registration: SHD1184E
Printed: 23/02/2019 9:47 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 2019-02-15

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
2583	REAR BUMPER REPAIR		20.0*	100.00
	Labour Cost		Hrs	WU
	Panel / Mechanical Labour		2.00	20.0
				100.00
	Total of Labour			100.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER REPAIR PAINT PLASTIC		13.0	

**Premier Automotive Services Pte
Ltd**

**#01-02, 23 Changi Sth Ave 2
486443**

Claim Reference:

Assessment number: SHD1184E

Version: 1810

Date calculated: 02/23/2019 09:46 AM

Full Report

Registration: SHD1184E

Printed: 23/02/2019 9:47 AM

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER REPAIR PAINT PLASTIC	30.60

Labour Cost - Paint

Factor

50.00 SGD/h

Hrs

WU

Price SGD

Time Paint

13.0

Preparation Comp. Work Plastic

1.70

17.0

85.00

Total

10 WU/h

3.00

30.0

150.00

Material Cost - Paint

Repair Painting Plastic

Price SGD

30.60

Material-constant Plastic

18.10

Total

48.70

Final Calculation

	SGD	SGD
Labour Time Base 10 WU/h		
✓Total 20.0 WU X 50.00 SGD/h	100.00	
Total of Labour		100.00
Paint Work Time Base 10 WU/h		
Labour Cost 30.0 WU X 50.00 SGD/h	150.00	
Material Cost	48.70	
Total Paint Including Material		198.70
Repair Cost Excludes GST		298.70
GST (+7.0%)		20.91
Repair Cost Included GST		319.61

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 February 2019 10:32 AM
To: 'Goh Wee Dek'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: SHD1184E- FINALIZE

Dear Week Dek,

WITHOUT PREJUDICE

Confirm repair \$298.70 before GST @ 2 working days.

Kindly send Final invoice and all supporting documents to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Saturday, 23 February 2019 9:49 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: SHD1184E- FINALIZE

Dear Taufikh

Please confirm repair \$298.70

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Feb 2019		15 Feb 2019 09:50 Edit Adj Rpt	S\$298.70 Edit Estimates	S\$298.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Tokyo Century Leasing (Singapore) Pte Ltd , Co. Reg. No.: 197901535G, Email: kenkwek@tcls.com.sg								
Main Claimant:	Premier Taxis Pte Ltd , Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHD1184E	Date of Loss:	12/02/2019 19:00 - :59 [23 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 225174	Policy/Cover Note No.:	1000806143 Coverage: 21/10/2018 - 20/10/2019						
Vehicle Reg. No. (Insured):	SKW1900U	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Taxis Pte Ltd (HQ) 23 Changi South Avenue 2, #04-03, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/03/2019]								
Driver/Custodian (Insured):	Winthrop Lucy Natalie (), NRIC: G5436597M, Tel: +6590047652 Email:								
Adj Asg. Remarks:	on WP. liability unclear. TP agree SJE - assign LKK Auto Consultants Pte Ltd contact: 6544 6676 / 6544 6689								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD1184E (225174)**
[SKW1900U]
TP
Premier Taxis Pte Ltd
Feb 12 2019 7:00PM
[Tokyo Century Leasing (Singapore) Pte Ltd]
Premier Taxis Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	20/02/19 15:00	Adjuster Immediate Advice				Load HTM	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
2	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
3	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
4	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
5	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
6	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
7	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
8	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
9	20/02/19 15:01	General View				Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 10:28	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
11	25/02/19 10:28	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
12	25/02/19 10:28	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
13	25/02/19 10:28	Reinspection Photo				Load JPG	<input checked="" type="checkbox"/>
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print
1	14/02/19 17:06	TP PRI NOTICE - SURVEY LISTING				Load PDF	
2	15/02/19 09:27	OI SKW1900U e-file report				Load PDF	
3	15/02/19 09:27	SHD1184E e-file report				Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19002901/T1VD3E2

Date: 28/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000806143

Claimant Vehicle No : SHD1184E

Insured Vehicle No : SKW1900U

Date of Loss: 12/02/2019

Nature of Claim: TP

Claim No: 225174

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD1184E**

Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)

Engine No: D4FBGZ114405

Reg. Date: 15/02/2017 (Man. Year: 2016)

Chassis No: TMAD281UVHJ124405

Colour: Silver

Odometer: 124789 km

Engine Capacity: 1582 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Maxxis 6 mm

Rear Left Side: Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48.00	0.00	48.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	298.70	298.70	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	346.70	298.70	48.00	13.84
+ GST 7.00/7.00% (\$\$)	24.27	20.91	3.36	13.84
Nett Amount (\$\$)	370.97	319.61	51.36	13.84

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 15/02/2019 Inspected At:

Premier Taxis Pte Ltd - Changi South (HQ)
23 CHANGI SOUTH AVENUE 2, #01-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 27 Feb 2019)
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD1184E)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CLIPS	Not Necessary	48.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					48.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	20.0 WU X 50.00 SGD / H	New	100.00	100.00
2	LABOUR COST 30.0 WU X 50.00 SGD / H	New	150.00	150.00
3	MATERIAL COST	New	48.70	48.70
Gross Labour Cost (S\$)			298.70	298.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >