

ASS. REC. BY:

REF:

CS/MSG/19002902/AGsd3

Special Instruction:

Surveyor

GHOONG

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time:

15/2/19 9.45am

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGC 2075 Y

Insured:

SKP 9672L

at Workshop m/s:

Hua Meng Spray

Tel:

67465519

of

1 Kalei Bldg Ave 6 H01-61

Policy No:

29 09 8388AT2

Claim No:

584990

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11.23am 15/2/19

Person Contacted:

June

Vehicle:

☒ N/A

Date/Time

Action/Instruction (✓) Estimate

SGC 2075Y - CS/FCI/19000465/Asb

DON: 31/12/18

SKP 9672L - NA/MSG/19000347/24

DWA: 6/1/2019

20/02/19

@ 17:04 p.m. revert pending estimate to Irene Tan via mthm.

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % J Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SGC 2075 Y Yr Regn: 2206, Jan.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: B. Grey A/C: Insured / Std / Nil / NASp. Reading: 71190 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MROS3ZEC107108913Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 15/02/19Survey held at 1st FloorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/04/19 TP MS16 Bullid Repair COE Expiry: 15/01/21
Confirmed HS @ 2,500/- @ 4 days with Adrian
(@ 3,242.52 Red - 61%)

MV: 14K
PV: 10.9K
Nett: 3.1K

RECEIVED 29 APR 2019 29/4/2019

Resurvey no. of Trip - 1

Date/Time, File Pass to?

Date/Time, File Return to?

1) Type

2)

3)

4)

5)

6)

Prel. Report

Final Report \$ 2,500/- HS

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		15 Feb 2019 09:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Tong Chee Wai, ID: S7432542D		
Main Claimant:	GOH KAH HOCK, ID: S1375758E		
Vehicle Reg. No.:	SGC2075Y	Date of Loss:	05/02/2019 11:00 - :59 [156 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584990	Policy/Cover Note No.:	29098388AT2 (Comprehensive) Coverage: 28/10/2018 - 27/10/2019
Vehicle Reg. No. (Insured):	SKP9672L	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/02/2019]		
Adj Asg. Remarks:	on WP. Liability (Non-reporting) SJE AGREE LKK. pls contact June @ 6747 8064 / 6746 5519		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SGC2075Y (584990)**
[SKP9672L]

TP
GOH KAH HOCK
Feb 5 2019 11:00AM
[Tong Chee Wai]
Hua Meng Spray Painting Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 20/02/2019 17:04 PM.
To irene_tan@sg.msig-asia.com
CC sur@lkkauto.com
Subject SGC2075Y (584990) [SKP9672L] TP

Dear Irene,

Please be informed that we have inspected the vehicle SGC 2075Y on 15/02/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5758E
Vehicle Details	
Vehicle No.:	SGC2075Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Grey
Manufacturing Year:	2005
Engine No.:	3ZZ4537037
Chassis No.:	MR053ZEC107108913
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,772.00
Original Registration Date:	16 Jan 2006
First Registration Date:	16 Jan 2006
Transfer Count:	0
Actual ARF Paid:	\$15,150.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Details	
COE Expiry Date:	15 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,317.00
COE Rebate Amount:	\$10,854.00
Total Rebate Amount:	\$10,854.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Feb 2019

OK



► **SEARCH**

► Used Car Comparison

— Comparing 3 Vehicles —

Toyota Corolla Altis 1.6A (COE till 09/2020)



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 10/2020)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 10/2020)



Add to Shortlist



Use search bar above to select to compare.

CAR DETAILS

Price	\$13,900	\$12,900	\$15,998	-
Instalment	N.A.	N.A.	N.A.	-
Registration Date	03-Oct-2005	12-Oct-2005	24-Oct-2005	-
Manufactured	2005	2005	2005	-
Mileage	100,000 km	182,151 km	-	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,598 cc	1,598 cc	1,598 cc	-
Road Tax	\$1,039 /yr	\$1,039 /yr	\$1,039 /yr	-
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)	-
Curb Weight	1,115 kg	1,115 kg	1,115 kg	-
Features	1.6L 16 Valves VVTi DOHC Reliable 108Bhp Engine, Smooth Auto With ETC, Climatic Control Aircon, 2 x Airbags, ABS, Low Maintainous Costs.	1.6L 16 Valves VVTi DOHC Reliable 108Bhp Engine, Smooth Auto With ETC, Climatic Control Aircon, 2 x Airbags, ABS, Low Maintainous Costs.	Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVTi Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon.	-
Accessories	Original Leather Seats, Multi Steering Control And Retractable Mirrors With Indicators.	Sports Rims, Audio System.	Original Leather Seats, Multi Steering Control And Retractable Mirrors With Indicators.	-
Description	High Loan Available, Extremely Low Mileage, Full Servicing Done, New Tyres, New Aircon Compressor, Careful Owner Brand New Road Tax, Trade In Available, Low Fuel Consumption, Don't Miss This Rare Opportunity, Kindly Call Us Today To View, Viewing By Appointment Only.	[Drive With Assurance] Easy Approval Loan Up To \$14k Affordable Monthly \$598 Very Low Usage! Selling At The Most Reasonable Price With A Peace Of Mind! STA/VICOM/AA/IDAC Evaluation Are Welcome! Viewing Available Daily By Appointment From 8am-8pm. Thank You.	Be Our Next Lucky Client To Own This Quality Pre-Owned Vehicle At Most Reasonable And Affordable Price. Rock Solid Altis! Fuel Consumption Of 14km/L. Very High Paper Value! Minimum Controlled Lost! STA Evaluation Welcome! Call Our Friendly Sales Consultant Now! All Loan Schemes Available!	-
COE	\$29,608	\$28,399	\$28,399	-
ONV	\$16,493	\$16,493	\$16,493	-
ARF	\$18,143	\$18,143	\$13,655	-
Depreciation	\$8,560 /yr	\$7,800 /yr	\$9,480 /yr	-
No. of Owners	1	3	4	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	COE Car, Low Mileage Car	COE Car	COE Car	-
Availability	Available	Available	Available	-
Remarks	COE expiry date 2020-10-23	COE expiry date 2020-10-23	COE expiry date 2020-10-23	-

MSME18020624 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 14/02/2019 11:47
 SUBMITTED BY: Chia Pui Ying

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 14/02/2019 11:55

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/02/2019 11:47
Date Of Accident	05/02/2019 11:15
Exact Location Of Accident	PIE TWDS TUAS (EXIT EUNOS)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGC2075Y
Insured/Policyholder	
Name Of Registered Owner	GOH KAH HOCK
NRIC No	S1375758E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91790858
Alternative Phone No	OFFICE-91790858
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5033688975-10
Cover Note Number	
Driver	
Name of Driver	JASON YEO ZHI YUAN
NRIC No	S1375758E
Date Of Birth	18/06/1990
Occupation	INDOOR
Date Of Driving Pass	18/11/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91790858
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 939 TAMPINES AVE 5 #08-177
 Postcode 520939
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - -
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : SHERLYN GOH
 GENDER: : FEMALE
 Passenger 2 NAME: : YEO ZHI YI
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG LANE 2 OF PIE TOWARDS TUAS EUNOS EXIT ON 05/02/2019 @ 1115HRS. I WAS WAITING FOR THE VEHICLE TO CLEAR ALONG THE MAIN ROAD. SUDDENLY, I HEARD A BANG SOUND AND FELT AN IMPACT FROM MY REAR. VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKP9672L
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver TONG CHEE WAI
 NRIC/Passport Number S7432542D
 Contact Number 96936375
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

13/2/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No:

Hua Wenxian

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT >

I was stationary along lane 2 of PIE towards Thas Ennos Exit on 05.02.2019 @ 11:55hrs. I was waiting the vehicles to clear along the main road. Suddenly, I heard a bang sound and felt an impact from my rear - Vehicle B was collided onto rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name
 NRIC/PPN No:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

GOH KAH HOCK

BLK 939 TAMPINES AVE 5

#08-177

S 520939

TPMS 1/4
Shiny.

Date

:25.02.2019

Vehicle no

:SGC 2075 Y

Make/Model

:TOYOTA ALTIS

Accident date

:05.02.2019

No	DESCRIPTION	Qty	Amount (S\$)
<u>List Items</u>			
1	Rear bumper <i>behind</i>	1	\$ 385.3 ✓
2	Rear bumper side holder @ \$17.20 <i>new</i>	2	\$ 34.4 ✓
3	Rear bumper bracket @ \$51.00 <i>new</i>	2	\$ 102.4 51.20 ✓
4	Rear bumper clips (1set) <i>new</i>	1	\$ 25 ✓
5	Rear LH lamp <i>cracked</i>	1	\$ 299.6 ✓
6	Rear LH lamp lower panel <i>Repair</i>	1	\$ 92.3 ✗
7	Rear LH lamp lower panel rivet @ \$3.00 <i>new</i>	3	\$ 9 ✗
8	Rear end panel <i>Dented</i>	1	\$ 708.3 ✓
9	Rear end panel inner top garnish <i>behind</i>	1	\$ 53.6 ✓
10	Rear boot lid <i>Repair</i>	1	\$ 845.3 ✗
11	Rear boot lid centre emblem	1	\$ 65.7 ✓
12	Rear boot lid 1.6E emblem	1	\$ 44.5 ✓
13	Rear boot lid VVTi emblem	1	\$ 41.7 ✓
14	Rear boot lid COROLLA emblem	1	\$ 65.7 ✓
15	Rear boot lid ALTIS emblem	1	\$ 65.7 ✓
16	Rear boot lid reflector @ \$80.60 <i>new</i>	2	\$ 161.2 ✗
17	Rear LH fender <i>new</i>	1	\$ 758.2 ✗
18	Rear windscreen rubber <i>new</i>	1	\$ 58.8 ✗
			\$ 3816.7
Less 25% Disc			\$ 954.18
Total			\$ 2862.52

Special Nett Items

1	Rear bumper reverse sensor (1set) <i>Damaged</i>	1	\$ 380 200 ✓
Total			\$ 380

200

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

GOH KAH HOCK
BLK 939 TAMPINES AVE 5
#08-177
S 520939

Date : 25.02.2019
Vehicle no : SGC 2075 Y
Make/Model : TOYOTA ALTIS
Accident date : 05.02.2019

No	DESCRIPTION	Qty	Amount (\$S)
----	-------------	-----	--------------

Labour Cost

- 1 To supply rear end panel inner sealant
- 2 Remove & reinstall reverse sensor
- 3 Remove & reinstall ~~boot lid inner garnish~~ *upholstery*
- 4 Remove, replace & repair consistent to the accident
- 5 Respray Painting
- 6 Remove & reinstall rear windscreen
- 7 Remove & reinstall petrol tank
- 8 To supply rear windscreen sealant

\$ 200 60.
\$ 150 52.
\$ ~~200~~ 60
\$ 1200 600
\$ 1000 800
\$ 150
\$ 150
\$ 50 x

Total

\$ 3100

Grand Total

\$ 6342.52

1570

total: 3150.52

c/s: 2.5k.

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2.5k

...CLAIM SUBFOLDER...(Pending for Survey Report)






























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		15 Feb 2019 09:45 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Tong Chee Wai , ID: S7432542D								
Main Claimant:	GOH KAH HOCK , ID: S1375758E								
Vehicle Reg. No.:	SGC2075Y	Date of Loss:	05/02/2019 11:00 - :59 [156 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 584990	Policy/Cover Note No.:	29098388AT2 (Comprehensive) Coverage: 28/10/2018 - 27/10/2019						
Vehicle Reg. No. (Insured):	SKP9672L	Policy No. (Claimant):							
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 16/02/2019]								
Adj Asg. Remarks:	on WP. Liability (Non-reporting) SJE AGREE LKK. pls contact June @ 6747 8064 / 6746 5519								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGC2075Y (584990)
 [SKP9672L]
 TP
 GOH KAH HOCK
 Feb 5 2019 11:00AM
 [Tong Chee Wai]
 Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Letters/Correspondences									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print	
1	14/02/19 16:53	Non Reporting Letter to OI							1 Load HTM			
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
2	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
3	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
4	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
5	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
6	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
7	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
8	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
9	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
10	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
11	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
12	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
13	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
14	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
15	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
16	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
17	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
18	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
19	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
20	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
21	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
22	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
23	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
24	29/04/19 09:34	General View							1 Load JPG		<input checked="" type="checkbox"/>	
25	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
26	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
27	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
28	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
29	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
30	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
31	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
32	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
33	29/04/19 09:34	Reinspection Photo							1 Load JPG		<input checked="" type="checkbox"/>	
34	29/04/19 09:34	Reinspection Photo							1 Load JPG			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	29/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/02/19 10:58	PRI	 Load PDF	
2	14/02/19 16:49	SJE AGREE LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19002902/AGSD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer: MSiG Insurance (Singapore) Pte. Ltd.

Policy No: 29098388AT2

Claimant Vehicle No : SGC2075Y

Insured Vehicle No : SKP9672L

Date of Loss: 05/02/2019

Nature of Claim: TP

Claim No: 584990

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGC2075Y

Make & Model: TOYOTA COROLLA, 1.6 (A)

Engine No: 3ZZ4537037

Reg. Date: 16/01/2006 (Man. Year: 2005)

Chassis No: MR053ZEC107108913

Colour: Grey

Odometer: 71190 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,242.52	1,580.52	1,662.00	51.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,570.00	1,530.00	49.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,342.52	3,150.52	3,192.00	50.33
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	6,342.52	2,500.00	3,842.52	60.58

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 15/02/2019 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: 143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGC2075Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	385.30 FL	*385.30 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	34.40 FL	*34.40 FL
3	1		*REAR BUMPER BRACKET	N/S Dented	102.40 FL	*51.20 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
5	1		*REAR LH LAMP	Cracked	299.60 FL	*299.60 FL
6	1		*REAR LH LAMP LOWER PANEL	Repair	92.30 FL	*- FL
7	3		*REAR LH LAMP LOWER PANEL RIVET	Not Necessary	9.00 FL	*- FL
8	1		*REAR END PANEL	Dented	708.30 FL	*708.30 FL
9	1		*REAR END PANEL INNER TOP GARNISH	Deformed	53.60 FL	*53.60 FL
10	1		*REAR BOOT LID	Repair	845.30 FL	*- FL
11	1		*REAR BOOT LID CENTRE EMBLEM	Necessary	65.70 FL	*65.70 FL
12	1		*REAR BOOT LID 1.6E EMBLEM	Necessary	44.50 FL	*44.50 FL
13	1		*REAR BOOT LID VVTI EMBLEM	Necessary	41.70 FL	*41.70 FL
14	1		*REAR BOOT LID COROLLA EMBLEM	Necessary	65.70 FL	*65.70 FL
15	1		*REAR BOOT LID ALTIS EMBLEM	Necessary	65.70 FL	*65.70 FL
16	2		*REAR BOOT LID REFLECTOR	Not Necessary	161.20 FL	*- FL
17	1		*REAR LH FENDER	Not Necessary	758.20 FL	*- FL
18	1		*REAR WINDSCREEN RUBBER	Not Necessary	58.80 FL	*- FL
19	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,196.70	2,040.70
- List Item Discount on L Items 25.00/25.00% (S\$)	954.18	460.18
Total Parts (S\$)	3,242.52	1,580.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
2	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
3	REMOVE & REINSTALL UPHOLSTERY	New	200.00	60.00
4	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
5	RESPRAY PAINTING	New	1,000.00	800.00
6	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	0.00
7	REMOVE & REINSTALL PETROL TANK	New	150.00	0.00
8	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	0.00
Gross Labour Cost (S\$)			3,100.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >