

2/10/2019

ASS. REC. BY:

REF:

CS3/MSG19002903/Bcd3²

Special Instruction:

Surveyor:
reimer

Mr Jim

ASSIGNMENT (Office)

From (Person): Chhira Nyuk Pui

of

MSG

Date/Time: 15/2/19 @ 9.47am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 5825M

Insured:

GBB 7865R

at Workshop m/s

K & M Motor

Tel:

9753 8067

of

53 Ubi Ave 1 # 01-19

Policy No:

29040188MKF

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

13/2/2019

After 3pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

up

Date/Time:

11:23am @ 15/2/19

Person Contacted:

vicki

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

GBH 5825M - X

GBB 7865R - X

Discontinue: 18/2/2019

REF:

MSIG

ASSIGNMENT

From:

Date: 15/2/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 5825A

at Workshop m/s K&M MOTOR

of 53 UBI AGE / # 01-19

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH 5825A Yr Regn: 20/7/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN 200 L3017

C.C. 1461

Colour: SILVER / GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 7996 T/Radio: Insured / Std / NI / NA

Eng/No: K2KE62SD43S059

C/No: WSKYBAN12CXC15841C

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175 / 70 R14

R: 175 / 70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 12/2/19

D.O.I. 15/2/19

Survey held at K&M MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 12,000/2 - 14,000/2

[Signature]
25/2/2019

MV 59,000/2

PV 29,225/2

NV 29,745/2

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 15

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I. (\$))

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		15 Feb 2019 09:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TRACTORS SINGAPORE LTD, Co. Reg. No.: 196600025H		
Main Claimant:	STARHUB CABLE VISION LTD, Co. Reg. No.: 199103398C		
Vehicle Reg. No.:	GBH5825M	Date of Loss:	13/02/2019 14:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29040188MKF (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
Vehicle Reg. No. (Insured):	GBB7865R	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	K & M Motor Pte Ltd (HQ) 53 Ubi Ave 1 #01-19 Paya Ubi Industrial Park, 408934 Ubi - Tel: 66945965		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/02/2019]		
Driver/Custodian (Insured):	RAMALINGAM RENGARASU (36 / Male), NRIC: G7791419L		
Adj Asg. Remarks:	on WP, SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100% CONTACT:VICKI 9753 8067		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2019 21:22
Date Of Accident	13/02/2019 14:25
Exact Location Of Accident	PIE TOWARDS TUAS- PAYA LEBAR FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH5825M
Insured/Policyholder	
Name Of Registered Owner	STARHUB CABLE VISION LTD
Co Reg No	199103398C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81136841
Alternative Phone No	OFFICE-68732828

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D19MFL0000071
Cover Note Number	

Driver

Name of Driver	HOON WEN HAO, LEONARD
NRIC No	S8842845E
Date Of Birth	01/11/1988
Occupation	OUTDOOR
Date Of Driving Pass	05/08/2011
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81136841
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 113 BISHAN STREET 12 #10-106
Postcode	570113
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 13 FEB 2019 AT/ ABOUT 1422HRS, I WAS DRIVING MY COMPANY VEHICLE GBH5825M ON PIE TOWARDS TUAS, WHEN SMH4105J (VEH B) BRAKE, I SLOWED DOWN MY VEHICLE. SUDDENLY, GBB7865R (VEH C) HIT THE REAR OF MY VEHICLE THUS MOVING MY VEHICLE FOWARD TO HIT (VEH B).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SMH4105J
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PENG ZHICAI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBB7865R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMALINGAM RENGARASU
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/02/2019, at about 1422hrs, I was driving my vehicle, GBH 5825M, on PIE towards Tuas, when vehicle B, brake, I slowed down my vehicle. Suddenly, vehicle C, GBB 7865 R, hit the rear of my vehicle thus moving my vehicle forward to hit vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/02/2019
1755hrs

Reporting Centre Personnel's Signature
Name: NURBIZAH
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/02/2019
1755hrs

Reporting Centre Personnel's Signature
Name: NUREZAH
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3398C
Vehicle Details	
Vehicle No.:	GBH5825M
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	K9KE628D438059
Chassis No.:	VSKYBAM20Z0158410
Maximum Power Output:	-
Open Market Value:	\$20,486.00
Original Registration Date:	20 Jul 2018
First Registration Date:	20 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$1,025.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,092.00
COE Rebate Amount:	\$29,255.00
Total Rebate Amount:	\$29,255.00

The information contained herein is correct as at 21 Feb 2019

OK

Dep 6,490/yr

MV 53,000/2

PV 29,255/2

NV 29,745/2

[Signature]

21/2/19



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



2.38%P.A. Lowest Interest! 9-GV
Cars Financing \$4800
Downpayment Monthly From
\$988
GV Credit Pte Ltd - StarAd



Browse by Category ▾

Sort by Date Posted ▾

100 results/page ▾

55 vehicles

Nissan NV200

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg. Date	Eng. Cap	Mileage	Veh. Type	Status
Search Selection	Nissan NV200		Any	Any	2018	Any	Any	Any	All
	Nissan	NV200 1.5M	\$60,288	\$6,220 /yr	30-Oct-2018	1,461 cc	-	Van	Available
Fuel Type: Diesel Last 3 Units! 100% Easy Approval In-House/Bank Loan Schemes/High Trade-In(s) Welcome! Immediate Delivery! We Assure, We Promise And We Deliver Always! Please Call Our Friendly Sales Staffs For A Non-O... SG Motor Link Pte Ltd Posted: 21-Feb-2019 Tags: 2018 Nissan NV200, 2018 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.5M	\$61,800	\$6,410 /yr	12-Oct-2018	1,461 cc	-	Van	Available
Fuel Type: Diesel Ready Stock Nissan NV200 1.6 Manual Euro 6. Low Interest Rate! Immediate Handover Tan Chong Warranty. 5 Years Or 140k Km Mileage Which Ever Come First. 3 Times Free Servicing Include Parts And Labour. KSL Automotive Pte Ltd Posted: 21-Feb-2019 Tags: 2018 Nissan NV200, 2018 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.5M	\$60,800	\$6,490 /yr	02-Jul-2018	1,461 cc	-	Van	Available
Fuel Type: Diesel Almost New, Ready Stock, Loan/In-House Financing Available With Lowest Interest Rate, All Trade-In Are Welcomed! Call Our Friendly Sales Representative Now For An Appointment And For An In-Depth Consu... Posted: 21-Feb-2019 Tags: 2018 Nissan NV200, 2018 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.6A	\$53,800	\$5,510 /yr	27-Nov-2018	1,597 cc	-	Van	Available
Fuel Type: Petrol Cheapest In The Market! New Automatic Nissan Nv200, Installment From \$600 Plus! Come With Full Rear Glass Panel And Recyclable Sofa Seats! Warranty And Free Servicing Provided! Ready Stock! 100% Loan ... Net Link Partners Pte Ltd Posted: 20-Feb-2019 Tags: 2018 Nissan NV200, 2018 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Lee Sheng Auto Pte Ltd - Spray Painting Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting. More info about this shop								
	Nissan	NV200 1.5M	\$55,800	\$5,790 /yr	12-Oct-2018	1,461 cc	-	Van	Available
Fuel Type: Diesel Guaranteed Lowest Price. Call Us Now. New Unit Offer, Only \$6000 Yearly Depreciation. Cheaper Than A Car. 100% Loan Available. Low Fuel Consumption Yet Powerful Vehicle! Comes Along With Warranty And ... Net Link Partners Pte Ltd Posted: 20-Feb-2019 Tags: 2018 Nissan NV200, 2018 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.6A	\$56,800	\$5,800 /yr	05-Dec-2018	1,597 cc	-	Van	Available
Fuel Type: Petrol Guaranteed Cheapest In The Entire Market, Enquire To Believe, Financing Can Be Done Up To 100% (Optional), High Trade In Value For Your Beloved Vehicle! Attractive Packages Available, Contact Us Now. Net Link Partners Pte Ltd Posted: 19-Feb-2019 Tags: 2018 Nissan NV200, 2018 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		15 Feb 2019 09:47 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRACTORS SINGAPORE LTD, Co. Reg. No.: 196600025H		
Main Claimant:	STARHUB CABLE VISION LTD, Co. Reg. No.: 199103398C		
Vehicle Reg. No.:	GBH5825M	Date of Loss:	13/02/2019 16:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 585224	Policy/Cover Note No.:	B29040188MKF (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
Vehicle Reg. No. (Insured):	GBB7865R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	K & M Motor Pte Ltd (HQ) 53 Ubi Ave 1 #01-19 Paya Ubi Industrial Park, 408934 Ubi - Tel: 66945965		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Imm.Advice due 16/02/2019]		
Driver/Custodian (Insured):	RAMALINGAM RENGARASU (36 / Male) , NRIC: G7791419L Email:		
Adj Asg. Remarks:	on WP. SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100% CONTACT:VICKI 9753 8067		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)


































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBH5825M (585224)**
[GBB7865R]
TP
STARHUB CABLE VISION LTD
Feb 13 2019 4:00PM
[TRACTORS SINGAPORE LTD]
K & M Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/02/19 15:41	Video - Accident (TP) - Front	 Load MP4	<input checked="" type="checkbox"/>
2	14/02/19 15:42	Video - Accident (TP) - Rear	 Load MP4	<input checked="" type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/02/19 09:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	25/02/19 09:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
81	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
82	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
83	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
84	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
85	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
86	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
87	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
88	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
89	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
90	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
91	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
92	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
93	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
94	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
95	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
96	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
97	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
98	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
99	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
100	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
101	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
102	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
103	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
104	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
105	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
106	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
107	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
108	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
109	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓
110	25/02/19 09:50	Photographs of Damaged Parts	Load JPG	✓

Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/02/19 15:34	GBB7865R E-FILE REPORT	Load PDF	
2	14/02/19 15:34	GBH5825M TP E-FILE REPORT	Load PDF	
3	14/02/19 15:34	SMH4105J TP E-FILE REPORT	Load PDF	
4	14/02/19 15:35	PRI - LAWRENCE LEE & CO	Load PDF	
5	14/02/19 17:13	SURVEY DISAGREE ON SJE - ASSIGN LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST


Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19002903/BCD3S2

Date: 27/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29040188MKF

Claimant Vehicle No : GBH5825M

Insured Vehicle No : GBB7865R

Date of Loss: 13/02/2019

Nature of Claim: TP

Claim No: 585224

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH5825M

Make & Model: NISSAN NV200, 1.5 (M)

Engine No: K9KE628D438059

Reg. Date: 20/07/2018 (Man. Year: 2017)

Chassis No: VSKYBAM20Z0158410

Colour: Green/Silver

Odometer: 7996 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14

Rear Tyre Size:

175/70R14

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 15/02/2019 Inspected At:

K & M Motor Pte Ltd (HQ)

53 Ubi Ave 1 #01-19 Paya Ubi Industrial Park

Singapore 408934

Estimated Period of Repair: 15.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,000.00 - \$14,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Feb 2019)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH5825M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >