

ASSIGNMENT

REF: CS/MSG/19002908/ Jvd30

Area of Instruction

SA/VEH/1
merimenHave Sir
Vimmaler

ASSIGNMENT (Office)

From (Person)

MS/G

Date/Time: 15/2/19 @ 3:41pm

Estimated Cost

Bill for

① TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJP 6618B

Insured:

at Workshop no:

SMRT

Tel:

68662672 / 65555556

of

60 woodlands Ind. Park E4

Esther

Policy No.

28882266

Claim No.

584636

Sum Insured

Excess:

\$700.00

Make of Veh.

(Client's Record)

D.O.A.

9/2/19

CA / RRV

/ REP. / REV 24 HRS

R.O.D. Endorsement

Date/Time:

5:40pm 15/2/19

Person Contacted

Vehicle: IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

Repairer amey on 18/1/19

SJP 6618B - X

21/2/19

Recd file from assignment Team.

21/2/19

Revert via merimen

21/2/19

Recd approved \$11,061.74 from Chen How by merimen

21/2/19

Informed Esther c/A on part by part ex \$700 by email

Hwa Jie

MSIG

18/2/19

SJP 6618B

27 Feb 2012

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Insured Vehicle No

SJP 6618B

4 Wheel drive

SMRT

at

60 Woodlands Ind-Park E 4

Insured

Policy No

Claim No

Sum Insured

Excess \$100.00

(Client's Record)

Make of Veh

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Truck / Trailer

Make BMW X1

1995

Colour white

AK Insured / Std / NI / NA

Sp Reading 93638

Tireallo Insured / Std / NI / NA

Engine

Chn WBAVL320X0VP94081

Gen Cond Good / Fair / Poor / Burnt

Steering Jammer / Jammed / Leaked / Burnt or

Brake Jammer / Jammed / Leaked / Burnt or

Mod Nil / L / STD A/Rim or

Tyre Size F: 225/50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal 6 mm

R/Bal 6 mm

L/Bal 6 mm

L/Bal 6 mm

D.O.A 9/2/12

D.O.I 18/2/19

Survey held at

Sumit

Des. of Damages Front / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV - \$59,000 \$55K.

PV - \$41,516

NV - \$17,484

RECEIVED 3 APR 2019

28/3/19

@ 905am Esther will email parts invoice

3/4/19

Final Ag \$10,995.74 (Red 4371.29, 28%) confirmed by email

[Signature]
2/4/2019

Sub/Line: File/Pass for



Preli. Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee

Transportation

1. S + P + M

1. H + G

1. R + G

1. S + G

Total

200

200

Sub/Line: File/Pass for



Final Report

Add Fee:



Site trip \$



Inter-city \$



Extra trip \$



Workshop \$

3/4 - typist

Report Format

menmen

Lump Sum / L.P. \$

10,995.74

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt.	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2019 09:31 Sendback Est	15 Feb 2019 09:51 S\$15,367.03	15 Feb 2019 15:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHOW KHUAN YEW , ID: S2562906Z, Tel: +6598192894, Email: illusion56@hotmail.com									
Vehicle Reg. No.: SJP6618B		Date of Loss: 09/02/2019 12:00 - :59 [85 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 584636		Policy/Cover Note No.: 28882266 (Comprehensive) Coverage: 28/03/2018 - 26/02/2019							
		Excess: S\$700.00							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/02/2019]									
Driver/Custodian: CHOW KHUAN YEW (57 / Male) , NRIC: S2562906Z, Tel: +6598192894									
Adj Asg. Remarks: Car in, survey on 18/02/19 morning. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 21 February 2019 2:43 PM
To: SUR; Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC)
(TeyChorKeng@smrt.com.sg)
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: SJP 6618B-DOA: 9/2/2019 (MSIG OD)

Dear Esther,

As instructed by our client , please proceed to repair the **insured vehicle SJP 6618B on part by part (Excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SJP6618B (584636)

OD

Feb 9 2019 12:00PM

[CHOW KHUAN YEW]

SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 21/02/2019 14:17 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11061.74) - SJP6618B - Claim Handler: Vimmaia D/O Raja Singam

Approved:11061.74.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Vimmala D/O Raja Singam	Date: 21 Feb 2019
<u>Preliminary Advice</u>	

Vehicle No	: SJP6618B	Accident Date	: 09/02/2019
Make	: BMW X1 SDRIVE18I	Policy No.	: 28882266
Assignment Date	: 15/02/2019	Excess	: S\$700.00
Date of Inspection	: 18/02/2019	Est. Duration of Repair	: 4.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,367.03
Revised Amount	:S\$	11,061.74
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,061.74

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	59,000.00
COE / PARF Rebate	:S\$	41,516.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,484.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)

D.O.A. 9/2/2019

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2906Z
Vehicle Details	
Vehicle No.:	SJP6618B
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18i AT D/AB 2WD 5DR GAS/D SR
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	B253J053N46B20BD
Chassis No.:	WBAVL320X0VP94081
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$30,315.00
Original Registration Date:	27 Feb 2012
First Registration Date:	27 Feb 2012
Transfer Count:	1
Actual ARF Paid:	\$30,315.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2022
PARF Rebate Amount:	\$19,704.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,340.00
COE Rebate Amount:	\$21,812.00
Total Rebate Amount:	\$41,516.00

15,157

The information contained herein is correct as at 21 Feb 2019

OK

3yr - 0.6 mth



BMW X1 sDrive18i **\$42,000** **\$12,150 /yr** **25-Mar-2011** **1,995 cc** **106,100 km** **SUV** **Available**

Full Loan And In House Loan Available! Servicing Done Regularly And Car Well Maintained, Repairs Done Recently So Buy And Drive With Peace Of Mind! Trade In Possible. Call For Viewing Now.

[CONTACT US](#)

Posted: 31-Jan-2019 Tags: 2011 BMW X1, 2011 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW



BMW X1 sDrive18i **\$115,000** **\$13,670 /yr** **14-Jul-2016** **1,499 cc** **49,624 km** **SUV** **Available**

Come With 5 Years Warranty And Servicing By PML (Until 2022). Enjoy Loan Interest Rate At 2.28%. Financing Possible. Trade In Welcome. 100% Accident Free. Well Maintained, View To Believe. Call/SMS To...

[CONTACT US](#)

Posted: 29-Jan-2019 Tags: 2016 BMW X1, 2016 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW



BMW X1 sDrive18i **\$41,800** **\$14,380 /yr** **17-Jan-2011** **1,995 cc** **107,000 km** **SUV** **Available**

Regularly Serviced And Maintained By Meticulous Owner. No Repairs Needed. Very Clean And Neat Interior, View And See It For Yourself! 6 Months Warranty And 1 Free Major Servicing! Witness Firsthand Fo...

Posted: 29-Jan-2019 Tags: 2011 BMW X1, 2011 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW



Sell to direct buyers at the price you want!

Make the choice to sell only if the price meets your expectations. Contact our agents to find out how to list on consignment.

[Find out more!](#)



BMW X1 sDrive18i (New 10-yr COE) **\$65,500** **\$6,540 /yr** **25-Jun-2010** **1,995 cc** **150,000 km** **SUV** **Available**

Panoramic Roof X1 sDrive18i With New 10 Years COE At Only \$6.5K Depreciation. Only 2 Owners. Enjoy This Powerful, Quiet And Stable x Series. Very Well Kept By Previous Owner. Wear And Tear Done By Rep...

Posted: 25-Jan-2019 Tags: 2010 BMW X1, 2010 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW



BMW X1 sDrive18i **\$102,000** **\$12,060 /yr** **26-May-2016** **1,499 cc** **65,000 km** **SUV** **Available**

Accident Free, Careful Driver, Park In Shaded Carpark Work And Home. All Services Done By Pml. Still Left Over 2 Years Of Warranty By Pml. Schedule A Test Drive Today. Viewing Strictly By Appointment...

[CONTACT US](#)

Carro

Posted: 24-Jan-2019 Tags: 2016 BMW X1, 2016 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW



BMW X1 sDrive18i **\$39,900** **\$11,540 /yr** **10-Mar-2011** **1,995 cc** **176,000 km** **SUV** **Available**

1 Owner And Accident Free. Periodic Maintenance And No Repairs Needed. Spacious Cabin And A Smooth Drive, Great For Family Usage, Beautiful Panoramic Roof Adds The icing To This Ride. Optional Warrant...

[CONTACT US](#)

Prem Roy Motoring

Posted: 19-Jan-2019 Tags: 2011 BMW X1, 2011 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW



BMW X1 sDrive18i **\$138,888** **\$13,630 /yr** **21-Dec-2017** **1,499 cc** **21,000 km** **SUV** **Available**

Excellent Condition, Sporty And Elegant Vehicle. 1st Owner. Warranty Package Until Dec 2020. Free Service Package With Munich Automobiles For 2 Years.

[CONTACT US](#)

Posted: 08-Jan-2019 Tags: 2017 BMW X1, 2017 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW



BMW X1 sDrive18i **\$117,800** **\$13,040 /yr** **06-Jan-2017** **1,499 cc** **26,000 km** **SUV** **Available**

Agent Unit With Agent Warranty! Fully Agent Serviced! Tip Top Condition! Well Maintained By Previous Owner! In House Financing And Trade In Available! Call Now To Enquire!

Hui Hua Credit Pte Ltd

Posted: 23-Dec-2018 Tags: 2017 BMW X1, 2017 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

40 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used BMW X1 sDrive18i, BMW X1 sDrive18i Singapore, used BMW X1 sDrive18i Singapore, used BMW X1 sDrive18i, used vehicles Singapore or even buy used BMW X1 sDrive18i Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/02/2019 08:28
 Date Of Accident 09/02/2019 12:55
 Exact Location Of Accident PIE JURONG BRFORE KPE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJP6618B
Insured/Policyholder
 Name Of Registered Owner CHOW KHUAN YEW
 NRIC No S2562906Z
 Email Address ILLUSION56@HOTMAIL.COM
 Mobile Phone No (LOCAL) +65-98192894
 Alternative Phone No OFFICE-98192894

Vehicle Particulars

Manufacturer BMW
 Model X1
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USAGE
 Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number A28832265QMY
 Cover Note Number

Driver

Name of Driver CHOW KHUAN YEW
 NRIC No S2562906Z
 Date Of Birth 05/07/1961
 Occupation INDOOR
 Date Of Driving Pass 15/08/1990
 Driving Experience 28 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98192894
 Fax Number
 Contact Number OFFICE-98192894
 Email Address ILLUSION56@HOTMAIL.COM

Address	4 LORONG 37 GEYLANG #06-01
Postcode	387902
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC6416J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



A: SJP 6615B3
B: SHC 6416J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/02/2019 @ 1255 hours as I was traveling along PIE towards Irving before KPE I noticed the car in front was stationary so I quickly stepped onto car brake but my car (SJP 6615B) was not in time to stop and hit the stationary car in front (Kitt SHC 6416J). My car had damages in front when I opened door and took on look at my car, a few cars in front also stopped and hit against the another.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

11/02/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

11/07/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

**SMRT Automotive Services Pte
Ltd**
**60 WOODLANDS INDUSTRIAL
PARK E4**
757705

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 02/14/2019 05:21 PM

Full Report
Registration: SJP6618B
Printed: 14/02/2019 5:21 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	SMRT Raymond	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-09
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	BMW		
Model:	X1 E84		
Sub Model:	X1 SDRIVE18I		
Model Sheet Number:	01 XA 02		
Registration:	SJP6618B		
VIN number:	WBAVL320X0VP94081		
Odometer:			
Model Specs			
FROM 03/2012	AIR CONDITIONING	2.0 LTR 110 KW	CHINA VERSION

**SMRT Automotive Services Pte
Ltd
60 WOODLANDS INDUSTRIAL
PARK E4
757705**

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 02/14/2019 05:21 PM

Full Report
Registration: SJP6618B
Printed: 14/02/2019 5:21 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 2019-02-13

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 12 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
41 35 600	RENEW L/F SIDE PANEL BRACKET FRONT		5.0	20.83
41 35 600	RENEW R/F SIDE PANEL BRACKET FRONT		5.0	20.83
41 35 040	R + R BOTH FRONT SIDE PANELS		23.0	95.83
41 33 039	R + R FRONT PANEL INCLUDES: R + R BUMPER, BUMPER CARRIER AND HEADLAMPS		23.0	95.83
41 33 040)	RENEW FRONT PANEL (REMOVED)		7.0	29.17
51 11 592	RENEW FRONT BUMPER COVER (FRONT BUMPER REMOVED)		9.0	37.50
63 12 505)	RENEW L/HEADLAMP (REMOVED)		1.0	4.17
63 12 509)	RENEW R/HEADLAMP (REMOVED)		1.0	4.17
41 61 600	R + R BONNET		4.0	16.67
41 61 514)	ADJUST BONNET		2.0	8.33
41 61 501	REPLACE BONNET (WITH BONNET REMOVED)		6.0	25.00
41 61 545	RENEW L/BONNET HINGE		1.0	4.17

**SMRT Automotive Services Pte
Ltd
60 WOODLANDS INDUSTRIAL
PARK E4
757705**

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 02/14/2019 05:21 PM

Full Report
Registration: SJP6618B
Printed: 14/02/2019 5:21 PM

Code	Description	WU	Price SGD
41 61 545	RENEW R/BONNET HINGE	1.0	4.17
NO NUMBER	R + R BONNET SEAL	1.0	4.17
64 50 509	DRAIN/REFILL AIR CONDITIONING	6.0	25.00
17 11 510	R + R RADIATOR	11.0	45.83
	INCLUDES: R + R ELECTRIC FAN DRAIN + REFILL COOLANT		
64 53 550)	R + R AIR CONDITIONING CONDENSER	1.0	4.17
17 11 536)	RENEW FAN SHROUD (REMOVED)	1.0	4.17
22 11 511)	R + R LEFT ENGINE BEARING	2.0	8.33
22 11 501)	R + R RIGHT ENGINE BEARING	2.0	8.33
22 11 521)	R + R ENGINE BEARING	3.0	12.50
1004	MECHANICAL LABOUR NIL		250.00*
Labour Cost		Hrs	WU
Panel / Mechanical Labour		9.60	115.0
Fixed Rate			250.00
Total of Labour			729.17

Paint

Paint Work		Time Basis 12WU/h	
Code	Description - MF	WU	Price SGD
99 68 821	FRONT BUMPER PAINTING STAGE 2	9.0	37.50
LE 0313	FRT TOWING EYE COVER PAINTING STAGE 2	2.0	8.33
99 61 529	BONNET PAINTING STAGE 2	28.0	116.67
99 35 519	L/F WING PAINTING STAGE 2	7.0	29.17
99 35 519	R/F WING PAINTING STAGE 2	7.0	29.17
NN	PAINTING NIL		300.00*
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	21.0	87.50
Total Paint		Hrs 6.20	WU 74.0
		Price SGD 308.33	
Labour Cost - Paint		Hrs	WU
Factor		50.00 SGD/h	
Preparation Main Work Metal		1.75	21.0
Total			300.0

**SMRT Automotive Services Pte
Ltd**
**60 WOODLANDS INDUSTRIAL
PARK E4**
757705

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 02/14/2019 05:21 PM

Full Report
Registration: SJP6618B
Printed: 14/02/2019 5:21 PM

Material Cost - Paint	Price SGD
New Part Painting	150.07
Material-constant Metal	13.47
Total	163.54

Spare Parts

				prices as at 2018-09-10/02
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3	DEF ✓	40.00
0283	FRONT BUMPER	51 11 2 993 565	BUC ✓	662.75 ✓
0284	FRT LWR BUMPER COVER	51 11 2 990 186	BUC ✓	177.95 ✓
0303	FRONT BUMPER GRILLE	51 11 2 990 368	NNSEA X	83.35
0307	FRT GRILLE TRIM SET	51 11 2 993 588	NNSEA X	85.35
0309	FRT AIR INTAKE COVER	51 11 2 991 406	CRA ✓	85.00 ✓
0313	FRT TOWING EYE COVER	51 11 2 990 204	NN X	31.75 ✓
0336	FRT BUMPER SUPPORT	51 11 2 990 187	DD ✓	495.25 ✓
0339	FRONT IMPACT DAMPER	51 11 2 990 205	CRA ✓	46.30 ✓
0351	FRT BUMPER CLAMP KIT	51 11 2 410 287	NEC ✓ NH	26.95
0415	L/F GRILLE	51 11 2 993 305	SCR ✓	86.75 ✓
0416	R/F GRILLE	51 11 2 993 306	SCR ✓	86.75 ✓
0431	GRILLE BADGE	51 14 8 132 375	NEC ✓	69.50 ✓
0471	BONNET	41 00 2 993 151	DD ✓	1,292.85 ✓
0475	L/BONNET HINGE	41 00 2 993 149	NN X	71.55
0476	R/BONNET HINGE	41 00 2 993 150	NN X	71.55
0493	CATCH HOOK STRUT	51 64 2 990 177	BT ✓	22.60 ✓
0494	SAFETY LATCH	51 23 2 990 367	CRA ✓	38.45 ✓
0497	L/F BONNET STRUT	41 61 2 990 344	SVC X	115.20
0498	R/F BONNET STRUT	41 61 2 990 344	SVC X	115.20
0503	L/BONNET LOCK	51 23 7 008 755	SVC X	105.95
0504	R/BONNET LOCK	51 23 7 008 755	SVC X	105.95
0527	BONNET FRT GASKET	51 76 2 990 363	NN X	34.65
0561	LEFT HEADLAMP ASSY	63 11 2 990 003	CRA ✓	1,155.00 ✓
0562	RIGHT HEADLAMP ASSY	63 11 2 990 004	CRA ✓	1,155.00 ✓
0741	L/F WING	41 00 2 993 155	Repair ✓	614.25
0742	R/F WING	41 00 2 993 156	Repair ✓	614.25
0765	L/F S/PANEL BRKT FRT	41 00 2 992 909	BT ✓	101.45 ✓
0766	R/F S/PANEL BRKT FRT	41 00 2 992 910	NN X	102.10
1009	FRONT PANEL	51 64 2 990 176	NN X CRA ✓	561.65 ✓
1015	FRONT AIR BAFFLE	51 64 2 990 178	CRA ✓	56.65 ✓
1187	L/HEADLAMP SUPPORT	51 64 2 990 179	CRA ✓	38.50 ✓
1188	R/HEADLAMP SUPPORT	51 64 2 990 180	CRA ✓	38.50 ✓
4465	CONDENSER	64 53 9 229 022	BT ✓	979.45 ✓

**SMRT Automotive Services Pte
Ltd
60 WOODLANDS INDUSTRIAL
PARK E4
757705**

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 02/14/2019 05:21 PM

Full Report
Registration: SJP6618B
Printed: 14/02/2019 5:21 PM

Code	Description	Part Number	Supplier	Price SGD
7761	RADIATOR	17 11 7 553 111	NN X	750.00
7771	L/LWR RADIATOR BRKT	17 11 7 591 647	NN X	33.60
7772	R/LWR RADIATOR BRKT	17 11 7 591 647	CRA ✓	33.60 ✓
7777	L/RADIATOR BRACKET	17 10 7 524 912	NN X	52.35
7778	R/RADIATOR BRACKET	17 10 7 524 914	CRA ✓	52.35 ✓
7789	ELECTRIC FAN CPL	17 42 7 563 259	CRA ✓	1,053.75 ✓
8631	L/ENGINE MOUNTING	22 11 6 768 853	NN X	188.65
8632	R/ENGINE MOUNTING	22 11 6 768 852	NN X	188.65
1000	AIR CLEANER BOX	NIL	NN X	355.00
1001	AIR CLEANER TOP CVR	NIL	NN X	275.00
1002	AIR CLEANER TOP EXT	NIL	NN X	145.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 12,496.35
u: Used parts				Addition(+10.00%) 1,249.64
Total				13,745.99

Extras

Code	Description	Price SGD
1005	TOP UP AIRCON GAS NIL	60 120.00*
Total Extras		120.00

**SMRT Automotive Services Pte
Ltd**
**60 WOODLANDS INDUSTRIAL
PARK E4**
757705

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 02/14/2019 05:21 PM

Full Report
Registration: SJP6618B
Printed: 14/02/2019 5:21 PM

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	12,496.35	
Total Parts	1,249.64	13,745.99
Labour Time Base 12 WU/h		
Total 115.0 WU X 50.00 SGD/h	479.17	
Fixed Rate	250.00	
Total of Labour	629.17	729.17
Total Of Extras		120.00
Paint Work Time Base 12 WU/h		
Labour Cost 74.0 WU X 50.00 SGD/h	308.33	
Material Cost	163.54	
Total Paint Including Material	471.87	771.87
Repair Cost Excludes GST		15,367.03
GST (+7.0%)		1,075.69
Repair Cost Included GST		16,442.72

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:


21/2/19
Hwee Jie-Lkk
18/2/19
P/P 4days
Not Authorise
Excess- \$700


REQUEST FOR SUPPLEMENTS PARTS

Contractor:			
Accident Case Number		Date of Collection	/ /
Vehicle No	SJP 6618 B	Date of Request	19/2/2019
Vehicle Model	BMW X1	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
1		FRONT BUMPER NOZZLE CRA	2	\$ 280.00

<<< Please submit photographs for damaged parts >>>

I, (Name) Ony Huse Jia - LKK

(Position) Surveyor

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

 19/2/19
 Signature of person making this declaration
 (to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission

All Enterprise Pte Ltd
 1 Kaki Bukit Ave 6, #02-26,
 Singapore 417883
jonathan@aep.com.sg
 GST Registration No: 201601557N



Tax Invoice

INVOICE TO

Cash Job

Vehicle Number: SJP 6618 B

INVOICE NO 1904001

DATE 19/2/2019

DUE DATE 18/3/2019

TERMS 30 TERM

SERVICE	DESCRIPTION	QTY	RATE	GST	AMOUNT
PART	FRONT BUMPER	1	\$ 662.75	7%	\$ 662.75
PART	FRONT LOWER BUMPER COVER	1	\$ 177.95	7%	\$ 177.95
PART	FRONT AIR INTAKE COVER	1	\$ 85.00	7%	\$ 85.00
PART	FRONT TOWING EYE COVER	1	\$ 31.75	7%	\$ 31.75
PART	FRONT BUMPER SUPPORT	1	\$ 495.25	7%	\$ 495.25
PART	FRONT IMPACT DAMPER	1	\$ 46.30	7%	\$ 46.30
PART	GRILLE LH	1	\$ 86.75	7%	\$ 86.75
PART	GRILLE RH	1	\$ 86.75	7%	\$ 86.75
PART	GRILLE BADGE	1	\$ 69.50	7%	\$ 69.50
PART	BONNET	1	\$ 1,292.85	7%	\$ 1,292.85
PART	LOCK CATCH HOOK	1	\$ 22.60	7%	\$ 22.60
PART	LOCK LATCH	1	\$ 38.45	7%	\$ 38.45
PART	LEFT HEADLAMP ASSY	1	\$ 1,155.00	7%	\$ 1,155.00
PART	RIGHT HEADLAMP ASSY	1	\$ 1,155.00	7%	\$ 1,155.00
PART	FRONT LH SIDE PANEL BRACKET	1	\$ 101.45	7%	\$ 101.45
PART	FRONT PANEL	1	\$ 561.65	7%	\$ 561.65
PART	FRONT AIR BAFFLE	1	\$ 56.65	7%	\$ 56.65
PART	HEADLAMP SUPPORT LH	1	\$ 38.50	7%	\$ 38.50
PART	HEADLAMP SUPPORT RH	1	\$ 38.50	7%	\$ 38.50
PART	CONDENSER	1	\$ 979.45	7%	\$ 979.45
PART	LOWER RADIATOR BRACKET RH	1	\$ 33.60	7%	\$ 33.60
PART	RADIATOR BRACKET RH	1	\$ 52.35	7%	\$ 52.35
PART	ELECTRIC FAN CPL	1	\$ 1,053.75	7%	\$ 1,053.75
PART	FRONT BUMPER NOZZLE	2	\$ 280.00	7%	\$ 280.00

SUBTOTAL \$ 8,601.80

GST TOTAL \$ 602.13

TOTAL \$ 9,203.93

BALANCE DUE **\$ 9,203.93**

GST SUMMARY

RATE	GST	NET
GST @ 7%	\$ 602.13	\$ 8,601.80

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 04/02/2019 05:08 PM

Full Report
Registration: SJP6618B
Printed: 02/04/2019 5:08 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-09
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	BMW		
Model:	X1 E84		
Sub Model:	X1 SDRIVE18I		
Model Sheet Number:	01 XA 02		
Registration:	SJP6618B		
VIN number:	WBAVL320X0VP94081		
Odometer:			
Model Specs			
FROM 03/2012	AIR CONDITIONING	2.0 LTR 110 KW	CHINA VERSION

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: WL/FEB2019/001
Version: 1810
Date calculated: 04/02/2019 05:08 PM

Full Report
Registration: SJP6618B
Printed: 02/04/2019 5:08 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection: 2019-02-13

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 12 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
41 35 600	RENEW L/F SIDE PANEL BRACKET FRONT		5.0	20.83
41 33 039	R + R FRONT PANEL INCLUDES: R + R BUMPER, BUMPER CARRIER AND HEADLAMPS		23.0	95.83
41 33 040)	RENEW FRONT PANEL (REMOVED)		7.0	29.17
51 11 592	RENEW FRONT BUMPER COVER (FRONT BUMPER REMOVED)		9.0	37.50
63 12 505)	RENEW L/HEADLAMP (REMOVED)		1.0	4.17
63 12 509)	RENEW R/HEADLAMP (REMOVED)		1.0	4.17
41 61 600	R + R BONNET		4.0	16.67
41 61 514)	ADJUST BONNET		2.0	8.33
41 61 501	REPLACE BONNET (WITH BONNET REMOVED)		6.0	25.00
64 50 509	DRAIN/REFILL AIR CONDITIONING		6.0	25.00
17 11 510	R + R RADIATOR INCLUDES: R + R ELECTRIC FAN		11.0	45.83

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: WL/FEB2019/001
 Version: 1810
 Date calculated: 04/02/2019 05:08 PM

Full Report
 Registration: SJP6618B
 Printed: 02/04/2019 5:08 PM

Code	Description	WU	Price SGD
	DRAIN + REFILL COOLANT		
64 53 550)	R + R AIR CONDITIONING CONDENSER	1.0	4.17
17 11 536)	RENEW FAN SHROUD (REMOVED)	1.0	4.17
1004	MECHANICAL LABOUR 000000		250.00*
0741	L/F WING REPAIR	7.0*	29.17
0742	R/F WING REPAIR	7.0*	29.17
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	7.60	91.0
	Fixed Rate		379.17
			250.00
	Total of Labour		629.17

Paint

Paint Work		Time Basis 12WU/h	
Code	Description - MF	WU	Price SGD
99 68 821	FRONT BUMPER PAINTING STAGE 2	9.0	37.50
LE 0313	FRT TOWING EYE COVER PAINTING STAGE 2	2.0	8.33
99 61 529	BONNET PAINTING STAGE 2	28.0	116.67
99 35 529	L/F WING PAINTING STAGE 3	12.0	50.00
99 35 529	R/F WING PAINTING STAGE 3	12.0	50.00
NN	PAINTING 000000		300.00*
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	22.0	91.67

Total Paint	Hrs	WU	Price SGD
	7.10	85.0	354.17

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			
Preparation Main Work Metal	50.00 SGD/h	1.83	22.0
Total			300.0

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: WL/FEB2019/001
 Version: 1810
 Date calculated: 04/02/2019 05:08 PM

Full Report
 Registration: SJP6618B
 Printed: 02/04/2019 5:08 PM

Material Cost - Paint	Price SGD
New Part Painting	114.81
Repair Painting	22.14
Material-constant Metal	13.47
Total	150.42

Spare Parts

				prices as at 2018-09-10/02
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	51 11 2 993 565		662.75
0284	FRT LWR BUMPER COVER	51 11 2 990 186		177.95
0309	FRT AIR INTAKE COVER	51 11 2 991 406		85.00
0313	FRT TOWING EYE COVER	51 11 2 990 204		31.75
0336	FRT BUMPER SUPPORT	51 11 2 990 187		495.25
0339	FRONT IMPACT DAMPER	51 11 2 990 205		46.30
0415	L/F GRILLE	51 11 2 993 305		86.75
0416	R/F GRILLE	51 11 2 993 306		86.75
0431	GRILLE BADGE	51 14 8 132 375		69.50
0471	BONNET	41 00 2 993 151		1,292.85
0493	CATCH HOOK STRUT	51 64 2 990 177		22.60
0494	SAFETY LATCH	51 23 2 990 367		38.45
0561	LEFT HEADLAMP ASSY	63 11 2 990 003		1,155.00
0562	RIGHT HEADLAMP ASSY	63 11 2 990 004		1,155.00
0765	L/F S/PANEL BRKT FRT	41 00 2 992 909		101.45
1009	FRONT PANEL	51 64 2 990 176		561.65
1015	FRONT AIR BAFFLE	51 64 2 990 178		56.65
1187	L/HEADLAMP SUPPORT	51 64 2 990 179		38.50
1188	R/HEADLAMP SUPPORT	51 64 2 990 180		38.50
4465	CONDENSER	64 53 9 229 022		979.45
7772	R/LWR RADIATOR BRKT	17 11 7 591 647		33.60
7778	R/RADIATOR BRACKET	17 10 7 524 914		52.35
7789	ELECTRIC FAN CPL	17 42 7 563 259		1,053.75
1007	FRONT BUMPER NOZZLE	00000		280.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	8,601.80
u: Used parts	Addition(+ 10.00%)	860.18
	Total	9,461.98

Extras

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: WL/FEB2019/001
 Version: 1810
 Date calculated: 04/02/2019 05:08 PM

Full Report
 Registration: SJP6618B
 Printed: 02/04/2019 5:08 PM

Code	Description	Price SGD
1005	TOP UP AIRCON GAS NIL	60.00*
1006	FRONT NUMBER PLATE	40.00*
	Total Extras	100.00

Final Calculation

	SGD	SGD
Parts	8,601.80	
Addition(+10.00%)	860.18	
Total Parts		9,461.98
Labour Time Base 12 WU/h		
Total 91.0 WU X 50.00 SGD/h	379.17	
Fixed Rate	250.00	
Total of Labour		629.17
Total Of Extras		100.00
Paint Work Time Base 12 WU/h		
Labour Cost 85.0 WU X 50.00 SGD/h	354.17	
Material Cost	150.42	
Total Paint Including Material		804.59
Repair Cost Excludes GST		10,995.74
GST (+7.0%)		769.70
Repair Cost Included GST		11,765.44

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 April 2019 9:54 AM
To: 'Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/One Stop Srv/One Stop Srv)'; SUR; Hwee Jie (LKK Auto)
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC); Peh Eng Hock (Auto Svcs/ARC/AR & SC/Taxis)
Subject: RE: SJP6618B MSIG OD - Finalise

Dear Esther,

Noted with thanks.

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/One Stop Srv/One Stop Srv) <TeyChorKeng@smrt.com.sg>
Sent: Wednesday, 3 April 2019 9:37 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Hwee Jie (LKK Auto) <hweejie@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC) <YewChung@smrt.com.sg>; Peh Eng Hock (Auto Svcs/ARC/AR & SC/Taxis) <PehEngHock@smrt.com.sg>
Subject: RE: SJP6618B MSIG OD - Finalise

Dear Veron,

We have confirmed the finalise amount \$10,995.74 before excess \$700 @ 4 working days.
Thank you.

Regards,
Esther

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: 03 April 2019 08:49
To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/One Stop Srv/One Stop Srv); SUR; Hwee Jie (LKK Auto)
Subject: RE: SJP6618B MSIG OD - Finalise

Dear Esther,

Finalize amount \$10,995.74 before excess \$700 @ 4 working days

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/One Stop Srv/One Stop Srv) <TeyChorKeng@smrt.com.sg>

Sent: Tuesday, 2 April 2019 10:36 AM

To: SUR <sur@lkkauto.com>; Hwee Jie (LKK Auto) <hweejie@lkkauto.com>

Subject: RE: SJP6618B MSIG OD - Finalise

Hi Veron,

Attached parts invoice as per your requested, thanks.

Kindly have your finalisation asap, thanks

Regards,
Esther

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2019 09:31 Sendback Est	15 Feb 2019 09:51 \$15,367.03	12 Mar 2019 14:07 Edit Adj Rpt	\$10,995.74 Edit Estimates	\$10,995.74 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHOW KHUAN YEW , ID: S2562906Z, Tel: +6598192894, Email: illusion56@hotmail.com									
Vehicle Reg. No.: SJP66188		Date of Loss: 09/02/2019 12:00 - :59 [83 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 584636		Policy/Cover Note No.: 28882266 (Comprehensive) Coverage: 28/03/2018 - 26/02/2019							
		Excess: S\$700.00							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimala D/O Raja Singam - 65942471]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 13/03/2019]									
Driver/Custodian: CHOW KHUAN YEW (57 / Male), NRIC: S2562906Z, Tel: +6598192894 Email: illusion56@hotmail.com									
Adj Asg. Remarks: Car in, survey on 18/02/19 morning. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (12/03/2019): Cancellation of Assignment: SJP66188 - MSIG_SG (21/02/2019): Alert - Adj Mandate Approved (\$11061.74) - SJP66188 - Claim Handler: Vimala D/...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJP6618B (584636)
OD
Feb 9 2019 12:00PM
[CHOW KHUAN YEW]
SMRT Automotive Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☐	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)		Thumbnail	Print					
1	11/02/19 08:40	Accident Statement	1	Load HTM						
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)		Thumbnail	Print					
1	15/02/19 09:51	Repairer Estimates	1	Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	21/02/19 09:48	Adjuster Immediate Advice	1	Load HTM						
Photos/Images							3 per page		☐	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)		Thumbnail	Print					
1	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
2	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
3	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
4	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
5	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
6	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
7	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
8	11/02/19 08:35	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
9	11/02/19 08:36	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
10	11/02/19 08:36	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
11	11/02/19 08:36	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
12	11/02/19 08:36	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
13	11/02/19 08:36	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	20/02/19 09:49	General View	1	Load JPG	☒					
2	20/02/19 09:49	General View	1	Load JPG	☒					
3	20/02/19 09:49	General View	1	Load JPG	☒					
4	20/02/19 09:49	General View	1	Load JPG	☒					
5	20/02/19 09:49	General View	1	Load JPG	☒					
6	20/02/19 09:49	General View	1	Load JPG	☒					
7	20/02/19 09:49	General View	1	Load JPG	☒					
8	20/02/19 09:49	General View	1	Load JPG	☒					
9	20/02/19 09:49	General View	1	Load JPG	☒					
10	20/02/19 09:49	General View	1	Load JPG	☒					
11	20/02/19 09:49	General View	1	Load JPG	☒					
12	20/02/19 09:49	General View	1	Load JPG	☒					
13	20/02/19 09:49	General View	1	Load JPG	☒					
14	20/02/19 09:49	General View	1	Load JPG						

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubl)	Thumbnail	Print
				☒
15	20/02/19 09:49	General View	 Load JPG	☒
16	20/02/19 09:49	General View	 Load JPG	☒
17	20/02/19 09:49	General View	 Load JPG	☒
18	20/02/19 09:49	General View	 Load JPG	☒
19	20/02/19 09:49	General View	 Load JPG	☒
20	20/02/19 09:49	General View	 Load JPG	☒
21	20/02/19 09:49	General View	 Load JPG	☒
22	20/02/19 09:49	General View	 Load JPG	☒
23	20/02/19 09:49	General View	 Load JPG	☒
24	20/02/19 09:49	General View	 Load JPG	☒
25	20/02/19 09:49	General View	 Load JPG	☒
26	20/02/19 09:49	General View	 Load JPG	☒
27	20/02/19 09:49	General View	 Load JPG	☒
28	20/02/19 09:49	General View	 Load JPG	☒
29	20/02/19 09:49	General View	 Load JPG	☒
30	20/02/19 09:49	General View	 Load JPG	☒
31	20/02/19 09:49	General View	 Load JPG	☒
32	20/02/19 09:49	General View	 Load JPG	☒
33	20/02/19 09:49	General View	 Load JPG	☒
34	20/02/19 09:49	General View	 Load JPG	☒
35	20/02/19 09:49	General View	 Load JPG	☒
36	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
37	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
38	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
39	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
40	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
41	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
42	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
43	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
44	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
45	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
46	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
47	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
48	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
49	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
50	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
51	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
52	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
53	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
54	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
55	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
56	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
57	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
58	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
59	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
60	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
61	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
62	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
63	20/02/19 09:49	Dismantled Parts	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
64	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
65	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
66	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
67	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
68	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
69	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
70	20/02/19 09:49	Dismantled Parts	 Load JPG	☒
71	21/02/19 08:34	Dismantled Parts	 Load JPG	☒
72	21/02/19 08:34	Dismantled Parts	 Load JPG	☒
73	21/02/19 08:34	Dismantled Parts	 Load JPG	☒
74	26/02/19 10:19	Replacement Part Photo	 Load JPG	☒
75	26/02/19 10:19	Replacement Part Photo	 Load JPG	☒
76	26/02/19 10:19	Replacement Part Photo	 Load JPG	☒
77	26/02/19 10:19	Replacement Part Photo	 Load JPG	☒
78	26/02/19 10:19	Replacement Part Photo	 Load JPG	☒
79	27/02/19 09:39	Photo After Spray	 Load JPG	☒
80	27/02/19 09:39	Photo After Spray	 Load JPG	☒
81	27/02/19 09:39	Photo After Spray	 Load JPG	☒
82	27/02/19 09:39	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	11/02/19 08:39	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	15/02/19 17:11	AUDATEX ESTIMATES	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/02/19 09:48	MARK ESTIMATE	 Load PDF	
2	09/04/19 12:51	Parts Invoice	 Load PDF	
3	09/04/19 13:54	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	11/02/19 08:40	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	11/02/19 08:35	Accident Photo	 Load JPG	☒
2	11/02/19 08:35	Accident Photo	 Load JPG	☒
3	11/02/19 08:35	Accident Photo	 Load JPG	☒
4	11/02/19 08:35	Accident Photo	 Load JPG	☒
5	11/02/19 08:35	Accident Photo	 Load JPG	☒
6	11/02/19 08:35	Accident Photo	 Load JPG	☒
7	11/02/19 08:35	Accident Photo	 Load JPG	☒
8	11/02/19 08:35	Accident Photo	 Load JPG	☒
9	11/02/19 08:36	Accident Photo	 Load JPG	☒
10	11/02/19 08:36	Accident Photo	 Load JPG	☒
11	11/02/19 08:36	Accident Photo	 Load JPG	☒
12	11/02/19 08:36	Accident Photo	 Load JPG	☒
13	11/02/19 08:36	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Ubi)	Thumbnail	Print
1	11/02/19 08:39	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Repairer ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19002908/JVD3E2

Date: 09/04/2019

REFERENCE

Insured/Claimant:	CHOW KHUAN YEW	Policy No:	28882266	
Date of Loss:	09/02/2019	Nature of Claim:	OD	Claim No: 584636

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP6618B		
Make & Model:	BMW X1 SDRIVE18I, 2.0 D/AB 2WD 5DR GAS/D SR (A)	Engine No:	B253J053N46B20BD
Reg. Date:	27/02/2012 (Man. Year: 2011)	Chassis No:	WBAVL320X0VP94081
Colour:	White	Odometer:	93638 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$59,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,745.99	9,501.98	4,244.01	30.87
Miscellaneous Items	120.00	60.00	60.00	50.00
Labour	729.17	629.17	100.00	13.71
Paintwork Labour	771.87	804.59	-32.72	-4.24
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,367.03	10,995.74	4,371.29	28.45
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	14,667.03	10,295.74	4,371.29	29.80
+ GST 7.00/7.00% (S\$)	1,026.69	720.70	305.99	29.80
Nett Amount (S\$)	15,693.72	11,016.44	4,677.28	29.80

INSPECTION

Date of Assignment:	12/03/2019 Present Location:	SMRT Automotive Services Pte Ltd (Woodlands)
Date Inspected:	18/02/2019 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

Adjuster: ONG HWEE JIE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2019)
Parts:	M1-SUV	BMW X1 SDRIVE18i 2.0 D/AB 2WD 5DR GAS/D SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP6618B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS (WCP)		12,496.35 F	*8,321.80 F
2	2		*FRONT BUMPER NOZZLE (WCP)	Cracked	-	*280.00 F
3	1		*FRONT NUMBER PLATE	Deformed	-	*40.00 FS
					Sub Total (S\$)	12,496.35
					+ Margin on L,N Items 10.00/10.00% (S\$)	1,249.64
					Total Parts (S\$)	13,745.99

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	TOP UP AIRCON GAS (TOTAL OF EXTRAS) (NECESSARY)	120.00	60.00
Sub Total (S\$)			120.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	PAINT	New	771.87	804.59
<u>Labour Items</u>				
2	LABOUR	New	729.17	629.17
Gross Labour Cost (S\$)			1,501.04	1,433.76

Report was unsubmitted during this print-out.

< END OF ESTIMATES >