

Surveyor

GQ

ASSIGNMENT (Office)

From (Person)

Orghiti

of

lpc

Date/Time

14/2

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKD 8549E

Insured:

GX 93084

at Workshop n/s

Alpha Car

Tel:

6509 8258

of

1 Kaki Bkt Ave 6 # 01-59

Policy No.

Claim No:

18/19/19/Vcos/021422

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

08/02/19

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time:

12:26pm 15/12/19

Person Contacted:

Cai ling

Vehicle

IN

OUT

Date/Time

Action/Instruction (4) Estimate

SKD 8549 E - X

GX 93084 - X

15/12/19

Submit PRS report

Dismantle: 20/12/19

After paint: 22/12/19

Nivitha (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 14 February 2019 4:46 PM
To: Admin-D (LKKAuto); assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: Your Ref: CP/PRI/SKD8549/19.na(sf) Our Ref: 18/19/19/vc05/021422 Accident inv GX9308U & SKD8549E on 08/02/2019 [External Confidential]
Attachments: PRI_SCAN_20190214_164301492_02142019_043949.pdf

Lonpac External - Confidential

Dear Catherine/Nivitha

fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: PRI Cpaglar [mailto:pri@cpaglar.com.sg]
Sent: Thursday, 14 February, 2019 4:44 PM
To: ONG LI LI
Cc: assignments@lkkauto.com; Admin-D (LKKAuto); MT_Claim_SG
Subject: Re: Your Ref: CP/PRI/SKD8549/19.na(sf) Our Ref: 18/19/19/vc05/021422 Accident inv GX9308U & SKD8549E on 08/02/2019 [External Confidential]

Dear Sir,

Please find enclosed.

Artika
Behalf of C Paglar & Co

On Thu, Feb 14, 2019 at 4:05 PM ONG LI LI <llong@lonpac.com> wrote:

Lonpac External - Confidential

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We refer to your fax of 14 February 2019.

Kindly note that our Claim dept fax number is 62962706.

We are not agreeable to your list of proposed surveyors, we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey.

Please let us know the details of your client's workshop and reply **BY EMAIL** to mt_claim@lonpac.com and all copied in this email.

Dear Catherine/Nivitha

Fya


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: ONG LI LI

Sent: Thursday, 14 February, 2019 11:48 AM

To: pri@cpaglar.com.sg

Cc: MT_Claim_SG

Subject: Your Ref: CP/PRI/SKD8549/19.na(sf) Our Ref: TBA Accident inv GX9308U & SKD8549E on 08/02/2019
[External Confidential]

Lonpac External - Confidential

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

| No. | Name | Please tick <input type="checkbox"/> |
|-----|------------------------------|--------------------------------------|
| 1 | Kalvin Ang | <input type="checkbox"/> |
| 2 | Xing Guo Qiang | <input type="checkbox"/> |
| 3 | Mohamad Taufikh | <input type="checkbox"/> |
| 4 | Bryan Ang | <input type="checkbox"/> |
| 5 | Adrian Ling | <input type="checkbox"/> |
| 6 | Mohammed Rasul | <input type="checkbox"/> |
| 7 | Marcus Chua | <input type="checkbox"/> |
| 8 | Kenneth Kong | <input type="checkbox"/> |
| 9 | Muhammad Nazril Bin Abdullah | <input type="checkbox"/> |
| 10 | Sathya Sai Kathirrasen | <input type="checkbox"/> |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

CPc

C PAGLAR & CO

ADVOCATES & SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275E

50 Chin Swee Road
#05-03 Thong Chai Building
Singapore 169874
Telephone: (65) 6536 5456
Facsimile: (65) 6836 2195
Email: pri@cpaglar.com.sg
SERVICE OF COURT DOCUMENTS BY FACSIMILE
WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: GX 9308U
Our Reference: CP/PRI/SKD8549/19.na

Date : 14th February 2019

LONPAC INSURANCE BERHAD
ATTN: MOTOR CLAIMS DEPT

BY FAX 6296 2706 ONLY

Dear Sirs,

CORRESPONDENCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES

We refer to your email dated 14th February 2019.

Please note that the said vehicle can be inspected at:

ALPHA CAR SERVICES PTE LTD
Blk C Kaki Bukit Avenue 6
#01-59 Autobay @KB
Singapore 417883
Contact No.: 6509 8258 / 8226 5945 (Ah Hwa / Cailing)

KINDLY REPLY BY EMAIL ONLY: pri@cpaglar.com.sg

Please note that the vehicle will only be available for the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you. All our client's rights are expressly reserved.

Yours faithfully,



C PAGLAR & CO

cc. [Client by email: alphacarservices@hotmail.com] - (SKD 8549E)

FOR SURVEYOR

Please initial here after completion of
pre-repair inspection.
Thank you

.....
Appointed Surveyor (Name & Signature)

.....
Date & Time of Inspection

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|-----------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 1860A |
| Vehicle Details | |
| Vehicle No.: | SKD8549E |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 18 Feb 2019 |
| Vehicle Make: | VOLVO |
| Vehicle Model: | S60 T4 1.6 AT ABS D/AB 2WD 4DR TC |
| Primary Colour: | White |
| Manufacturing Year: | 2011 |
| Engine No.: | B4164T1064517 |
| Chassis No.: | YV1FS485BC2116928 |
| Maximum Power Output: | 132.0 kW (177 bhp) |
| Open Market Value: | \$35,116.00 |
| Original Registration Date: | 13 Jan 2012 |
| First Registration Date: | 13 Jan 2012 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$35,116.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 12 Jan 2022 |
| PARF Rebate Amount: | \$21,069.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 12 Jan 2022 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$46,889.00 |
| COE Rebate Amount: | \$13,600.00 |
| Total Rebate Amount: | \$34,669.00 |

The information contained herein is correct as at 18 Feb 2019

OK



| PRE-REPAIR INSPECTION REPORT | | | |
|--|--|---|---|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | Ref: CS3/LPC19002941/Gvd3n2 Date: 26-02-2019 Code: LPC2 |  |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | |
| Insured Veh. | GX 9308U | Veh. Inspected | SKD 8549E |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | 18/19/19/VC05/021422 | Excess (\$) | 0.00 |
| Assign From | ONG LI LI | Assign Date | 14/02/2019 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | VOLVO S60 T4 | c.c | 1596 |
| Engine No. | HIDDEN | Year of Reg. | 2012 |
| Chassis No. | YV1FS485BC2116928 | Colour | WHITE |
| Odometer | 198771 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 215/50 R17 | TOYO | 6 mm |
| L/H Front Tyre | 215/50 R17 | TOYO | 6 mm |
| R/H Rear Tyre | 215/50 R17 | TOYO | 6 mm |
| L/H Rear Tyre | 215/50 R17 | TOYO | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | |  | |
| 5. General Information | | | |
| Accident Date | 08/02/2019 | Inspect Date / Time | 15/02/2019 (03:50 PM) |
| Survey held at | ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | |

Report Ref No. CS3/LPC19002941/Gvd3n2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.