

REF: CS/FCI 19002942/Kub3n2 Special Instruction
 ASSIGNMENT (Office)
 From (Person): Hunny kao of FCI Date/Time: 9:44am @ 15/2/19
 Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. SJW 197B Insured: SHC 7247Z

at Workshop in/ Hua Hong Tel: 6661 9688

of 250 Surgeni Road St. 1

Policy No. Claim No. D19001038MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 4/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{1 up} H.O.D. Endorsement:

Date/Time: 10:14am @ 15/2/19 Person Contacted: jerleen Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SJW 197B-X

SHC 7247Z - CC3/CT118001823/Kub3n2 DOA: 26/1/2018

12/3/19 Email preli revised to FCI

27/3/19 @ 5:31pm Mrs Tan will email us finalised

23/5/19 @ 11:03am Final fig \$ 712 confirmed with Mrs Tan (Ref 2562-440, 7820)
 (No LS)

000000

Passau

REF:

66880

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SW 197B**
 at Workshop n/s: **Hua Hong**
 of: **Sunhai Keng**
 Insured: **FCI**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **16K**
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SW 197B** Yr Bgn: **2010** / **Per**
 Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or
 Make: **Honda AIRWAVE 1.8MA** cc **1496**
 Colour: **WHITE** A/C: ☐ Insured / Std / Nil / NA
 Sp Reading: **180546** T/Radio: ☐ Insured / Std / Nil / NA
 Eng/No: _____
 C/No: **GJ11306653**
 Gen. Cond: Good ☒ Fair / Poor / Burnt
 Steering: ☒ Harder / Jammed / Leaked / Burnt or
 Brake: ☒ Harder / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ R/Rim / STD A/Rim or
 Tyre Size: F: **215/45 R17**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: **6** mm Rear: **6** mm
 R/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **04/02/19** D.O.I: **07/03/19**
 Survey held at: **Hua Hong**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 MAY 2019

[Signature]
 23/5/2019

Date/Time: File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Date/Time: File Return to?

21 **23/5- typist**

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Workshop (\$)

Report Format: **CWS**

Lump Sum / L.B. (\$) **712/2**

Survey Fee:

Transportation:

2. Survey Fee:

3. Charge:

4. Others:

5. Total:

6. Total:

130
50
50
30

260



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001038MFSH

Our Ref: CS/FCI19002942/R1vd3

Date : 12/3/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJW 197B


We thank you for your instruction on 15/2/2019

Please be informed that we had conducted the inspection of the above mentioned
7/3/2019 at the premises of M/s HUA HONG PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$3,274.40
Revised Estimate Amount	: S\$616.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s front poriton



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-02-2019	Our Ref No. D19001038MFSH
Accident Date	04-02-2019	Claim Type. Third Party
Insured Vehicle	SHC7247Z	Third Party Vehicle. SJW197B
Survey Location	25D SUNGEI KADUT STREET 1	
Contact Person.	JERLEEN TANG	
Contact No.	66619688/ 0	Fax No. 66619699
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA HONG PRIVATE LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 16 May 2019 9:27 AM
To: Ashley Tan
Cc: Veron Chen (LKKAUTO)
Subject: RE: Finalisation for Vehicle No. SJW197B

Hi Ashley,

Finalised amount is \$ 712 / 3 days part by part
Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Ashley Tan [mailto:ashley@huahong.com.sg]
Sent: Monday, 8 April, 2019 12:18 PM
To: Veron Chen (LKKAUTO); Rasul (LKKAUTO)
Subject: Finalisation for Vehicle No. SJW197B

Dear all

Please refer to the files attached for:-

- After paint
- Front fender inner shield

Please confirm LS finalisation.

Thanks & Regards

Ashley Tan



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9690 | M. 9816 4151 | F. 6661 9699
Follow us @ huahong.com.sg



Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 12 March 2019 9:33 AM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001038MFSH/1, SJW 197B
Attachments: SJW 197B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJW 197B
Date of survey: 7/3/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 15 February 2019 10:22 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001038MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 15 February 2019 9:44 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001038MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6688D
Vehicle Details	
Vehicle No.:	SJW197B
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L15A5208135
Chassis No.:	GJ11306653
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$17,974.00
Original Registration Date:	26 Feb 2010
First Registration Date:	26 Feb 2010
Transfer Count:	3
Actual ARF Paid:	\$17,974.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2020
PARF Rebate Amount:	\$8,987.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,340.00
COE Rebate Amount:	\$1,963.00
Total Rebate Amount:	\$10,950.00

The information contained herein is correct as at 08 Mar 2019

OK

16,000
10,950
5050



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

26 February 2019

First Capital Insurance Limited
36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SJW 197 B & SHC 7247 Z ON 04/02/2019 AT JURONG WEST ST 64
AT ABOUT 1615 HOURS

Insured : LIM SONG SENG (LIN SONGSHENG)
Vehicle Registration No : SJW 197 B
Vehicle Make : HONDA
Vehicle Model : AIRWAVE 1.5M A
Vehicle Chassis No : GJ11306653
Policy No : MP306035
Date of Accident : 04/02/2019

LKK Auto Consultants hereby notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party sum HHTPClaims19-25 basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

			Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper repair X		\$ 1,050.00
2	10	Front Bumper Clip re- /	\$ 2.00	\$ 20.00
3	1	Front Fender (RH) repair X		\$ 570.00
4	1	Front Fender Inner Shield (RH) repair X		\$ 120.00
5	1	Front Head Lamp (RH) X 11	140	\$ 635.00
6	1	Front Head Lamp Bracket (RH) X 11	20%	\$ 48.00
			112	\$ 2,443.00
			Less 20%	\$ (488.60)
				\$ 1,954.40

To dismantle & change front bumper, front RH head lamp, front RH fender,
knocking & pull straight front RH wheel house panel

To perform wire checking

To perform 4 wheel alignment

To spray front bumper, front RH fender and touch up front RH wheel house

7% GST

Total

\$ 600.00
\$ 20.00 X 11
\$ 100.00 X 11
\$ 600.00 X 11
\$ 3,274.40
\$ 229.21
\$ 3,503.61



Authorised by Claims Dept
Mrs Tan @ 9639 9195



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002942/R1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7247Z	Veh. Inspected	SJW 197B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001038MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	15/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA AIRWAVE 1.5M A	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	GJ11306653	Colour	WHITE	
Odometer	180546	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/02/2019	Inspection Date	07/03/2018	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 197B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,050.00	-
10	FRONT BUMPER CLIP @\$2.00	NECESSARY	20.00	20.00
1	FRONT FENDER (RH)	TO REPAIR SEE LABOUR	570.00	-
1	FRONT FENDER INNER SHIELD (RH)	CUT	120.00	120.00
1	FRONT HEAD LAMP (RH)	NOT NECESSARY	635.00	-
1	FRONT HEAD LAMP BRACKET (RH)	NOT NECESSARY	48.00	-
1	TYRE PRESSURE KIT (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-488.60	-28.00
			1,954.40	112.00
	LABOUR			
	TO DISMANTLE & CHANGE FRONT BUMPER,FRONT RH HEAD LAMP,FRONT RH FENDER,KNOCKING & PULL STRAIGHT FRONT RH WHEEL HOUSE PANEL.		600.00	200.00
	TO PERFORM WIRE CHECKING.	NOT NECESSARY	20.00	-
	TO PERFORM 4 WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO SPRAY FRONT BUMPER,FRONT RH FENDER AND TOUCH UP FRONT RH WHEEL HOUSE.		600.00	400.00
			1,320.00	600.00
	GRAND TOTAL		3,274.40	712.00

RECOMMENDED COST OF REPAIRS			712.00
------------------------------------	--	--	---------------

Report Ref No. CS/FCI19002942/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.