

ASS. REC. BY:

REP: CS/FCI19002944/Utd3n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

(WS)

From (Person): Karen Tan

of FCI

Date/Time: 5:35pm @ 15/2/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKE 3670P

Insured: SH 9676Z

at Workshop in/s SME Motor

Tel: 6747 6106

of 1 Kaki Bkt Ave 6 # 02-15

Policy No:

Claim No: D19000931 MFSH

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 1/2/2019

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsment:

Date/Time: 1:32pm @ 15/2/19

Person Contacted:

poi ying

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKE 3670P - X

SH 9676Z - X

Job-

Revised via email preli advise.

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

FCI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKC 3670P
at Workshop m/s Sme Ham
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: Ask
IDAC Accident Rpt: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LN 69938

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKC 3670P Yr Regn: 212
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or LA
Make: BMW 730Li c.c. 2996
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 100643 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBAKB22020C951422
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: M / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 245/50R18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
L/Bal. 6 mm D.O.A. 11/2/19 D.O.I. 19/2/19
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
8/3/19 confirmed L/S @ 2000 with Atty
(Red: 1713.46; 46%)

RECEIVED 13 MAR 2019

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

1) 133 Typist
Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:
Transportation: 50
S + RS. 50
Photos 29
Others

130
50
50
29
TOTAL
259

Report Format: TP

Lump Sum / I.B.I: (\$ 2000)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000931MFSH

Date: 20/2/2019

Our Ref: CS/FCI19002944/Utd

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKE 3670P

Please be informed that we had conducted the inspection of the abovementioned vehicle 19/2/2019 at the premises of M/s SME Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,713.46</u>
Revised Estimate Amount	: S\$ <u>2,535.52</u>
"Check" Items Amount	: S\$ <u>865.65</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-02-2019	Our Ref No. D19000931MFSH
Accident Date	01-02-2019	Claim Type. Third Party
Insured Vehicle	SH9676Z	Third Party Vehicle. SKE3670P
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT	
Contact Person.	PEIYING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 20 February 2019 4:11 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000931MFSH/1
Attachments: PRELI ADVISED SKE 3670P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKE 3670P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 15 February 2019 1:35 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000931MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now



Flexible Loan, Trade In Are
Welcome. 100% Deposit Refund
For Unapproved Loan.
Classic Credit StarAd



Browse by Category

Sort by Date Posted

7 vehicles

730

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	730		Any	Any	2012	Any	Any	
	BMW	7 Series 730Li Sunroof	\$86,888	\$17,190 /yr	28-Feb-2012	2,996 cc	58,000 km	
One Of The Best Unit With Lower Mileage And Full PML Service History. Selling At Reasonable Offer.								
Posted: 20-Feb-2019 Tags: 2012 BMW 730Li, 2012 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	BMW	7 Series 730Li Sunroof	\$82,800	\$15,590 /yr	01-Mar-2012	2,996 cc	91,000 km	
Well Kept And Maintained By Previous Owner, PML Agent Unit, Genuine Low Mileage! Serviced Regularly. Pristine Stock Condition With View To Believe! Ultimate Driving Performance, Excell...								
Posted: 14-Feb-2019 Tags: 2012 BMW 730Li, 2012 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	BMW	7 Series 730Li Sunroof	-	N.A	28-Feb-2012	2,996 cc	125,747 km	
Auction Closing Time: 20th Feb 2019 at 05:00 PM								
Tender Applicable To Business Entities Only. Road Tax Due On 27/02/2019. Road Tax Renewal Fee: \$1241.00								
Posted: 13-Feb-2019 Tags: 2012 BMW 730Li, 2012 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	BMW	7 Series 730Li Sunroof	\$84,800	\$16,200 /yr	27-Feb-2012	2,996 cc	84,000 km	
PML Agent Unit, Low Mileage Of 84000Km. Pristine Condition Vehicle Interior/Exterior. Very Well Taken Care Of By Previous Owner. No Needed. Accident Free. In House Finance Available! Attractiv...								
Think One Automobile & Trading								
Posted: 12-Feb-2019 Tags: 2012 BMW 730Li, 2012 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								
	Pioneer	D-Series Component Speaker Package						
Pioneer delivers sonic excellence and performance quality with the new D-Series TS-D1730C component speakers, featuring Twaron tec								
Read this article								
	BMW	7 Series 730Li Sunroof	\$103,900	\$17,650 /yr	26-Dec-2012	2,996 cc	112,981 km	
Luxurious At Its Best. 7 Series Has Long Been A TOP Favourite For Luxurious Business Car. Combining Look, Performance As Comfort In Vehicle. This Is Great For Business Professional Or Even ...								
ad: 30-Jan-2019 Tags: 2012 BMW 730Li, 2012 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW								

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7632A
Vehicle Details	
Vehicle No.:	SKE3670P
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	11007965N52B30AF
Chassis No.:	WBAKB22020C951422
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$73,293.00
Original Registration Date:	27 Feb 2012
First Registration Date:	27 Feb 2012
Transfer Count:	0
Actual ARF Paid:	\$73,293.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2022
PARF Rebate Amount:	\$47,640.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$73,890.00
COE Rebate Amount:	\$22,298.00
Total Rebate Amount:	\$69,938.00

The information contained herein is correct as at 20 Feb 2019

OK

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01
 CITY HOUSE
 Singapore 068877
TEL: 65073848 **FAX:** 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-028 (02)
Claim Type: Third Party
Accident Date: 01/02/2019
TP Veh Reg No: SH9676Z

Estimate No: EST0004644
Date: 14 Feb 2019
Policy No: D18MTPV01003545
Veh Reg No: SKE3670P
Make/Model: BMW 730LI
Chasis No: WBAKB22020C951422
Engine No: 11007965N52B30AF
Reg. Date: 27/02/2012

Estimate Repair Cost to Vehicle No :SKE3670P

Description	Quantity	List Price	Amount
		SS	SS
List Price			
1 REAR BUMPER	1 PC	1,674.00	—
2 REAR BUMPER CLIP	10 PC	30.00	—
3 REAR BUMPER REINFORCEMENT	1 PC	865.65	✓
4 REAR BUMPER REVERSE SENSOR	1 PC	368.80	✓
5 REAR BOOT CENTER LOGO	1 PC	69.50	✗
6 REAR BOOT '730I' EMBLEM	1 PC	62.55	✗
		3,070.50	
	Less 10%	307.05	2,763.46
Labour			
7 WIRE CHECKING	1 UNIT	30.00	20
8 REPROGRAMME REVERSE SENSOR	1 UNIT	120.00	50
9 LABOUR CHARGE	1 UNIT	300.00	200
10 SPRAY PAINTING	1 UNIT	500.00	400
		950.00	950.00
	Total		SS 3,713.46
	Add GST @ 7%		259.94
	Total Amount Payable		SS 3,973.40

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED SEVENTY THREE AND CENTS FORTY ONLY

not held
rec
2/5 \$ 2000
3000
19/2/19
take the other eye

For SME Motor Pte Ltd

2072-8
 2536-50

AUTHORISED SIGNATURE to notify

- the following conditions apply:
- The repair must be done by spray painting
- All damaged parts must be replaced during recovery
- All work must be done on a "Without Prejudice" basis
- Approval of the insurance company is required
- Any work done must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002944/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-03-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9676Z	Veh. Inspected	SKE 3670P
Policy No.		Coverage (\$)	0.00
Claim No.	D19000931MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	15/02/2019
2. Vehicle Particulars & Condition			
Make & Model	BMW 730LI (A)	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBAKB22020C951422	Colour	BLACK
Odometer	100643	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/50 R18	PIRELLI	6 mm
L/H Front Tyre	245/50 R18	PIRELLI	6 mm
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/02/2019	Inspection Date	19/02/2019
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 3670P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,674.00	1,674.00
10	REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	865.65	-
1	REAR BUMPER REVERSE SENSOR	SHORTED	368.80	368.80
1	REAR BOOT CENTRE LOGO	NOT NECESSARY	69.50	-
1	REAR BOOT "730I" EMBLEM	NOT NECESSARY	62.55	-
	LESS 10% DISCOUNT		-307.04	-207.28
			2,763.46	1,865.52
LABOUR				
	WIRE CHECKING.		30.00	20.00
	REPROGRAMME REVERSE SENSOR.		120.00	50.00
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		300.00	200.00
	SPRAY PAINTING.		500.00	400.00
			950.00	670.00
GRAND TOTAL			3,713.46	2,535.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/FC119002944/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.