36.92062 ASS, REG, BY:		REF CS3/FC	19002945 Eco	3. Special Induscrion:
CMS -	Steve tor	ASSIG	NMENT (Office)	Date/Fime: [Hlames 15/2/19
From (Person): Estimated Cost: OD / TV WS To Inspect Veh	TTP RES / OD RE		Bill to:	Insured: SHA 538 9X
at Workshop u	Js	spoodu	Motorcycle Ind. Parle 2A	Tel: 64815567 #05-21 DIGOOO80MF84
Policy No: Sum Insured: Make of Veh: (Client's Record			Excess: _	D.O.A. 11/00/2019
CA / REV	/ REP. / REV 24 -		acted: YIYI-	H.O.D. Endorsement: Vehicle IN JOUT
Date/Time	FBC 3RET Z	(X) Est		
	SHA 5389 Diemantle	200 C/81:	00.2891 Klvd3	DOR: 11/2/2019

ASILAMENT

20.	
tion. Date:	FBC 38872 VERSON 27/02/08
Estimated Cost	Type: M.Car/ (1.Gyste)/Eus/Van/Lorry/Taxi/Prime Mover/
OD/TE/WS/TERES/ODRES/EVA/INV/MV	- Truck / Trailer or
to in pect Vehicle No	Make SYZYKI OL 1090 K8 996
at Work thep unes	Colour Gifty A/C Insured / Std / NL/ NA
	Sp.Reading 74817 T/Radio Insured / Std / NE/ NA
· of	Eng/No:
Instruct.	JS 18 S 1111 00 123 698
Folicy No	Gen. Cond. Good / Cair Poor / Burnt
Chams Ho Sum houred Excess	Steering (norder) Jammed / Leaked / Burnt or
	Brake: norder Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / 6/Rim / STD A/Rim or
Make of Veh:	110 00 019
X	150/70 017
(Policy Condition)	
Remark. The veh had commenced its repair at the time of inspection.	- 116
repair at the time of dispection.	1
Bal. or Market Value.	Front Rear
IDAG Accident Rport. Consistent7 : Yes or No	R/Bal 6 mm
GIA / PR Seen Consistent? : Yes or No	L/Bal. mm L/Bal. mm
Est Repairs. days Res.: Yes or No	D.O.A. 11/02/19 D.O.1 15/2/19 2.381
Lum Sum: % 3 Val.: Yes or No	Survey held at Spee dy Motor
GA / REV / REP. / 24 HRS Vehicle: IN / O	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Confacted.	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	.,,
MV - 15,000 PV - 5293 NV - 9,707	
PV - 5293	
NV - 9,101	
25/2/200	(· · · · · · · · · · · · · · · · · · ·
	4. 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
Outofine Feb Eass to Proli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee
Date/Time, File Reform 197	Transportation
Add F	Invested 1
	Internew (\$) Helio
Report Format : PRC .	tech this (\$) office.
Lumo Sym / LB !: /5	West-and is



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068977 Tel: (65) 6507 3848 Fax: (55) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

13-02-2019

Our Ref No. D19001080MFSH

Accident Date

11-02-2019

Claim Type. Third Party

Insured Vehicle

SHA5389X

Third Party Vehicle. FBC3887Z

Survey Location

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #05-21

Contact Person.

MR LIM SAM HEE

Contact No.

64815567/93886867

Fax No. 64825567

Survey Type

WITHOUT PREJUDICE: NO EST. * (NAF)

Appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

SPEEDY MOTOR CYCLE

Attention. NIL

P

SERVICE CENTRE
JUSEQUITY LAW

Cc: TP Solicitor

CORPORATION

TP Solicitor Fax No. NA

Officer Incharge

SERENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 14/02/2019 17:23

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

9000

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

TO THE REPORT OF THE PARTY OF T	ACCIDENT STATEMENT
Date Of Report	14/02/2019 15:15
Date Of Accident	11/02/2019 19:25
Exact Location Of Accident	GEYLANG ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	FBC3887Z
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD ARIFIN MUSTAFA
NRIC No	S8102428F
Email Address	ARIFINMUSTAFA24@GMAIL.COM
Mobile Phone No	(LOCAL) +65-84822463
Alternative Phone No	OTHERS-84822463
Vehicle Particulars	
Manufacturer	SUZUKI
Model	DL1000K8
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE, LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D18MTMC01000619
Cover Note Number	27/01/2018 - 26/02/2019
Driver	
Name of Driver	MUHAMMAD ARIFIN MUSTAFA
NRIC No	S8102428F
Date Of Birth	24/01/1981
Occupation	INDOOR
Date Of Driving Pass	02/11/2011
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84822463
Fax Number	

OTHERS-84822463

ARIFINMUSTAFA24@GMAIL.COM

Address

BLK 55 MARINE TERRACE #03-05

Postcode

440055

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident Was any body injured in the Accident?

Was any injured conveyed to hospital by

YES

ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

4

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

MARINE PARADE N.P.C

Police Station Address

ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO.: T/20190212/2086.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHA5389X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

ivo. Or Passenger (including Driver)	· · · · · · · · · · · · · · · · · · ·
Carrier and the property of	DETAILS OF INJURED PERSON 1
Name	MUHAMMAD ARIFIN MUSTAFA
Approximate Age	
Injuries Sustain	ABRASION ON LEFT FINGER, ELBOW, KNEE, PAIN ON CHEST, HEEL & SPINE AREA
Injured person in which vehicle?	FBC3887Z
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

2 of 3

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296

Tel No: 1800-4428999

AB

CONTINUATION OF REPORT

Report No. T/20190212/2086

Details of Perso	on Involved	We take periods	CANTES SHOW	0-12ma-13m	17 MS-1106	
Any Pedestrian I	nvolved: No		Control of the Control			
No. of Pedestria	ns Injured: NIL		Use of Pe	doctrio	n C	in was kin
Rider	A THE PROPERTY OF STREET	7.5 SEC. 19.55	CSC OF FE	uestria	III Cross	sing: NA
Name	MUHAMMAD ARIFIN MUSTAFA		ID No	D.	S8102428F	
Related Vehicle	FBC3887Z (Motorcycle)		Conta	act No.	84822463	
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class Drivin Licen Expin	ng	Class: 2B,2A,2,3 Date of Expiry: NIL	
Date Treatment	ate Treatment 11/02/2019		Date Disch		-	/2019
No. of Days granted Medical Leave 05			Degree of			

Brief Details.

On 11.02.2019 at 1930hrs I was riding my motorbike (FBC3887Z) alone on the second lane along Geylang Road. I was at the traffic light and there was taxi (SHA5389X) on my right side. When the traffic light turned green the taxi beside me was also half turning right.

When I turned into the right lane the taxi suddenly went straight instead of turning right. Due to that he collided with my motorcycle. I fell out from my motorbike and I was in the shock state and I was unable to call who talk to me and all. I felt pain and I could not stand up. There is passer-by (Hakim, hp91145907) assisted me throughout the accident. The driver approached me and asked whether am I ok.

After which I was conveyed by ambulance to Tan Tock Seng Hospital and I was given 5-day MC and I suffered abrasion on my left finger, elbow, knee, pain of the left chest and the heel area and also pain at my spine area

> Back to OneMotoring

Enquire Transfer Fee

enquire manarer rec			
Vehicle Details			
Vehicle No.:	FBC3887Z		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Mo	ped	
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	SUZUKI		
Vehicle Model:	DL1000K8		
Chassis No.:	JS1BS111100123698		
Propellant:	Petrol		
Engine No.:	T507140028		
Engine Capacity:	996 cc		
Maximum Power Output:	*		
Maximum Laden Weight:			
Unladen Weight:	208 kg		
Year Of Manufacture :	2007		
Original Registration Date:	27 Feb 2008		
Lifespan Expiry Date:	•		
COE Category :	D - Motorcycle		
PQP Paid:	\$5,910.00		
COE Expiry Date :	31 Jan 2028		
Road Tax Expiry Date:	26 Feb 2019		
Inspection Due Date :	26 Feb 2019		
Intended Transfer Date :	16 Feb 2019		
CO2 Emission :	*		
CO Emission :	•		
HC Emission :	•		
NOx Emission :	*		
PM Emission :	\$(
The current road tax expiry is 26 renewed after 26 Feb 2019, later	Feb 2019. You may renew the road tax from 27 No renewal fee(s) will be imposed. Please use Enquire	ov 2018 with all pre-requisite(s) full	filled. If the road tax is
Road tax, including Over Paymen Amount Payable (From 27 Fe	t (if any), of a vehicle will follow the vehicle to the	new registered owner when its own	nership is being transferred.
	Amount Before GST	GST Amount	Amount After GST
	(5\$)	(5\$)	(\$\$)
Transfer Fee :	25.00	•	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	150.00	1. e 11	150.00
Total Amount Payable :	h 2019 to 24 Eab 2020)		175.00

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	•	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	150.00		150.00
Total Amount Payable : Amount Payable (From 27 Feb 20	19 to 26 Feb 2020)		175.00
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00		25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	300.00	12	300.00
Total Amount Payable :			325.00
Various and a ship and a facility	•		

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	2428F	
Vehicle No.:	FBC3887Z	
Vehicle to be Exported:	No	
Intended Deregistration Date:	16 Feb 2019	
Vehicle Make:	SUZUKI	
Vehicle Model:	DL1000K8	
Primary Colour:	Grey	
Secondary Colour:	Black	
Manufacturing Year:	2007	
Engine No.:	T507140028	
Chassis No.:	JS1BS111100123698	
Maximum Power Output:		
Open Market Value:	\$10,282.00	
Original Registration Date:	27 Feb 2008	
First Registration Date:	27 Feb 2008	
Transfer Count:	9	
Actual ARF Paid: Intended PARF Rebate Details	\$1,543.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	4	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	31 Jan 2028	
COE Category:	D - Motorcycle	
COE Period(Years):	10	
PQP Paid:	\$5,910.00	
COE Rebate Amount:	\$5,293.00	
Total Rebate Amount:	\$5,293.00	

The information contained herein is correct as at 16 Feb 2019


OK



Home (/) → Motorbikes (/categories/motorbikes-108) → Motorbikes for Sale (/categories/motorbikes-108/motorbikes-for-sale-1592) rbikes-108/motorbikes-for-sale-1592/class-2-1593)



Share This Listing



u=https://sg.carousell.com/p/suzuki-v-strom- url=https://sg.can 2002-model-196570332/) v-strom-2002-mo

Public Comments

Be the first to write a public comment. Ask a question or Imention a friend to check this out!

Post a New Comment

Suzuki V Strom 2002 model





Getting This


Meet The Seller



Feedback (/wizegut/) ⊕85 ⊕2 ⊕3 >







Read All (/wizegut/)

YOU MAY ALSO LIKE

Home (/) > Motorbikes (/categories/motorbikes-108) > Motorbikes for Sale (/categories/motorbikes-108/motorbikes-for-sale-1592) rbikes-for-sale-1592/class-2-1593)




Suzuki DL1000 V-Strom 31 Aug 2005

♥ 20	Chat	Make Offer				
⊕ 4 we	eks ago by jasb	ay (/jasbay)				
Ø S\$8,	000					
© 20 L	© 20 Likes					
⊕ Used	1					
· In Ci	ass 2 (/categorie	es/class-2-1593)				
whe good trad- resa tip-t	Own a used one at \$8k - COE till Jul 2023 when new would set you back \$37k, Very good condition- see pictures. Open to trade with any other bikes with similar resale value. Note: I'm 1.8m and I've to tip-toe so do your own assessment on the					
Suzu	ıki					
Adve	enture					

0

Share This Listing



(https://www.facebook.com/sharer/sharer.php? url=https://sg.can u=https://sg.carousell.com/p/suzuki-dl1000-v- dl1000-v-strom-3 strom-31-aug-2005-210256567/)

(https://twitter.co 210256567/)

Public Comments

Be the first to write a public comment. Ask a question or @mention a friend to check this out!

Post a New Comment

Getting This

6 Meet-up

Redhill Market & Food Centre (https://www.google.com/maps/place/1.2873)

Meet The Seller




jasbay (/jasbay/) Joined 3 years ago. Verified 👼

Feedback (/jasbay/) □38 □0 □0 >

















Read All (/jasbay/)

YOU MAY ALSO LIKE



YOU MAY ALSO LIKE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR	NSPECTION REPORT	Conversable Report	
MS	FIRST CAPITAL IN	ISURANCE LTD	Ref: CS3/FCI1900294	5/Ecd3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 27-02-2019			
			Code: FCI2		
1.		Policy Particu	lars :- (THIRD PARTY CLAIN	1)	
	Insured Veh.	SHA 5389X	Veh. Inspected	FBC 3887Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D19001080MFSH	Excess (\$)	0.00	
	Assign From	SERENE LER	Assign Date	15/02/2019	
2.		Vehicle	Particulars & Condition	WE STATE OF THE	
	Make & Model	SUZUKI DL1000K8	c.c	996	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	JS1BS111100123698	Colour	GREY	
	Odometer	74817 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	1. 并列口原则	Co	enditions of Tyres	MISSIST STREET	
		Size	Make	Balance	
	R/H Front Tyre	110-80 R19	METZELER	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	150/70 R17	METZELER	6 mm	
	L/H Rear Tyre			mm	
4.		Desc	cription of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE	N/S AND O/S BODY		
5.		Ge	neral Information		
	Accident Date	11/02/2019	Inspect Date / Time	15/02/2019 (02:35 PM)	
	Survey held at	SPEEDY MOTOR CYCLE S	SERVICE CENTRE		
		BLK 10 ANG MO KIO IND.P	ARK 2A #05-21 SINGAPORE 56	8047	
5a.		THE STREET, ST	Remarks		
	B) THE REPAIR E: THE REPAIRER W	STIMATE WAS NOT PRESE! IAS TOLD TO PREPARE THI EASE FIND DAMAGED VEH!		S. TION.	

Report Ref No. CS3/FCI19002945/Ecd3s2

Inspected By

6

CHEN TSUE YEE **Automotive Assessor** K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or torf, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.