COMFORTDELGRO ENGINEERING

Our Ref: 3092 69477

Date: (8.02.2019

Time of Fax : 0955km

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Your Insured : SOW 8804 4

Date of Acc: 15.02.2019

Workshop

Attn: Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHC 8518 K

Loyang 59 Loyang Drive Singapore 508969 Fax no. 6546 8156

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Tel no. 62148355 or Hp no. 98240811 Lim Kwok Eng.

Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305

Tel no. 62148398 or Hp no. 96358546 Lim Tien Siona

Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006 Fauzy Bin Mokhtar Tel no: 62148319 or Hp no: 81259176

Larry Ng Tel: 6214 8316

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

Larry Ng

for Vice President Crash Repairs & Claims Recovery











COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 8518K

DATE 16/2/2019 11:47

MAKE

Qty	: HYUNDAI i40 Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 544.50
	Front Bumper Bracket (LH)			\$ 24.60
	Headlamp (LH)			\$ 1,388.00
	Front Fender (LH)			\$ 566.30
	Front Fender Shield (LH)			\$ 175.90
	Tront render Sineid (E11)			Φ 1/3.90
	SUB TOTAL			\$ 2,699.30
	LESS 20%			\$ 539.86
	DISCOUNTED TOTAL			
	DISCOUNTED TOTAL			\$ 2,159.44
		-		
				.04
	Labour Charge			
	Panel Beating			\$ 500.0
	Spray Painting Charge			\$ 500.0
	Wiring			\$ 30.0
	Tuff Kote			\$ 50.0
	TOTAL LABOUR			\$ 1,080.0
				, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	ESTIMATE TOTAL			\$ 3,239.4
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
		9.		
Larry Ng				
Lu				
	This is an initial estimate based on a visual inspection of the	e above vel	nicle. The final renai	r quantum will
	be prepared after the vehicle is surveyed by a motor Surve			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.		
The secretary of the second	ACCIDENT STATEMENT	
Date Of Report	16/02/2019 12:21	
Date Of Accident	15/02/2019 21:35	
Exact Location Of Accident	FLYOVER FROM PIE TO CTE AMK	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC8518K	
Insured/Policyholder		
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD	
Co Reg No	199303821R	
Email Address	FLEETSAFETY@CDGTAXI.COM.SG	
Mobile Phone No		
Alternative Phone No	OFFICE-65508768	
Vehicle Particulars		
Manufacturer	HYUNDAI	
Model	140	
Exact Purpose for which vehicle was being used a time of accident	at	
Are you claiming under your own insurance policy for repair to your vehicle?	[/] NO	
If No, Please state action to be taken	THIRD PARTY	
Vehicle Category	TAXI	
Insurance Company		
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD	
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT	
Fleet Policy	YES	
Policy Number	D-18088936MFSH	
Cover Note Number		
Driver		
Name of Driver	SEE THO SOOK HAN	
NRIC No	S7218707E	
Date Of Birth	30/05/1972	
Occupation	OUTDOOR	
Date Of Driving Pass	06/01/2005	
Driving Experience	14 YEARS AND 1 MONTH	
Gender	FEMALE	
Mobile Number	(LOCAL) +65-96556201	
Fax Number		

ISAACTAN51@YAHOO.COM.SG

Address

573A #06-630 WOODLANDS DR16

Postcode

731573

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJW8804E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAN TIONG KENG CYRIL

NRIC/Passport Number

S0182663H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR RHT

No. Of Passenger (Including Driver)

rétch plan	
+++++++++++	╎╏╏╏╏╏╏╏╏╏╏╏╏╏╏╏╏╏╏╏╏╏
HIAISHCIBE	╡ ╫ ┇╫╛┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼
B: 37W 82	
+++171-17111-195	11-11-11-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
- - - - - - - - - -	╌┼┼┼┼┼╎┼┼╎╎┼┼┼┼╬╚╗┼┼┼┼┼┼╎╎╎┼┼├┤┼╎╵
DESCRIBE CIRCUMSTANCES OF T	THE ACCIDENT .
On	15/2/19 at about 09:40 his, I was
	The state of the s
1	
slowly arinha	at above said to cation. due to
the truffec con	ndition. Suddenly Weh B come out
THE CONT	Ton the state of t
0	
from my 1ety	squeezed. through a small gap
	,
hoeween min to	oni and the railing. As it took place
. 1 :	
two fast, 1 (could not take evasive action to preven
	!
the collision	As a result, Veh B of right rear
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
portion his au	nd grazed oneo the funt left
1	
portion of min	-luxi: Ol male passumer on boa
1	The state of the s
my tenxi Mo	injum reported at the point of
aceident.	
DECLARATION	Δ
I/We declare the foregoing particular	, , , , , , , , , , , , , , , , , , , ,
COMFORT TRANSPORTATION	N PTE LI- All Was Yieng
CO. REG. NO. 1993038	3218
Policyholder's Signature	Driver's Signature Reporting Centre Personnel's Signature
Date & Time:	(If driver is not the policyholder) Name:

Sketch Plan Pg. 2

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CO. REG. NO. 199303821R /

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .: