



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002978/Bga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 09-10-2019



ATTN: XINYOU

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 5808Z	Veh. Inspected	SLW 8250D
Policy No.	GA186933	Coverage (\$)	0.00
Claim No.	S9M01DWN	Excess (\$)	0.00
Assign From	XINYOU	Assign Date	18/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA MARK X 2.5G	c.c	2499
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GRX1203069260	Colour	BLACK
Odometer	161279	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GOODYEAR	6 mm
L/H Front Tyre	215/60 R16	GOODYEAR	6 mm
R/H Rear Tyre	215/60 R16	GOODYEAR	6 mm
L/H Rear Tyre	215/60 R16	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/02/2019	Inspection Date	25/02/2019
Survey held at	JKS MOTOR WORKS PTE LTD 8 KAKI BUKIT AVE 4 #03-45 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------